2010 ENGINE General Information (Engine Mechanical) - Tucson

2010 ENGINE

General Information (Engine Mechanical) - Tucson

SPECIFICATIONS

GENERAL SPECIFICATIONS

Description	Specifications	Limit
General		
Туре	In-line, Double Overhead Camshaft	
Number of cylinder	4	
Bore	86mm (3.385in) / 88mm (3.464in)	
Stroke	86mm (3.385in) / 97mm (3.819in.)	
Total displacement	1998cc (121.92in) / 2359cc (143.90cu.in.)	
Compression ratio	10.5	
Firing order	1-3-4-2	
Valve timing	•	•
Intake valve		
Opens (ATDC / BTDC)	ATDC 7° ~ BTDC 38°	
Closes (ABDC)	ABDC 67° ~ 22°	
Exhaust		
Opens (BBDC)	BBDC 44° ~ 4°	
Closes (ATDC)	ATDC $0^{\circ} \sim 40^{\circ}$	
Valve	·	·
Valve length		
Intake	113.18mm (4.4559in.)	112.93mm (4.4460in)
Exhaust	105.84mm (4.1669in.)	105.59mm (4.1570in)
Stem O.D.		
Intake	5.465 ~ 5.480mm (0.2151 ~ 0.2157in.)	
Exhaust	5.458 ~ 5.470mm (0.2149 ~ 0.2153in.)	
Face angle	45.25° ~ 45.75°	
Margin		
Intake	1.02mm (0.0401in.)	
Exhaust	1.09mm (0.0429in.)	
Valve stem to valve guide c	learance	
Intake	0.020 ~ 0.047mm (0.00078 ~ 0.00185in.)	0.07mm (0.00275in.)

jueves, 18 de febrero de 2021 11:47:49 p. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.
--	--------	--

Exhaust	0.030 ~ 0.054mm (0.00118 ~ 0.00212in.)	0.09mm (0.00354in.)
Valve guide		
Length		
Intake	43.8 ~ 44.2mm (1.7244 ~ 1.7401in.)	
Exhaust	43.8 ~ 44.2mm (1.7244 ~ 1.7401in.)	
Valve seat		
Width of seat contact		
Intake	1.16 ~ 1.46mm (0.0457 ~ 0.0575in.)	
Exhaust	1.35 ~ 1.65mm (0.0531 ~ 0.0649in.)	
Seat angle	44.75° ~ 45.10°	
Valve spring		
Free length	47.44mm (1.8677in.)	
Load	19.0 ± 0.6kg/35.0mm (41.88 ± 1.32lb/1.3779in.)	
Squarences	39.8 ± 1.2kg/26.0mm (87.74 ± 2.64lb/1.0236in.)	
	1.5° MAX.	
Valve clearance		
Cold	(20°C[68°F])	
Intake	0.17 ~ 0.23mm (0.0067 ~ 0.0090in.)	$0.10 \sim 0.30$ mm ($0.0039 \sim 0.0118$ in.)
Exhaust	0.27 ~ 0.33mm (0.0106 ~ 0.0129in,)	0.20 ~ 0.40mm (0.0078 ~ 0.0157in.)
Cylinder head		
Flatness of gasket surface	Max. 0.05mm (0.0019in.)	
Flatness of manifold mounting surface	Max. 0.10mm (0.0039in.)	
Cylinder block		
Cylinder bore [2.0 / 2.4]	86.00 ~ 86.03mm (3.3858 ~ 3.3870in.) / 88.00 ~ 88.03mm (3.4645 ~ 3.4657in.)	
Out-of-round and taper of cylinder bore	Less than 0.05mm (0.0019in.)	
Clearance with piston	0.015 ~ 0.035mm (0.0005 ~	
(To set limits to new parts)	0.0013in.)	
Piston		
	85.975 ~ 86.0050mm (3.3848 ~	

jueves, 18 de febrero de 2021 11:47:46 p. m.	Page 2	© 2011 Mitchell Repair Information Company, LLC.
--	--------	--

O.D (To set limits to new parts) [2.0 / 2.4]		ew parts)	3.3860in.) / 87.975 ~ 88.005mm (3.4635 ~ 3.4647in.)	
Ring groove	width			
No. 1			1.235 ~ 1.250mm (0.0486 ~ 0.0492in.)	1.26mm (0.0496in.)
No. 2			1.230 ~ 1.250mm (0.0484 ~ 0.0492in.)	1.26mm (0.0496in.)
Oil ring			2.01 ~ 2.03mm (0.0791 ~ 0.0799in.)	2.05mm (0.0807in.)
Piston ring				
Side clearance	e			
No. 1			0.05 ~ 0.08mm (0.0019 ~ 0.0031in.)	0.1mm (0.004in.)
No. 2			0.04 ~ 0.08mm (0.0015 ~ 0.0031in.)	0.1mm (0.004in.)
Oil ring			0.06 ~ 0.15mm (0.0023 ~ 0.0059in.)	0.2mm (0.008in.)
End gap				
No. 1			0.15 ~ 0.30mm (0.0059 ~ 0.0118in.)	0.6mm (0.0236in.)
No. 2			0.37 ~ 0.52mm (0.0145 ~ 0.0204in.)	0.7mm (0.0275in.)
Oil ring side	rail		0.20 ~ 0.70mm (0.0078 ~ 0.0275in.)	0.8mm (0.0315in.)
Connecting	rod			
Bend			0.05mm (0.0020in.) or less	
Twist			0.1mm (0.004in.) or less	
Connecting recrankshaft side			0.100 ~ 0.250mm (0.0039 ~ 0.010in.)	0.35mm (0.0138in.)
Connecting	rod beari	ing	· · · · · · · · · · · · · · · · · · ·	
Oil clearance new parts)	(To seat	limits to	0.031 ~ 0.045mm (0.0012 ~ 0.0017in.)	0.05mm (0.0078in.)
Camshaft				•
	Intake		44.20mm (1.7401in.)	
Cam height	Exhaust		45.00mm (1.7716in.)	
Journal O.D		No. 1	ø 30mm (1.1811in.)	
		No. 2, 3, 4, 5	ø 24mm (0.9449in.)	
	Exhaust	No. 1	ø 36mm (1.4173in.)	
		No. 2, 3, 4, 5	ø 24mm (0.9449in.)	
		No. 1	0.022 ~ 0.057mm (0.0008 ~	0.09mm (0.0035in.)

1		1	0.0022in.)	
Bearing oil	Intake	No. 2, 3, 4, 5	0.045 ~ 0.082mm (0.0017 ~ 0.0032in.)	0.12mm (0.0047in.)
clearance		No. 1	$0 \sim 0.032$ mm ($0 \sim 0.0012$ in.)	
	Exhaust	No. 2, 3, 4, 5	0.045 ~ 0.082mm (0.0017 ~ 0.0032in.)	0.12mm (0.0047in.)
End play	.1	1., 5	0.04 ~ 0.16mm (0.0015 ~ 0.0062in.)	0.20mm (0.0047in.)
Crankshaft			010002111)	
Pin O.D.			47.954 ~ 47.972mm (1.8879 ~ 1.8886in.)	
Journal O.D.			51.942 ~ 51.960mm (2.0449 ~ 2.0456in.)	
End play			0.07 ~ 0.25mm (0.0027 ~ 0.0098in.)	
Crankshaft	bearing			
Oil clearance	2		0.020 ~ 0.038mm (0.0007 ~ 0.0014in.)	
Cooling method			Water-cooled, pressurized. Forced circulation with water pump	
Radiator			1 1	
Туре			Pressurized corrugated fin type	
Radiator ca	p			
Main valve o	pening pr	essure	83 ~ 110kpa (12 ~ 16psi, 0.83 ~ 1.1kg/cm ²)	
Vacuum valv	e opening	g pressure	-7kpa (-100psi, -0.07kg/cm ²) or less	
Thermostat			1655	
Туре			Wax pellet type with jiggle valve	
Valve openir	ng tempera	ature	82 ± 1.5 °C (177 ± 1.8°F)	
Full-opening temperature		ure	95°C (201°F)	
Coolant pump			Centrifugal type impeller	
Drive belt				
Type			V-ribbed belt	
Engine oil				
	Total [2.	0 / 2.4]	4.7L (4.97US qt, 4.13lmp qt) / 5.5L (5.81US qt, 4.84lmp qt)	When replacing a short engine or a block assembly
Oil quantity	Oil pan [2.0 / 2.4]		3.8L (4.01US qt, 3.34lmp qt) / 4.2L (4.44US qt, 3.69lmp qt)	
	Drain and refill [2.0 / 2.4]		4.1L (4.33US qt, 3.61lmp qt) / 4.6L (4.86US qt, 4.05lmp qt) Including oil filter	
			1	

∥iue∖	es. 18	de febrero	de 2021	11:47:46	p. m.
-------	--------	------------	---------	----------	-------

2010 ENGINE General Information (Engine Mechanical) - Tucson

Oil and de	Recommendation	5W-20/GF4&SM	If not available, refer to the recommended API or ILSAC classification and SAE viscosity number.
Oil grade	Classification	API SL, SM or above ILSAC GF3, GF4 or above	Satisfy the requirement of the API or ILSAC classification.
	SAE viscosity grade	Recommended SAE viscosity number	Refer to the " <u>LUBRICATION</u> <u>SYSTEM</u> "
Oil pressure (at 1000rpm) [2.0 / 2.4]		108kPa (1.1kg/cm ² , 15.6psi) or above / 147kPa (1.5kg/cm ² , 21.3psi) or above	Oil temperature in oil pan: 110±2°C (230 ± 36°F)

TIGHTENING TORQUES

TIGHTENING TORQUES SPECIFICATIONS

Item	N.m	kgf.m	lb-ft
Ladder frame bolt	[8.8~9.8] + [17.7~20.6] + [27.5~31.4]	[0.9~1.0] + [1.8~2.1] + [2.8~3.2]	[6.5~7.2] + [13.0~15.2] + [20.3~23.1]
Balance shaft module bolt [2.4L Engine only]	[22.5~26.5] + [103~ 107°]	[2.3~2.7] + [103~ 107°]	[18.6~19.5] + [103~ 107°]
Oil pump bolt [2.0L Engine only]	$ [7.8\sim11.8] + [17.7\sim21.6] + [27.5\sim31.4] $	[0.8~1.2] + [1.8~2.2] + [2.8~3.2]	[5.8~8.7] + [13.0~15.9] + [20.3~23.1]
Timing chain cover bolt (8X28)	18.6 ~ 22.5	1.9 ~ 2.3	13.7 ~ 16.6
Timing chain cover bolt (6X25)	7.8 ~ 9.8	0.8 ~ 1.0	5.8 ~ 7.2
Timing chain cover bolt (10X45)	39.2 ~ 44.1	4.0 ~ 4.5	28.9 ~ 32.5
Timing chain cover bolt (10X40)	39.2 ~ 44.1	4.0 ~ 4.5	28.9 ~ 32.5
Oil pan bolt (M6)	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
Oil pan bolt (M9)	30.4 ~ 34.3	$3.1 \sim 3.5$	22.4 ~ 25.3
Camshaft bearing cap bolt (M6)	[5.9] + [10.8~12.7]	[0.6] + [1.1~1.3]	[4.3] + [7.9~9.4]
Camshaft bearing cap bolt (M8)	[14.7] + [27.4~31.4]	[1.5] + [2.8~3.2]	[10.8] + [20.3~23.1]
Cylinder head bolt	[32.4~36.3] + [90~95°] + [90~95°]	[3.3~3.7] + [90~95°] + [90~95°]	[23.9~26.8] + [90~95°] + [90~95°]
Engine hanger bolt	27.5 ~ 31.4	$2.8 \sim 3.2$	20.3 ~ 23.1
Cylinder head cover bolt	$[3.9\sim5.9] + [7.8\sim9.8]$	$[0.4 \sim 0.6] + [0.8 \sim 1.0]$	[2.9~4.3] + [5.8~7.2]
Crankshaft pulley bolt	166.6 ~ 176.4	17.0 ~ 18.0	122.9 ~ 130.1
Connecting rod bearing cap bolt	[17.7~21.6] + [88~92°]	[1.8~2.2] + [88~92°]	[13.0~15.9] + [88~92°]
	[14.7] + [27.5~31.4] +	[1.5] + [2.8~3.2] +	[10.8] + [20.3~23.1] +

Main bearing cap bolt	[120~125°]	[120~125°]	[120~125°]
Flywheel bolt	117.6 ~ 127.4	12.0 ~ 13.0	86.8 ~ 93.9
Drive plate bolt	117.6 ~ 127.4	12.0 ~ 13.0	86.8 ~ 93.9
Timing chain tensioner bolt	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
Timing chain tensioner arm bolt	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
Timing chain guide bolt	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
OCV bolt	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
CVVT bolt	53.9 ~ 63.7	5.5 ~ 6.5	39.7 ~ 47.0
BSM chain tensioner arm bolt [2.4L Engine only]	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
BSM chain guide bolt [2.4L Engine only]	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
BSM chain tensioner bolt [2.4L Engine only]	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
Oil pump chain guide bolt [2.0L Engine only]	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
Oil pump chain tensioner bolt [2.0L Engine only]	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
Oil cooler hose & pipe bolt [2.4L Engine only]	$18.6\sim23.5$	1.9 ~ 2.4	13.7 ~ 17.4
Water pump bolt	$18.6 \sim 23.5$	1.9 ~ 2.4	13.7 ~ 17.4
A/C compressor bracket bolt	$19.6 \sim 23.5$	2.0 ~ 2.4	14.5 ~ 17.4
Tensioner assy integrated bracket bolt	$39.2 \sim 44.1$	4.0 ~ 4.5	28.9 ~ 32.5
Water temp. control nut	18.6 ~ 23.5	1.9 ~ 2.4	13.7 ~ 17.4
Water temp. control bolt	$14.7 \sim 19.6$	1.5 ~ 2.0	10.8 ~ 14.5
Water inlet pipe bolt	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7
Oil level gauge assembly bolt	7.8 ~ 11.8	0.8 ~ 1.2	5.8 ~ 8.7
Ignition coil bolt	$3.9 \sim 5.9$	$0.4 \sim 0.6$	2.9 ~ 4.3
Intake manifold bolt	$18.6 \sim 23.5$	1.9 ~ 2.4	13.7 ~ 17.4
Intake manifold nut	$18.6 \sim 23.5$	1.9 ~ 2.4	13.7 ~ 17.4
Intake manifold stay bolt	18.6 ~ 23.5	1.9 ~ 2.4	13.7 ~ 17.4
Exhaust manifold heat protector bolt	7.8 ~ 11.8	0.8 ~ 1.2	5.8 ~ 8.7
Exhaust manifold nut	49.0 ~ 53.9	5.0 ~ 5.5	36.2 ~ 39.8
Exhaust manifold stay bolt (M8)	18.6 ~ 27.5	1.9 ~ 2.8	13.7 ~ 20.3
Exhaust manifold stay bolt (M10)	51.9 ~ 57.9	5.3 ~ 5.9	38.3 ~ 42.7
Muffler bolt	39.2 ~ 58.8	4.0 ~ 6.0	28.9 ~ 43.4
Engine cover mounting bracket bolt	9.8 ~ 11.8	1.0 ~ 1.2	7.2 ~ 8.7

jueves, 18 de febrero de 2021 11:47:46 p. m. Page 6 © 2011 Mitchell Repair Information Company, I	jueves, 18 de febrero de 2021 11:47:46 p. m.	Page 6	© 2011 Mitchell Repair Information Company, LLC.
---	--	--------	--

2010 ENGINE General Information (Engine Mechanical) - Tucson

Crankshaft position sensor bolt	3.9 ~ 5.9	0.4 ~ 0.6	2.9 ~ 4.3
Oxygen sensor	44.1 ~ 49.0	4.5 ~ 5.0	32.5 ~ 36.1
Knock sensor	18.6 ~ 23.5	1.9 ~ 2.4	13.7 ~ 17.4
Camshaft position sensor	9.8 ~ 11.8	1.0 ~ 1.2	$7.2 \sim 8.7$
Oil pressure switch	7.8 ~ 11.8	0.8 ~ 1.2	5.8 ~ 8.7
Oil filter	11.8 ~ 15.7	1.2 ~ 1.6	8.7 ~ 11.6

REPAIR PROCEDURES

COMPRESSION PRESSURE INSPECTION

NOTE: If the there is lack of power, excessive oil consumption or poor fuel economy, measure the compression pressure.

1. Warm up and stop engine.

Allow the engine to warm up to normal operating temperature.

2. Disconnect the injector connectors (A) and ignition coil connectors (B).




Fig. 1: Identifying Injector Connectors And Ignition Coil Connectors Courtesy of HYUNDAI MOTOR CO.

3. Remove ignition coils (A).

2010 ENGINE General Information (Engine Mechanical) - Tucson





Fig. 2: Identifying Ignition Coils
Courtesy of HYUNDAI MOTOR CO.

4. Remove spark plugs.

Using a 16mm plug wrench, remove the 4 spark plugs.

- 5. Check cylinder compression pressure.
 - A. Insert a compression gauge into the spark plug hole.



<u>Fig. 3: Checking Compression Gauge Into Spark Plug Hole</u> Courtesy of HYUNDAI MOTOR CO.

- B. Fully open the throttle.
- C. While cranking the engine, measure the compression pressure.

NOTE: Always use a fully charged battery to obtain engine speed of 200 rpm or more.

D. Repeat steps (A) through (C) for each cylinder.

2010 ENGINE General Information (Engine Mechanical) - Tucson

NOTE: This measurement must be done in as short a time as possible.

Compression pressure:

1,283kPa (13.0kgf/cm², 185psi)

Minimum pressure:

1,135kPa (11.5kgf/cm², 164psi)

Difference between each cylinder:

100kPa (1.0kgf/cm², 15psi) or less

- E. If the cylinder compression in 1 or more cylinders is low, pour a small amount of engine oil into the cylinder through the spark plug hole and repeat steps (A) through (C) for cylinders with low compression.
 - If adding oil helps the compression, it is likely that the piston rings and/or cylinder bore are worn or damaged.
 - If pressure stays low, a valve may be sticking or seating is improper, or there may be leakage past the gasket.
- 6. Reinstall spark plugs.
- 7. Install ignition coils.
- 8. Connect the injector connectors and ignition coil connectors.

Valve Clearance Inspection And Adjustment

NOTE: Inspect and adjust the valve clearance when the engine is cold (Engine coolant temperature: 20°C (68°F)) and cylinder head is installed on the cylinder block.

- 1. Remove the cylinder head cover. (Refer to <u>TIMING SYSTEM</u> in this group)
- 2. Set No. 1 cylinder to TDC/compression.
 - A. Turn the crankshaft pulley and align its groove with the timing mark "T" of the lower timing chain cover.

2010 ENGINE General Information (Engine Mechanical) - Tucson





Fig. 4: Identifying Crankshaft Pulley And Timing Mark Courtesy of HYUNDAI MOTOR CO.

B. Check that the mark (A) of the CVVT sprockets are in straight line on the cylinder head surface as shown in the illustration.


If not, turn the crankshaft one revolution (360°)



<u>Fig. 5: Identifying CVVT Sprockets Mark</u> Courtesy of HYUNDAI MOTOR CO.

- 3. Inspect the valve clearance.
 - A. Check only the valve indicated as shown in illustration. [No. 1 cylinder: TDC/Compression] measure the valve clearance.

2010 ENGINE General Information (Engine Mechanical) - Tucson



No1. Cylinder TDC/compression

<u>Fig. 6: Valve Clearance Measuring Positions (No. 1 Cylinder TDC/Compression)</u> Courtesy of HYUNDAI MOTOR CO.

- Using a thickness gauge, measure the clearance between the tappet and the base circle of camshaft.
- Record the out-of-specification valve clearance measurements. They will be used later to determine the required replacement adjusting tappet.

Valve clearance

Specification

Engine coolant temperature: 20°C [68°F]


Limit

Intake: $0.10 \sim 0.30$ mm $(0.0039 \sim 0.0118$ in.)

Exhaust: $0.20 \sim 0.40$ mm $(0.0079 \sim 0.0157$ in.)

- B. Turn the crankshaft pulley one revolution (360°) and align the groove with timing mark "T" of the lower timing chain cover.
- C. Check only valves indicated as shown in illustration. [NO. 4 cylinder: TDC/compression]. Measure the valve clearance.


2010 ENGINE General Information (Engine Mechanical) - Tucson



No4. Cylinder TDC/compression

Fig. 7: Valve Clearance Measuring Positions (No. 4 Cylinder TDC/Compression) Courtesy of HYUNDAI MOTOR CO.

- 4. Adjust the intake and exhaust valve clearance.
 - A. Set the No. 1 cylinder to the TDC/compression.
 - B. Marks on the timing chain and camshaft timing sprockets.
 - C. Remove the service hole bolt (A) of the timing chain cover.




<u>Fig. 8: Identifying Service Hole Bolt Of Timing Chain Cover</u> Courtesy of HYUNDAI MOTOR CO.

CAUTION: The bolt must not be reused once it has been assembled.

D. Insert the SST (A) (09240-2G000) in the service hole of the timing chain cover and release the ratchet.

2010 ENGINE General Information (Engine Mechanical) - Tucson



<u>Fig. 9: Identifying SST (09240-2G000) And Timing Chain Cover</u> Courtesy of HYUNDAI MOTOR CO.

E. Remove the front camshaft bearing cap (A).




Fig. 10: Identifying Front Camshaft Bearing Cap Courtesy of HYUNDAI MOTOR CO.

- F. Remove the exhaust camshaft bearing cap and exhaust camshaft.
- G. Remove the intake camshaft bearing cap and intake camshaft.

CAUTION: When disconnecting the timing chain from the camshaft timing sprocket, tie or hold the timing chain so it does not fall into the timing cover.

H. Tie down timing chain so that it doesn't move.

CAUTION: Be careful not to drop anything inside timing chain cover.

I. Measure the thickness of the removed tappet using a micrometer.




Fig. 11: Measuring Thickness Of Tappet Using Micrometer Courtesy of HYUNDAI MOTOR CO.

J. Calculate the thickness of a new tappet so that the valve clearance comes within the specified value.

Valve clearance (Engine coolant temperature: 20°C [68°F])

T: Thickness of removed tappet

A: Measured valve clearance

N: Thickness of new tappet

Intake: N = T + [A - 0.20mm (0.0079in.)]

Exhaust: N = T + [A-0.30mm (0.0118in.)]

K. Select a new tappet with a thickness as close as possible to the calculated value.

NOTE: Shims are available in 47size increments of 0.015mm (0.0006in.) from 3.00mm (0.118in.) to 3.690mm (0.1452in.)

- L. Place a new tappet on the cylinder head.
- M. Hold the timing chain, and install the intake camshaft and CVVT assembly.
- N. Align the matchmarks on the timing chain and CVVT sprocket.
- O. Install the exhaust camshaft and CVVT assembly.
- P. Install the front bearing cap.

Tightening torque:

$$14.7$$
N.m $(1.5$ kgf.m, 10.8 lb-ft) + $27.4 \sim 31.4$ N.m $(2.8 \sim 3.2$ kgf.m, $20.3 \sim 23.1$ lb-ft)


Q. Install the service hole bolt.

Tightening torque:

2010 ENGINE General Information (Engine Mechanical) - Tucson

 $11.8 \sim 14.7 \text{N.m} \ (1.2 \sim 1.5 \text{kgf.m}, 8.7 \sim 10.8 \text{lb-ft})$

R. Turn the crankshaft two turns in the operating direction (clockwise) and realign crankshaft sprocket and CVVT sprocket timing marks (A).



<u>Fig. 12: Identifying CVVT Sprocket Timing Marks</u> Courtesy of HYUNDAI MOTOR CO.

S. Recheck the valve clearance.

Valve clearance (Engine coolant temperature: 20°C [68°F])

[Specification]

Intake: $0.17 \sim 0.23$ mm $(0.0067 \sim 0.0090$ in.)

Exhaust: $0.27 \sim 0.33$ mm $(0.0106 \sim 0.0129$ in.)

TROUBLESHOOTING

TROUBLESHOOTING CHART

Symptom	Suspect area	Remedy
En sin a mistina mith	Worn crankshaft bearings Loose or improperly engine flywheel	Replace the crankshaft and bearings as required. Repair or replace the flywheel as required.
	or may not cause the engine to mistire t	Inspect the cylinder for a loss of compression. Repair or replace as required.
	Worn crankshaft thrust bearings	Replace the crankshaft and bearings as required
Engine misfire with	Stuck valves. (Carbon buildup on the valve stem)	Repair or replace as required
abnormal valve train noise.	Excessive worn or mis-aligned timing chain	Replace the timing chain and sprocket as required.
	Worn camshaft lobes.	Replace the camshaft and valve lifters.

jueves, 18 de febrero de 2021 11:47:46 p. m.	Page 15	© 2011 Mitchell Repair Information Company, LLC.
--	---------	--

Engine misfire with coolant consumption	 Faulty cylinder head gasket or other damage to the cylinder head and engine block cooling system. Coolant consumption may or may not cause the engine to overheat. 	 Inspect the cylinder head and engine block for damage to the coolant passages and/or a faulty head gasket. Repair or replace as required.
Engine misfire with	Worn valves, guides and/or valve stem oil seals.	Repair or replace as required.
excessive oil consumption	Worn piston rings. (Oil consumption may or may not cause the engine to misfire)	Inspect the cylinder for a loss of compression.Repair or replace as required.
Engine noise on start-	Incorrect oil viscosity	 Drain the oil. Install the correct viscosity oil.
up, but only lasting a few seconds.	Worn crankshaft thrust bearing.	Inspect the thrust bearing and crankshaft.Repair or replace as required.
	Low oil pressure	Repair or replace as required.
	Broken valve spring.	Replace the valve spring.
	Worn or dirty valve lifters.	Replace the valve lifters.
Upper engine noise, regardless of engine speed.	Stretched or broken timing chain and/or damaged sprocket teeth.	Replace the timing chain and sprockets.
	Worn timing chain tensioner, if applicable.	Replace the timing chain tensioner as required.
	Worn camshaft lobes.	 Inspect the camshaft lobes. Replace the timing camshaft and valve lifters as required.
	Worn valve guides or valve stems.	Inspect the valves and valve guides, then repair or replace as required.
	Stuck valves. (Carbon on the valve stem or valve seat may cause the valve to stay open).	Inspect the valves and valve guides, then repair or replace as required.
	Worn drive belt, idler, tensioner and bearing.	Replace as required
	Low oil pressure	Repair or required.
	Loose or damaged flywheel.	Repair or replace the flywheel.
	Damaged oil pan, contacting the oil pump screen.	 Inspect the oil pan. Inspect the oil pump screen. Repair or replace as required.
	Oil pump screen loose, damaged or restricted.	Inspect the oil pump screen.Repair or replace as required.
	Excessive piston-to-cylinder bore	• Inspect the piston, piston pin and

jueves, 18 de febrero de 2021 11:47:46 p. m.	Page 16	© 2011 Mitchell Repair Information Company, LLC.
--	---------	--

	clearance.	cylinder bore.
	Excessive piston pin-to-piston clearance	 Repair or replace as required. Inspect the piston, piston pin and the connecting rod.
		Repair or replace as required.
		Inspect the following components and repair or replace as required.
	Excessive connecting rod bearing clearance	The connecting rod bearings.
Lower engine noise,		The connecting rods.
regardless of engine		 The crankshaft pin journals.
speed		Inspect the following components, and repair or replace as required.
	Excessive crankshaft bearing clearance	The crankshaft bearings.
		• The crankshaft main journals.
		The cylinder block
	Incorrect piston, piston pin and connecting rod installation	 Verify the piston pins and connecting rods are installed correctly.
		Repair as required.
	Low oil pressure	Repair or replace as required.
Ensine neise vaden		Inspect the following components and repair or replace as required:
	Excessive connecting rod bearing clearance	The connecting rod bearings.
		The connecting rods.
Engine noise under load		The crankshaft
		Inspect the following components, and repair or replace as required.
	Excessive crankshaft bearing clearance	The crankshaft bearings.
		• The crankshaft main journals.
		The cylinder block.
	Hydraulically looked cylinder	Remove spark plugs and check for fluid.
	Hydraulically locked cylinder	2. Inspect for broken head gasket.
	Coolant/antifreeze in cylinder. Oil in cylinder.	3. Inspect for cracked engine block or cylinder head.
	Oil in cylinder.Fuel in cylinder	4. Inspect for a sticking fuel injector and/or leaking fuel regulator.

jueves, 18 de febrero de 2021 11:47:46 p. m.	Page 17	© 2011 Mitchell Repair Information Company, LLC.

2010 ENGINE General Information (Engine Mechanical) - Tucson

Engine will not crank, crankshaft will not rotate	Broken timing chain and/or timing chain and/or timing chain gears.	 Inspect timing chain and gears. Repair as required.
	Material in cylinder Broken valve Piston material Foreign material Seized crankshaft or connecting rod bearings.	 Inspect cylinder for damaged components and/or foreign materials. Repair or replace as required. Inspect crankshaft and connecting rod bearing. Repair as required.
	Bent or broken connecting rod.	Inspect connecting rods. Repair as required.
	Broken crankshaft	 Inspect crankshaft. Repair as required.

SPECIAL SERVICE TOOLS

SPECIAL TOOLS CHART

Tool (Number and name)	Illustration	Use
Crankshaft front oil seal installer (09214-3K000) (09231-H1100)	B	Installation of the front oil seal A. 09214-3K000 B. 09231-H1100
Ring gear stopper (09231-2B100)		Holds ring gear so that engine doesn't turn/move.

Torque angle adapter (09221-4A000)		Installation of bolts & nuts needing an angular method of adjustment.
Valve stem oil seal installer (09222-4A000)		Installation of the valve stem oil seal
Valve spring compressor & holder (09222-3K000) (09222-3K100)		Removal and installation of the intake or exhaust valve 09222-3K100 (holder)
Crankshaft rear oil seal installer (09214-3K100) (09231-H1100)	B	Installation of the crankshaft rear oil seal A. 09214-3K100 B. 09231-H1100
Timing chain tensioner ratchet holder (09240-2G000)		Timing chain tension release In vehicle inspection and adjustment of valve clearance.

jueves, 18 de febrero de 2021 11:47:46 p. m.	Page 19	© 2011 Mitchell Repair Information Company, LLC.
--	---------	--

Oil pan remover (09215-3C000)	Removal of oil pan


2010 ENGINE Cylinder Block - Tucson

2010 ENGINE

Cylinder Block - Tucson

COMPONENTS AND COMPONENTS LOCATION

COMPONENTS



<u>Fig. 1: Identifying Cylinder Block Components With Torque Specification (1 Of 2)</u> Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Block - Tucson





Fig. 2: Identifying Cylinder Block Components With Torque Specification (2 Of 2) Courtesy of HYUNDAI MOTOR CO.

REPAIR PROCEDURES

DISASSEMBLY


- 1. M/T: remove flywheel.
- 2. A/T: remove drive plate.
- 3. Attach the engine to an engine stand for disassembly.
- 4. Remove timing chain. (Refer to **TIMING SYSTEM**.)
- 5. Remove cylinder head. (Refer to **CYLINDER BLOCK**.)
- 6. Remove the oil dip stick (A).

2010 ENGINE Cylinder Block - Tucson



<u>Fig. 3: Identifying Oil Dip Stick</u> Courtesy of HYUNDAI MOTOR CO.

7. Remove knock sensor (A).



<u>Fig. 4: Identifying Knock Sensor</u> Courtesy of HYUNDAI MOTOR CO.

8. Remove oil pressure sensor (A).

2010 ENGINE Cylinder Block - Tucson




Fig. 5: Identifying Oil Pressure Sensor Courtesy of HYUNDAI MOTOR CO.

9. Remove the sensor cover and the CKP sensor (A).




Fig. 6: Identifying CKP Sensor Courtesy of HYUNDAI MOTOR CO.

- 10. Remove water pump.
- 11. Remove balance shaft module (oil pump).
- 12. Remove ladder frame (A).




Fig. 7: Identifying Ladder Frame Courtesy of HYUNDAI MOTOR CO.

- 13. Check the connecting rod end play.
- 14. Remove the connecting rod caps and check oil clearance.
- 15. Remove piston and connecting rod assemblies.
 - 1. Using a ridge reamer, remove all the carbon from the top of the cylinder.
 - 2. Push the piston, connecting rod assembly and upper bearing through the top of the cylinder block.

NOTE:

- · Keep the bearings, connecting rod and cap together.
- Arrange the piston and connecting rod assemblies in the correct order.
- 16. Remove crankshaft bearing cap and check oil clearance.
- 17. Check the crankshaft end play.
- 18. Lift the crankshaft (A) out of the engine, being careful not to damage journals.

NOTE: Arrange the main bearings and thrust bearings in the correct order.




Fig. 8: Identifying Crankshaft

2010 ENGINE Cylinder Block - Tucson

Courtesy of HYUNDAI MOTOR CO.

19. Check fit between piston and piston pin.

Try to move the piston back and forth on the piston pin. If any movement is felt, replace the piston and pin as a set.

- 20. Remove piston rings.
 - 1. Using a piston ring expender, remove the 2 compression rings.
 - 2. Remove 2 side rails and the spacer by hand.

NOTE: Arrange the piston rings in the correct order only.

21. Disconnect connecting rod from piston.

INSPECTION

Connecting Rod And Crankshaft

1. Check the connecting rod end play.

Using a feeler gauge, measure the end play while moving the connecting rod back and forth.

Standard end play: $0.1 \sim 0.25 \text{mm} (0.004 \sim 0.010 \text{in.})$

Maximum end play: 0.35mm (0.0138in.)




Fig. 9: Measuring Connecting Rod End Play Courtesy of HYUNDAI MOTOR CO.

A. If out-of-tolerance, install a new connecting rod.

2010 ENGINE Cylinder Block - Tucson

- B. If still out-of-tolerance, replace the crankshaft.
- 2. Check the connecting road bearing oil clearance.
 - 1. Check the matchmarks on the connecting rod and cap are aligned to ensure correct reassembly.
 - 2. Remove 2 connecting rod cap bolts.
 - 3. Remove the connecting rod cap and bearing half.
 - 4. Clean the crank pin and bearing.
 - 5. Place plastigage across the crank pin.
 - 6. Reinstall the bearing half and cap, and torque the bolts.

Tightening torque

 $17.7 \sim 21.6 \text{Nm} (1.8 \sim 2.2 \text{kgf.m}, 13.0 \sim 15.9 \text{lb-ft}) + 88 \sim 92^{\circ}$

NOTE: Do not turn the crankshaft.

- 7. Remove 2 bolts, connecting rod cap and bearing half.
- 8. Measure the plastigage at its widest point.

Standard oil clearance

 $0.031 \sim 0.045$ mm ($0.0012 \sim 0.0017$ in.)




Fig. 10: Measuring Plastigage At Widest Point Courtesy of HYUNDAI MOTOR CO.

9. If the plastigage measures too wide or too narrow, remove the upper half of the bearing, install a new, complete bearing with the same color mark (select the color as shown in the next column), and recheck the clearance.

CAUTION: Do not file, shim, or scrape the bearings or the caps to adjust clearance.

2010 ENGINE Cylinder Block - Tucson

10. If the plastigage shows the clearance is still incorrect, try the next larger or smaller bearing (the color listed above or below that one), and check clearance again.

NOTE: If the proper clearance cannot be obtained by using the appropriate larger or smaller bearings, replace the crankshaft and start over.

CAUTION: If the marks are indecipherable because of an accumulation of dirt and dust, do not scrub them with a wire brush or scraper. Clean them only with solvent or detergent.

Connecting Rod Mark Location



Fig. 11: Identifying Connecting Rod Mark Location Courtesy of HYUNDAI MOTOR CO.

Discrimination Of Connecting Rod

CONNECTING ROD SPECIFICATIONS

Class	Mark	Inside Diameter
a	A	51.000 ~ 51.006mm (2.0079 ~ 2.0081in.)
b	В	51.006 ~ 51.012mm (2.0081 ~ 2.0083in.)
С	С	51.012 ~ 51.018mm (2.0083 ~ 2.0085in.)

Crankshaft Pin Mark Location Discrimination Of Crankshaft

2010 ENGINE Cylinder Block - Tucson



<u>Fig. 12: Identifying Crankshaft Pin Mark Location</u> Courtesy of HYUNDAI MOTOR CO.


NOTE: Conform to read stamping order as shown arrow direction from #1.

Discrimination Of Crankshaft

CRANKSHAFT SPECIFICATIONS

Class	Mark	Outside Diameter Of Pin
I	1	47.966 ~ 47.972mm (1.8884 ~ 1.8886in.)
II	2	47.960 ~ 47.966mm (1.8881 ~ 1.8884in.)
III	3	47.954 ~ 47.960mm (1.8879 ~ 1.8881in.)

Place Of Identification Mark (Connecting Rod Bearing) Discrimination Of Connecting Rod Bearing



<u>Fig. 13: Identifying Connecting Rod Bearing Color</u> Courtesy of HYUNDAI MOTOR CO.

Discrimination Of Connecting Rod Bearing

CONNECTING ROD BEARING SPECIFICATIONS

Class	Mark	Thickness Of Bearing
AA	Blue	1.515 ~ 1.518mm (0.0596 ~ 0.0597in.)
A	Black	1.512 ~ 1.515mm (0.0595 ~ 0.0596in.)
В	None	1.509 ~ 1.512mm (0.0594 ~ 0.0595in.)

jueves, 18 de febrero de 2021 11:47:06 p. m.	Page 9	© 2011 Mitchell Repair Information Company, LLC.
--	--------	--

2010 ENGINE Cylinder Block - Tucson

С	Green	1.506 ~ 1.509mm (0.0592 ~ 0.0594in.)
D	Yellow	1.503 ~ 1.506mm (0.0591 ~ 0.0592in.)

(11) Selection

IDENTIFICATION MARK SPECIFICATIONS

Crankshaft Identification Mark	Connecting Rod Identification Mark	Assembling Classification Of Bearing
	a (A)	D (Yellow)
I (1)	b (B)	C (Green)
	c (C)	B (None)
	a (A)	C (Green)
II (2)	b (B)	B (None)
	c (C)	A (Black)
	a (A)	B (None)
III (3)	b (B)	A (Black)
	c (C)	AA (Blue)

- 3. Check the crankshaft bearing oil clearance.
 - 1. To check main bearing-to-journal oil clearance, remove the main caps and bearing halves.
 - 2. Clean each main journal and bearing half with a clean shop tower.
 - 3. Place one strip of plastigage across each main journal.
 - 4. Reinstall the bearings and caps, then torque the bolts.

Tightening torque

 $14.7 Nm \; (1.5 kgf.m, \; 10.8 lb-ft) + 27.5 \sim 31.4 Nm \; (2.8 \sim 3.2 kgf.m, \; 20.3 \sim 23.1 lb-ft) + 120 \sim 125^{\circ}$

NOTE: Do not turn the crankshaft.

5. Remove the cap and bearing again, and measure the widest part of the plastigage.

Standard oil clearance

 $0.020 \sim 0.038 mm \ (0.0008 \sim 0.0015 in.)$

2010 ENGINE Cylinder Block - Tucson




Fig. 14: Measuring Widest Part Of Plastigage Courtesy of HYUNDAI MOTOR CO.

6. If the plastigage measures too wide or too narrow, remove the upper half of the bearing, install a new, complete bearing with the same color mark (select the color as shown in the next column), and recheck the clearance.

> CAUTION: Do not file, shim, or scrape the bearings or the caps to adjust clearance.

7. If the plastigage shows the clearance is still incorrect, try the next larger or smaller bearing (the color listed above or below that one), and check clearance again.

NOTE: If the proper clearance cannot be obtained by using the appropriate larger or smaller bearings, replace the crankshaft and start over.

CAUTION: If the marks are indecipherable because of an accumulation of dirt and dust, do not scrub them with a wire brush or scraper. Clean them only with solvent or detergent.

Connecting Rods

- 1. When reinstalling, make sure that cylinder numbers put on the connecting rod and cap at disassembly match. When a new connecting rod is installed, make sure that the notches for holding the bearing in place are on the same side.
- 2. Replace the connecting rod if it is damaged on the thrust faces at either end. Also if step wear or a severely rough surface of the inside diameter of the small end is apparent, the rod must be replaced as
- 3. Using a connecting rod aligning tool, check the rod for bend and twist. If the measured value is close to the repair limit, correct the rod by a press. Any connecting rod that has been severely bent or distorted should be replaced.

Allowable bend of connecting rod:

jueves, 18 de febrero de 2021 11:47:06 p. m.	Page 11
--	---------

2010 ENGINE Cylinder Block - Tucson

0.05mm / 100mm (0.0020 in./3.94 in.) or less

Allowable twist of connecting rod:

0.1mm / 100mm (0.0039 in./3.94 in.) or less

Crankshaft bore mark location

Letters have been stamped on the block as a mark for the size of each of the 5 main journal bores.

Use them, and the numbers or bar stamped on the crank (marks for main journal size), to choose the correct bearings.




Fig. 15: Identifying Crankshaft Bore Mark Location Courtesy of HYUNDAI MOTOR CO.

Discrimination Of Cylinder Block

CYLINDER BLOCK SPECIFICATIONS

Class	Mark	Inside Diameter
a	A	56.000 ~ 56.006mm (2.2047 ~ 2.2049in.)
ь	В	56.006 ~ 56.012mm (2.2049 ~ 2.2052in.)
c	C	$56.012 \sim 56.018$ mm ($2.2052 \sim 2.2054$ in.)

Crankshaft Journal Mark Location Discrimination Of Crankshaft

2010 ENGINE Cylinder Block - Tucson



<u>Fig. 16: Identifying Crankshaft Journal Mark Location</u> Courtesy of HYUNDAI MOTOR CO.

NOTE: Conform to read stamping order as shown arrow direction from #1.

Discrimination Of Crankshaft

CRANKSHAFT SPECIFICATIONS

Class	Mark	Outside Diameter Of Journal
I	1	51.954 ~ 51.960mm (2.0454 ~ 2.0456in.)
II	2	51.948 ~ 51.954mm (2.0452 ~ 2.0454.)
III	3	51.942 ~ 51.948mm (2.0449 ~ 2.0452in.)

Place Of Identification Mark (Crankshaft Bearing) Discrimination Of Crankshaft Bearing




Fig. 17: Identifying Crankshaft Bearing Color Courtesy of HYUNDAI MOTOR CO.

Discrimination Of Crankshaft Bearing

CRANKSHAFT BEARING SPECIFICATIONS

Class	Mark	Thickness Of Bearing
AA	Blue	$2.026 \sim 2.029 \text{mm} \ (0.0797 \sim 0.0798 \text{in.})$
A	Black	2.023 ~ 2.026mm (0.0796 ~ 0.0797in.)
В	None	2.020 ~ 2.023mm (0.0795 ~ 0.0796in.)

jueves, 18 de febrero de 2021 11:47:06 p. m.	Page 13	© 2011 Mitchell Repair Information Company, LLC.

2010 ENGINE Cylinder Block - Tucson

С	Green	2.017 ~ 2.020mm (0.0794 ~ 0.795in.)
D	Yellow	2.014 ~ 2.017mm (0.0793 ~ 0.0794in.)

Selection

IDENTIFICATION MARK SPECIFICATIONS

Crankshaft Identification Mark	Crankshaft Bore Identification Mark	Assembling Classification Of Bearing
I (1)	a (A)	D (Yellow)
	b (B)	C (Green)
	c (C)	B (None)
II (2)	a (A)	C (Green)
	b (B)	B (None)
	c (C)	A (Black)
III (3)	a (A)	B (None)
	b (B)	A (Black)
	c (C)	AA (Blue)

4. Check crankshaft end play.

Using a dial indicator, measure the thrust clearance while prying the crankshaft back and forth with a screwdriver.

Standard end play

 $0.07 \sim 0.25$ mm $(0.0027 \sim 0.0098$ in.)

Limit: 0.30mm (0.0118in.)




Fig. 18: Checking Crankshaft End Play Courtesy of HYUNDAI MOTOR CO.

If the end play is greater than maximum, replace the thrust bearings as a set.

2010 ENGINE Cylinder Block - Tucson

Thrust bearing thickness

 $1.925 \sim 1.965$ mm (0.0758 ~ 0.07736 in.)

5. Inspect main journals and crank pins

Using a micrometer, measure the diameter of each main journal and crank pin.

Main journal diameter: $51.942 \sim 51.960$ mm ($2.0449 \sim 2.0456$ in.)

Crank pin diameter: 47.954 ~ 47.972mm (1.8879 ~ 1.8886in.)




Fig. 19: Measuring Diameter Of Main Journal And Crank Pin Courtesy of HYUNDAI MOTOR CO.

Cylinder Block

1. Remove gasket material.

Using a gasket scraper, remove all the gasket material from the top surface of the cylinder block.

2. Clean cylinder block

Using a soft brush and solvent, thoroughly clean the cylinder block.

3. Inspect top surface of cylinder block for flatness.

Using a precision straight edge and feeler gauge, measure the surface contacting the cylinder head gasket

2010 ENGINE Cylinder Block - Tucson

for warpage.

Flatness of cylinder block gasket surface

Standard: Less than 0.05mm (0.0020 in.)




Fig. 20: Inspecting Top Surface Of Cylinder Block For Flatness Courtesy of HYUNDAI MOTOR CO.

4. Inspect cylinder bore diameter

Visually check the cylinder for vertical scratches.

If deep scratches are present, replace the cylinder block.

5. Inspect cylinder bore diameter

Using a cylinder bore gauge, measure the cylinder bore diameter at position in the thrust and axial directions.

Standard diameter

[2.4]: $88.00 \sim 88.03$ mm (3.4645 ~ 3.4657 in.)

[2.0]: $86.00 \sim 86.03$ mm (3.3858 ~ 3.3870 in.)

2010 ENGINE Cylinder Block - Tucson





Fig. 21: Measuring Cylinder Bore Diameter Courtesy of HYUNDAI MOTOR CO.

NOTE: Measure position (from the bottom of the cylinder block) : 110.7mm (4.3582in.)/160mm (6.2992in.)/210mm (8.2677in.)

6. Check the cylinder bore size code on the cylinder block.



<u>Fig. 22: Identifying Crankshaft Bore Mark Location</u> Courtesy of HYUNDAI MOTOR CO.

Cylinder Bore Inner Diameter

CYLINDER BORE INNER DIAMETER SPECIFICATIONS

Size Code	2.0	2.4
A	86.00 ~ 86.01mm (3.3858~ 3.3862in.)	88.00 ~ 88.01mm (3.4645~ 3.4649in.)
В	86.01 ~ 86.02mm (3.3862~ 3.3866in.)	88.01 ~ 88.02mm (3.4649~ 3.4653in.)
С	86.02 ~ 86.03mm (3.3866~ 3.3870in.)	88.02 ~ 88.03mm (3.4653~ 3.4657in.)

7. Check the piston size code on the piston top face.

2010 ENGINE Cylinder Block - Tucson




Fig. 23: Identifying Piston Size Code Courtesy of HYUNDAI MOTOR CO.

NOTE: Stamp the grade mark of basic diameter with rubber stamp.

Piston Outer Diameter

PISTON OUTER DIAMETER SPECIFICATIONS

Size Code	2.0	2.4
A	85.975 ~ 85.985mm (3.3848~ 3.3852in.)	87.975 ~ 87.985mm (3.4635~ 3.4639in.)
В	85.985 ~85.995mm (3.3852~ 3.3856in.)	87.985 ~ 87.995mm (3.4639~ 3.4643in.)
С	85.995 ~ 86.005mm (3.3856~ 3.3860in.)	87.995 ~88.005mm (3.4643~ 3.4647in.)

8. Select the piston related to cylinder bore class.

Clearance: $0.015 \sim 0.035$ mm $(0.00059 \sim 0.00137$ in.)

Piston And Rings

- 1. Clean piston
 - 1. Using a gasket scraper, remove the carbon from the piston top.
 - 2. Using a groove cleaning tool or broken ring, clean the piston ring grooves.
 - 3. Using solvent and a brush, thoroughly clean the piston.

NOTE: Do not use a wire brush.

2. The standard measurement of the piston outside diameter is taken 34.5 mm (1.35 in.) from the top land of the piston.

Standard diameter

[2.4]: $87.975 \sim 88.005$ mm ($3.4635 \sim 3.4647$ in.)

2010 ENGINE Cylinder Block - Tucson

[2.0]: $85.975 \sim 86.005$ mm (3.3848 ~ 3.3860 in.)




Fig. 24: Measuring Piston Outside Diameter Courtesy of HYUNDAI MOTOR CO.

3. Calculate the difference between the cylinder bore diameter and the piston diameter.

Piston-to-cylinder clearance

 $0.015 \sim 0.035$ mm $(0.00059 \sim 0.00137$ in.)

4. Inspect the piston ring side clearance.

Using a feeler gauge, measure the clearance between new piston ring and the wall of the ring groove.

Piston ring side clearance

Standard

No. 1: $0.05 \sim 0.08$ mm $(0.0019 \sim 0.0031$ in.)

No. 2: $0.04 \sim 0.08$ mm $(0.0015 \sim 0.0031$ in.)

Oil ring: $0.06 \sim 0.15$ mm $(0.0023 \sim 0.0059$ in.)


Limit

No. 1: 0.1mm (0.004in.)

No. 2: 0.1mm (0.004in.)

Oil ring: 0.2mm (0.008in.)

2010 ENGINE Cylinder Block - Tucson



<u>Fig. 25: Measuring Clearance Between Piston Ring And Wall Of Ring Groove</u> Courtesy of HYUNDAI MOTOR CO.

If the clearance is greater than maximum, replace the piston.

5. Inspect piston ring end gap.

To measure the piston ring end gap, insert a piston ring into the cylinder bore. Position the ring at right angles to the cylinder wall by gently pressing it down with a piston. Measure the gap with a feeler gauge. If the gap exceeds the service limit, replace the piston ring. If the gap is too large, recheck the cylinder bore diameter against the wear limits, If the bore is over the service limit, the cylinder block must be rebored.

Piston ring end gap

Standard

No. 1: $0.15 \sim 0.30$ mm $(0.0059 \sim 0.0118$ in.)

No. 2: $0.37 \sim 0.52$ m ($0.0145 \sim 0.0204$ in.)

Oil ring: $0.20 \sim 0.70$ mm $(0.0079 \sim 0.0275$ in.)

Limit

No. 1: 0.6mm (0.0236in.)

No. 2: 0.7mm (0.0275in.)

Oil ring: 0.8mm (0.0315in.)




Fig. 26: Checking Piston Ring End Gap Courtesy of HYUNDAI MOTOR CO.

Piston Pins

1. Measure the diameter of the piston pin.

Piston pin diameter

 $21.001 \sim 21.006$ mm (0.8268 ~ 0.8270 in.)




Fig. 27: Measuring Diameter Of Piston Pin Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Block - Tucson

2. Measure the piston pin-to-piston clearance.

Piston pin-to-piston clearance

$$0.013 \sim 0.023$$
mm ($0.0005 \sim 0.0009$ in.)

3. Check the difference between the piston pin diameter and the connecting rod small end diameter.

Piston pin-to-connecting rod interference

$$0.016 \sim 0.032$$
mm ($0.00063 \sim 0.00126$ in.)

REASSEMBLY

NOTE:

- Thoroughly clean all parts to assembled.
- Before installing the parts, apply fresh engine oil to all sliding and rotating surfaces.
- Replace all gaskets, O-rings and oil seals with new parts.
- 1. Assemble piston and connecting rod.
 - 1. Before pressing the piston pin, apply a coat of lubricant oil to the piston pin outer and connecting rod.

CAUTION:

- Take care that piston pin is not to be damaged during pressing process.
- When replace the piston pin, check the piston pin outer diameter and connecting rod small end inner diameter as below.

Piston pin outer DIA.:

```
21.001 \sim 21.006mm (0.8268 \sim 0.8270in)
```

Connecting rod small end inner DIA.:


 $20.974 \sim 20.985$ mm (0.8257 ~ 0.8261 in)

Interference:

$$-0.032 \sim -0.016 \text{ mm} (-0.0013 \sim -0.0006 \text{ in.})$$


- 2. Use a hydraulic press for installation.
- 3. The piston front mark and the connecting rod front mark must face the timing belt side of the engine.

2010 ENGINE Cylinder Block - Tucson



<u>Fig. 28: Identifying Piston Front Mark And Connecting Rod Front Mark</u> Courtesy of HYUNDAI MOTOR CO.

- 2. Install piston rings.
 - 1. Install the oil ring spacer and 2 side rails by hand.
 - 2. Using a piston ring expander, install the 2 compression rings with the code mark facing upward.
 - 3. Position the piston rings so that the ring ends are as shown in the illustration.



<u>Fig. 29: Position For Installing Piston Rings</u> Courtesy of HYUNDAI MOTOR CO.

- 3. Install connecting rod bearings.
 - 1. Align the bearing claw with the groove of the connecting rod or connecting rod cap.
 - 2. Install the bearings (A) in the connecting rod and connecting rod cap (B).

2010 ENGINE Cylinder Block - Tucson




Fig. 30: Identifying Bearings And Connecting Rod Cap Courtesy of HYUNDAI MOTOR CO.

4. Install main bearings.

NOTE: Upper bearings have an oil groove of oil holes; Lower bearings do not.

1. Align the bearing claw with the claw groove of the cylinder block, push in the 5 upper bearings (A).




Fig. 31: Identifying Upper Bearings Courtesy of HYUNDAI MOTOR CO.

- 2. Align the bearing claw with the claw groove of the main bearing cap, and push in the 5 lower bearings.
- 5. Install thrust bearings.

Install the 2 thrust bearings (A) under the No. 3 journal position of the cylinder block with the oil grooves facing outward.

2010 ENGINE Cylinder Block - Tucson



Fig. 32: Identifying Thrust Bearings Courtesy of HYUNDAI MOTOR CO.

6. Place crankshaft (A) on the cylinder block.




Fig. 33: Identifying Crankshaft
Courtesy of HYUNDAI MOTOR CO.

- 7. Place main bearing caps on cylinder block.
- 8. Install main bearing cap bolts.

CAUTION: Always use new main bearing cap bolts.

NOTE:

- The main bearing cap bolts are tightened in 2 progressive steps.
- If any of the bearing cap bolts in broken or deformed, replace it.
- 1. Apply a light coat of engine oil on the threads and under the bearing cap bolts.
- 2. Install and uniformly tighten the 10 bearing cap bolts (A), in several passes, in the sequence shown in the illustration.

2010 ENGINE Cylinder Block - Tucson

Tightening torque

14.7Nm (1.5kgf.m, 10.8lb-ft) + 27.5~31.4Nm (2.8~3.2kgf.m, 20.3~23.1lb-ft) + 120~125°




Fig. 34: Identifying Bearing Cap Bolts Tightening Sequence Courtesy of HYUNDAI MOTOR CO.

- 3. Check that the crankshaft turns smoothly.
- 9. Check crankshaft end play.
- 10. Install piston and connecting rod assemblies.

NOTE: Before installing the pistons, apply a coat of engine oil to the ring grooves and cylinder bores.

- 1. Remove the connecting rod caps, and slip short sections of rubber hose over the threaded ends of the connecting rod bolts.
- 2. Install the ring compressor, check that the bearing is securely in place, then position the piston in the cylinder, and tap it in using the wooden handle of a hammer.
- 3. Stop after the ring compressor pops free, and check the connecting rod-to-check journal alignment before pushing the piston into place.
- 4. Apply engine oil to the bolt threads. Install the rod caps with bearings, and torque the bolts.


Tightening torque

 $17.7 \sim 21.6 \text{Nm} (1.8 \sim 2.2 \text{kgf.m}, 13.0 \sim 15.9 \text{lb-ft}) + 88 \sim 92^{\circ}$

CAUTION: Always use new connecting rod cap bolts.

NOTE: Maintain downward force on the ring compressor to prevent the rings from expanding before entering the cylinder bore.

2010 ENGINE Cylinder Block - Tucson



<u>Fig. 35: Installing Rod Caps With Bearings</u> Courtesy of HYUNDAI MOTOR CO.

11. Apply liquid gasket to the mating surface of cylinder block and ladder frame.

NOTE:

- Be assembling ladder frame, the liquid sealant Loctite 5900 or THREEBOND 1217H should be applied ladder frame.
- The part must be assembled within 5 minutes after sealant was applied.
- Apply sealant to the inner threads of the bolt holes.




Fig. 36: Identifying Sealant Applying Area On Cylinder Block And Ladder Frame
Courtesy of HYUNDAI MOTOR CO.

12. Install ladder frame (A) with 10 bolts in several passes in sequence shown in the illustration.

Tightening torque

Step 1: $8.8 \sim 9.8$ N.m $(0.9 \sim 1.0$ kgf.m, $6.5 \sim 7.2$ lb-ft)

2010 ENGINE Cylinder Block - Tucson

Step 2: $17.7 \sim 20.6$ N.m $(1.8 \sim 2.1$ kgf.m, $3.0 \sim 15.2$ lb-ft)

Step 3: $27.5 \sim 31.4$ N.m ($2.8 \sim 3.2$ kgf.m, $20.3 \sim 23.1$ lb-ft)




Fig. 37: Identifying Ladder Frame Courtesy of HYUNDAI MOTOR CO.




Fig. 38: Identifying Ladder Frame Bolts Tightening Sequence Courtesy of HYUNDAI MOTOR CO.

- 13. Install rear oil seal.
 - 1. Apply engine oil to a new oil seal lip.
 - 2. Using SST (09231-H1100, 09214-3K100) and a hammer, tap in the oil seal until its surface is flush with the rear oil seal retainer edge.
- 14. Install balance shaft module (oil pump).
- 15. Install water pump.
- 16. Install CKP sensor (A) and sensor cover.

Tightening torque

 $9.8 \sim 11.8$ N.m (1.0 ~ 1.2kgf.m, 7.2 ~ 8.7lb-ft)

2010 ENGINE Cylinder Block - Tucson




Fig. 39: Identifying CKP Sensor Courtesy of HYUNDAI MOTOR CO.

- 17. Install oil pressure sensor.
 - 1. Apply adhesive to 2 or 3 threads.

Adhesive: MS 721-39 (B) or equivalent.

2. Install the oil pressure sensor (A).

Tightening torque

 $7.8 \sim 11.8$ N.m ($0.8 \sim 1.2$ kgf.m, $5.8 \sim 8.7$ lb-ft)




Fig. 40: Identifying Oil Pressure Sensor Courtesy of HYUNDAI MOTOR CO.

18. Install knock sensor (A).

Tightening torque

 $18.6 \sim 23.5$ N.m $(1.9 \sim 2.4$ kgf.m, $13.7 \sim 17.4$ lb-ft)

2010 ENGINE Cylinder Block - Tucson




Fig. 41: Identifying Knock Sensor Courtesy of HYUNDAI MOTOR CO.

- 19. Install oil level gauge assembly.
 - 1. Install a new O-ring on the oil dip stick.
 - 2. Apply engine oil on the O-ring.
 - 3. Install the oil dip stick (A) with the bolt.

Tightening torque

 $7.8 \sim 11.8$ N.m ($0.8 \sim 1.2$ kgf.m, $5.8 \sim 8.7$ lb-ft)




Fig. 42: Identifying Oil Dip Stick Courtesy of HYUNDAI MOTOR CO.

- 20. Install the cylinder head. (Refer to **CYLINDER HEAD ASSEMBLY**.)
- 21. Install the timing chain. (Refer to **TIMING SYSTEM**.)
- 22. Install the oil pan.
 - 1. Using a razor blade and gasket scraper, remove all the old gasket material from the gasket surfaces.

NOTE: Check that the mating surfaces are clean and dry before applying liquid gasket.

2010 ENGINE Cylinder Block - Tucson

2. Apply liquid gasket as an even bead, centered between the edges of the mating surface.

Use liquid gasket LOCTITE5900H or THREEBOND 1217H or equivalent (MS721-40).

Bead width: 3.0mm (0.12in)




Fig. 43: Identifying Liquid Gasket Courtesy of HYUNDAI MOTOR CO.

NOTE:


- To prevent leakage of oil, apply liquid gasket to the inner threads of the bolt holes.
- Do not install the parts if five minutes or more have elapsed since applying the liquid gasket. Instead, reapply liquid gasket after removing the residue.
- After assembly, wait at least 30 minutes before filling the engine with oil.
- 3. Install the oil pan (A).

Uniformly tighten the bolts in several passes.

Tightening torque

M9 (B):30.4
$$\sim$$
 34.3N.m (3.1 \sim 3.5kgf.m, 22.4 \sim 25.3lb-ft)

$$M6 (C):9.8 \sim 11.8 N.m (1.0 \sim 1.2 kgf.m, 7.2 \sim 8.7 lb-ft)$$



<u>Fig. 44: Identifying Oil Pan With Bolts</u> Courtesy of HYUNDAI MOTOR CO.

- 23. Remove engine stand.
- 24. A/T: Install drive plate (A).


Tightening torque

 $117.7 \sim 127.5$ N.m ($12 \sim 13$ kgf.m, $86.8 \sim 94.0$ lb-ft)

M/T: Install flywheel (B).

Tightening torque

 $117.7 \sim 127.5$ N.m ($12 \sim 13$ kgf.m, $86.8 \sim 94.0$ lb-ft)



<u>Fig. 45: Identifying Drive Plate And Flywheel With Bolts</u> Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Block - Tucson

NOTE:

- Always use new flywheel (drive plate) bolts (C).
- Apply sealant to the screw part (8mm from the end of the bolt) when using new flywheel bolts.

Sealant: Three bond 2403, Loctite 200 or 204




Fig. 46: Identifying Sealant Applying Area On Flywheel Bolt Courtesy of HYUNDAI MOTOR CO.

Install and uniformly tighten the 7 bolts, in several passes.

2010 ENGINE Cylinder Head Assembly - Tucson


2010 ENGINE

Cylinder Head Assembly - Tucson

CYLINDER HEAD

COMPONENTS AND COMPONENTS LOCATION

Components



<u>Fig. 1: Identifying Cylinder Head Components With Torque Specification</u> Courtesy of HYUNDAI MOTOR CO.

REPAIR PROCEDURES

jueves, 18 de febrero de 2021 11:47:28 p. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.
--	--------	--

2010 ENGINE Cylinder Head Assembly - Tucson

Removal

CAUTION:

- Use fender covers to avoid damaging painted surfaces.
- To avoid damaging the cylinder head, wait until the engine coolant temperature drops below normal temperature (20°C [68°F]) before removing it.
- When handling a metal gasket, take care not to fold the gasket or damage the contact surface of the gasket.
- To avoid damage, unplug the wiring connectors carefully while holding the connector portion.

NOTE:

- Mark all wiring and hoses to avoid misconnection.
- Turn the crankshaft pulley so that the No. 1 piston is at top dead center.
- 1. Disconnect the battery negative terminal (A).
- 2. Remove the engine cover (B).
- 3. Remove the air duct (C).




Fig. 2: Identifying Air Duct, Engine Cover And Battery Negative Terminal Courtesy of HYUNDAI MOTOR CO.

- 4. Disconnect the breather hose (A), air intake hose (B) and then remove the air cleaner assembly (C).
- 5. Disconnect the battery positive terminal and then remove the battery (D).

2010 ENGINE Cylinder Head Assembly - Tucson




Fig. 3: Identifying Breather Hose, Air Intake Hose And Air Cleaner Assembly Courtesy of HYUNDAI MOTOR CO.

6. Remove the under cover (A).




Fig. 4: Identifying Under Cover Courtesy of HYUNDAI MOTOR CO.

7. Loosen the drain plug (A), and drain the coolant.

Remove the radiator cap to speed draining.

2010 ENGINE Cylinder Head Assembly - Tucson




Fig. 5: Identifying Drain Plug Courtesy of HYUNDAI MOTOR CO.

WARNING: Never remove the radiator cap when the engine is hot. Serious scalding could be caused by hot fluid under high pressure escaping from the radiator.

8. Remove the radiator upper hose (A) and lower hose (B).





Fig. 6: Identifying Radiator Upper Hose And Lower Hose Courtesy of HYUNDAI MOTOR CO.

- 9. Disconnect the wiring connectors, harness clamps from the engine.
 - 1. OCV connector (A)



<u>Fig. 7: Identifying OCV Connector</u> Courtesy of HYUNDAI MOTOR CO.

- 2. VIS connector (A)
- 3. Oil pressure switch (B)
- 4. Knock sensor connector (C)
- 5. A/C compressor switch connector (D)
- 6. Alternator connector (E)





Fig. 8: Identifying VIS Connector, Oil Pressure Switch, Knock Sensor Connector, A/C Compressor Switch Connector And Alternator Connector Courtesy of HYUNDAI MOTOR CO.

- 7. Injector connectors (A)
- 8. Ignition coil connectors (B)
- 9. Intake CMPS connector (C)
- 10. Exhaust CMPS connector (D)
- 11. Exhaust OCV connector (E)

2010 ENGINE Cylinder Head Assembly - Tucson



<u>Fig. 9: Identifying Injector Connectors And Ignition Coil Connectors</u> Courtesy of HYUNDAI MOTOR CO.

12. VCM connector (A)




Fig. 10: Identifying VCM Connector Courtesy of HYUNDAI MOTOR CO.

- 13. ETC connector (A)
- 14. MAP & IATS connector (B)




Fig. 11: Identifying ETC Connector Courtesy of HYUNDAI MOTOR CO.

- 15. PCSV connector (A)
- 16. ECT sensor connector (B)
- 17. Condenser connector (C)
- 18. CKP sensor connector (D)





Fig. 12: Identifying PCSV Connector And ECT Sensor Connector Courtesy of HYUNDAI MOTOR CO.


- 19. Oxygen sensor connector (E)
- 10. Disconnect the fuel hose (A), brake booster vacuum hose (B) and heater hoses (C).

2010 ENGINE Cylinder Head Assembly - Tucson




<u>Fig. 13: Identifying Fuel Hose, Brake Booster Vacuum Hose And Heater Hoses</u> Courtesy of HYUNDAI MOTOR CO.

11. Disconnect the throttle body coolant hoses (A).



<u>Fig. 14: Identifying Throttle Body Coolant Hoses</u> Courtesy of HYUNDAI MOTOR CO.

12. Remove the water inlet pipe mounting bolt (A).



<u>Fig. 15: Identifying Water Inlet Pipe Mounting Bolt</u> Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Head Assembly - Tucson

13. Disconnect the oil cooler hoses (A) and then remove the water temperature control assembly (B).




Fig. 16: Identifying Oil Cooler Hoses And Water Temperature Control Assembly Courtesy of HYUNDAI MOTOR CO.

- 14. Remove the timing chain. (Refer to **TIMING SYSTEM** in this group)
- 15. Remove the intake & exhaust manifold. (Refer to **INTAKE AND EXHAUST SYSTEM** in this group)
- 16. Remove the intake & exhaust CVVT assembly.




Fig. 17: Identifying Intake & Exhaust CVVT Assembly Courtesy of HYUNDAI MOTOR CO.

- 17. Remove the cam shaft.
 - A. Remove the front cam shaft bearing cap (A).




Fig. 18: Identifying Front Cam Shaft Bearing Cap Courtesy of HYUNDAI MOTOR CO.

B. Remove the exhaust cam shaft upper bearing (A).




Fig. 19: Identifying Exhaust Cam Shaft Upper Bearing Courtesy of HYUNDAI MOTOR CO.

C. Remove camshaft bearing cap (A), in the sequence shown in illustration.




Fig. 20: Identifying Camshaft Bearing Cap In Sequence Courtesy of HYUNDAI MOTOR CO.

D. Remove the cam shaft (A).





Fig. 21: Identifying Cam Shaft Courtesy of HYUNDAI MOTOR CO.

E. Remove the exhaust cam shaft lower bearing (A).



<u>Fig. 22: Identifying Exhaust Cam Shaft Lower Bearing</u> Courtesy of HYUNDAI MOTOR CO.

18. Use a torx wrench, remove the intake OCV (A).




Fig. 23: Identifying Intake OCV Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Head Assembly - Tucson

19. Remove the exhaust OCV.




Fig. 24: Identifying Exhaust OCV Courtesy of HYUNDAI MOTOR CO.

- 20. Remove the cylinder head bolts, then remove the cylinder head.
 - A. Using triple square wrench, uniformly loosen and remove the 10 cylinder head bolts, in several passes, in the sequence shown in illustration.




Fig. 25: Identifying Cylinder Head Bolts In Loosening Sequence Courtesy of HYUNDAI MOTOR CO.

CAUTION: Head warpage or cracking could result from removing bolts in an incorrect order.

B. Lift the cylinder head from the dowels on the cylinder block and place the cylinder head on wooden blocks on a bench.

CAUTION: Be careful not to damage the contact surfaces of the cylinder head and cylinder block.


21. Remove the cylinder head gasket.

2010 ENGINE Cylinder Head Assembly - Tucson

Disassembly

NOTE: Identify MLA (Mechanical Lash Adjuster), valves, valve springs as they are removed so that each item can be reinstalled in its original position.


1. Remove MLAs (A).



<u>Fig. 26: Identifying MLAs</u> Courtesy of HYUNDAI MOTOR CO.

2. Remove valves.

1. Using SST (09222-3K000, 09222-3K100), compress the valve spring and remove retainer lock.



<u>Fig. 27: Compressing Valve Spring And Retainer Lock</u> Courtesy of HYUNDAI MOTOR CO.

- 2. Remove the spring retainer.
- 3. Remove the valve spring.
- 4. Remove the valve.
- 5. Using needle-nose pliers, remove the valve stem seal.

Inspection

Cylinder Head


2010 ENGINE Cylinder Head Assembly - Tucson

1. Inspect for flatness.

Using a precision straight edge and feeler gauge, measure the surface the contacting the cylinder block and the manifolds for warpage.

Flatness of cylinder head gasket surface

Standard: Less than 0.05mm (0.002in.)



<u>Fig. 28: Measuring Surface Contacting Cylinder Block And Manifolds For Warpage</u> Courtesy of HYUNDAI MOTOR CO.

2. Inspect for cracks.

Check the combustion chamber, intake ports, exhaust ports and cylinder block surface for cracks. If cracked, replace the cylinder head.


Valve And Valve Spring

- 1. Inspect valve stems and valve guides.
 - 1. Using a caliper gauge, measure the inside diameter of the valve guide.

Valve guid I.D.

Intake / Exhaust: $5.500 \sim 5.512$ mm ($0.216 \sim 0.217$ in.)

2010 ENGINE Cylinder Head Assembly - Tucson



<u>Fig. 29: Measuring Inside Diameter Of Valve Guide</u> Courtesy of HYUNDAI MOTOR CO.

2. Using a micrometer, measure the diameter of the valve stem.

Valve stem O.D.

Intake: $5.465 \sim 5.480$ mm (0.2151 ~ 0.2157 in.)

Exhaust: $5.458 \sim 5.470$ mm $(0.2149 \sim 0.2153$ in.)




Fig. 30: Measuring Diameter Of Valve Stem Courtesy of HYUNDAI MOTOR CO.

3. Subtract the valve stem diameter measurement from the valve guide inside diameter measurement.

Valve stem-to-guide clearance

[Standard]

Intake: $0.020 \sim 0.047$ mm $(0.0008 \sim 0.0018$ in.)

Exhaust: $0.030 \sim 0.054$ mm $(0.0012 \sim 0.0021$ in.)

2010 ENGINE Cylinder Head Assembly - Tucson

[Limit]

Intake: 0.07mm (0.0027in.)

Exhaust: 0.09mm (0.0035in.)

If the clearance is greater than maximum, replace the valve and valve guide.

2. Inspect valves.

- 1. Check the valve is ground to the correct valve face angle.
- 2. Check that the surface of the valve for wear.

If the valve face is worn, replace the valve.

3. Check the valve head margin thickness.

If the margin thickness is less than minimum, replace the valve.

Margin

[Standard]

Intake: 1.02mm (0.0401in.)

Exhaust: 1.09mm (0.0429in.)




Fig. 31: Checking Valve Head Margin Thickness Courtesy of HYUNDAI MOTOR CO.

4. Check the valve length.

Valve length

[Standard]

2010 ENGINE Cylinder Head Assembly - Tucson

Intake: 113.18mm (4.456in.)

Exhaust: 105.84mm (4.167in.)

[Limit]

Intake: 112.93mm (4.446in.)

Exhaust: 105.59mm (4.157in.)

5. Check the surface of the valve stem tip for wear.

If the valve stem tip is worn, replace the valve.

3. Inspect valve seats

Check the valve seat for evidence of overheating and improper contact with the valve face.

Replace the seat if necessary.

Before reconditioning the seat, check the valve guide for wear. If the valve guide is worn, replace it, then recondition the seat. Recondition the valve seat with a valve seat grinder or cutter. The valve seat contact width should be within specifications and centered on the valve face.

4. Inspect valve springs.


- 1. Using a steel square, measure the out-of-square of the valve spring.
- 2. Using a vernier calipers, measure the free length of the valve spring.

Valve spring

[Standard]

Free height: 47.44mm (1.8677in.)

Out-of-square: 1.5°



2010 ENGINE Cylinder Head Assembly - Tucson

Fig. 32: Measuring Free Length Of Valve Spring Courtesy of HYUNDAI MOTOR CO.

If the free length is not as specified, replace the valve spring.

MLA

1. Inspect MLA.

Using a micrometer, measure the MLA outside diameter.

MLA O.D.

Intake/Exhaust: $31.964 \sim 31.980$ mm (1.2584 ~ 1.2590 in.)

2. Using a caliper gauge, measure MLA tappet bore inner diameter of cylinder head.

Tappet bore I.D.

Intake/Exhaust: $32.000 \sim 32.025$ mm (1.2598 ~ 1.2608 in.)

3. Subtract MLA outside diameter measurement from tappet bore inside diameter measurement.

MLA to tappet bore clearance

[Standard]

Intake/Exhaust: $0.020 \sim 0.061$ mm ($0.0008 \sim 0.0024$ in.)

[Limit]

Intake/Exhaust: 0.07mm (0.0027in.)

Camshaft

1. Inspect cam lobes.


Using a micrometer, measure the cam lobe height.

Cam height

[Standard value]

Intake: $44.10 \sim 44.30$ mm $(1.7362 \sim 1.7440$ in.)

Exhaust: $44.90 \sim 45.10$ mm $(1.7677 \sim 1.7756$ in.)



<u>Fig. 33: Measuring Cam Lobe Height</u> Courtesy of HYUNDAI MOTOR CO.

If the cam lobe height is less than standard, replace the camshaft.

- 2. Inspect camshaft journal clearance.
 - 1. Clean the bearing caps and camshaft journals.
 - 2. Place the camshafts on the cylinder head.
 - 3. Lay a strip of plastigage across each of the camshaft journal.




Fig. 34: Inspecting Camshaft Journal Clearance Courtesy of HYUNDAI MOTOR CO.

4. Install the bearing caps.

CAUTION: Do not turn the camshaft.

- 5. Remove the bearing caps.
- 6. Measure the plastigage at its widest point.

Bearing oil clearance

2010 ENGINE Cylinder Head Assembly - Tucson

[Standard value]

Intake

No. 1 journal: $0.022 \sim 0.057$ mm ($0.0008 \sim 0.0022$ in.)

No. 2,3,4,5, journal: $0.045 \sim 0.082$ mm $(0.0018 \sim 0.0032$ in.)

Exhaust

No. 1 journal: $0 \sim 0.032$ mm ($0 \sim 0.0012$ in.)

No. 2,3,4,5, journal: $0.045 \sim 0.082$ mm $(0.0017 \sim 0.0032$ in.)

[Limit]:

Intake

No. 1 journal: 0.09mm (0.0035in.)

No. 2,3,4,5 journal: 0.12mm (0.0047in.)

Exhaust: 0.12mm (0.0047in.)




Fig. 35: Measuring Plastigage At Widest Point Courtesy of HYUNDAI MOTOR CO.

If the oil clearance is greater than maximum, replace the camshaft. If necessary, replace cylinder head.

- 7. Completely remove the plastigage.
- 8. Remove the camshafts.
- 3. Inspect camshaft end play.
 - 1. Install the camshafts.
 - 2. Using a dial indicator, measure the end play while moving the camshaft back and forth.

2010 ENGINE Cylinder Head Assembly - Tucson

Camshaft end play

[Standard value]: $0.04 \sim 0.16$ mm $(0.0015 \sim 0.0062$ in.)

[Limit]: 0.20mm (0.0078in.)




Fig. 36: Measuring Camshaft End Play Courtesy of HYUNDAI MOTOR CO.

If the end play is greater than maximum, replace the camshaft. If necessary, replace cylinder head.

3. Remove the camshafts.

Exhaust Cam Shaft Bearing

1. Check the cylinder head bore mark.

Location Of Cylinder Head Bore Mark




Fig. 37: Locating Cylinder Head Bore Mark Courtesy of HYUNDAI MOTOR CO.

Discrimination Of Cylinder Head

2010 ENGINE Cylinder Head Assembly - Tucson

CYLINDER HEAD DISCRIMINATION CHART

Class	Mark	Exhaust No. 1 Inside Diameter Of Cylinder Head Bore
a	A	40.000 ~ 40.008 mm (1.5748 ~ 1.5751 in.)
b	В	40.008 ~ 4.016 mm (1.5751 ~ 1.5754 in.)
С	С	40.016 ~ 40.024 mm (1.5754 ~ 1.5757 in.)

2. Select class of camshaft bearing same as class of cylinder head as shown on the table below.

Place Of Exhaust Cam Shaft Bearing Identification Mark




Fig. 38: Identifying Color Courtesy of HYUNDAI MOTOR CO.

Discrimination Of Exhaust Camshaft Bearing

EXHAUST CAMSHAFT BEARING DISCRIMINATION CHART

Cylinder Head Bore Class	Bearing Class For Installing (Color)	Thickness Of Bearing
a (A)	C (Green)	1.996~2.000mm (0.0785~0.0787in.)
b (B)	B (None color)	2.000~2.004mm (0.0787~0.0788in.)
c (C)	A (Black)	2.004~2.008mm (0.0788~0.0790in.)

Oil clearance: $0 \sim 0.032 \text{mm} \ (0 \sim 0.0012 \text{in.})$

CVVT Assembly

- 1. Inspect CVVT assembly.
 - 1. Check that the CVVT assembly will not turn.
 - 2. Apply vinyl tape to the retard hole except the one indicated by the arrow in the illustration.

Verify the hold to tape and the hold to put air in.

[Intake]

jueves, 18 de febrero de 2021 11:47:25 p. m.	Page 22	© 2011 Mitchell Repair Information Company, LLC.

2010 ENGINE Cylinder Head Assembly - Tucson





Fig. 39: Locating Intake Retard And Advance Courtesy of HYUNDAI MOTOR CO.

[Exhaust]



<u>Fig. 40: Locating Exhaust Retard And Advance</u> Courtesy of HYUNDAI MOTOR CO.

(3) Wind tape around the tip of the air gun and apply air of approx. 150kpa (1.5kgf/cm², 21psi) to the port of the camshaft. (Perform this in order to release the lock pin.)

NOTE: When the oil splashes, wipe it off with a shop rag and the likes.

(4) With air applied, as in step (3), turn the CVVT assembly to the advance angle side (the arrow marked direction in the illustration) with your hand.

Depending on the air pressure, the CVVT assembly will turn to the advance side without applying force by hand. Also, under the condition that the pressure can be hardly applied because of the air leakage from the port, there may be the case that the lock pin could be hardly released.

2010 ENGINE Cylinder Head Assembly - Tucson




Fig. 41: Turning CVVT Assembly To Advance Angle Side Courtesy of HYUNDAI MOTOR CO.

(5) Turn the CVVT assembly back and forth and check the movable range and that there is no disturbance.

Standard:

Should move smoothly in a range from about

22.5° (Intake) / 20.0° (Exhaust)

(6) Turn the CVVT assembly with your hand and lock it at the maximum delay angle position (counter clockwise).

Reassembly

NOTE: Thoroughly clean all parts to be assembled.

Before installing the parts, apply fresh engine oil to all sliding and rotating

surfaces.

Replace oil seals with new ones.

1. Install valves.

1. Using SST (09222-4A000), push in a new oil seal.

NOTE: Do not reuse old valve stem seals.

Incorrect installation of the seal could result in oil leakage past the

valve guides.




Fig. 42: Pushing Oil Seal Using SST (09222-4A000) Courtesy of HYUNDAI MOTOR CO.

2. Install the valve, valve spring and spring retainer.

NOTE: Place valve springs so that the side coated with enamel faces toward the valve spring retainer and then installs the retainer.

3. Using the SST (09222-3K000, 09222-3K100), compress the spring and install the retainer locks. After installing the valves, ensure that the retainer locks are correctly in place before releasing the valve spring compressor.




Fig. 43: Compressing Spring And Retainer Locks Courtesy of HYUNDAI MOTOR CO.

- 4. Lightly tap the end of each valve stem two or three times with the wooden handle of a hammer to ensure proper seating of the valve and retainer lock.
- 2. Install MLAs.

Check that the MLA rotates smoothly by hand.

2010 ENGINE Cylinder Head Assembly - Tucson




Fig. 44: Identifying MLA Courtesy of HYUNDAI MOTOR CO.


NOTE: MLA can be reinstalled in its original position.

Installation

NOTE:

- Thoroughly clean all parts to be assembled.
- · Always use a new head and manifold gasket.
- The cylinder head gasket is a metal gasket. Take care not to bend it.
- Rotate the crankshaft, set the No. 1 piston at TDC.

1. Install OCV filter.



<u>Fig. 45: Installing OCV Filter</u> Courtesy of HYUNDAI MOTOR CO.

CAUTION: Keep the OCV filter clean.

2. Install the cylinder head gasket (A) on the cylinder block.

2010 ENGINE Cylinder Head Assembly - Tucson

NOTE:

- Be careful of the installation direction.
- Apply liquid gasket (Loctite 5900H) on the mark (B).
- After applying sealant, assemble the cylinder head in five minutes.




Fig. 46: Identifying Cylinder Head Gasket On Cylinder Block Courtesy of HYUNDAI MOTOR CO.

- 3. Place the cylinder head carefully in order not to damage the gasket with the bottom part of the end.
- 4. Install cylinder head bolts.
 - A. Apply a light coat if engine oil on the threads and under the heads of the cylinder head bolts.
 - B. Using hexagon wrench, install and tighten the 10 cylinder head bolts and plate washers, in several passes, in the sequence shown in illustration.

Tightening torque:

$$32.4\sim36.3$$
Nm $(3.3\sim3.7$ kgf.m, $23.9\sim26.8$ lb-ft) + $(90\sim95^\circ)$ + $(90\sim95^\circ)$




Fig. 47: Identifying Cylinder Head Bolts Tightening Sequence Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Head Assembly - Tucson

NOTE: Always use new cylinder head bolt.

5. Install the intake OCV (A).

Tightening torque:

 $9.8 \sim 11.8$ N.m (1.0 ~ 1.2kgf.m, 7.2 ~ 8.7lb-ft)




Fig. 48: Identifying Intake OCV Courtesy of HYUNDAI MOTOR CO.

6. Install the exhaust OCV (A).

Tightening torque:

 $9.8 \sim 11.8$ N.m (1.0 ~ 1.2kgf.m, 7.2 ~ 8.7lb-ft)




Fig. 49: Identifying Exhaust OCV Courtesy of HYUNDAI MOTOR CO.

CAUTION:


- Do not reuse the OCV when dropped.
- Keep the OCV filter clean.

2010 ENGINE Cylinder Head Assembly - Tucson

- Do not hold the OCV sleeve during servicing.
- When the OCV is installed on the engine, do not move the engine with holding the OCV yoke.
- 7. Install the camshafts.


NOTE: Apply a light coat of engine oil on camshaft journals.

A. Install the exhaust camshaft lower bearing (A).



<u>Fig. 50: Identifying Exhaust Camshaft Lower Bearing</u> Courtesy of HYUNDAI MOTOR CO.

B. Install the camshafts (A).



<u>Fig. 51: Identifying Camshafts</u> Courtesy of HYUNDAI MOTOR CO.

C. Install the exhaust camshaft upper bearing (A).

2010 ENGINE Cylinder Head Assembly - Tucson




Fig. 52: Identifying Exhaust Camshaft Upper Bearing Courtesy of HYUNDAI MOTOR CO.

D. Install camshaft bearing caps in their proper locations.

Tightening order.

Group A --> Group B --> Group C.

Tightening torque

Step 1

M6: 5.9N.m(0.6kgf.m, 4.3lb-ft)

M8: 14.7N.m(1.5kgf.m, 10.8lb-ft)

Step 2

M6: $10.8 \sim 12.7$ N.m $(1.1 \sim 1.3$ kgf.m, $7.9 \sim 9.4$ lb-ft)

M8: $27.5 \sim 31.4$ N.m ($2.8 \sim 3.2$ kgf.m, $20.3 \sim 23.1$ lb-ft)




Fig. 53: Identifying Camshaft Bearing Caps In Tightening Sequence Courtesy of HYUNDAI MOTOR CO.

8. Install the water temperature control assembly (B) and then connect the oil cooler hoses (A).

Tightening torque:

2010 ENGINE Cylinder Head Assembly - Tucson

Bolts: $14.7 \sim 19.6$ N.m $(1.5 \sim 2.0 \text{ kgf.m}, 10.8 \sim 14.5 \text{ lb-ft})$

Nut: $18.6 \sim 23.5$ N.m $(1.9 \sim 2.4 \text{ kgf.m}, 13.7 \sim 17.4 \text{ lb-ft})$





Fig. 54: Identifying Water Temperature Control Assembly And Oil Cooler Hoses Courtesy of HYUNDAI MOTOR CO.

CAUTION:

- Assemble water temp control assembly and water inlet pipe to water pump assembly before bolt for assembling of water inlet pipe to be tightened.
- Always use a new O-ring.
- 9. Install the water inlet pipe mounting bolt (A).

Tightening torque:

 $9.8 \sim 11.8$ N.m (1.0 ~ 1.2 kgf.m, $7.2 \sim 8.7$ lb-ft)




<u>Fig. 55: Identifying Water Inlet Pipe Mounting Bolt</u> Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Head Assembly - Tucson

- 10. Install the timing chain. (Refer to **TIMING SYSTEM** in this group)
- 11. Check and adjust valve clearance. (Refer to **GENERAL INFORMATION (ENGINE MECHANICAL)** in this group)
- 12. Install the cylinder head cover.
 - A. The hardening sealant located on the upper area between timing chain cover and cylinder head should be removed before assembling cylinder head cover.
 - B. After applying sealant, it should be assembled within 5 minutes.

Bead width: 2.5mm (0.1in.)

Sealant: LOCTITE 5900H




<u>Fig. 56: Identifying Sealant Applying Area On Timing Chain Cover And Cylinder Head</u> Courtesy of HYUNDAI MOTOR CO.

- C. Running the engine or performing a pressure test should not be performed within 30 minutes of assembly
- D. Install the cylinder head cover bolts in the following sequence.

Tightening torque:

Step 1: $3.9 \sim 5.9 N.m (0.4 \sim 0.6 kgf.m, 2.9 \sim 4.3 lb-ft)$

Step 2: $7.8 \sim 9.8$ N.m $(0.8 \sim 1.0$ kgf.m, $5.8 \sim 7.2$ lb-ft)



2010 ENGINE Cylinder Head Assembly - Tucson

Fig. 57: Identifying Cylinder Head Cover Bolts Tightening Sequence Courtesy of HYUNDAI MOTOR CO.

CAUTION: Do not reuse cylinder head cover gasket.

- 13. Install the intake & exhaust manifold. (Refer to **INTAKE AND EXHAUST SYSTEM** in this group)
- 14. Connect the throttle body coolant hoses (A).




Fig. 58: Identifying Throttle Body Coolant Hoses Courtesy of HYUNDAI MOTOR CO.

15. Connect the fuel hose (A), the brake booster vacuum hose (B) and heater hoses (C).





Fig. 59: Identifying Fuel Hose, Brake Booster Vacuum Hose And Heater Hoses Courtesy of HYUNDAI MOTOR CO.

- 16. Connect the wiring connectors and harness clamps.
 - 1. OCV connector (A)



<u>Fig. 60: Identifying OCV Connector</u> Courtesy of HYUNDAI MOTOR CO.

- 2. VIS connector (A)
- 3. Oil pressure switch (B)
- 4. Knock sensor connector (C)
- 5. A/C compressor switch connector (D)
- 6. Alternator connector (E)





Fig. 61: Identifying VIS Connector, Oil Pressure Switch, Knock Sensor Connector, A/C Compressor Switch Connector And Alternator Connector Courtesy of HYUNDAI MOTOR CO.

- 7. Injector connectors (A)
- 8. Ignition coil connectors (B)
- 9. Intake CMPS connector (C)
- 10. Exhaust CMPS connector (D)
- 11. Exhaust OCV connector (E)

2010 ENGINE Cylinder Head Assembly - Tucson



<u>Fig. 62: Identifying Injector Connectors And Ignition Coil Connectors Courtesy of HYUNDAI MOTOR CO.</u>

12. VCM connector (A)




Fig. 63: Identifying VCM Connector Courtesy of HYUNDAI MOTOR CO.

- 13. ETC connector (A)
- 14. MAP & IATS connector (B)

2010 ENGINE Cylinder Head Assembly - Tucson




Fig. 64: Identifying ETC Connector Courtesy of HYUNDAI MOTOR CO.

- 15. PCSV connector (A)
- 16. ECT sensor connector (B)
- 17. Condenser connector (C)
- 18. CKP sensor connector (D)




Fig. 65: Identifying PCSV Connector And ECT Sensor Connector Courtesy of HYUNDAI MOTOR CO.

- 19. Oxygen sensor connector (E)
- 17. Connect the radiator upper hose (A) and low hose (B).

2010 ENGINE Cylinder Head Assembly - Tucson





Fig. 66: Identifying Radiator Upper Hose And Low Hose Courtesy of HYUNDAI MOTOR CO.

18. Install the under cover (A).

Tightening torque:

 $19.6 \sim 24.5 \text{ N.m} (2.0 \sim 2.5 \text{ kgf.m}, 14.5 \sim 18.1 \text{ lb-ft})$



<u>Fig. 67: Identifying Under Cover</u> Courtesy of HYUNDAI MOTOR CO.

19. Install the battery (D) and connect the battery positive terminal.

Tightening torque:

(+) terminal: $7.8 \sim 11.8 \text{ N.m} (0.8 \sim 1.2 \text{ kgf.m}, 5.8 \sim 8.7 \text{ lb-ft})$

Bracket bolt: $9.8 \sim 11.8 \text{ N.m} (1.0 \sim 1.2 \text{ kgf.m}, 7.2 \sim 8.7 \text{ lb-ft})$

20. Install the air cleaner assembly (C) and then connect the air intake hose (B) and breather hose (A).

2010 ENGINE Cylinder Head Assembly - Tucson


Tightening torque

Hose clamp bolt:

 $2.9 \sim 4.9 \text{ N.m} (0.3 \sim 0.5 \text{ kgf.m}, 2.2 \sim 3.6 \text{ lb-ft})$

Air cleaner assembly bolts:

 $7.8 \sim 11.8 \text{ N.m} (0.8 \sim 1.2 \text{ kgf.m}, 5.8 \sim 8.7 \text{ lb-ft})$




<u>Fig. 68: Identifying Air Cleaner Assembly, Air Intake Hose And Breather Hose</u> Courtesy of HYUNDAI MOTOR CO.

- 21. Install the air duct (C).
- 22. Install the engine cover (B).
- 23. Connect the battery negative terminal (A).

Tightening torque:

(-) terminal: $4.0 \sim 6.0 \text{ N.m}$ ($0.4 \sim 0.6 \text{ kgf.m}$, $3.0 \sim 4.4 \text{ lb-ft}$)



<u>Fig. 69: Identifying Air Duct, Engine Cover And Battery Negative Terminal</u> Courtesy of HYUNDAI MOTOR CO.

2010 ENGINE Cylinder Head Assembly - Tucson

NOTE:

- Refill engine oil.
- Clean the battery posts and cable terminals with sandpaper.
 Assemble and then apply grease to prevent corrosion.
- · Inspect for fuel leakage.
 - After assembling the fuel line, turn on the ignition switch (do not operate the starter) so that the fuel pump runs for approximately two seconds and fuel line pressurizes.
 - Repeat this operation two or three times, then check for fuel leakage at any point in the fuel lines.
- Refill radiator and reservoir tank with engine coolant.
- Bleed air from the cooling system.
 - Start engine and let it run until it warms up. (Until the radiator fan operates 3 or 4 times.)
 - Turn Off the engine and let it cool down. Check the level in the radiator, add coolant if needed. This will allow trapped air to be removed from the cooling system.
 - Put radiator cap on tightly, then run the engine again and check for leaks.