### **ABOUT THE EMS\* DIAGNOSTIC MANUAL**

\*Engine Management System

The EMS(Engine Management System) diagnostic manual outlines the detailed procedures to troubleshoot complaints related to the Common Rail Diesel Engine and its controller (EMS ECU) fitted on **Scorpio VIx/Sle/Lx (Refresh)** vehicle. Procedures to treat each DTC retrieved from the EMS ECU is given in a step by step , trouble-shooting tree structure.

This manual covers -

- EMS ECU re-programming/Re-flashing procedures, including micro-hybrid related parameters.
- Trouble shooting and diagnosis of DTCs (Defect Trouble Codes)
- Actuator tests
- Symptom Based diagnosis

The EMS ECU is linked to Engine immobilizer ECU(ICU) system and hence it is recommended that only trained CoTEKs carryout re-programming operations in the system, if required.

This Diagnostic manual supersedes all earlier manuals vis-a-viz MAN-00029, MAN-00030 and MAN-00038. For issues related to non-Transponder based immobilizer (Mahindra Secure) systems, refer to the section "Analog Based Immobilizer" in the manual MAN-00057.

In spite of our best efforts to make the manual error-free, a few errors could have inadvertently crept in. If you identify errors, functional or typographical, please inform your TEKline or <a href="mailto:pillay.ajay@mahindra.com">pillay.ajay@mahindra.com</a>. Suggestions to improve the manual and make it more user-friendly are also welcome.

© **2009 Mahindra & Mahindra Ltd**. All rights reserved. This book may not be reproduced or copied, in whole or in part, without the written permission of Mahindra & Mahindra Ltd.

# **Contents**

How to use this manual

Over view of the vehicle communication network

**Brief Specification- Engine.** 

**Note on Engine Stop-Start (Micro Hybrid)** 

Recommended trouble shooting procedure

**IQA** code

**Warranty & Other Information** 

**EMS ECU Programming /Flashing** 

Reprogramming procedure

**List of DTC codes** 

**DTC Codes.** 

**Actuator Tests** 

**Symptom Based Diagnosis** 

**Conformity Check / Resistance Values.** 

Analog Based Immobilizer (Applicable to Scorpio VIx non-refresh models only)

**Release Notes** 

MAN-00057-2 March 2009/Rev 3

#### How to Use this manual

If the DTC code is known, then go to the Index of DTC code, and click on the group under which the DTC appears. The codes/groups are hyperlinked to the respective trouble shooting chart/pages.

The following is the structure of the Diagnostic Manual –

- Sketch/Photo of the sensor/actuator involved
- Brief description about the sensor/Actuator and its functions
- Possible defect codes related to that sensor/actuator
- Normal/Abnormal operating conditions of the sensor/actuator, possible causes and vehicle/engine reactions
- Related circuit diagram, connectors and wiring plans
- Trouble shooting process

Always use the diagnostic manual along with the vehicle's wiring manual (MAN-00058).

The Diagnostic tester has the ability to test certain actuators.

For GEN3 Immobilizer related errors, the DTCs in the Engine EMS and along with that the DTCs in the Immobilizer ECU(ICU) need to be analyzed together. Refer to the Diagnostic Manual (Immobilizer) – **MAN-00056** for details. The possible causes and corrective action are to be taken based on the combination of the codes.


There are certain complaints for which no DTC codes are generated. The trouble shooting procedure for the same is covered in the Symptom based Diagnosis.

The Micro-hybrid (Engine Stop-Start) is variant specific and will not be available in all models. At present, the micro-hybrid feature is available only in the VIx variant. Introduction of this feature in other variants will be communicated through TSB.

#### Note:

Prior to introduction of transponder based immobilizer, Scorpio VIx vehicles sold between Dec 2007 and March 2009, had Analog immobilizer linked to the Security system and EMS ECU. The details of trouble shooting of this system are appended under the chapter "Analog based immobilizer". Use the corresponding wiring manual, MAN-00028, while trouble-shooting.

### Overview of the in-vehicle communication network



Scorpio VIx, Sle, Lx (Refresh)

#### M Hawk Engine Brief Data (2.2L- BS III/BS IV)

Bore : 85 mm Stroke : 96 mm

Power - Max 86.7 kW BHP @ 3800

Torque -Max 277 Nm@1800

Firing Order 1-3-4-2

Type Of ECU : Bosch EDC 16C39


### **Note on Engine Stop-Start System**

The Engine Stop-Start System (ESS) is a feature which automatically switches off the engine, when certain conditions are met.

Once the engine has switched off due to ESS, it can be restarted by pressing the clutch pedal.

ESS switch needs to be switched ON to activate the system.

With ESS switch ON, below schematic representation explains the ESS functionality.




The block diagram of how the ESS functions is given in the next page.


ESS is controlled from the EMS ECU. If any of the sensors malfunction then the ESS is disabled and an error code generated.

For details of each sensor electrical function refer the section on brief description, associated with the relevant Defect Trouble Code (DTC).

### I/O of ESS



#### I/O of ESS



#### Note:

- 1) If the feature selection switch is reset (From ON OFF ON) when vehicle is in auto stop mode, then clutch start will not be possible but key crank would be possible.
- 2) If Bonnet is opened when the vehicle is in auto-stop mode, clutch start would be disabled and only key crank would be possible.

However under both the above conditions, auto stop / start would be possible if all required conditions for auto-stop are met again.

### **Recommended Trouble Shooting Process**

#### **Customer complaint**



#### **Record/Understand Customer Verbatim**

- What happened?
- When it happened?
- What was the event before that?
- Does it happen all the time?
- Does it happen only in some condition?



Search for Published quick solution in TEKnet.



Follow DTC based diagnosis



Contact **TEKliner** with **TAR** (Technical Assistance Request)

### **IQA/IMA Code Programming**

An ECU controlled engine needs precise metering of fuel. Due to manufacturing tolerances, each injector deviates slightly from its idealized behavior. Thus, each injector has a correction factor, which is engraved on top of it, in the form of a 7-character alphanumeric code. This is known as an IQA code/IMA code. For optimal performance of the engine, the ECU needs to know the IQA code/IMA code of each injector. This information is programmed into the ECU when the vehicle is manufactured. However, if you need to replace an injector(s), then the IQA code/IMA code for that new injector has to be updated in the ECU.

As a first step, you need to select the cylinder number of the injector being replaced. After the cylinder number is selected by clicking on the check-button next to the number, the IQA code/IMA code should be entered in the box provided.

Click the button to the right of the text box. If the Injector code is valid and accepted by the ECU, a message is displayed, indicating that the operation is performed successfully.

A message "Invalid IQA code" will be displayed, if an incorrect IQA/IMA code is keyed in. IQA codes are case sensitive.

Programming IQA codes is an extremely important activity. In order to ensure that the correct code has been entered and that it has been entered in the correct cylinder, SMART tester allows you to verify the codes that you have entered.

Select an injector, and click the button below the "Verify" line in figure. The IQA codes present in the ECU will be read back and displayed in the text box before this button. It is recommended that you carry out the verification activity whenever you change an IQA code.

PLEASE ENSURE TO PROGRAM IQA/IMA CODES WHEN YOU REPLACE AN INJECTOR, ECU or ENGINE.

The following are the fonts of the alphanumeric characters of the IQA/IMA code, as etched on the injectors.

0123456789

ABC DEFGHIJKLM NOPQRSTUVWXYZ

MAN-00057-9 March 2009/Rev 3

#### **Warranty & Other Information**

All failures/complaints encountered on EMS ECU and/or ICU controllers need to be reported through a Common Rail Failure Report (CrFR)/Service Complaint Report (SCR).

Replacement of any of the EMS ECU or ICU controller requires approval of the TEKline. Ensure that a TAR is raised in the TEKnet website for approval, attaching the CrFR/SCR. While raising a warranty claim, the TAR no should be quoted on the warranty claim.

# Only a trained and certified CoTEK can raise a TAR (in TEKnet website)

### **EMS ECU Programming/Flashing**

The EMS ECU required to be flashed in the following conditions –

#### **BLANK ECU**

1. Procure blank EMS ECU from spare part dept.

**0315CM0031N** ECU WITHOUT ETK **C39**\*\*

- \*\* Check for the correct/latest part no in parts catalogue/Technical Service Bulletins.
- 2. Flash the EMS ECU dataset with a **latest dataset** as per TSB or at the advice of TEKline.

#### REFLASHING AN EXISTING ECU

- 1. Flash the EMS ECU with the correct/latest dataset(Field dataset). The matrix of the vehicles and the related latest dataset will be released through TSB if in doubt ask the TEKline.
- 2. Wrong dataset flashing may result in vehicle not starting and can lead to EMS ECU failure.
- 3. If a different version dataset is used on Micro Hybrid (ESS) enabled vehicles, the Starter Motor will engage continuously, when the ignition is switched ON.

Model	Software Version	ECU Type	Plant Dataset ID	Field Dataset ID
Scorpio VIx (Refresh) TBI ESS MT - BS III	V76	EDC16C39	1037397155	Will be released through a TSB
Scorpio VIx (Refresh) TBI ESS MT BS IV	V76	EDC16C39	1037397191	Will be released through a TSB
Scorpio Sle/Lx (Refresh) TBI MT BS III	V71	EDC16C39	1037397093	1037397128
Scorpio VIx (Non-Refresh) TBI MT BS III	V71	EDC16C39	1037397090	1037397127
Scorpio VIx (Non-Refresh) TBI AT BS III	V75	EDC16C39	1037397150	Will be released through a TSB
Scorpio VIx (Non-Refresh) AT BS III	V64	EDC16C39	1037392587	1037392587
Scorpio VIx (Non-Refresh) MT BS III	V52	EDC16C39	1037392417	1037392417
Scorpio VIs (Non-Refresh) MT BS III	V52	EDC16C39	1037392423	1037392423

TBI – Transponder Based Immobiliser

ESS – Engine Stop-Start

MT - Manual transmission

AT – Automatic Transmission

BS III - Emission Level Bharat Stage 3


BS IV - Emission Level Bharat stage 4

#### Notes -


- 1. Ensure that the there is no communication breakdown once the flashing begins. Check Python connections are secure.
- 2. Ensure that the SMART tester has -
  - Enough battery reserve/Connected to AC power
  - Screen saver/Battery saver mode turned off,
  - Vehicle's ignition is ON
  - Battery terminals connected securely.
  - Battery earth connection is good.
- 3. Never touch the ECU pins by hand/finger.

#### RE-PROGRAMMING PROCEDURE

Caution while flashing on vehicles with ESS feature: Before switching ON the ignition with a blank ECU for start of flashing, ensure that the starter relay is disconnected. This is a safety precaution.




Connect using the "Python1BConfig0404".




#### Click on to the ECU flash tool




Scorpio VIx, SIe, Lx (Refresh)



Write the correct 17 digit VIN



- Click on "Select Hex File" (Refer to latest TSB)
- Select the applicable dataset and click "open"
- Click "Flash"



- After completion of flashing, switch OFF the ignition for 1 minute and switch it ON
- Learn the EMS with Immobilizer ECU (ICU) Refer to diagnostic manual (immobilizer).
- Refit the starter relay if it has been removed for vehicle with ESS

### MAN-00057-15 March 2009/Rev 3

### **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

#### Index

Group	Code	Label	Page No
_	D 0422	Voltage above upper limit	_
	P-0123		
APP1			23
AFFI	P-0122	Voltage below lower limit.	25
	P-1120	Plausibility with APP2 violated.	
	P-0223	Voltage above upper limit	
	P-0222	Voltage helew lower limit	
	P-0222	Voltage below lower limit.	
APP2	P-1220	Plausibility with APP1 violated	28
	1-1220	l lausibility with Al 1 1 violated	
	<b>D</b> 4004	Accelerator Pedal signal not	
	P-1221	plausible with brake	
	P-1604	Short circuit Battery	
DDA	P-1605	Short circuit Ground	33
<u>BPA</u>	P-1606	No Load	33
	P-1607	Excess Temperature	
	P-235	Boost pressure sensor-	
		Voltage above upper limit	
DD0	P-236	Boost pressure sensor- Voltage	40
<u>BPS</u>		below lower limit	40
	P-1236	Boost pressure sensor not	
		plausible with atmospheric pressure sensor.	
	P-0340	No camshaft signal	
<u>Camshaft</u>	P-0341	Wrong camshaft signal	45
		P-0335 No crankshaft signal	
<u>Crankshaft</u>	P-0336	Wrong crankshaft signal	48
	P-0103	Voltage above upper Limit	
Air Flow			51
	P-0102	Voltage below lower Limit	
	P-0113	Voltage above upper limit.	
Air temperature	B 0410	1/16 1 1 1 1 1 1	57
	P-0112	Voltage below lower limit.	
Rail Pressure	P-0193	Voltage above upper limit.	61
	P-0192 P-1192	Voltage below lower limit.	
	P-1192	Maximum positive Rail pressure deviation exceeded	
		Maximum positive Rail	65
	P-1193	pressure deviation exceeded	<del>0</del> 3
		concerning the set flow value	
Rail pressure		Maximum negative rail	68
<u>deviation</u>	D 4404	pressure deviation with	
	P 1194	metering unit on lower limit is	
		exceeded.	
	P-1195	Minimum rail pressure	69
exceeded.			
<u>K Line</u>	No communication with Diagnostic		70

### MAN-00057-16 March 2009/Rev 3

### **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

	P-0406	Short Circuit Battery	
	P-0405	Short Circuit Ground	
<u>EGR</u>	P-0403	No Load	72
<del> </del>	P-0404	Excess Temperature	
Error path of		Offset between camshaft	75
offset	P-1340	and crankshaft	73
Fuel Temperature	P-0182	Voltage above upper limit	
Sensor	P-0183	Voltage below lower limit	79
<u>Gerrisor</u>	P-1252	Short Circuit to Battery	
	1 1202	Chort Great to Battery	
Metering Unit	P-1253	Short Circuit to Ground	83
metering ont	P-1250	No Load	00
<del>                                   </del>	P-1251	Excess Temperature	
	P-121A	Main relay does not open	
	1-121A	in time	
Main relay		Main relay opens too	87
	P-121B	early	
	P-0577	SRC MAX error for analog	
	1 -0077	signal	
		SRC MIN error for analog	
Cruise	P-0576	signal	90
<u>ordise</u>		Plausibility error for	30
	P-0575	analog signal	
	1-0373	analog signal	
	P-0563	Voltage above upper limit	
Battery	1 0000	voltage above apper mini	95
<u> </u>	P-0562	Voltage below lower limit.	
	P-1792	Brake signal is defective	
		Drane eignarie dereenve	
Brake Switch		Brake signals not	96
	P-1791	plausible	
01 4 1 6 11 1	<b>D</b> 0-0 (	Clutch signal is not	99
Clutch Switch	P-0704	plausible	
	P-0118	Voltage above upper limit	
Coolant Temp	F-0110		102
Sensor(CTS)	D 0445	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	102
	P-0117	Voltage below lower limit	
		Minimum Temperature	
	P-2558	not reached within time	
OTO -1 1 1 2		limit.	
CTS absolute &			106
dynamic test		NAC CONTRACTOR OF CONTRACTOR O	
	D 4466	Minimum temperature or	
	P-1126	temperature raise no	
		reached within time limit	
	P-165E	Short Circuit to Battery	
Overheat lamp	P-165F	Short Circuit to Battery	108
	P-1660	No Load	
	P-1661	Excess Temperature	

Scorpio VIx, Sle, Lx (Refresh)

Atm pressure	P-0108	Voltage above upper limit	
sensor			111
	P-0107	Voltage below lower limit	
	P1623	Below lower limit of enegising time- Injector #	
<u>Injector</u>	P1625	Below lower limit of enegising time- Injector #	112
Energizing Time	P161F	Below lower limit of enegising time- Injector #	
	P1621	Below lower limit of enegising time- Injector #	
Communication monitoring	P-162A	Communication error of CJ940	113
Controller & TPU Monitoring	P-1659	Deviation between TPU and system time	114
ECU Monitoring	P-1638	Set, if error-counter of Watchdog or controller are not plausible or the system must shut down	115
	P-162B	EEPROM: error during last read operation	
EEPROM Monitoring	P-162C	EEPROM: error during last write operation	116
	P-162D	EEPROM: default value used	
	P-160C	Short Circuit to Battery	
<u>Tachometer</u> <u>Signal</u>	P-160D	Short Circuit to Ground	117
	P-160E	No Load	
	P-1608	Short circuit to battery	
<u>Coolant</u> <u>temperature</u>	P-1609	Short circuit to ground	120
<u>output</u>	P-160A	No load	
	P-160B	Excess temperature	
	P-1530	Short circuit to battery	
	P-1531	Short circuit to ground	
Air condition	P-1532	No load	123
	P-1533	Excess temperature	

	P-1210 P-1211 P-1212	Chip-specific errors: CY33X internal reset / clock loss / under voltage  Chip-specific errors: CY33X is unlocked / CY33X init error Chip-specific errors:CY33X is in Test mode	
Injector Power	P-1213	Chip-specific errors: CY33X SPI communication error /checksum/read back	125
<u>Stage</u>	P-1214	Chip-specific errors - >CY33X internal parity error	
	P-1215	Chip-specific errors - >CY33X internal program flow error	
	P-1216	Chip-specific errors - >CY33X check of inv. YSEL during ON failed	
	P-1217	Chip-specific errors - >CY33X ON timeout for at least 1 cylinder	
Monitoring communication	P-1664	The fault path contains the supervision of the SPI-Handler Set, if SPI-communication failed	126
	P-1641	Test of redundant shut off paths during initialization: Watch dog switch off path defect	
Power stage Monitoring	P-1642	Test of redundant shut off paths during initialization: Voltage monitoring upper limit shut off path defect	127
	P-1643	Test of redundant shut off paths during initialization: Voltage monitoring lower limit shut off path defect	
Power Stage Voltage	P-1631	(Hardware) CJ940 upper limit: internal supply voltage upper limit (Hardware)	128
<u>Monitoring</u>	P-1632	CJ940 lower limit: internal supply voltage lower limit	

Scorpio VIx, Sle, Lx (Refresh)

	P-1644	Voltage above upper limit	
Sensor Supply	1 1044	voltage above apper mini	129
Monitoring 1	P-1645	Voltage below lower limit	
Sensor Supply	P-1646	Voltage above upper limit	400
Monitoring 2	P-1647	Voltage below lower limit	132
	P-1654	Short Circuit to Battery	
Custom Lower	P-1655	Short Circuit to Battery	405
System Lamp	P-1656	No Load	135
	P-1657	Excess Temperature	
Terminal 15 ( Ignition Switch)	P-1658	No Terminal T15 signals detected	137
	P-0503	Exceeding of the maximum vehicle speed	
	P-0500	HW signal for vehicle	
Vehicle Speed		speed not valid	139
		Vehicle speed not	
	P-0501	plausible with injection	
		mass and engine speed	
	P-1387	Short Circuit to Battery	
Glow Control	P-1388	Short Circuit to Ground	
(if applicable)			141
in approactor	P-1389	No Load	
	D 4200	Evene tamperatura	
	P-1390 P-0513	Excess temperature	144
		Invalid key error  Communication wire may	144
Immobilser	P1832	open	145
Codes	P-183A	Signature Mismatch	148
<u> </u>	P-183B	EMS is locked.	150
	P-183E	EEPROM error	152
		Injector bank 1: short	
	P-201	circuit	
		Injector bank 1: short	
Foult noth hanks	P-1201	circuit on Low Side to	
Fault path bank1- specific errors ->		ground	153
stop engine		Injector bank 1 specific	155
Stop engine	P-1203	error depending on	
		application	
	P-1204	Injector bank 1 not-	
		classifiable error	
	P-1205	Injector bank 1specific	
	F-12U0	warning : depending on application	
<u> </u>		Injector bank 1specific	
Fault path bank1-	P-1206	warning : depending on	
specific warning -	200	application	154
> stop engine	<b>.</b>	Injector bank 1specific	. • .
	P-1207	warning open load	
		Injector bank 1specific	
	P-1208	warning depending on	
		application	

### MAN-00057-**20** March 2009/Rev 3

### **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

Pressure control	P-1400	AirCtl permanent positive governor deviation: Positive governor deviation above limit	155
Regulation (VGT control)	P-1401	AirCtl permanent negative governor deviation: negative governor deviation below limit	155
CAN error	P-1705	Main Clutch CAN signal error	157
Transmission clutch signal-CAN	P-0704	Main Clutch signal not Plausible error	158
TCU error	P-0302	TCU error state	159
EMS ECU Mute Error	P-0073	EMS ECU in confirmed Mute error	160
CAN Vehicle speed not valid	P-1827	CAN signal for Vehicle speed not valid	161
Gear Neutral	P-1704	Gear Neutral signal is not plausible	163
Switch	P-168E	Gear Neutral signal is not plausible in Standstill Condition	166
	P-170D	Short Circuit Battery	169
Starter Power stage	P-170E	Short Circuit to Ground	172
	P-1710	Excess Temperature	171
Gear Neutral	P-1712	No Load	173
Switch Relay	P-1714	GNS Relay Sticking	176
Redundant Clutch Switch	P-170A	Clutch signal is not plausible	180
	P-1AE9	Short Circuit Battery	183
Stop Lamp Power	P-1AEA	Short Circuit to Ground	184
Stage	P-1AEB	No Load	185
	P-1AEC	Excess Temperature	187
T 50 (Ignition Switch)	P-1715	Terminal 50 Always pressed.	188

Scorpio VIx, Sle, Lx (Refresh)

Group	Code	Label	Page No
	Home Screen for Ac	tuator	189
	ACT # 1	System lamp Actuator test	190
Actuator Test	ACT # 2	Coolant Overheat Lamp	192
	ACT # 3	Air Conditioning	193
	ACT # 4	EGR	194
	ACT # 5	Boost Pressure Actuator (BPA)	195
Symptom Pacad	SBD #1	Vehicle not starting & no error codes	196
Symptom Based Diagnosis	SBD # 2	Vehicle not starting also may get P1192/1193	198


For Analog Immobilizer Code (Applicable for Scorpio VLX without Transponder Based Immobilizer, sold between Dec 2007 to March 2009)

Group	Code	Label	Page No
	P-1828	Immobilizer	
		communication	205
		wire open or short	
	P-1829	Immobilizer	
		communication	207
		wire short to	207
		ground.	
	P-182A	Immobilizer signal	211
		in error zone	211
	P-182B	ECU is locked	213
		completely	213
	P-182C	Immobilizer	
		controller has not	245
		received correct	215
		pattern (RF signal)	

MAN-00057-22 March 2009/Rev 3

**Accelerator Pedal Module 1** 

P-0123 P-0122 P-1120



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-23 March 2009/Rev 3

#### P-0123 P-0122 P-1120

#### **Accelerator Pedal Module 1**

#### **Description:**

The Accelerator pedal module (APM) mounts in place of accelerator pedal and is connected to the ECU by wires. The APM sensor is a variable resistor (potentiometer) whose resistance changes according to the pedal position. ECU applies a reference voltage to the APM sensor and then measures the voltage that is present on the APM sensor signal circuit. The ECU uses the APM sensor signal for further calculation of fuelling & other engine operational parameters.

DTC	Diagnostic item
P-0123	Voltage above upper limit
P-0122	Voltage below lower limit.
P-1120	Plausibility with APP2 violated.

DTO detection condition	Duckahla asusa
DTC detection condition	Probable cause
Normal Operation	
<ul> <li>The Accelerator pedal module (APM) outputs a voltage, which is proportional to the Position of accelerator pedal.</li> <li>The ECU checks whether the voltage output by the Accelerator pedal module is within a specified range. In addition, it checks that the voltage output does not become too large while the engine is in idling.</li> </ul>	<ul> <li>Open or shorted         Accelerator pedal         module circuits, loose         or wrongs         connections.</li> <li>Accelerator pedal         module failed or         maladjusted.</li> </ul>
Proper Performance Sensor output voltage has continued to between 0 to 5V, varying accelerator pedal position.	
Malfunction; out-of-range     With the changing Accelerator pedal position, the sensor output voltage has continued to be 5V or 0V.	
<ul> <li>Reaction:</li> <li>The engine speed not varying with changing accelerator pedal position. (Constant 1200 rpm)</li> <li>The system lamp is continuously on.</li> </ul>	


### MAN-00057-24 March 2009/Rev 3

P-0123

P-0122 P-1120 **ECU** K45 K09 K30 **K46 K31 K08** Gr-B G-R R-WSb W-R P 5-GND 4-O/P 1 6-O/P 2 **3-GND** Vcc Vcc APP1 APP2

Scorpio VIx, Sle, Lx (Refresh)

#### MAN-00057-25 March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)


MAN-00057-**26**March 2009/Rev 3

#### Test Procedure APP1 -

P-0123 P-0122 P-1120

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify either P0123 or P122 or P1120 are present.
- Turn Ignition switch OFF & disconnect Accelerator Pedal connector.
- Turn the Ignition ON & measure voltage between terminal 2 & terminal 3 of the APP1 (from the APP1 connector side.)
- It should be 5 ± 0.3 V
- Is it?

•



#### MAN-00057-27 March 2009/Rev 3

P-0123 P-0122 P-1120

Yes	No
Clear the code.	Replace the Accelerator pedal Module
Verify that the complaint has been eliminated.	

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-28 March 2009/Rev 3

> P-0223 P-0222

> P-1220

#### **Accelerator Pedal (APP2)**


#### **Description:**

P-1221 The Accelerator pedal module (APM) mounts in place of accelerator pedal and is connected to the ECU by wires. The APM sensor is a variable resistor (potentiometer) whose resistance changes according to the pedal position. ECU applies a reference voltage to the APM sensor and then measures the voltage that is present on the APM sensor signal circuit. The ECU uses the APM sensor signal for further calculation of fuelling & other engine operational parameters.

DTC	Diagnostic item
P-0223	Voltage above upper limit
P-0222	Voltage below lower limit.
P-1220	Plausibility with APP1 violated
P-1221	Accelerator Pedal signal not plausible with brake


DTC detection condition	Probable cause
Proper Performance	
Sensor output voltage has continued to between 0 to 2.5V, with varying accelerator pedal position.	Open or shorted     Accelerator pedal     module circuits, loose or
Malfunction; out-of-range	wrong connections.
<ul> <li>With the fully pressed Accelerator pedal module,</li> </ul>	
the sensor output voltage has continued to be 2.5V or 0 for 4 sec.	Accelerator pedal module failed or maladjusted.
Reaction	,
<ul> <li>The engine speed not varying with changing accelerator pedal position. (Constant 1200 rpm)</li> <li>The system lamp is continuously on.</li> </ul>	


P-0223 P-0222 P-1220 P-1221



MAN-00057-**30** March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)





Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-31 March 2009/Rev 3

#### Test Procedure APP2 -

P-0223 P-0222


1. Connect the 'Smart Tester' to diagnostic connector.

P-1220

2. Turn Ignition Switch ON.

P-1221

- 3. Verify that either P0223/P0222/P1220 / or P1221 is present.
- Turn Ignition switches OFF & disconnect Accelerator pedal connector.
- Turn the Ignition ON & measure voltage between terminal 2 & terminal 3 of the APP2 (from the APP2 connector side.)
- It should be  $2.5 \pm 0.15 \text{ V}$
- Is it?




Scorpio VIx, Sle, Lx (Refresh)

#### MAN-00057-32 March 2009/Rev 3

P-0223 P-0222

> P-1220 P-1221

Reconnect. Before reconnection check that the pins are not bent or oxidation has not taken place.	Repair the damaged line/ connection.
Clear the codes.	Clear code.
Does the problem persist?	Verify that the complaint has been eliminated.




Yes	No	
	Replace the Accelerator pedal Module	
Clear code.		
Verify that the complaint has been eliminated.		

MAN-00057-33 March 2009/Rev 3

**Boost Pressure Actuator** 

P-1604 P-1605 P-1606 P-1607



Scorpio VIx, Sle, Lx (Refresh)

#### MAN-00057-34 March 2009/Rev 3

#### Description -

In normal operation and during an actuator test, the PWM power stage of ECU is tested for short circuit to battery voltage, short circuit to ground, open circuit and excess temperature. Once the errors are confirmed, the power stage is switched off.

P-1604 P-1605 P-1606 P-1607

The BPA in turn controls the Variable vanes operation through vacuum.


#### Hint:

Short circuit to battery and excess temperature errors can be detected only when the power stage is switched on.

Short circuit to ground and no load errors can be detected only when the power stage is switched off.

DTC	Diagnostic item	
P-1604	Short circuit Battery	
P-1605	Short circuit Ground	
P-1606	No Load	
P-1607	Excess Temperature	
	DTC detection condition	Probable cause
Proper Performance		Possible Causes
The ECU monito	ors the Boost pressure actuator (	
modulator) during the normal operation as well as during		<ul> <li>Short circuit to battery</li> </ul>
actuator test)		or ground.
Malfunction; out-of-range		<ul> <li>Excess temperature</li> </ul>
<ul> <li>With the fully pressed Accelerator pedal module,</li> </ul>		No load.
the sensor output voltage has continued to be		
2.5V or 0	) for 4 sec.	
Reaction		
<ul> <li>Torque v</li> </ul>	vill be reduced	
EGR is s	witched off.	
<ul><li>System (</li></ul>	Check lamp is ON	


#### MAN-00057-35 March 2009/Rev 3



MAN-00057-36 March 2009/Rev 3



P-1605 P-1606 P-1607



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-37 March 2009/Rev 3

> P-1604 P-1605 P-1606 P-1607

The BPA can give errors due to the following causes:

- 1. Error present in modulator and reported by ECU.
- 2. There is vacuum leak in the system. Thus when the x amount of boost but the actual amount is y. The BPA will supply more vacuum to the VGT so that the vanes open further and boost is
  - increased. If however the VGT movement is not proportional to the demand, then after a limit, the complaint will be registered as an error.
- 3. If the boost pressure is not proportional to the expected performance as the VGT is not able to respond to the changes then the ECU will register is as an error of the BPA.

We suggest that the diagnostic procedure has to be  $1 \longrightarrow 2 \longrightarrow 3$ 

#### **Test Procedure BPA**

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P1604/P1605/P1606/P1607 is present.

#### For Defect Codes P 1605 & P1606 -

- Turn Ignition switches OFF & disconnect BPA connector.
- Turn the Ignition ON & measure voltage between terminal 2 & terminal 3 of the APP2 (from the APP2 connector side.)
- It should be 4.5 ± 0.15 V
- Is it?

Check the continuity from BPA to A15

Is it OK?



taken place.

Clear the codes.

Clear the code

taken place. Clear the codes.

Does the problem persist?

the pins are not bent or oxidation has not

MAN-00057-38 March 2009/Rev 3

P-1604 P-1605 P-1606 Repair the damaged line/ connection Measure the continuity from Battery to BPA P-1607 Clear code Verify that the complaint has been eliminated. No Yes Reconnect. Before reconnection check that Check the vacuum lines (in particular the pins are not bent or oxidation has not the line from the BPA to the actuatorcheck for looseness. Or hardening due to aging. Does the problem persist? No **V**Yes Change the BPA with a known good one Reconnect. Before reconnection check that

lack	<b>\</b>	
Yes	No	
Replace the VGT	Replace the Accelerator pedal Module	
Clear code.		
Verify that the complaint has been eliminated.		

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-39 March 2009/Rev 3

#### For Defect Codes P 1604 & P1607 -

- Turn Ignition switches ON & connect BPA connector.
- Turn the Ignition ON & measure voltage coming to the BPA it should 5 V.

Is it?

P-1604 P-1605 P-1606

P-1607

Is it OK?

Yes	No
<b>\</b>	<b>\</b>
Check the voltage at A15. is it 5 V?	Check the grounding from battery to BPA. Repair or Replace the wire, clear the codes. & confirm.
No	
No	
Check for shorting to ground from BPA to A15.	Check the vacuum lines (in particular the line from the BPA to the actuator-check for looseness Or hardening due to aging.
Replace the wires.	
Clear the codes and confirm.	

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-**40** March 2009/Rev 3

P-235 P-236 P-1236

#### **Boost Pressure Sensor**

#### **Description:**

The boost pressure signal is monitored. This signal is used as a feedback for the control of the VGT and also for the EGR.


The boost pressure sensor is mounted on the outlet of the intercooler.


DTC	Diagnostic item	
P-235	Boost pressure sensor- Voltage above upper limit	
P-236	Boost pressure sensor- Voltage below lower limit	
P-1236	Boost pressure sensor not plausible with atmospheric pressure	
	sensor.	

DTC detection condition	Probable cause
Proper Performance	Possible Causes
The ECU monitors the Boost pressure	Short circuit to battery or ground.
Malfunction; out-of-range	No load.
<ul> <li>Monitors the pressure build up or decrease.</li> <li>Also monitors the plausibility with the atmospheric pressure sensor</li> </ul>	Defective sensor
Reaction	
System Check lamp is ON	
Engine torque is limited.	
Air mass – default values taken	

### MAN-00057-41 March 2009/Rev 3








Scorpio VIx, Sle, Lx (Refresh)


MAN-00057-42 March 2009/Rev 3



P-235 P-236 P-1236



SENSOR



The BPS can give errors due to the following causes:

There is vacuum leak in the system.

1. If the boost pressure is not proportional to the expected performance as the VGT is not able to respond to the changes then the ECU will register is as an error of the BPA.


#### **Test Procedure BPA**

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P235/P236/P1236 is present.
- Turn Ignition switches OFF & disconnect BPA connector.
- Turn the Ignition ON & measure voltage between terminal 2 & terminal 3 of the APP2 (from the APP2 connector side.)
- It should be  $4.5 \pm 0.15 \text{ V}$
- Is it?

Check the continuity from BPS to A13 to 1, A23-2; A40-3

Is it OK?


## MAN-00057-43 March 2009/Rev 3



MAN-00057-44 March 2009/Rev 3

**Camshaft Speed Sensor** 

P-0340 P-0341



Scorpio VIx, SIe, Lx (Refresh)

### Camshaft speed sensor


P-0340 P-0341


DTC	Diagnostic item
P-0340	No camshaft signal
P-0341	Wrong camshaft signal


#### Description

The Hall effect camshaft position sensor senses the Top dead center (TDC) point of the # 1 cylinder in the compression stroke. Which allows the ECU to determine when to start the injection.

DTC detection condition	Probable cause
Normal Operation  When the engine is running, the Camshaft Position sensor outputs a pulse signal.  The ECU checks whether the pulse signal is input.  Malfunction  Normal signal pattern has not been input for cylinder identification from the camshaft position	<ul> <li>Open or shorted camshaft position sensor circuit, loose or wrong connection.</li> <li>Camshaft Position sensor malfunction.</li> </ul>
sensor signal for 4 sec. (Engine should be cranked to check this error).  Reaction  Engine will not start  System lamp will be continuously on.	







P-0340 P-0341

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P0340 or P0341 are present.
- Switch off the Ignition.
- Disconnect the camshaft sensor connector.
- Turn ON the Ignition.
- Measure the voltage between the pins in the camshaft connector Pin No. 3 &1.
- It should be  $5 \pm 0.3$  Volts
- Is it?

<b>Y</b> es	No <sup>¥</sup>	
Turn the Ignition OFF <sup>♥</sup>	Repair the wires A 11 to Pin No.3 &A 20 to Pin No. 1.	
Disconnect ECU connector A.	Clear the error codes & verify.	
Measure the continuity of Ground (between sensor pin no 1 & ECU terminal A20) in the camshaft phase sensor harness.		
Is it OK?		
√es	No √	
Measure the continuity of signal (between	Repair the connection.	

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-**47** March 2009/Rev 3

sensor pin no 2 & ECU terminal A50) in the	
camshaft phase sensor harness.	
Is it OK?	Clear the error codes & verify
Yes	No
Check for physical damage to pins or oxidation.	Repair the connection.
Also check if the connectors are moving backwards when inserted.	Clear the error codes & verify.
Is it OK?	
Yes	No <sup>¥</sup>
Replace the camshaft phase sensor.	Repair the connection.
Clear the error codes & verify.	Clear the error codes & verify.

### MAN-00057-48 March 2009/Rev 3

Crankshaft sensor P-0335 P-0336 Phase Sensor Mounting on Camshaft Single Mass Flywheel Speed Sensor Mounting on Crankshaft

#### **Crankshaft Sensor**

P-0335 P-0336

<u>Description</u> - In order that the ECU can control the engine at all the position of the crankshaft must be known so that the cylinder in compression and the timing of the next fuel injection can be calculated. The CKP is an inductive pulse generator, which scans protrusions on the flywheel. Two teeth are missing, and this gap is situated at 90° before TDC.

DTC	Diagnostic item	
P-0335	No crankshaft signal	
P-0336	Wrong crankshaft signal	

DTC detection condition	Probable cause
Background	
<ul> <li>When the engine is running, the Crankshaft Position sensor outputs a pulse signal.</li> </ul>	<ul> <li>Open, shorted or wrong connection</li> </ul>
The ECU checks whether the pulse signal is input while the engine is cranking.	crankshaft position sensor circuit.
Normal Operating condition	<ul> <li>Failed or damaged crankshaft position</li> </ul>
Engine is being cranked.	sensor.
Malfunction	
<ul> <li>Normal signal pattern has not been input for cylinder identification from the crankshaft position sensor signal for 4 sec.</li> </ul>	
<ul> <li>No synchronization between crankshaft &amp; camshaft signal.</li> </ul>	
Reaction	
System lamp continuously on.	
Engine will not start.	
<ul> <li>If engine is running &amp; this fault occurs, engine will stop immediately.</li> </ul>	

#### ISS (Incremental speed sensor/ Crankshaft speed sensor)


**ECU** Sensor N S Y 1 A 27 **Positive** 2 A 12 **Negative** Shield A 21 3

#### MAN-00057-**50** March 2009/Rev 3

P-0335


P-0336

Scorpio VIx, Sle, Lx (Refresh)



**Test Procedure ISS** 


- 1. Connect the 'Smart Tester' to diagnostic connector.
- Turn Ignition Switch ON.
   Verify that either P0335 or P0336 are present. Please verify while cranking the engine.
- Turn the Ignition switch OFF.
- Disconnect the crankshaft position sensor connector and also the connector at ECU.
- Measure the continuity between the sensor terminal 1 and ECU terminal A 27.



MAN-00057-**51** March 2009/Rev 3

**Air Flow** 

P-0103 P-0102



Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-**52** March 2009/Rev 3

#### **Air Flow**

P-0103 P-0102


#### **Description** -

Mass air flow rate is measured by detection of heat transfer from a hot film probe because the change of the mass air flow rate causes change in the amount of heat being transferred from the hot film probe surface to the air flow. The airflow sensor generates a pulse so it repeatedly opens and closes between the 5V voltage supplied from the engine control module. This results in the change of the temperature of the hot film probe and in the change of resistance.

DTC	Diagnostic item	
P-0103	Voltage above upper Limit	
P-0102	Voltage below lower Limit	


DTC detection condition	Probable cause
Normal Operation	
<ul> <li>The HFM sensor outputs a voltage, which corresponds to the intake airflow.</li> </ul>	Open or shorted HFM sensor circuit, loose or
<ul> <li>The ECU checks whether this voltage is within a specified range.</li> </ul>	<ul><li>wrong connections.</li><li>Failed HFM sensor.</li></ul>
Normal Operating Requirements	
Ignition switch: ON	
<ul> <li>Malfunction lamp: OFF after 2 Sec</li> </ul>	
<ul> <li>Battery voltage is 8V-16V or more.</li> </ul>	
Malfunction	
<ul> <li>The sensor output voltage has continued to be 5V or higher.</li> </ul>	
The sensor output voltage has continued to be	
0.5V or lower.	
Reactions:	
<ul> <li>System lamp will continuously blink.</li> </ul>	
Engine will continue to run with default air flow (depending	
on Speed & Fuelling)	

MAN-00057-**53** March 2009/Rev 3




### MAN-00057-**54** March 2009/Rev 3

Scorpio VIx, SIe, Lx (Refresh)



#### **Test Procedure HFM**

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P0103 or P0102 are present.



Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-**55** March 2009/Rev 3


P-0103 P-0102

Check the output voltage ( with engine running)	Check fuses	
Signal voltage within the range	Check continuity between	
	the A29 & 4 (voltage)	
	Check continuity between A44 & 3 (	
	Ground)	
Is it?	Repair the open wire.	
1	Clear codes and verify that the HFM	
	signal ratio is within limit.	
¥Yes	No ↓	
Outlab off the Lord Co.		
Switch off the Ignition		
Check the connectors if the pins are bent or	Check the continuity between the A42 &	
Check the connectors if the pins are bent or having oxidation.	5 ( Signal)	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are		
Check the connectors if the pins are bent or having oxidation.	5 ( Signal) Rectify	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are	5 ( Signal)  Rectify  Clear codes and verify that the HFM	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are	5 ( Signal) Rectify	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are eliminated.	5 ( Signal)  Rectify  Clear codes and verify that the HFM	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are	5 ( Signal)  Rectify  Clear codes and verify that the HFM	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are eliminated.	5 ( Signal)  Rectify  Clear codes and verify that the HFM	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are eliminated.	5 ( Signal)  Rectify  Clear codes and verify that the HFM signal ratio is within limit.	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are eliminated.	5 ( Signal)  Rectify  Clear codes and verify that the HFM signal ratio is within limit.	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are eliminated.  No  Check the resistance of the HFM sensor ( between 5.892 KOhms	5 ( Signal)  Rectify  Clear codes and verify that the HFM signal ratio is within limit.	
Check the connectors if the pins are bent or having oxidation.  Clear codes & verify if the codes are eliminated.  No  Check the resistance of the HFM sensor ( better the bent or having oxidation.	5 ( Signal) Rectify Clear codes and verify that the HFM signal ratio is within limit.  ween 5 & 3) it should be between 5.119 to	

MAN-00057-**56** March 2009/Rev 3

**Air Temperature** 

P-0113 P-0112



MAN-00057-**57** March 2009/Rev 3

### **Air Temperature**

P-0113 P-0112


DTC	Diagnostic item
P-0113	Voltage above upper limit.
P-0112	Voltage below lower limit.

<u>Description:</u> The function acquires the raw voltage of the induction air temperature. The raw value is linearised and monitored for compliance with the signal range. The sensor is mounted in HFM.

DTC detection condition	Probable cause
Normal Operation	
<ul> <li>The HFM temperature sensor outputs a voltage, which corresponds to the temperature of intake airflow.</li> <li>The ECU checks whether this voltage is within a specified range.</li> </ul>	Open or shorted HFM temperature sensor circuit, loose or wrong connections.
	Failed HFM
<ul> <li>Normal Operating Requirements</li> <li>Ignition switch: ON</li> <li>Malfunction lamp: OFF after 2 Sec</li> <li>Battery voltage is 8V –16 V.</li> </ul>	temperature sensor.
Malfunction	
<ul> <li>The sensor output voltage has continued to be 5V or higher.</li> </ul>	
<ul> <li>The sensor output voltage has continued to be 0.2 V or lower.</li> </ul>	
Reactions	
<ul> <li>Engine will run with default air temp of 20 Degrees Centigrade</li> </ul>	
System lamp status for this error is off.	


### MAN-00057-**58** March 2009/Rev 3

P-0113 P-0112



MAN-00057-**59** March 2009/Rev 3






#### Test Procedure AFTSCD -

Codes: P0112, P0113


- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P0113 or P0112 are present.

Turn the ignition OFF
Disconnect HFM sensor Connector.
Turn the Ignition ON
Measure the voltage between the Terminal 3
& 4 of HFM Sensor Connector.
It should be 5 ± 0.3 Volts
Is it



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-**60** March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-61 March 2009/Rev 3

#### **Rail Pressure Sensor**

P-0193 P-0192

DTC	Diagnostic item
P-0193	Voltage above upper limit.
P-0192	<b>V</b> oltage below lower limit.

DTC detection condition	Probable cause
<ul> <li>Normal operation</li> <li>When ignition is ON rail pressure sensor getting supply from ECU.</li> <li>ECU reads the rail pressure in terms of voltage.</li> <li>Engine is starting properly.</li> <li>Building pressure in rail.</li> </ul>	<ul> <li>Open, shorted or wrong connection of rail pressure sensor circuit.</li> <li>Rail pressure sensor failed.</li> </ul>
Malfunction     Rail pressure output voltage is below	
<ul> <li>Reaction</li> <li>When ignition is ON system lamp is glowing.</li> <li>Engine is not starting &amp; error is set in ECU</li> <li>Error memory.</li> </ul>	

## MAN-00057-**62** March 2009/Rev 3


P-0193 P-0192 **ECU A28** A43 A08 O-B R 0 3 2 1 V cc V out **GND** Rail Pressure Sensor

Scorpio VIx, Sle, Lx (Refresh)


#### MAN-00057-63 March 2009/Rev 3




P-0193 P-0192



- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P-0193 or P-0192 is present.
- Switch off the Ignition
- Disconnect the rail pressure sensor connector.
- Turn ON the Ignition.
- Measure the voltage between the supply and the ground of the Rail pressure sensor (Pin no 1 & 3 of the RPS connector).
- It should be 5 ± 0.3 Volts
- Is it?



#### MAN-00057-**64** March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-65 March 2009/Rev 3

#### **Rail Pressure Deviation**


P-1192 P-1193

DTC	Diagnostic item
P-1192	Maximum positive Rail pressure deviation exceeded
P-1193	Maximum positive Rail pressure deviation exceeded concerning the set flow value

DTC detection condition	Probable cause
Proper Performance	Possible Causes
The ECU compares the rail pressure monitored through the RPS against the expected pressure generated due to HPP (Based on MPROP position and the engine RPM and other parameters)	<ul> <li>Defective fuel tank cap ( improper breathing)</li> <li>Fuel filter</li> <li>Filter assembly</li> <li>Tank strainer choked.</li> </ul>
<ul> <li>Malfunction; out-of-range</li> <li>If the deviation is more then error is generated.</li> </ul>	Injector stuck in open condition
Reaction	M-Prop valve stuck
Engine will be switched OFF	
<ul><li>Engine can not be started</li><li>System Check lamp is ON</li></ul>	
Gystem oncok lamp is on	

#### MAN-00057-**66** March 2009/Rev 3


P-1192 P-1193



#### **Test Procedure Rail Pressure Deviation -**

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P1192/1193 is present.

#### MAN-00057-**67** March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-68 March 2009/Rev 3

#### **Rail Pressure Deviation**

P-1194

DTC	Diagnostic item
P-1194	Maximum negative rail pressure deviation with metering unit on lower limit is exceeded.

DTC detection condition	Probable cause
Proper Performance	Possible Causes
The negative pressure deviation is within the limit	Metering unit is stuck in open position,
Malfunction; out-of-range	
The error is reported if the negative rail pressure	Metering unit without power
deviation is more then the specified in the map and at the same time the flow rate is also less	due to electrical error.
Reaction	
* The fuelling is controlled	
* System Check lamp is ON	
, , , , , , , , , , , , , , , , , , , ,	

MAN-00057-69 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)

#### **Rail Pressure Deviation**

P-1195


DTC	Diagnostic item
P-1195	Minimum rail pressure exceeded.

DTC detection condition	Probable cause
Proper Performance	Possible Causes
The rail pressure is within the limit.  Malfunction; out-of-range If the rail pressure falls below engine speed threshold Then the error is generated	Possible causes in low pressure system: Pressure before gear pump too low, gear pump output too low due to (filter clogged up, leak on low pressure side),.
* System Check lamp is ON	Leakage in the high pressure section due to:- injection nozzle stuck in open position, worn high pressure pump, worn injector, leaking pressure limiting valve

Diagnostic tester does not get connected

#### K line: Diagnostic connector

The diagnostic tester does not get connected.



#### INTER-CONNECTOR DETAILS

SR.NO.	DESCRIPTION	TYPE	LOCATION	PIN
11	I/C IP TO ENGINE	MALE	A PILLAR LEFT	20

MAN-00057-71 March 2009/Rev 3

Connect the 'Smart Tester' to the Diagnostic Connector. Turn the Ignition ON.

Diagnostic tester does not get connected

Check for the connection on the 'Smart Tester'. Is it OK?

No	Yes
Remove the smart tester from the connector.	Diagnostic connector is OK.
Switch on the Ignition.	
Check the voltage of the pin no 4/5 & 7 of the	
connector ( It should show 12 Volts when	
Ignition is ON and show 0 Volts when Ignition	
is switched OFF.	
Is it OK?	
•	$\downarrow$
No	Yes
<b>∀</b>	<b>∀</b>
▼ Check connectivity between K25 and	V Check the voltage between the
Check connectivity between K25 and diagnostic connector pin no 7.	connector pins10 & pin 4/5. It should
•	connector pins10 & pin 4/5. It should show 12 V continuously.  If it is not showing, repair the
diagnostic connector pin no 7.  If is not OK, then repair.	connector pins 10 & pin 4/5. It should show 12 V continuously.  If it is not showing, repair the connection.
diagnostic connector pin no 7.	connector pins10 & pin 4/5. It should show 12 V continuously.  If it is not showing, repair the connection.  Otherwise it indicates
diagnostic connector pin no 7.  If is not OK, then repair.  Check the voltage.	connector pins 10 & pin 4/5. It should show 12 V continuously.  If it is not showing, repair the connection.  Otherwise it indicates less/poor/intermittent contact.
diagnostic connector pin no 7.  If is not OK, then repair.	connector pins10 & pin 4/5. It should show 12 V continuously.  If it is not showing, repair the connection.  Otherwise it indicates
diagnostic connector pin no 7.  If is not OK, then repair.  Check the voltage.	connector pins 10 & pin 4/5. It should show 12 V continuously.  If it is not showing, repair the connection.  Otherwise it indicates less/poor/intermittent contact.
diagnostic connector pin no 7.  If is not OK, then repair.  Check the voltage.  Is it OK.  Yes	connector pins10 & pin 4/5. It should show 12 V continuously.  If it is not showing , repair the connection.  Otherwise it indicates less/poor/intermittent contact.  Repair
diagnostic connector pin no 7.  If is not OK, then repair.  Check the voltage.  Is it OK.	connector pins10 & pin 4/5. It should show 12 V continuously.  If it is not showing , repair the connection.  Otherwise it indicates less/poor/intermittent contact.  Repair

Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-**72** March 2009/Rev 3

#### **EGR** power stage


### **Description**

A pulse-width-modulated signal is output for the Exhaust Gas Recirculation actuator control. Converting the air control output into duty cycle carries this out. The possible defects are short circuit to battery, ground & no load.

P-0406 P-0405 P-0403 P-0404

DTC	Diagnostic item
P-0406	Short Circuit Battery
P-0405	Short Circuit Ground
P-0403	No Load
P-0404	Excess Temperature

DTC detection condition	Probable cause
Background	
<ul> <li>* The ECU checks current flows in the EGR solenoid drive circuit when the solenoid is ON and OFF. Range of check, set conditions.</li> <li>* When the EGR solenoid is turned OFF, no surge voltage is detected.</li> <li>Normal operation</li> <li>• When engine is running per the EGR mapping.</li> <li>• System lamp off after 2 sec.</li> <li>Malfunction</li> </ul>	<ul> <li>* Open or shorted EGR solenoid circuit, loose or wrong connection.</li> <li>* EGR solenoid failed</li> <li>* EGR control vacuum is too low</li> </ul>
EGR valve will remain open in case of short circuit to ground fault & remain closed for other fault conditions.  Reaction	
<ul> <li>System lamp will blink in case of short circuit to ground condition i.e.P0405.For all other fault condition (related to EGR) lamp will be OFF.</li> <li>Emission will affect.</li> </ul>	




- \*- Twisted pair
  - 1. Connect the 'Smart Tester' to diagnostic connector.
  - 2. Turn Ignition Switch ON.
  - 3. Verify that either P0406 or P0405 or P0403 or P0404 are present.
- Disconnect the EGR control solenoid valve connector.
- Turn Ignition ON
- Check the voltage between Ground & EGR control solenoid, valve harness connector terminal. Battery voltage should be present.
- It should be 12 V when Ignition ON.

• IS IT?		
Yes	No <b>∀</b>	
I		
Turn Ignition OFF. ♥	Verify that the 15 Amp use is OK (same fuse is also used for brake &clutch switch).	
Disconnect the EGR control solenoid.	Repair open or short to Ground on wire	

### MAN-00057-**74** March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)



Note - The Modulator for EGR is Black in colour.

Scorpio VIx, Sle, Lx (Refresh)

# MAN-00057-**75** March 2009/Rev 3

P-1340

### Error path of offset between camshaft and crankshaft


DTC	Diagnostic item	
P-1340	Offset between camshaft and crankshaft	

	DTC detection condition	Probable cause
	Normal operation	
*	Engine is being cranked & started.	<ul> <li>Mounting of phase sensor, speed sensor</li> </ul>
	Malfunction	or flywheel is loose.
*	Normal signal pattern has not been input for cylinder identification from the crankshaft position sensor signal and camshaft position sensor signal for 4 sec.  No synchronization between crankshaft & camshaft signal.	<ul><li>Manufacturing defect.</li><li>Sensors faulty or damaged.</li></ul>
	Reaction	
*	Engine is not being cranked.	
*	System lamp will continuously ON.	


MAN-00057-**76** March 2009/Rev 3


**Segment Speed Sensor (camshaft sensor)** 

P-1340



Vs= Supply voltage- 5V








P-1340

### ISS (Incremental speed sensor/ Crankshaft speed sensor)


**ECU** Sensor







ENGINE SPEED SENSOR



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-78 March 2009/Rev 3

- 1. Connect the 'Smart Tester' to diagnostic connector
- 2. Turn Ignition Switch ON.
- 3. Verify that P1340 is present.

P-1340

Turn the Ignition OFF.

Disconnect the camshaft & also the crankshaft sensors.


Yes	No <sup>↓</sup>
Check the sensor mounting of crank shaft	Correct the mounting. ♥
speed sensor.	
Check the wiring harness continuity between	Clear codes & verify that the signal is
the cam sensor to ECU & also the crankshaft	within limit.
speed sensor to ECU.	
Flywheel mounting is OK.	
Check the phase sensor for any nicks.	

Wes	No ↓
Check for any manufacturing defects.	Correct the mounting.
Clear codes & verify that the signal is within	Clear codes & verify that the signal is
limit.	within limit.
If it is not in limit, change the corresponding	
sensor.	

MAN-00057-**79** March 2009/Rev 3

**Fuel Temperature Sensor** 

P-0182 P-0183



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-80 March 2009/Rev 3

### **Fuel Temperature Sensor**


### Description -

P-0182 P-0183


Fuel temperature sensor acquires the raw value of the fuel temperature. The raw value is linearised and monitored for compliance with the signal range. The sensor is a NTC type

DTC	Diagnostic item
P-0182	Voltage above upper limit
P-0183	Voltage below lower limit

	DTC detection condition	Probable cause
Back	ground	
*	The fuel temperature sensor converts the engine fuel temperature to a voltage and outputs it. The ECU checks whether the voltage is within a specified range.	Open or shorted     Engine fuel     temperature sensor     circuit, loose or wrong     connection
Malfu	nction; out-of-range	Fuel temperature
*	Sensor output voltage has continued to be 5V or higher for 4 sec.	sensor failed.
*	Sensor output voltage has continued to be 0.1V or lower for 4 sec.	
React	tion	
*	System lamp will blink continuously.	
*	Engine will run with default fuel temp of 20 Deg C.	




### MAN-00057-81 March 2009/Rev 3



### <u>Test Procedure Fuel Temperature Sensor</u> -

Codes: P-0182, P-0183

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn the Ignition Switch ON.
- 3. Verify that either P0182 or P0183 are present.
- Turn the Ignition OFF.
- Disconnect the FTS connector.
- Turn the Ignition ON and check the voltage between FTS' signal terminal 1 and ground.
- It should be 5 V ± 0.3 when Ignition ON
- Is it?



All copyrights reserved by
The repair methods given by the manufacturer in this document are based on the technical specifications current at the time of release. The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which the vehicles are manufactured. The reproduction, translation, transmission, in part of whole of the present document, are prohibited without the prior written consent of © 2009 Mahindra & Mahindra Ltd.

MAN-00057-82 March 2009/Rev 3

> P-0182 P-0183

Turn the Ignition OFF.	Open or short between
	FTS signal terminal 1 and ECU.
Measure continuity between A 52 of ECU &	Repair as necessary.
connector terminal 1.	
Measure continuity between A 51 of ECU &	
connector terminal 2.	
Is it OK?	
Yes	No <sup>v</sup>
Connect FTS connector.	Open or short between FTS signal
	terminal 1 and ECU.
Turn Ignition ON.	Repair as necessary.
Check the voltage of FTS ( at A51 & A52)	
Is it as per specification?	
↓	<b>↓</b>
Yes	No
Poor terminal contact due to oxidation , bent	Temporarily install a known good FTS
or misplaced terminal.	and check for proper operation.
Repair as necessary.	If problem is corrected, replace FTS.
rrepair as riecessary.	I II DIODIGIII IS COITECIEU, TEDIACE I I S.

- Return vehicle to original condition. Clear all DTC.
- Verify by driving vehicle with "Smart Tester" connected and monitor for error codes.

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-83 March 2009/Rev 3

### Metering unit pump -Power stage

DTC Diagnostic item Short Circuit to Battery P-1252 P-1253 Short Circuit to Ground No Load P-1250 **Excess Temperature** P-1251

P-1252
P-1253
P-1250
P-1251


DTC detection condition	Probable cause
Normal operation	
<ul><li>When ignition is ON pump is getting supply from ECU.</li><li>Engine is starting properly.</li></ul>	Open, shorted or wrong connection of pump circuit.
Malfunction	
<ul> <li>When ignition is ON pump is not getting PWM signal from ECU.</li> </ul>	
Reaction	
<ul> <li>Engine is not starting &amp; error is recorded in ECU error memory.</li> </ul>	
Fuel output is not available from pump.	
System lamp will remain ON.	


MAN-00057-84 March 2009/Rev 3

> P-1252 P-1253


> > P-1250 P-1251

### **High Pressure Pump (with fuel metering unit)**







### MAN-00057-85 March 2009/Rev 3



- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P-1252 or P-1253 or P-1250 or P-1251 is present.
- Check the connections to the pump.
- Check that the connections are connected correctly; and that it is not connected in reverse way.
- Disconnect the pump and ECU connectors.
- Check the continuity between the ECU terminal A19 and pump terminal 2.
- Check the continuity between the ACY terminal A49 with pump terminal 1.
- Is it OK?



### MAN-00057-86 March 2009/Rev 3



Hint: The Error Code P 1251 can also be generated if there is leakage in the HPP adaptor.

Scorpio VIx, Sle, Lx (Refresh)


# MAN-00057-87 March 2009/Rev 3

### Main relay

P-121A P-121B

DTC	Diagnostic item	
P-121A	Main relay does not open in time	
P-121B Main relay opens too early		

DTC detection condition	Probable cause
Normal operation	
While cranking engine will start properly.	<ul> <li>Open, shorted or wrong connection of</li> </ul>
Malfunction	main relay.
Supply will not come to ECU input.	<ul> <li>Main relay fuse is blown.</li> </ul>
Reaction	<ul> <li>Relay is not working</li> </ul>
Engine will not start.	
<ul> <li>No communication with smart tester.</li> </ul>	
System check lamp will be on.	



Engine not cranking – 'Smart Tester' not responding.

Turn the Ignition OFF.

Check battery voltage. It should be greater than 8 Volts. Check the 30 Amp fuse.

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P121A or P121B is present.
- Ensure that the main relay is inserted properly in the connector
- Remove relay.
- · Check the relay externally.
- Give 12 Volts to terminal 86 and Ground the terminal 85.
- A clicking sound should be heard.
- If the sound is not heard, replace the relay.
- Check if 12 Volts is available at terminal 30, 86 & 85.
- With respect to ground, terminal 87 should show 0 Volts.
- Is it OK?

# MAN-00057-89 March 2009/Rev 3

P-121A P-121B

Yes	No
Switch ON the Ignition.	Check the wiring harnes.
Measure the voltage at terminal K72 of ECU	Repair the main relay connections (
or terminal 85 of the relay.	check the 30 Amp fuse)
Is it showing 0 Volts?	Clear codes & verify that the main relay
	is working properly.
I	1
Yes	No ↓
Measure the voltage at ECU terminal	Check that the terminal K 28 of ECU is
K05/K01. Or at terminal 87 of the relay.	showing 12 Volts. If not repair the
	connection.
It should show 12 Volts.	
Yes	No *
1	
	<b>.</b>
Clear codes and verify that the main relay is	Replace the relay with a known good
working properly.	component.
	Clear codes and verify that the main
	relay is working properly.

Scorpio VIx, Sle, Lx (Refresh)

# MAN-00057-90 March 2009/Rev 3


P-0577 P-0576 P-0575

#### **Cruise Control**

DTC	Diagnostic item	
P-0577	SRC MAX error for analog signal	
P-0576	SRC MIN error for analog signal	
P-0575	Plausibility error for analog signal	


	DTC detection condition	Pı	robable cause
•	Normal operation  When vehicle is running, no clutch & brake is pressed, by pressing cruise control switch vehicle will go into cruise mode.  Pressing resume key; vehicle will set the previous set speed.  Pressing set + or Set - vehicle speed can be adjusted.  Pressing OFF switch, vehicle will come out of cruise mode.  It will be operational in 2 <sup>nd</sup> /3 <sup>rd</sup> /4 <sup>th</sup> & 5 <sup>th</sup> Gear.  Clutch signal & brake switch signal are ok.  Engine RPM is > 1200	*	Open, shorted or wrong connection of cruise control circuit. Brake or clutch error is set into ECU. Switches are not responding or faulty. Engine RPM less than 1200.
Malfunction			
•	By pressing any of the cruise control switch vehicle will not go into cruise mode.		
•	Vehicle will not respond to set +, Set -, OFF or resume switch when vehicle is in cruise mode.		

P-0577 P-0576 P-0575



Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-92 March 2009/Rev 3



### INTER-CONNECTOR DETAILS

SR.NO.	DESCRIPTION	TYPE	LOCATION	PIN
10	I/C IP TO ENGINE	MALE	A PILLAR LEFT	21
11	I/C IP TO ENGINE	MALE	A PILLAR LEFT	20

Scorpio VIx, Sle, Lx (Refresh)


MAN-00057-93 March 2009/Rev 3

> P-0577 P-0576 P-0575

Connect the 'Smart Tester' to diagnostic connector.

- 1. Turn the Ignition Switch ON.
- 2. Verify that either P0577 or P0576 or P0575 is present.
- Turn the Ignition OFF/ON to measure the Voltages.
- Check the resistances across all the switches when they are activated


Parameter	Resistance	Voltage
No key pressed	4.323 K Ω	4.35 V
ON/OFF	150 Ώ	0.9823 V
Coast/Reset	1.63 K Ω	3.61 V
Set +	810 Ώ	2.845 V
Set -	420 K Ώ	2.035 V



# MAN-00057-94 March 2009/Rev 3

**Battery** 

P-0563 P-0562



Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-95 March 2009/Rev 3

> P-0563 P-0562

#### **Battery**

### **Description:**

The system voltage has to guarantee to perform diagnosis functions. The Electronic Control Unit (ECU) monitors battery voltage. If this code is set, the System Lamp is off.


DTC	Diagnostic item	
P-0563	Voltage above upper limit	
P-0562	Voltage below lower limit.	

DTC detection condition	Probable cause	
<b>Detecting Condition</b>		
<ul> <li>* Battery voltage &lt;8 V</li> <li>Enable Condition</li> <li>No main relay failure</li> </ul>	<ul> <li>Charging system not working.</li> <li>Wiring harness to ECU faulty.</li> </ul>	
<ul><li>* Battery voltage &gt; 16V</li><li>Enable Condition</li><li>No main relay failure</li></ul>		

#### **Test Procedure Battery -**

- Check charging system.
- Check charging system (including battery) for proper operation.
- Refer the charging system section in the Electrical.

Charging system OK. (Voltage during cranking should be at least 9 volts)



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-96 March 2009/Rev 3

#### **Brake Switch**

P-1792 P-1791

### **Description:**


The function acquires and processes the information via the brake contact and the redundant brake contact. The status message of the brake position is the output.

DTC	Diagnostic item	
P-1792	Brake signal is defective	
P-1791	Brake signals not plausible	

DTC detection condition	Probable cause
Principle	
<ul> <li>* The brake switch outputs a voltage, which corresponds to the brake position.</li> <li>* The ECU checks whether this voltage is within</li> </ul>	5
specified range (0 or 12V).	<ul> <li>Brake switch damage or faulty</li> </ul>
Normal Operation	<ul> <li>Brake switch failed or</li> </ul>
* Ignition switch: ON	maladjusted.
<ul> <li>* System lamp: OFF after 2 Sec</li> </ul>	
* Battery voltage is 8V –16V.	·
Malfunction	
* The sensor output voltage has continued to be in spite of brake pedal being pressed/not press	
* The sensor output voltage has continued to 12' spite of brake pedal being pressed/not pressed	
<ul><li>* Main or redundant switch is not working.</li></ul>	
Reaction	
<ul> <li>System lamp will be off.</li> </ul>	
Cruise control will not work.	

Scorpio VIx, SIe, Lx (Refresh)

### MAN-00057-97 March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)


### MAN-00057-98 March 2009/Rev 3


#### Test Procedure Brake switch --

P-1792 P-1791


Codes: P-01792, P-1791

- 1. Connect the 'Smart Tester' to diagnostic connector
- 2. Turn Ignition Switch ON
- 3. Verify that either P1791 or P1792 are present. Disconnect the brake switch connector.
- Turn Ignition ON and check the supply voltage to brake switch two point connector.
- It should be 12 V when Ignition ON





Replace the brake switch with known good	Turn Ignition OFF
component.	
Check for error.	Remove brake switch connection & check continuity between terminal K17 & K80 to brake switch connector.
Clear the error memory.	Is it OK?



Scorpio VIx, Sle, Lx (Refresh)

# MAN-00057-99 March 2009/Rev 3

### Clutch Switch - (With MT)


P-0704


DTC	Diagnostic item	
P-0704	Clutch signal is not plausible	

### **Description**

The clutch signal is acquired as a hardware signal. The signal is checked for plausibility using gear information. Error is detected, if there is a valid gear change without the clutch being pressed during the time that elapsed since the last gear change.

DTC detection condition	Probable cause
Normal Operation	
<ul> <li>* The clutch switch outputs a voltage, which corresponds to the clutch position.</li> <li>* The ECU checks whether this voltage is within a specified range (0 or 12V).</li> </ul>	<ul> <li>Open, shorted, loose or wrong connections of brake switch Wiring.</li> <li>Clutch switch failed or maladjusted.</li> </ul>
Normal Operating Requirements:	Clutch switch damage
* Ignition switch: ON	or faulty.
<ul> <li>* Malfunction lamp: OFF after 2 Sec</li> </ul>	
* Battery voltage is 8V –16V.	
Malfunction	
<ul> <li>* The sensor output voltage has continued to be 0V</li> </ul>	
in spite of clutch pedal being pressed/not pressed.	
* The sensor output voltage has continued to 12V in	
spite of clutch pedal being pressed/not pressed.	
Reaction:	
System lamp will be off.	
* Cruise control will not work.	





### Test Procedure Clutch switch -

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that error P 0704 is present.


Verify that no error related to vehicle speed (vehicle speed sensor related) is present. If present, first attend to those complaints then verify if the error P 0704 is present and then proceed.

Disconnect clutch switch connector.


Turn the ignition ON.

Check supply voltage to clutch switch on connector.

It should be 12 V, when Ignition is ON. Is it?



### **Coolant Temperature Sensor**



MAN-00057-103 March 2009/Rev 3

### **Coolant Temperature Sensor**


P-0118 P-0117


**Description:** The Water temperature sensor (WTF) is located in the coolant pipe of the cylinder head. The WTF sensor is a variable resistor whose resistance changes as the temperature of the engine coolant flowing past the sensor changes.(NTC resistor) When the coolant temperature is low, the sensor resistance is high; when the coolant temperature is high, the sensor resistance is low. The ECU checks WTF voltage and uses the information to help smoothen the engine operation.

DTC	Diagnostic item	
P-0118	Voltage above upper limit	
P-0117	Voltage below lower limit	

DTC detection condition	Probable cause	
Background		
* The engine coolant temperature sensor converts the engine coolant temperature to a voltage and outputs it.	* Open or shorted Engine Coolant Temperature	
* The ECU checks whether the voltage is within a specified range. In addition, it checks that the engine coolant temperature (signal) does not drop while the engine is warming up.	sensor circuit, or loose or wrong connection * Engine Coolant	
Malfunction; out-of-range	Temperature sensor failed.	
<ul> <li>Sensor output voltage has continued to be 5V or higher for 4 sec.</li> </ul>		
<ul> <li>Sensor output voltage has continued to be 0.1V or lower for 4 sec.</li> </ul>		
Reaction:		
System lamp will be on.		
Engine will continue to run with water		
temperature of 120 deg C.		

### MAN-00057-104 March 2009/Rev 3





### <u>Test Procedure Coolant Temperature Sensor</u> --


Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-105 March 2009/Rev 3

- 1. Connect the 'Smart Tester' to diagnostic connector
- 2. Turn Ignition Switch ON

P-0118 P-0117

- Verify DTC P0118 or P0117 are present.
- Turn the Ignition OFF
- Disconnect the CTS connector.
- Turn Ignition ON and check the voltage between 'CTS' signal terminal 1 and ground.
- It should be 5 V when Ignition ON
- Is it?



- Return vehicle to original condition. Clear all DTC.
- Verify by driving vehicle with "Insight" connected and monitor for error codes.

# MAN-00057-106 March 2009/Rev 3

# **Diagnostic Manual (EMS)**

Scorpio VIx, Sle, Lx (Refresh)

### Coolant temperature sensor absolute & dynamic test


P-2558 P-1126

<u>Description</u> - When the engine is switched ON then the ECU detects the temperature. After that when the engine runs then the temperature output on a time frame is detected and compared against predetermined slope.

DTC	Diagnostic item
P-2558	Minimum Temperature not reached within time limit.
P-1126	Minimum temperature or temperature raise no reached within time limit

DTC detection condition	Probable cause
Proper Performance The coolant temperature rises to a specified temperature within a specific time period.  It also compares the rate of rise with a defined rate of rise	<ul> <li>Defective temperature sensor.</li> <li>Thermostat stuck in open condition</li> </ul>
Malfunction; out-of-range The coolant temperature do not rise enough within a specific time period,  • The coolant temperature do not reach a warmed-up fuel control temperature within a specific time period.	Thermostat removed.
Reaction System check lamp : OFF	

## MAN-00057-107 March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-108 March 2009/Rev 3

P-165E P-165F P-1660 P-1661


### Coolant overheat Lamp - power stage

DTC	Diagnostic item
P-165E	Short Circuit to Battery
P-165F	Short Circuit to Battery
P-1660	No Load
P-1661	Excess Temperature

DTC detection condition	Probable cause
<ul> <li>Normal operation</li> <li>When ignition is ON coolant overheat lamp will be ON &amp; OFF after 2 sec.</li> <li>When coolant temperature crosses the set value lamp will glow.</li> <li>Malfunction</li> <li>Coolant overheat lamp will not respond, during the lamp test.</li> <li>Show wrong display.</li> </ul>	<ul> <li>Open short circuit to battery or ground.</li> <li>Wrong connection for coolant overheats lamp circuit.</li> </ul>

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-109 March 2009/Rev 3



### INTER-CONNECTOR DETAILS

SR.NO.	DESCRIPTION	TYPE	LOCATION	PIN
5	I/C IP TO ENGINE ROOM	MALE	A PILLAR RIGHT	5+2
10	I/C IP TO ENGINE	MALE	A PILLAR LEFT	21
11	I/C IP TO ENGINE	MALE	A PILLAR LEFT	20

Scorpio VIx, Sle, Lx (Refresh)


MAN-00057-110 March 2009/Rev 3

Connect the 'Smart Tester' to diagnostic connector.

- 1. Turn Ignition Switch ON.
- 2. Verify that either P1660 or P1661 or P165E or P165F is present.

P-165E P-165F P-1660 P-1661

- Switch off the Ignition
- Check the connection to the coolant overheat lamp.
- Go to the Actuator Test # ACT 1. If the lamp is working as per the command then the lamp & connections are OK.
- If not working then:-
- Check the continuity between ECU terminal K94 with overheat lamp.
- Is it OK?




### **Atmospheric pressure sensor**

P-0108 P-0107

DTC	Diagnostic item
P-0108	Voltage above upper limit
P-0107	Voltage below lower limit

nospheric sensor.
•
sensor.

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P0108 or P0107 is present.
- Check the battery voltage.
- Clear the error codes.
- Verify if the error has been cleared.



### **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-112 March 2009/Rev 3

### Injector Energising time

**Description:** Controller not able to control power stage

DTC	Diagnostic item	
P1623	Below lower limit of enegising time- Injector # 1	
P1625	Below lower limit of enegising time- Injector # 2	
P161F	Below lower limit of enegising time- Injector # 3	
P1621	Below lower limit of enegising time- Injector # 4	

Reaction: The System Check lamp will be Off.

Vehicle speed may drop.

- 1. Pl. confirm IMA (IQA) codes are flashed.
- 2. Confirm no fuel leakage in low & high pressure circuit. (including the injector backflow
- 3. Check the continuity for the high & low sides.
- 4. Confirm battery voltage is above 10V.
- 5. Ensure fuel filter is not clogged. (Service interval followed as per schedule)
- 6. Check with swapping Injector.
- 7. If still error persists change the injector.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-113 March 2009/Rev 3

#### **Communication Monitoring**

P-162A

**Description:** Communication between controller and power stage inside the ECU is not OK

DTC	Diagnostic item
P-162A	Communication error of CJ940

Reaction: The System Check lamp will be continuously ON.

- 1. Switch ON Ignition
- 2. Using smart tester, clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using smart tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-114 March 2009/Rev 3

P-1659

#### **Controller and TPU Monitoring**

**Description:** Controller and Time processing unit out of sync.

DTC	Diagnostic item
P-1659	Deviation between TPU and system time

Reaction: The System Check lamp will be continuously ON.

- 1. Switch ON Ignition
- 2. Using smart tester, clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using smart tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-115 March 2009/Rev 3

P-1638

### **ECU Monitoring**

**Description:** Monitoring module inside ECU reports a defect.

DTC Diagnostic item	
P-1638	Set, if error-counter of Watchdog or controller are not plausible or the
	system must shut down

Reaction: The System Check lamp will be continuously ON.

Engine will shut down.

- 1. Switch ON Ignition.
- 2. Using 'Smart Tester', clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using smart tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-116 March 2009/Rev 3

#### **EEPROM Monitoring**

**Description:** EEPROM storage device inside ECU is not OK

P-162B P-162C P-162D

DTC	Diagnostic item
P-162B	EEPROM: error during last read operation
P-162C	EEPROM: error during last write operation
P-162D	EEPROM: default value used

Reaction: The System Check lamp will be continuously ON.

- 1. Switch ON Ignition.
- 2. Using 'Smart Tester', clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using smart tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-117 March 2009/Rev 3

P-160C P-160D P-160E


### **Error path for the Tachometer signal**

DTC	Diagnostic item
P-160C	Short Circuit to Battery
P-160D	Short Circuit to Ground
P-160E	No Load


DTC detection condition	Probable cause
Normal operation	
<ul> <li>When ignition is ON system lamp will be switch OFF after 2sec.</li> </ul>	* Open, shorted or wrong connection
<ul> <li>When engine is running it will show corresponding</li> </ul>	of tachometer
engine speed on dash panel.	circuit.
Malfunction	
When engine is running it wouldn't show	
corresponding engine speed on dash panel.	
Reaction	
3. No impact on vehicle performance. Only engine	
speed indication on dash panel can not be seen.	
4. Cruise control will not work.	

### MAN-00057-118 March 2009/Rev 3

Scorpio VIx, SIe, Lx (Refresh)




P-160C P-160D P-160E



#### INTER-CONNECTOR DETAILS


SR.NO.	DESCRIPTION	TYPE	LOCATION	PIN
10	I/C IP TO ENGINE	MALE	A PILLAR LEFT	21

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P160C or P160D or P160E is present.
- Turn the Ignition OFF.
- Disconnect the tachometer connector from the cluster connections.
- Check the continuity between the ECU connector terminal K48 and cluster tachometer connections.
- Is it OK?



MAN-00057-119 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-120 March 2009/Rev 3

P-1608

P-1609 P-160A

### Error path of coolant temperature output


#### Description

P-160B The component driver for the coolant temperature outputs the variable as a PWM signal to the power stage. (Output on the cluster) In normal operation, the PWM power stage is tested for short circuit to battery, to ground, open circuit and excess temperature.

DTC	Diagnostic item
P-1608	Short circuit to battery
P-1609	Short circuit to ground
P-160A	No load
P-160B	Excess temperature

	DTC detection condition	Probable cause
	Normal Operation	<ul> <li>* Open or shorted</li> </ul>
*	The coolant temperature output voltage, which is	Engine Coolant
	given to the cluster from ECU as an output.	Temperature
*	The ECU checks whether this voltage is within a	output sensor
	specified range (0 or 5V).	circuit, or loose or
	,	wrong connection.
	Normal Operating Conditions	
*	Ignition switch: ON	
*	System lamp: OFF after 2 Sec	
	Malfunction	
•	No indication of water temperature on the instrument cluster.	

## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)




### Test Procedure Coolant temperature output --

- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that the either of the error codes P1608 or P1609 or P160A or P160B is present.

#### Turn the Ignition OFF.

- Remove the cluster connections of the coolant temperature indicator.
- Check the continuity between coolant temperature output connector with K29 of the ECU.
- Is it OK?



### MAN-00057-122 **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh) March 2009/Rev 3 P-1608 P-1609 P-160A P-160B Check the cluster lamp fuse Open or short between coolant temperature output & ECU K29 Check the temperature value in smart tester. Repair as necessary. Compare it with physical measurements. Check the output at K29 when Ignition is ON. Is it OK? Clear the error & verify. No ₩es Replace the instrument cluster. Clear codes & verify.

Verify DTC with coolant temperature output.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-123 March 2009/Rev 3

P-1530

P-1531 P-1532

P-1533

### Fault path of air condition power stage

## is pain of an containon power stage

Description –

The A/C compressor routes the A/C compressor control signal to the digital power stage output. The power stage is monitored. An error such as short circuit, open circuit or excess temperature, occurring at the power stage is reported.


The function routes the control signal for the A/C compressor to the power stage.

DTC	Diagnostic item
P-1530	Short circuit to battery
P-1531	Short circuit to ground
P-1532	No load
P-1533	Excess temperature
	<u> </u>

		-
	DTC detection condition	Probable cause for
		malfunction
Norma	al Operation	<ul> <li>No AC gas available.</li> </ul>
*	AC relay is OFF when the AC switch & blower switch is OFF.	<ul> <li>AC relay is not working.</li> </ul>
*	The ECU checks whether AC switch is ON then it will try to switch ON the AC relay provided blower is ON.	Open or shorted AC circuits, loose or
*	When AC relay is energized then it will switch ON the AC compressor.	<ul><li>wrong connections.</li><li>Compressor is not working</li></ul>
	Normal Operation	ECU AC circuit faulty.
*	Ignition switch: ON	200 / to on our radity.
*	Engine is ON	
*	System lamp: OFF after 2Sec	
*	Battery voltage is 8V –16V.	
*	AC switch & blower switches are ON.	
	Malfunction	
*	ECU not recognizing 12V when AC switch is ON.	
*	ECU output to AC relay has continued to 0.5V or	
	more.	
	Reaction	
*	System lamp will blink continuously.	
*	AC will not work.	

Connect the 'Smart Tester' to diagnostic connector.

- 1. Turn the Ignition Switch ON.
- 2. Verify that either P1530 or P1531 or P1532 or P1533 are present.
- Check that all the AC connections are fitted.
- · Check the AC charging.
- Check that the AC & compressor relay both are functioning properly
- Is it OK?



The repair methods given by the manufacturer in this document are based on the technical specifications current at the time of release. The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which the vehicles are manufactured. The reproduction, translation, transmission, in part of whole of the present document, are prohibited without the prior written consent of © 2009 Mahindra & Mahindra Ltd.

## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-124

March 2009/Rev 3

P-1530 P-1531 P-1532

P-1533

Turn the Ignition OFF.	If needed change the relay & repair the connections.
Measure continuity between K54 and AC switch & AC relay.	Clear codes & verify.
Measure continuity between K 70 & ECU relay.	
Is it OK?	

ΨYes	No <sup>∲</sup>	
Switch ON the Ignition.	Check the fuses (15 Amp AC fuse)	
Switch ON the AC switch.	If required, replace it.	
Check the voltage between the ECU terminal K54 & Ground.	Repair the connections.	
Also check the voltage between K70 & ground.		
At K70- Gnd. It should be 0 Volts when in OFF condition and 12 Volts when in ON condition.	Clear codes & verify that AC is working properly.	
Switch on the blower.		
Check the voltage between K 70 & ground. It should show 0 Voltage.		
Is it OK?		

res	NO
Check AC compressor connections & supply.	Repair the connections as per the circuit diagram.
Clear codes & verify AC is working.	Clear codes & verify AC is working properly.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-125 March 2009/Rev 3

P-1210 P-1211 P-1212 P-1213 P-1214 P-1215

P-1216 P-1217

### Injector power stage- chip specific errors

### **Description:**

Injector power stage inside ECU defective

DTC	Diagnostic item
P-1210	Chip-specific errors : CY33X
	internal reset / clock loss / under voltage
P-1211	Chip-specific errors: CY33X is unlocked / CY33X init error
P-1212	Chip-specific errors:CY33X is in Test mode
P-1213	Chip-specific errors: CY33X SPI communication error /checksum/read
	back
P-1214	Chip-specific errors ->CY33X internal parity error
P-1215	Chip-specific errors ->CY33X internal program flow error
P-1216	Chip-specific errors ->CY33X check of inv. YSEL during ON failed
	Chip-specific errors ->CY33X ON timeout for at least 1 cylinder
P-1217	

Reaction: The System Check lamp will be continuously ON. Engine stops.

- 1. Switch ON Ignition.
- 2. Using 'Smart Tester' clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using diagnostic tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-126 March 2009/Rev 3

#### **Monitoring module communication Monitoring**

P-1664

**Description:** Communication failure with monitoring module.

DTC	Diagnostic item
P-1664	The fault path contains the supervision of the SPI-Handler
	Set, if SPI-communication failed

Reaction: The System Check lamp will be continuously ON.

- 1. Switch ON Ignition.
- 2. Using 'Smart Tester', clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using smart tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-127 March 2009/Rev 3

### **Power Stage Monitoring**

**Description:** Controller not able to control power stage

P-1641 P-1642 P-1643

DTC	Diagnostic item
P-1641	Test of redundant shut off paths during initialization: Watch dog switch
	off path defect
P-1642	Test of redundant shut off paths during initialization: Voltage
	monitoring upper limit shut off path defect
P-1643	Test of redundant shut off paths during initialization: Voltage
	monitoring lower limit shut off path defect

Reaction: The System Check lamp will be continuously ON.

- 1. Switch ON Ignition.
- 2. Using 'Smart Tester', clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using smart tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-128 March 2009/Rev 3

#### **Power stage voltage Monitoring**

**Description:** Over / Under voltage to power stage detected

P-1631
P-1632

DTC	Diagnostic item	
P-1631	(Hardware) CJ940 upper limit: internal supply voltage upper limit	
	(Hardware) CJ940 lower limit: internal supply voltage lower limit	
P-1632		

Reaction: The System Check lamp will be continuously ON.

- 1. Switch ON Ignition.
- 2. Using 'Smart Tester', clear the ECU faults.
- 3. Switch OFF Ignition key and wait for 2 minutes.
- 4. Switch ON Ignition.
- 5. Using smart tester check whether any of the above mentioned fault is present.
- 6. If fault is still present, switch OFF ignition.
- 7. Replace the ECU with a new one and repeat steps 4 & 5.
- 8. If fault is not present in the new ECU, then the old ECU is defective and has to be sent back to M&M.

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-129 March 2009/Rev 3

## **Sensor supply monitoring 1**

P-1644 P-1645


DTC	Diagnostic item	
P-1644	P-1644 Voltage above upper limit	
P-1645	Voltage below lower limit	


DTC detection condition	Probable cause
Normal Operation The ECU monitors the supply voltage to camshaft phase sensor, and accelerator pedal ( APP1)	
Malfunction The voltages are beyond the range.	
Reactions	
System lamp status for this error is ON.	

## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)


### MAN-00057-130 March 2009/Rev 3

















#### INTER-CONNECTOR DETAILS

SR.NO.	DESCRIPTION	TYPE	LOCATION	PIN
10	I/C IP TO ENGINE	MALE	A PILLAR LEFT	21
11	I/C IP TO ENGINE	MALE	A PILLAR LEFT	20

Connect the 'Smart Tester' to diagnostic connector.

- 1. Turn Ignition Switch ON.
- 2. Verify that either P-1644 or P-1645 is present.
- This is related to the cam shaft sensor supply & also APP1 supply voltage.
- Check the connection of the cam shaft sensor supply & accelerator pedal connector.
- Is it OK?



Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-131 March 2009/Rev 3

		ı P-1644
camshaft sensor & the Accelerator pedal.		P-1645
Clear the error.	Clear codes and verify.	F-1043
If the error heals then the problem may be		
due to poor connection.		
Does it heal?		
		•
<b>↓</b>	<b>\</b>	
No	Yes	
		•
Clear the codes & verify.	Check the continuity between the ECU	
•	connector A11 and the camshaft	
	terminal 3.	
	&	
	Between ECU connector K 45 and	
	Accelerator pedal Terminal 2.	
	,	
	Repair the connection.	
If the error is still present, then the ECU is	Reconnect everything.	
suspect.	January 3	
Replace ECU with a known good one.	Clear codes and check cam phase	
Clear codes & verify.	sensor and Accelerator pedal are	
	working properly.	

Scorpio VIx, Sle, Lx (Refresh)


## MAN-00057-132 March 2009/Rev 3

P-1646 P-1647


## **Sensor supply monitoring 2**

DTC	Diagnostic item	
P-1646	Voltage above upper limit	
P-1647	Voltage below lower limit	

DTC detection condition	Probable cause
Normal Operation	
The ECU monitors the supply voltage to Rail pressure	
sensor, HFM and accelerator pedal (APP 2)	
Malfunction	
The voltages are beyond the range.	
Reactions	
Reactions	
System lamp status for this error is ON.	



- 1. Connect the 'Smart Tester' to diagnostic connector.
- 2. Turn Ignition Switch ON.
- 3. Verify that either P-1646 or P-1647 is present.
- This is related to the rail pressure sensor, HFM and APP2 supply voltage.
- Check the connection of the rail pressure sensor, HFM & accelerator pedal connector.
- Is it OK?



Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-134 March 2009/Rev 3

P-1646 P-1647

If the error heals then the problem may be	
due to poor connection.	
Does it heal?	
	·
*No	Yes ♥
Clear the codes & verify.	Check the continuity between the ECU connector A 29 and the HFM terminal 4. Check the continuity between the Rail pressure connector terminal 3 and terminal A14 of the ECU Check the continuity of between terminal 1 of the Accelerator pedal (APP2) and K 46 of the ECU.  Repair the connection.
If the error is still present, then the ECU is suspect.	Reconnect everything.
Replace ECU with a known good one. Clear codes & verify.	Clear codes and verify.

Scorpio VIx, Sle, Lx (Refresh)


### MAN-00057-135 March 2009/Rev 3

P-1654 P-1655 P-1656 P-1657

### **System lamp -Power Stage fault status**

DTC	Diagnostic item	
P-1654	Short Circuit to Battery	
P-1655	Short Circuit to Battery	
P-1656	No Load	
P-1657	Excess Temperature	

DTC detection condition	Probable cause
<ul> <li>Normal Operation</li> <li>When Ignition is switched ON the system lamp will glow ON for 2 sec.</li> <li>It will switch OFF if no error is set.</li> </ul>	Open, shorted or wrong connection of system lamp circuit.
<ul> <li>Malfunction</li> <li>When ignition is switched ON the system lamp does not glow ON.</li> </ul>	



Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-136

P-1654 P-1655

P-1656 P-1657

March 2009/Rev 3

1. Connect the 'Smart Tester' to diagnostic connector.

- 2. Turn Ignition Switch ON
- 3. Verify that either P1654 or P1655 or P1666 or P1667 is present.

Go to the Actuator Test # ACT 2. If the system check lamp works with the actuator test then the system check lamp, wiring & ECU are OK.

#### If not working then:

- Switch off the Ignition
- Disconnect the camshaft sensor connector.
- The connections to the system lamp.
- Check the continuity between the ECU terminal K71 with system lamp
- Is it OK?

Yes	No ↓
Turn the Ignition OFF <sup>♥</sup>	Check the fuse.   ▼
Disconnect ECU connector A	Repair the wire.
Measure the continuity of Ground (between	Clear the error codes & verify
sensor pin no 1 & ECU terminal A20) in the	
camshaft phase sensor harness.	
Is it OK?	
Yes	No
	Ţ
Lamp failure	Repair the connection.
Replace lamp	Clear codes and verify that the system
	lamp is working properly.
Clear codes and verify that the system lamp	
is working properly.	

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-137 March 2009/Rev 3

## Terminal 15 (Ignition)- contains plausibility error [Sig] of T15

P-1658

DTC	Diagnostic item	
P-1658	No Terminal T15 signals detected	

DTC detection condition	Probable cause
Normal operation	
<ul><li>When ignition is ON relay coil will get energized.</li><li>Engine being started.</li></ul>	<ul> <li>Open, shorted or wrong connection of T15 circuit.</li> </ul>
Malfunction	
When ignition is ON supply is not coming to ECU.	
Main relay coil will not get energized.	
Engine will not start.	

Scorpio VIx, Sle, Lx (Refresh)


MAN-00057-138 March 2009/Rev 3

Connect the 'Smart Tester' to diagnostic connector.

- 1. Turn Ignition Switch ON.
- 2. Verify that P-1658 is present.

P-1658

- Check that the main relay is getting energized.
- To check that the relay is getting energized, hear for the clicking sound from the main relay when the Ignition is switched ON.
- Is it OK?



<b>Y</b> es <b>Y</b> es	No *
Check for loose or intermittent connection.  Repair the connection	Repair the connection.  Clear the codes and verify that the vehicle is working perfectly.
Clear the codes and verify that the vehicle is working perfectly.	

Scorpio VIx, SIe, Lx (Refresh)


### MAN-00057-139 March 2009/Rev 3


### Vehicle speed sensing


P-0503 P-0500 P-0501

DTC	Diagnostic item	
P-0503	Exceeding of the maximum vehicle speed	
P-0500	HW signal for vehicle speed not valid	
P-0501	Vehicle speed not plausible with injection mass and engine speed	

	DTC detection condition	Probable cause
	Normal Operation	
*	The vehicle speed sensor outputs a pulse signal while the vehicle is driven.	<ul> <li>Failed vehicle speed sensor.</li> </ul>
*	The ECU checks whether the pulse signal is present.	<ul> <li>Open shorted vehicle- speed sensor circuit, loose or wrong connection.</li> </ul>
	Malfunction	
*	Sensor output voltage has not changed (No pulse signal) for 4 sec.	







### INTER-CONNECTOR DETAILS

	SR.NO.	DESCRIPTION	TYPE	LOCATION	PIN
ľ	10	I/C IP TO ENGINE	MALE	A PILLAR LEFT	21


Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-**140** March 2009/Rev 3

- 1. Connect the 'Smart Tester' to diagnostic connector
- 2. Turn Ignition Switch ON
- 3. Verify that either P0503 or P0500 or P0501 is present.

P-0503 P-0500 P-0501

- Drive the vehicle.
- Does the speedometer show the correct value? (Compare the values of speedometer with the value visible in the "Smart Tester"- use the live data tab in 'Smart Tester'.)



Turn the Ignition OFF.	Repair the cable (from the pin no 1 to pin no 5 of the instrument cluster socket- C24).
Inspect the interface between the VSS and	Clear the error codes & verify.
the speedometer gear in the Gearbox.	
Is it OK?	

₹es	No <sup>♥</sup>
Disconnect VSS	Repair the interface between he speedometer & the VSS
Disconnect ECU connector	Clear codes & verify that VSS signal is within limit.
Measure the continuity between the ECU	
terminal K75 and sensor terminal 3	
Is it OK?	

¥es	No ↓	
Check the open circuit between the sensor	Repair the wire between VSS connector	
Ground & positive supply	& ECU terminal	
Is it OK	Clear codes & verify that VSS signal is	
	within limit.	

,	res		NO	
Verify that the ECU connections are OK		Repair short circuit to Ground or another circuit in wire between VSS harness connector		
If OK replace VSS with a known good VSS		Clear codes and verify t signal is within range.	hat the VSS	
Clear codes and verify that the VSS signal is				
within range.				
If problem persist- replace ECU				

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-141 March 2009/Rev 3

P-1387 P-1388 P-1389

P-1390


## Glow control relay actuator (If Applicable)

DTC	Diagnostic item	
P-1387	Short Circuit to Battery	
P-1388	Short Circuit to Ground	
P-1389	No Load	
P-1390	Excess temperature	

DTC detection condition	Probable cause
<ul> <li>Normal operation</li> <li>When ignition is ON after 2 seconds the system lamp will switch OFF.</li> <li>When Ignition is ON glow relay will switch ON &amp; switch OFF after 10 sec. (If temp. is lesser than 0 Degree Centigrade)</li> <li>Glow relay will get energized as per the logic in the ECU.</li> </ul>	* Open, shorted or wrong connection of glow circuit. * Fuse is blown. * Relay is not working.
<ul> <li>Malfunction</li> <li>When ignition is ON system lamp will be ON.</li> <li>Relay will not get energized as per ECU logic.</li> </ul>	

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-142 March 2009/Rev 3




#### INTER-CONNECTOR DETAILS

SR.NO.	DESCRIPTION	TYPE	LOCATION	PIN
10	I/C IP TO ENGINE	MALE	A PILLAR LEFT	21
11	I/C IP TO ENGINE	MALE	A PILLAR LEFT	20

- 1. Connect the 'Smart Sensor' to diagnostic connector.
- 2. Turn Ignition Switch ON
- 3. Verify that either P-1888 or P-1889 or P-1890 or P1887 is present.
- Check the 15 Amp fuses. If defective, replace.
- Check when the Ignition ON the Glow lamp is ON (Check lamp check: the system lamp & the overheat lamp should come On for 2 seconds and then go off)
- If not On then check lamp & replace.
- Check the insertion of glow plug & glow relays.

## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-143 March 2009/Rev 3



MAN-00057-144 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)

#### **Immobilizer**

P-0513

DTC	Diagnostic item
P-0513	Invalid Key error

#### + Immobilizer code

DTC	Diagnostic item	
90A0	Key is rejected by Immobilser ECU	

Vehicle behaviour: Engine does not start, check lamp will blink/ON

#### **Probable Cause:**

Invalid key error.

Key is rejected by Immobiliser ECU

#### **Corrective Action:**

Replace the key. Perform the transponder learning Clear error at both EMS ECU and Immobiliser ECU Inform the customer about the theft attempt.

#### + Immobilizer code

DTC	Diagnostic item	
90A1	Invalid Transponder password is found.	

### **Probable Cause:**

Somebody duplicated the mechanical key and tried starting the vehicle. Theft attempt is made

### **Corrective Action:**

Clear the errors at EMS and ICU Alert the customer.

If more than one error is found in EMS please follow the priority of the errors during. Here below the errors are listed in the priority error.

EMS Errors	Priority
P0513	1
P183A	2
P0633	3
P183E	4
P183B	5
P1832	6

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-145 March 2009/Rev 3

#### **Immobilizer**

P-1832

DTC	Diagnostic item	
P-1832	Immobilized condition	

#### + Immobilizer code

DTC	Diagnostic item
90A3	No EMS ACK after the signature response

Vehicle behaviour: Engine does not start, check lamp will blink/ON

#### **Probable Cause:**

Immobilizer circuit is faulty Immobiliser ECU is not working properly. Transponder is not working/faulty EMS is flashed with wrong dataset

### **Corrective Action:**

Check the Immobilizer circuit. Clear error at both EMS ECU and Immobiliser ECU Inform the customer about the theft attempt. If wrong dataset- flash the correct dataset.

### + Immobilizer code

DTC	Diagnostic item	
90A4	Mismatch in checksum 1	
90A5	Mismatch in Checksum 2	
90A6	90A6 Mismatch in Checksum 3	

### **Probable Cause:**

EMS is responding in wrong manner Invalid immobiliser ICU-EMS not learned


### **Corrective Action:**

Replace immobiliser ECU Perform transponder learning Perform ICU- EMS learning Clear all errors in both EMS and ICU

If more than one error is found in EMS please follow the priority of the errors during. Here below the errors are listed in the priority error.

EMS Errors	Priority
P0513	1
P183A	2
P0633	3
P183E	4
P183B	5
P1832	6

## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)



Scorpio VIx, SIe, Lx (Refresh)

## MAN-00057-147 March 2009/Rev 3

### **Immobilizer**

P-1832

DTC	Diagnostic item
P-1832	Immobilized condition

#### + Immobilizer code

DTC	Diagnostic item
90A3	No EMS ACK after the signature response

Vehicle behaviour: Engine does not start, check lamp will blink/ON

### **Probable Cause:**

No EMS Ack after the signature mismatch Theft attempt is made.

#### **Corrective Action:**

Clear all errors in both EMS and ICU

If more than one error is found in EMS please follow the priority of the errors during. Here below the errors are listed in the priority error.

EMS Errors	Priority
P0513	1
P183A	2
P0633	3
P183E	4
P183B	5
P1832	6

Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-148 March 2009/Rev 3

#### **Immobilizer**

P-183A

DTC	Diagnostic item	
P-183A	Signature Mismatch	

#### + Immobilizer code

DTC	Diagnostic item
90A3	No EMS ACK after the signature response

Vehicle behaviour: Engine does not start, check lamp will blink/ON

#### **Probable Cause:**

Invalid immobilizer/EMS. Signature mismatch.

#### **Corrective Action:**


Check the CAN wiring – if it is correct. Perform ICU- EMS learning. Clear all errors in both EMS and ICU

If more than one error is found in EMS please follow the priority of the errors during. Here below the errors are listed in the priority error.

EMS Errors	Priority
P0513	1
P183A	2
P0633	3
P183E	4
P183B	5
P1832	6

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-149 March 2009/Rev 3



### **Diagnostic Manual (EMS)** Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-150 March 2009/Rev 3

Immobilizer	P-183B	ı
		,

DTC	Diagnostic item	
P-183B	EMS is locked	

### + Immobilizer code

DTC	Diagnostic item
90A4	Mismatch in checksum 1
90A5	Mismatch in Checksum 2
90A6	Mismatch in Checksum 3

Vehicle behaviour: Engine does not start, check lamp will blink/ON

### **Probable Cause:**

- Invalid immobilizer.
- CAN wiring related problem.
- EMS is locked.
- No EMS ACK from EMS.

### **Corrective Action:**

- Check the CAN wiring if it is correct- replace immobiliser.
- Perform transponder learning.
- Perform ICU EMS learning.
- Clear all errors in both ICU & EMS.

### + Immobilizer code


DTC	Diagnostic item	
90A2 No response from EMS ECU after signature mismatch		

If more than one error is found in EMS please follow the priority of the errors during. Here below the errors are listed in the priority error.

EMS Errors	Priority
P0513	1
P183A	2
P0633	3
P183E	4
P183B	5
P1832	6

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-151 March 2009/Rev 3



Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-152 March 2009/Rev 3

#### **Immobilizer**

P-183E

DTC	Diagnostic item
P-183E	EEPROM ERROR

### **Probable Cause:**

EMS is flashed with different dataset EMS is faulty.

### **Corrective Action:**

Flash it with the correct the dataset. Replace the EMS Perform the ICU- EMS learning. Clear all the errors in the EMS and ICU.

If more than one error is found in EMS please follow the priority of the errors during. Here below the errors are listed in the priority error.

EMS Errors	Priority
P0513	1
P183A	2
P0633	3
P183E	4
P183B	5
P1832	6

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-153 March 2009/Rev 3

### Fault path bank1-specific errors -> stop engine

P-201 P-1201 P-1203 P-1204

DTC	Diagnostic item
P-201	Injector bank 1: short circuit
P-1201	Injector bank 1: short circuit on Low Side to ground
P-1203	Injector bank 1 specific error depending on application
P-1204	Injector bank 1 not-classifiable error

DTC detection condition	Probable cause
Proper Performance	Possible Causes
The rail pressure is within limit	201- general short circuit of the injector cable
Malfunction; out-of-range	1201- short circuit on low
If rail pressure exceeds the limits specified in the map then the error is generated	side to ground cable
Reaction	
The Engine is switched off.	
System check lamp is ON	

MAN-00057-154 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)

P-1205 P-1206 P-1207 P-1208

## Fault path bank1-specific warning -> stop engine

DTC	Diagnostic item
P-1205	Injector bank 1specific warning : depending on application
P-1206	Injector bank 1specific warning: depending on application
P-1207	Injector bank 1specific warning open load
P-1208	Injector bank 1specific warning depending on application

DTC detection condition	Probable cause
Proper Performance	Possible Causes
The rail pressure is within limit	Open load.
Malfunction; out-of-range If rail pressure exceeds the limits specified in the map then the error is generated	
Reaction  The Engine is switched off. System check lamp is ON	

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-155 March 2009/Rev 3

P-1400 P-1401


### **Air Control Governor Deviation**

DTC	Diagnostic item
P-1400	AirCtl permanent positive governor deviation: Positive governor deviation above limit
P-1401	AirCtl permanent negative governor deviation: negative governor deviation below limit

DTC detection condition	Probable cause
Normal operation  * ECU monitors the boost pressure and maintains as per the set value by controlling the VGT.  Malfunction  * The boost pressure value is going beyond the limits which can be compensated by the VGT  Reaction  * If Error present/healed then  * Check lamp is ON.  * EGR is off  * Torque is limited- poor drivability.	Air leak between TC and inlet manifold  VGT stuck in open or closed condition.  Vacuum leak between modulator to VGT.  VGT modulator defective  Vacuum supply to VGT modulator intermittent  Intercooler leak  BPS mounting loose

MAN-00057-156 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)



Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-157 March 2009/Rev 3

### **CAN Signal Error**

DTC	Diagnostic item
P-1705	Main Clutch CAN signal error

DTC detection condition	Probable cause
Normal operation	
* ECU monitors the CAN network	Open circuit in Can network
Malfunction	
* No signal received over the CAN network	
Reaction	
* Malfunction Indication lamp (MIL) is <b>Off</b> .	
* The TCU will go into a limp home mode	
* Cruise control will not work	

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-158 March 2009/Rev 3

## **CAN Signal Plausiblity Error**

DTC	Diagnostic item
P-0704	Main Clutch signal not Plausible error

DTC detection condition	Probable cause
Normal operation	
* ECU monitors the CAN network	Can Hi and Can Low shorted?
Malfunction	
* The signal is not plausible	
Reaction  * Malfunction indication lamp is Off.  * The TCU will go into a limp home mode  * Cruise control will not work	

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-159 March 2009/Rev 3

### **TCU Error State**

DTC	Diagnostic item
P-0302	TCU error state

DTC detection condition	Probable cause
Normal operation	
Malfunction	Can Hi and Can Low shorted ?
Reaction  * Malfunction indication lamp is ON.  * The TCU will go into a limp home mode	

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-160 March 2009/Rev 3

### **EMS ECU confimed Mute error**

DTC	Diagnostic item
P-0073	EMS ECU in confirmed Mute error

DTC detection condition	Probable cause
Normal operation	
Malfunction	
Reaction  * Malfunction indication lamp is ON.	

Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-161 March 2009/Rev 3

## CAN signal for vehicle speed not valid

DTC	Diagnostic item
P-1827	CAN signal for Vehicle speed not valid


DTC detection condition	Probable cause
Normal operation	
Malfunction	
Reaction	
* Malfunction indication lamp is <b>OFF</b> .	
* AC is switched off	
<ul> <li>* After run test is disabled.</li> </ul>	
<ul> <li>* ECU programming cannot be done.</li> </ul>	


## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-162 March 2009/Rev 3

**Gear Neutral Switch** 

P-1704 P-168E





3 D and the installation view of the Gear Neutral Switch

### **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-163 March 2009/Rev 3

### **Gear Neutral Switch**


P-1704

### **Description:**


The gear neutral switch is a hall effect based sensor, mounted on the gear shift selector. The gap between sensor and magnet shall be 6±1mm. This gap has to be maintained within the specification to ensure the proper function of gear neutral sensor.

DTC	Diagnostic item
P-1704	Gear Neutral signal is not plausible

DTC detection condition	Probable cause
Normal operation  The ECU monitors the vehicle speed and gear ratio.  During each gear change it monitors if the neutral is detected.	Gear Neutral Switch ( GNS)defective/wrong signal
Malfunction When ECU detects gear change but no neutral position then it takes it as an error Reaction * Check lamp does not glow, error is registered.	
* The Engine Start Stop system will not work	
* Gets healed if GNS status change (Neutral) is detected for 3 consecutive gear shifts in that particular driving cycle.	




Scorpio VIx, Sle, Lx (Refresh)



Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-165 March 2009/Rev 3



## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-166 March 2009/Rev 3

### **Gear Neutral Switch**


P-168E

### **Description:**


The gear neutral switch is a Hall Effect based sensor, mounted on the gear shift selector. The gap between sensor and magnet shall be 6±1mm. This gap has to be maintained within the specification to ensure the proper function of gear neutral sensor.

DTC	Diagnostic item	
P-168E	Gear Neutral signal is not plausible in Standstill Condition	

DTC detection condition	Probable cause
Normal operation	
The ECU monitors the vehicle speed, accelerator and	
clutch and gear. If the accelerator is pressed and vehicle is	1.GNS
not moving and clutch is not pressed then it indicates that	2. Clutch 10% & 90%
the vehicle is in neutral	switches
Malfunction	
During this condition if the gear switch shows that the	
gear is engaged, then this error is registered.	
Reaction	
<ul> <li>Check lamp does not glow, error is registered</li> </ul>	
* Start Stop will not function.	
Healing :	
Condition for healing: When Neutral is detected this error	
is healed immediately	
Note: If this error happens and when in signal if gear	
neutral is detected with all other stop conditions then this	
error is healed and the vehicle will stop due to start stop	
system	




### **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)



Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-168 March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-169 March 2009/Rev 3

### **Starter Power Stage**

### **Description:**

P-170D P-170E P-1710

The ECU has a power stage which controls the starter actuation when the ESS Is ON. It also monitors the power stage.

DTC	Diagnostic item
P-170D	Short Circuit Battery
P-170E	Short Circuit to Ground
P-1710	Excess Temperature

DTC detection condition	Probable cause
Normal operation	
Power stage functioning OK	
Malfunction	
Reaction  * Check lamp does not glow  * The Engine Start Stop system will not work	

## Diagnostic for P 170 D- short circuit to Battery P-170D **GNS** relay Check for short circuit with contact on the battery and replace the output shorted wiring with battery D CLUTCH START RELAY COMP REL GNS RELAY ECU MAIN RELAY AC ON RELAY 0 0 10A EMS K69 0 0 mammINSTRUMENT EWS K72 **Check for short** circuit with

**Note**: This error will be registered only if the ESS is enabled.


This is connected through EMS ECU Main relay.

battery.

The main relay after ignition off will be held for 40 seconds after which it will be released. Even after this, if the above shown line is found connected (Shorted) directly to Batt. then this error will get registered.

So, while checking, T15 must be switched off and you must wait for EMS ECU to be reset and then check continuity of this line with direct battery.

Scorpio VIx, Sle, Lx (Refresh)




Note: This error will be registered only if the ESS is enabled.

MAN-00057-172 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)

P-170E



P 170E is registered when any of the wires are short to ground- replice the wiring.

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-173 March 2009/Rev 3

### **Gear Neutral Switch Relay**

P-1712

### **Description:**


The gear neutral switch relay has to close when the gear is in neutral. When the gear is engaged then relay has to open

DTC	Diagnostic item
P- 1712	No Load

DTC detection condition	Probable cause
Normal operation The ECU monitors the vehicle speed, gear position and the signal from the gear neutral switch and Pin No K69. This error is detected by monitoring Pin No K69 along with Gear Neutral switch.	<ol> <li>Relay</li> <li>Wiring</li> <li>Instrument cluster.</li> </ol>
Whenever there is a gear change, then the status of relay (by monitoring the K69 pin) also should change. If it changes then relay is diagnosed to be fine.	
Malfunction If the signal is always open i.e. the gear switch always shows the gear engaged then this code is registered.	
Reaction  * Check lamp does not glow, error is registered.  * ESS is disabled and will not work.	


MAN-00057-174 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)



All copyrights reserved by
The repair methods given by the manufacturer in this document are based on the technical specifications current at the time of release. The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which the vehicles are manufactured. The reproduction, translation, transmission, in part of whole of the present document, are prohibited without the prior written consent of  $\, \, \odot \, 2009 \, \, \mathbf{Mahindra} \, \, \mathbf{\&} \, \, \mathbf{Mahindra} \, \, \mathbf{Ltd.} \,$ 

## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)



Scorpio VIx, Sle, Lx (Refresh)

## MAN-00057-176 March 2009/Rev 3

### **Gear Neutral Switch Relay**

P-1714


The gear neutral switch relay has to close when the gear is in neutral. When the gear is engaged then relay has to open

DTC	Diagnostic item
P- 1714	GNS relay sticking.


DTC detection condition	Probable cause
Normal operation The ECU monitors the vehicle speed, gear position and the signal from the gear neutral switch and Pin No K69. This error is detected by monitoring Pin No K69 along with Gear Neutral switch.	a)Relay b)Wiring c)Instrument cluster
Whenever there is a gear change, then the status of relay (by monitoring the K69 pin) also should change. If it changes then relay is diagnosed to be fine.	
Malfunction If the signal is always closed i.e. the gear switch always shows the gear lever is in neutral then this code is registered.	
Reaction  * Check lamp does not glow, error is registered.  * ESS is disabled and will not work.	

MAN-00057-177 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)



MAN-00057-178 Scorpio VIx, Sle, Lx (Refresh) March 2009/Rev 3




## **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-179 March 2009/Rev 3

**Redundant Clutch Switch** 

P-170A





Nut for removing the clutch switch

MAN-00057-180 March 2009/Rev 3

#### **Redundant Clutch Switch**

P-170A

### **Description**


The ECU monitors the signal from the normal clutch switch- which is at 10% of the pedal travel and also the redundant clutch switch (which is at 90% clutch pedal travel)


DTC	Diagnostic item
P-170A	Clutch signal is not plausible

DTC detection condition	Probable cause
Normal operation	
In normal operation the signal from the 10% switch will	
come before the 90% switch.	a) 90% clutch switch
	b) Wiring.
Malfunction	
If the signal from the 10% switch has not come but the	
90% switch has come then it is considered as a plausibility	
error.	
Reaction	
* Check lamp does not glow, error is registered.	
* ESS is disabled and will not work.	

MAN-00057-181 March 2009/Rev 3

Scorpio VIx, Sle, Lx (Refresh)





Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-183 March 2009/Rev 3

### **Lamp Power Stage**


**P-1AE9** 

#### **Description**

The stop lamp of the ESS is driven by the ECU's power stage. The output stage is monitored and checked for errors.

DTC	Diagnostic item
P-1AE9	Short Circuit Battery

DTC detection condition	Probable cause
Normal operation Stop lamp is powered through the ECU Main relay. The lamp is driven by pulling the other end of lamp to ground by EMS ECU stop lamp power stage. 40 seconds after ignition is switched off, the ECU main relay contacts open. When the ignition is ON (Or till Main relay contacts are closed) Pin K68 sees +12VSo the pin K68 should be showing open circuit after the main relay contacts open. Malfunction If it does not show open circuit, it only means that the power supply for lamps is short directly to battery.	Wiring short.
Reaction  * Check lamp does not glow, error is registered.  * .	



Scorpio VIx, Sle, Lx (Refresh)

### **Lamp Power Stage**


P-1AEA

#### **Description**

The stop lamp of the ESS is driven by the ECU's power stage. The output stage is monitored and checked for errors.

DTC	Diagnostic item
P-1AEA	Short Circuit to Ground

DTC detection condition	Probable cause
Normal operation When the power stage is switched off then it does not detect a short to Ground	Wiring short.
Malfunction When it detects a short	
Reaction  * Check lamp does not glow, error is registered.  * .	



All copyrights reserved by
The repair methods given by the manufacturer in this document are based on the technical specifications current at the time of release. The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which the vehicles are manufactured. The reproduction, translation, transmission, in part of whole of the present document, are prohibited without the prior written consent of  $\, \, \odot \, 2009 \, \, \mathbf{Mahindra} \, \, \mathbf{\&} \, \, \mathbf{Mahindra} \, \, \mathbf{Ltd.} \,$ 

MAN-00057-185 March 2009/Rev 3

### **Lamp Power Stage**

P-1AEB

### **Description**


The stop lamp of the ESS is driven by the ECU's power stage. The output stage is monitored and checked for errors.

DTC	Diagnostic item
P-1AEB	No Load

DTC detection condition	Probable cause
Normal operation When Ignition is ON and the power stage is switched off, then at Pin K68 point EMS ECU monitoring of lamp power stage will be seeing a +12V. When power stage is switched ON then monitoring will see a ground at K68 pin.	Open circuit Instrument cluster Loose connector Pin Backout
Malfunction When the power stage is switched OFF and ignition is ON, if +12V is not detected at Input to pin K68 (i.e, no load is detected) this error is logged	
Reaction  * Check lamp does not glow, error is registered.  * .	

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-186 March 2009/Rev 3



All copyrights reserved by
The repair methods given by the manufacturer in this document are based on the technical specifications current at the time of release. The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which the vehicles are manufactured. The reproduction, translation, transmission, in part of whole of the present document, are prohibited without the prior written consent of  $\, \, \odot \, 2009 \, \, \mathbf{Mahindra} \, \, \mathbf{\&} \, \, \mathbf{Mahindra} \, \, \mathbf{Ltd.} \,$ 

### **Lamp Power Stage**


P-1AEC

#### **Description**

The stop lamp of the ESS is driven by the ECU's power stage. The output stage is monitored and checked for errors.

DTC	Diagnostic item
P-1AEC	Excess temperature

DTC detection condition	Probable cause
Normal operation The temperature of the power stage is monitored and is within range	ECU
Malfunction When it detects that there is excess temperature	
Reaction  * Check lamp does not glow, error is registered.  * .	



### T 50 (Igniation Switch) Always pressed ON


P-1715

#### **Description**

The signal from the igniaton switch ( for cranking ) is monitored for duration


DTC	Diagnostic item
P-1715	T50 Always pressed ON

DTC detection condition	Probable cause
Normal operation	
The time duration of the signal is within normal	
	Wiring
Malfunction	Ignition switch
When the cranking signal is detected beyond the range	
then it is assigned as the T50 is pressed ON.	
Reaction	
* Check lamp does not glow, error is registered.	



#### **Actuator Tests**

Home screen for the Actuator test



Scorpio VIx, SIe, Lx (Refresh)


MAN-00057-190 March 2009/Rev 3

ACT #1 - System Lamp

Test condition: Ignition ON

Actuate: Click on the System Lamp ON.


ACT#1



Click on the release to release the lamp

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-191 March 2009/Rev 3



Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-192 March 2009/Rev 3

ACT#2


**ACT # 2– Coolant Overheat Lamp Test** 

Test condition: Engine Running

Actuate: Click the switch ON.

Expected Result: The coolant overheat lamp at the end of the temperature scale will light

up.



Scorpio VIx, SIe, Lx (Refresh)

MAN-00057-193 March 2009/Rev 3

ACT # 3- Air Conditioning Actuator

ACT#3

Test condition: Engine at Idle or With Ignition ON

Document1 - Mic.

Mahindra Diagno...

DiagnosticsTeste... EN

(SEARCH

Actuate

**Expected result:** The air condition actuator will become ON, you can hear the compressor engage

Note: This actuator does not get released automatically. You have to manually release DiagnosticsTester: Connected to ECU - 1037375393 ECU Configure Help Bosch Part Number - 1037375393 Hardware Version - EDC16C39/BAS Software Version - C56052A Dataset ID - 1037387203 🖫 🚜 Read Dynamically De GROUP1 GROUP2 GROUP3 GROUP4 GROUP5 Test Actuators O Engine Test Average Engine Speed 800.67 🖽 🚜 Diagnostic Trouble Ci Actual Injection Quantity 8.47 Coolant Over heat Lamp 27.11 degC Coolant Overheat Indicator Lamp Switch ON Air conditioning Actuator Air conditioning Actuator ON Switch OFF Release 26,07,2007 - 11:07:03: Actuator released successfully 26,07,2007 - 11:07:15: Actuator released successfully 26,07,2007 - 11:07:19. Actuator released successfully 26,07,2007 - 11:10:04: Actuator released successfully 26,07,2007 - 11:10:04: Actuator released successfully

start Post-it(R) Softw...

MAN-00057-194 March 2009/Rev 3


**ACT #4- EGR Actuator** 

ACT#4

#### Test condition:

Engine Running at Idle

Note the quantity of the injection and the air mass.



Action: Put EGR quantity >80%. In the Enter duty cycle. Actuate

**Expected result:** The actual duty cycle will change.

The air mass quantity and the injection quantity should change. The value are very small Air mass by around 4 and fuel quantity change of around 0.47.


Note: If not released manually, the system will automatically release the entered duty cycle after 30 seconds

Scorpio VIx, Sle, Lx (Refresh)

### MAN-00057-195 March 2009/Rev 3

#### **ACT #5– Boost Pressure Actuator (BPA) Test**

ACT#5



Enter duty cycle – between 0 to 100%. Click on Test

Expected result: There is a change in Engine RPM and also the air mass quantity changes. The engine noise change is also clearly audible

**Disabled Actuator Test:** 

- Rail Pressure set Point
- Metering Unit Actuator
- Glow Lamp & Glow relay

#### MAN-00057-196 **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh) March 2009/Rev 3

### Symptom Based Diagngosis - SBD # 1

**SBD#1** 

Complaint - Engine not starting Error codes - No error codes.

Look in Data Packet Group - Rail/Meu Values- Serial no 6 - Information for trouble in starting of the engine.

Note the value. Convert it into binary. See the bit positon and look at the table below

Bit position of	Conditions to be met	Implication	Look at this area
0	The engine speed is above the minimum threshold, but the Pressure built up in the rail is not sufficient.	Problem in low pressure circuit or HPP	LPC including injector back leak, copper washers. HPP to be changed in last step.
1	There is sufficient pressure in the rail but the engine speed is below the minimum threshold	Cranking RPM less	4. Battery 5. Starter 6. Engine partial seizure
2	There is sufficient pressure build-up in the rail and the engine speed is above the minimum threshold, but a problem has arisen with the engine synchronisation	Synchronisation issue	Look at the synchorisination label and follow the chart in the next page.
3	There is a reversible shut-off request . The application constant determines which shut-off conditions are to be taken into account.	Look at the table to find the reason	Please contact tekliner/ tekhub.

### MAN-00057-**197** March 2009/Rev 3

### Diagnostic Manual (EMS) Scorpio VIx, Sle, Lx (Refresh)

4	There is an irreversible shut-off	Please contact tekliner/ tekhub.	SBD#1	
	request			

# Synchronisation state Code Description

- 0 INIT: Basic initialization of state machine
- 1 RECOVER: Resetting the counters
- 2 TIMEOUT: Engine stops or error case in which all engine speed sensors of system are defective
- 3 INTERIMS: Additional asynchronous interrupts which is generated when engine position is detected based on the time condition of system.
- WAIT\_INC: Plausibility test is done on the events of the redundant sensor system w/o the mail sensor system delivering events. Interrupts are generated with min. system freq.
- 5 PHASE\_FREQ\_CHK: Plausibility test is done on the events of the redundant sensor system w/o the mail sensor system delivering events. Interrupts are generated with max. system freq.
- 8 PHASE\_PLAUS\_CHK: Plausibility test is done on the events of the redundant sensor system w/o the main system delivering events.
- POLLING: The overall system behaves frq. Synchronous & waits for further events to determine the phases.
- WAIT PHASE: Waits for the unique positioning by the phase system.
- VERIFY A unique positioning of the system has occurred. A plausibility test is run on all sensor systems wrt each other in their status & angle info.
- 34 RESYNC\_OVERFLOW: No unique position was found
- 35 RESYNC OFFSET

48

- POST: The system wait until there is a complete engine stop.
- 128 VERIFY\_BACKUP
- 129 BACK UP
- 130 START BACKUP
- 131 WAIT\_BACKUP: Engine has decelerated. Metering unit no longer be activated.

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-198 March 2009/Rev 3

### Symptom Based Diagngosis - SBD # 2. Injector Back leak

SBD#2

Applicable to
7100000000
Scorpio CRDe 2.2, Xylo 2.49

#### **DTC** code

None

(Will happen when injectors stuck close)

P1193/P1192

( Will happen when injectors are stuck open)

	<b>Engine</b>	Status
_	<u>l</u>	

Can not be started

State of Starting System Code		Synchronization status Code
•	1	Jumps from 3 to 48

#### **Tools required for Doing the test**

- Test tubes with graduations, (capacity 30 to 75 ml)
- 4 no rubber tube of 310 mm (Recommend part number 9350042680 -Engine—Tube Connection Injection Pump)

### MAN-00057-199 March 2009/Rev 3

### **Diagnostic Manual (EMS)** Scorpio VIx, Sle, Lx (Refresh)

SBD#2


<u>Caution</u> - The ID of the tube is important; hence please use this part number.

Blow air around the injectors to remove the dust.


Remove injector overflow connector holder clips from all the four injectors.

Remove injector overflow connections from all the four injectors.

Do not remove overflow tube connection from the fuel return line 'T' joint



Insert the pipes open end in to the test tubes as shown in photograph).



MAN-00057-201 March 2009/Rev 3

The root cause for the injectors stuck open or close is the presence of water in the fuel or poor fuel quality.

Investigate & advice the customer accordingly to avoid repeat failure.

In case of water - please advise the customer how to drain water when the indicator comes ON.

If it is suspected due to poor fuel quality- please advise accordingly.

## **Conformity Check**

#### **Coolant temperature Sensor/ Fuel Temperature sensor**

Temperature	Resistance Min kΩ	Resistance Max kΩ
10	8.244	10.661
20	2.262	2.76
80	0.304	0.342
100	0.178	0.196

### **Accelerator pedal**

	Poti 1	Poti 2
Accelerator pedal:- 0%	2.160KOhm,	2.672KOhm
Accelerator pedal :-100%	1.321KOhm	2.112KOhm
Poti 1	1.2 $k\Omega \pm 0.4$	$1.7 \text{ k}\Omega \pm 0.4$

### HFM (Air flow)

Air flow	R Min(Kohm)	R Max (Kohm)
-10	7.942	9.3
0	5.119	5.892
30	1.573	1.752
60	0.565	0.654
90	0.238	0.285
100	0.184	0.222

### Injector Solenoid coil

Nominal value: 0.255 Ohm

Min: 0.215 Ohm, Max: 0.295 Ohm

Measured at 20-70 degrees centigrade.

#### **MPROP** coil resistance

Between Minimum: 2.60 Ohm & Maximum: 3.15 Ohm


Measured at 20 degrees centigrade.

MAN-00057-203 March 2009/Rev 3

# ANALOG BASED IMMOBILIZER (SCORPIO VLX)

SOLD BETWEEN DEC 2007 AND MAR2009

# Overview of the in-vehicle communication network-with analog Immobilizer



### Note on Function of Analog based immobilizer -


- 1. In the Analog immobilizer, the immobilizer function will become active, only if the vehicle is locked using the remote.
- 2. Using the mechanical key to lock the vehicle will not activate the immobilizer function.
- 3. The customer should be educated to change the PIN code of the immobilizer unit (Refer to relevant TSB)

Immobilizer communication wire open or shorted to Vbatt+

P-1828

DTC	Diagnostic item
P-1828	Immobilizer communication wire open or short

DTC detection condition	Probable cause
Normal operation	
<ul> <li>ECU receives signal from RKE, as authentic and allows the engine to crank.</li> </ul>	<ul><li>Open circuit</li><li>Improper earthing</li></ul>
Malfunction	
Correct signal not received	
Reaction	
If Error present and active then	
Check lamp is ON.	
Engine will not start	
If Error is healed but recorded in ECU then	
Check lamp is ON	
<ul> <li>Engine will start.</li> </ul>	



#### Checking the earthing:

Main earth near the battery on the LH fender. Check for the star washer's presence.

### MAN-00057-207 March 2009/Rev 3




P-1828

Remove the washer – ensure that the cutting edge is facing downwards. This will ensure that the paint is removed and proper earthing takes place.-

- A. If the washer is not there please add.
- B. If reversed- correct the orientation.
- C. If flattened- change.



#### Checking the connectors:



DESCRIPTION	LOCATION	IC No	PINS	M/F
IP to ENGINE	A-PILLAR LEFT	10	21	M
IP to FLOOR	A-PILLAR RIGHT	26	20	F
FLOOR to CDL	BELOW CO- DRIVER SEAT	27	21	М

# Immobilizer communication wire open or shorted to ground.

P-1829


	DTC	Diagnostic item
Ī	P-1829	Immobilizer communication wire short to ground.

DTC detection condition	Probable cause
Normal operation	
<ul> <li>ECU receives signal from RKE, as authentic and allows the engine to crank.</li> </ul>	Immobilizer communication wire short to ground.
Malfunction	<ul> <li>Improper earthing</li> </ul>
Correct signal not received	
Reaction	
If Error present and active then	
Check lamp is ON.	
Engine will not start	
If Error is healed but recorded in ECU then	
Check lamp is ON	
<ul> <li>Engine will start.</li> </ul>	

Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-209 March 2009/Rev 3

Probable Causes:



### Checking the earthing:

P-1829

Main earth near the battery on the LH fender. Check for the star washer's presence.




Remove the washer – ensure that the cutting edge is facing downwards. This will ensure that the paint is removed and proper earthing takes place.-

- D. If the washer is not there please add.
- E. If reversed- correct the orientation.
- F. If flattened- change.



### Checking the connectors:



# Immobilizer signal in error zone

P-182A

DTC	Diagnostic item
P-182A	Immobilizer signal in error zone

DTC detection condition	Probable cause
Normal operation	
<ul> <li>ECU receives signal from RKE, as authentic and allows the engine to crank.</li> </ul>	<ul><li>Improper Earthing / Grounding.</li><li>Loose Connection</li></ul>
Malfunction	of the any connectors
Correct signal not received	(from CDL to EMS ECU)
Reaction	Poor Battery / poor
If Error present and active then	starting system /
Check lamp is ON.	multiple cranking.
Engine will not start	
If Error is healed but recorded in ECU then	
Check lamp is ON	
Engine will start after 3 Ignition ON.( To understand the coorelation of theft attempt and ECU locking a	
table is given below.	

Number of theft attempts	No. of Ignition cycles required to start the engine
1	1+1
2	2+1
3	ECU is locked

#### Possible causes

- A. Improper Earthing / Grounding.
- B. Loose Connection of the any connectors (from CDL to EMS ECU)
- C. Poor Battery / poor starting system / multiple cranking.

#### Probable causes:

- Both A & C 1.
- 2. A alone
- 3. Both B & C
- B alone

#### Checking the earthing:

P-182A

Main earth near the battery on the LH fender. Check for the star washer's presence.




Remove the washer – ensure that the cutting edge is facing downwards. This will ensure that the paint is removed and proper earthing takes place.-

- G. If the washer is not there please add.
- H. If reversed- correct the orientation.
- If flattened- change.



#### Checking the connectors:



## Immobilizer signal in error zone

P-182B

DTC	Diagnostic item
P-182B	ECU is locked completely

DTC detection condition	Probable cause
Normal operation	
<ul> <li>ECU receives signal from RKE, as authentic and allows the engine to crank.</li> </ul>	<ul><li>Improper Earthing / Grounding.</li><li>Loose Connection</li></ul>
<ul> <li>Malfunction</li> <li>Wrong signal received continuously hence the ECU is locked. (P182A with multiple crank/Ignition ON)</li> </ul>	of the any connectors (from CDL to EMS ECU)  Poor Battery / poor starting system /
Reaction  • If Error present/healed then  • Check lamp is ON.  • Engine will not start	<ul><li>multiple cranking.</li><li>Wrong signal received continuously.</li></ul>

#### Possible causes

This error will only occur if P182A happens multiple times.

- A. Improper Earthing / Grounding.
- B. Loose Connection of the any connectors (from CDL to EMS ECU)
- C. Poor Battery / poor starting system / multiple cranking.

#### Probable causes:

- 1. Both A & C
- 2. A alone
- Both B & C 3.
- 4. B alone

MAN-00057-214 March 2009/Rev 3

IC No PINS M/F

21

20

M

F

M

10

26

27

Scorpio VIx, Sle, Lx (Refresh)

Checking the earthing:

P-182B

Main earth near the battery on the LH fender. Check for the star washer's presence.




Remove the washer – ensure that the cutting edge is facing downwards. This will ensure that the paint is removed and proper earthing takes place.-

- J. If the washer is not there please add.
- K. If reversed- correct the orientation.
- L. If flattened- change.



#### Checking the connectors:



# Immobilizer controller has not received correct pattern (RF signal)

Immobilizer signal in error zone


P-182C

DTC	Diagnostic item
D 400C	5
P-182C	Immobilizer controller has not received correct pattern (RF signal)

DTC detection condition	Probable cause
Normal operation	
ECU receives signal from RKE, as authentic and allows the engine to crank.	Mechanical Key used for unlocking the vehicle / RKE Remote
Malfunction	NOT used for
<ul> <li>This error is lodged when the vehicle has been locked/ armed by the security system and has not received the correct pattern of the remote signal before an attempt to start the engine was made.</li> </ul>	unlocking the vehicle & IGN ON. Loose Connection of the any connectors (from CDL to EMS ECU)
Reaction	<ul> <li>RKE Remote NOT</li> </ul>
<ul> <li>If Error present/healed then</li> <li>Check lamp is ON.</li> <li>Engine will start</li> </ul>	working properly/Remote battery low.  Theft attempt

Note: The healing will occur if after hearing the remote siren the correct remote key is pressed and the security system validates it. .

Possible causes and the probability:



Scorpio VIx, Sle, Lx (Refresh)

MAN-00057-217 March 2009/Rev 3

#### **Release Notes**

This manual supersedes the following earlier versions

MAN -00029, Rev 1 : 2.2 L + non transponder based immobilser. EDC 16C39

MAN -00038, Rev 2: Revision 1 + AT

Changes incorporated in MAN -00057, Rev 3 (EDC 16C39, AT, + TBI, ESS)

In BPA and BPS the voltage mentioned was 2.5, corrected to 4.5 V

Added DTC details: 1194,1195;P-201;P-1201;P-1203;P-1204;P-1205;P-1206;P-1207;P-1208;

ESS related errors

P-1704;P-168E;P-170D;P-170E;P-170F;P-1710;P-1712;P-1714;P-170A;P-1AE9;P-1AEA;P-1AEB;P-1AEC;P-1715

Corrected the code no for Glow plug controller relay.