2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

2012 ENGINE

Engine Mechanical - 1.8L (LUW) - Cruze

SPECIFICATIONS

FASTENER TIGHTENING SPECIFICATIONS

Fastener Tightening Specifications

	Specification	
Application	Metric	English
AC Compressor and Condenser Hose Nut	19	14 lb ft
AC Compressor Bolt	22	16 lb ft
AC Evaporator Hose Assembly Nut	19	14 lb ft
Air Intake Hose Clamps	3.5	31 lb in
Automatic Transmission Flex Plate Bolt	60 (2)	44 lb ft (2)
Camshaft Adjuster Bolt		
• First Pass	50 (1)	37 lb ft (1)
Second Pass	150 degrees	
• Final Pass	15	degrees
Camshaft Adjuster Closure Plug	30	22 lb ft
Camshaft Bearing Cap Bolt	8	71 lb in
Camshaft Closure Bolt	30	22 lb ft
Camshaft Cover Bolt	8	71 lb in
Camshaft Position Actuator Solenoid Valve Bolt	6	53 lb in
Camshaft Position Sensor Bolt	6	53 lb in
Cold Start Rail Bolt	4	35 lb in
Connecting Rod Bearing Cap Bolt		
• First Pass	35 (1)	26 lb ft (1)
Second Pass	45 degrees	
• Final Pass	15 degrees	
Coolant Pipe Pump Module Bolt	8	71 lb in
Coolant Pipe Thermostat Housing Bolt	8	71 lb in
Crankshaft Balancer Bolt		
• First Pass	95 (1)	70 lb ft (1)
Second Pass	45 degrees	
• Final Pass	15	degrees
Crankshaft Bearing Cap Bolt		
• First Pass	50(1)	37 lb ft (1)

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:13 a. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Second Pass	45 degrees	
• Final Pass	15 degrees	
Crankshaft Position Sensor Bolt	5	44 lb in
Cylinder Head Bolt		
• First Pass	25 (1)	18 lb ft (1)
Second Pass	90	degrees
Third Pass	90 degrees	
Fourth Pass	90 degrees	
• Final Pass	45 degrees	
Drive Belt Tensioner Bolt	55	41 lb ft
Engine Coolant Pipe Bolts	9	80 lb in
Engine Coolant Thermostat	8	71 lb in
Engine Coolant Thermostat Housing	8	71 lb in
Engine Coolant Thermostat Housing Coolant Pipe Bolt	8	71 lb in
Engine Flywheel Bolt - Transmission D16/D20/F17		
• First Pass	35 (1)	26 lb ft (1)
Second Pass	30 degrees	
• Final Pass	15 degrees	
Engine Flywheel Bolt - Transmission M32		
• First Pass	60 (1)	44 lb ft (1)
Second Pass	45	degrees
• Final Pass	15	degrees
Engine Front Cover (Oil Pump Housing)	20	15 lb ft
Engine Lift Front Bracket	25	18 lb ft
Engine Mount Bolt	62	46 lb ft
Engine Mount Bolt to Engine Mount Bracket - M10		
• First Pass	50 (1)	37 lb ft (1)
Second Pass	60 degrees	
• Final Pass	75 degrees	
Engine Mount Bracket Bolt to Engine Mount		
First Pass	50 (1)	37 lb ft (1)
Second Pass	60	degrees
• Final Pass	75	degrees
Engine Mount Bracket to Engine Block/Cylinder Head		
• First Pass	60 (1)	46 lb ft (1)
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252

Page 2

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

45 degrees	
60 degrees	
46 lb ft	
71 lb ft	
18 lb ft	
71 lb in	
71 lb in	
89 lb in	
15 lb ft	
48 lb ft	
48 lb ft	
48 lb ft	
62 lb in	
15 lb ft	
15 lb ft (1)	
16 lb ft	
15 lb ft	
26 lb ft	
71 lb in	
31 lb ft	
71 lb in	
53 lb in	
15 lb ft	
71 lb in	
71 lb in	
62 lb in	
15 lb ft	
62 lb in	
18 lb ft	
15 lb ft	
11 lb ft	
89 lb in	
89 lb in	
124 lb in	
30 lb ft	
44 lb ft	
11 lb ft	
15 lb ft	
_	

Page 3

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Oil Pressure Switch	20	15 lb ft
Oil Pump Cover Bolt	8	71 lb in
Power Steering Fluid Reservoir Bolt	9	80 lb in
Spark Plugs	25	18 lb ft
Throttle Body Bolt	8	71 lb in
Timing Belt Idler Pulley Bolt		
• First Pass	20 (1)	15 lb ft (1)
Second Pass	120 degrees	
• Final Pass	15 d	egrees
Timing Belt Lower Front Cover Bolt	6	53 lb in
Timing Belt Rear Cover Bolt	6 (2)	53 lb in (2)
Timing Belt Tensioner Bolt	<u> </u>	
• First Pass	20 (1)	15 lb ft (1)
Second Pass	120 degrees	
• Final Pass	15 degrees	
Timing Belt Upper Front Cover Bolt	6	53 lb in
Transmission to Cylinder Block Bolt	75	55 lb ft
Transmission to Oil Pan Bolt	50	37 lb ft
Water Pump Bolt	8	71 lb in
Water Pump Pulley Bolt	20 (2)	15 lb ft (2)
Wiring Harness Ground Nut	9	80 lb in
1 = Use NFW fastener		

^{1 =} Use NEW fastener

ENGINE MECHANICAL SPECIFICATIONS

Engine Mechanical Specifications

Spe	cification	
Metric	English	
4-Cyl	inder Inline	
	16	
1.7961	109.59 cu in	
80.5 mm	3.169 in	
86 mm	3.386 in	
88.2 mm	3.472 in	
	10.5:1	
	1.796 l 80.5 mm 86 mm 88.2 mm	

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:49 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

^{2 =} Recut threads and insert NEW bolts with screw locking compound.

For screw locking compound, refer to electronic parts catalogue.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

 Maximum Power / Engine Speed kW/RPM - Gasoline Maximum Power / Engine Speed kW/RPM - E85 Ethanol 	103 KW/6300 106 KW/6300	
 Maximum Torque / Engine Speed - Gasoline Y/RPM/lb ft/RPM Maximum Torque / Engine Speed - E85 Ethanol Y/RPM/lb ft/RPM 	170 N.m/ 3800 183 N.m/ 3800	125 lb ft/3800 135 lb ft/3800
Idle Speed RPM	700-780	
Overspeed RPM		6500
Firing Order		1-3-4-2
Engine Length - RFB to Front of Poly V Belt	513 mm	20 in
Engine Height - Crank Center to Top	420 mm	17 in
Engine Weight - MT Version	120.5 kg	266 lb
Block		
Cylinder Block Height	198.5 mm	8 in
 Cylinder Bore Diameter - Standard Size Guiding Value 00 	80.492-80.508 mm	3.169-3.1694 in
 Cylinder Bore Diameter - Standard Size Guiding Value 05 	80.542-80.558 mm	3.171-3.1716 in
Cylinder Bore Diameter - Oversize Guiding Value 00+05	80.992-81.008 mm	3.188-3.1893 in
Crankshaft		
 Crankshaft Main Bearing Journal 1-5 Diameter Standard Size (brown/green) 	54.980-54.997 mm	2.165-2.166 in
 Crankshaft Main Bearing Journal 1-5 Diameter Undersize 0.25 (brown/green) 	54.730-54.747 mm	2.155-2.156 in
 Crankshaft Main Bearing Journal 1-5 Diameter Undersize 0.50 (brown/green) 	54.482-54.495 mm	2.145-2.146 in
Crankshaft Main Bearing Journal 3 Width - Standard Size	26.000-26.052 mm	1.024-1.026 in
Crankshaft Main Bearing Journal 3 Width - Undersize 0.25	26.200-26.252 mm	1.032-1.034 in
 Crankshaft Main Bearing Journal 3 Width - Undersize 0.50 	26.400-26.452 mm	1.040-1.042 in
Con-Rod Bearing Journal - Standard Size	42.971-42.987 mm	1.692-1.693 in
Con-Rod Bearing Journal - Undersize 0.25 (blue)	42.721-42.737 mm	1.682-1.683 in
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 6

Page 5

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

 Con-Rod Bearing Journal - Undersize 0.50 (white) 	42.471-42.487 mm	1.672-1.673 in
 Crankshaft Main Bearing 1-5 - Bearing Shell Thickness - Standard Size (brown) 	1.987-1.993 mm	0.0783-0.0785 in
 Crankshaft Main Bearing 1-5 - Bearing Shell Thickness - Standard Size (green) 	1.993-1.999 mm	0.0785-0.0787 in
 Crankshaft Main Bearing 1-5 - Bearing Shell Thickness - Undersize 0.25 (brown/blue) 	2.112-2.118 mm	0.0832-0.0834 in
 Crankshaft Main Bearing 1-5 - Bearing Shell Thickness - Undersize 0.25 (green/blue) 	2.118-2.124 mm	0.0834-0.0836 in
 Crankshaft Main Bearing 1-5 - Bearing Shell Thickness - Undersize 0.50 (brown/blue) 	2.237-2.243 mm	0.0842-0.0844 in
Crankshaft Main Bearing 1-5 - Bearing Shell Thickness - Undersize 0.50 (green/blue)	2.243-2.249 mm	0.0884-0.0886 in
Crankshaft Bearing Allowable Clearance	0.005-0.059 mm	0.0002-0.0024 in
Crankshaft Bearing Allowable End Clearance	0.100-0.202 mm	0.004-0.008 in
Crankshaft Main Bearing 3 Width - Standard Size	25.85-25.90 mm	1.018-1.020 in
Crankshaft Main Bearing 3 Width - Undersize 0.25	26.05-26.10 mm	1.026-1.028 in
Crankshaft Main Bearing 3 Width - Undersize 0.50	26.25-26.30 mm	1.034-1.036 in
Con-Rod Bearing Shell Thickness - Standard Size	1.485-1.497 mm	0.0585-0.0590 in
Con-Rod Bearing Shell Thickness - Undersize 0.25	1.610-1.622 mm	0.0634-0.0639 in
Con-Rod Bearing Shell Thickness - Undersize 0.50	1.735-1.747 mm	0.0684-0.0688 in
Con-Rod Bearing Allowable Clearance	0.019-0.071 mm	0.0007-0.0028 in
Pistons and Pins		
 Piston Diameter - Standard Size Guiding Value 00 	80.455-80.465 mm	3.1676-3.1680 in
 Piston Diameter - Standard Size Guiding Value 00 	80-505-80.51 mm	3.1695-3.1697 in
• Piston Diameter - Oversize Guiding Value 00+05	80.955-80.965 mm	3.1872-3.1876 in
Piston Clearance	0.027-0.053 mm	0.0011-0.0021 in
Pin Diameter	19 mm	0.785 in
Pin Longitude	49.84 mm	1.962 in
Pin to Piston Clearance	0.020-0.060 mm	0.0008-0.0024 in
Pin to Con-Rod Clearance	0.015-0.021 mm	0.0006-0.0009 in
Piston Rings	L	
Piston Ring Thickness - First Compression Ring	1.170-1.190 mm	0.0461-0.0469 in
Piston Ring Thickness - Second Compression	1.170-1.190 mm	0.0461-0.0469 in
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 3

Page 6

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Ring		
Piston Ring Thickness - Oil Control Ring	1.900-1.980 mm	0.0749-0.0780 in
Piston Ring End Gap - First Compression Ring	0.20-0.40 mm	0.0079-0.0158 in
Piston Ring End Gap - Second Compression Ring	0.40-0.60 mm	0.0158-0.0237 in
Piston Ring End Gap - Oil Control Ring	0.25-0.75 mm	0.0098-0.0295 in
Piston Ring to Groove Clearance - First Compression Ring	0.040-0.080 mm	0.0016-0.0032 in
 Piston Ring to groove Clearance - Second Compression Ring 	0.030-0.070 mm	0.0012-0.0028 in
• Piston Ring to Groove Clearance - Oil Control Ring	0.030-0.130 mm	0.0012-0.051 in
Cylinder Head		
	0.05 mm	0.00197 in
• Surface Flatness - Block Deck - Longitude	If the deck surface is out of specification, replace the cylinder head. Do not machine the cylinder head.	
	0.03 mm	0.00118 in
	If the deck surface is out of specification, replace the cylinder head. Do not machine the cylinder head.	
• Surface Flatness - Block Deck - Transverse		out of specification, replace
Surface Flatness - Block Deck - Transverse Valve Seat Width - Intake		out of specification, replace On not machine the cylinder
	the cylinder head. D	out of specification, replace to not machine the cylinder head.
Valve Seat Width - Intake	1.0-1.4 mm 1.4-1.8 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in
Valve Seat Width - Intake Valve Seat Width - Exhaust	the cylinder head. In	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle	the cylinder head. In	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees)
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper	the cylinder head. In	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees)
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower	the cylinder head. In	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) s (+/- 0.5 degrees)
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size	1.0-1.4 mm 1.4-1.8 mm 45 degrees 60 degrees 5.000-5.016 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150 Valve Guide Assembly Height	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm 10.70-11.00 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in 0.422-0.434 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150 Valve Guide Assembly Height Valve Guide Longitude	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm 10.70-11.00 mm 36.70-37.30 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in 0.422-0.434 in 1.445-1.468 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150 Valve Guide Assembly Height Valve Guide Longitude Valve Assembly Height - Intake	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm 10.70-11.00 mm 36.70-37.30 mm 36.33 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in 0.422-0.434 in 1.445-1.468 in 1.430 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150 Valve Guide Assembly Height Valve Guide Longitude Valve Assembly Height - Intake Valve Assembly Height - Exhaust	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm 10.70-11.00 mm 36.70-37.30 mm 36.33 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in 0.422-0.434 in 1.445-1.468 in 1.430 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150 Valve Guide Assembly Height Valve Guide Longitude Valve Assembly Height - Intake Valve Assembly Height - Exhaust Camshaft	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm 10.70-11.00 mm 36.70-37.30 mm 36.33 mm 36.33 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in 0.422-0.434 in 1.445-1.468 in 1.430 in 1.430 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150 Valve Guide Assembly Height Valve Guide Longitude Valve Assembly Height - Intake Valve Assembly Height - Exhaust Camshaft • Cam Stroke Intake	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm 10.70-11.00 mm 36.33 mm 36.33 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in 0.422-0.434 in 1.445-1.468 in 1.430 in 0.394 in
Valve Seat Width - Intake Valve Seat Width - Exhaust Valve Seat Angle Valve Seat Angle Adjustment - Upper Valve Seat Angle Adjustment - Lower Valve Guide Bore Norm Size Valve Guide Bore Oversize 0.075 Valve Guide Bore Oversize 0.150 Valve Guide Assembly Height Valve Guide Longitude Valve Assembly Height - Intake Valve Assembly Height - Exhaust Camshaft Cam Stroke Intake Cam Stroke Exhaust	1.0-1.4 mm 1.4-1.8 mm 45 degrees 30 degrees 5.000-5.016 mm 5.075-5.091 mm 5.150-5.166 mm 10.70-11.00 mm 36.33 mm 36.33 mm	out of specification, replace to not machine the cylinder head. 0.040-0.056 in 0.056-0.071 in s (- 0.25 degrees) s (+/- 0.5 degrees) 0.1969-0.1975 in 0.1999-0.2005 in 0.2028-0.2034 in 0.422-0.434 in 1.445-1.468 in 1.430 in 0.394 in

Page 7

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

 Valves Oversize Longitude 0.075 - Intake 	100.70-100.90 mm	3.965-3.972 in
Valves Oversize Longitude 0.075 - Exhaust	100.00-100.20 mm	3.937-3.945 in
Valves - Valve Stem Norm Diameter - Intake	4.965-4.980 mm 0.1955-0.1961 in	
Valves - Valve Stem Norm Diameter - Exhaust	4.950-4.965 mm	0.1949-0.1955 in
• Valves - Valve Stem Oversize Diameter 0.075 - Intake	5.040-5.055 mm	0.1985-0.1991 in
• Valves - Valve Stem Oversize Diameter 0.075 - Exhaust	5.025-5.050 mm	0.1979-0.1989 in
Valves - Valve Stem to Guide Clearance - Intake	0.020-0.051 mm	0.0008-0.0021 in
 Valves - Valve Stem to Guide Clearance - Exhaust 	0.035-0.066 mm	0.0014-0.0026 in
• Valves - Valve Stem allowable Run-Out	0.05 mm	0.0019 in
Valves - Valve Disk Diameter - Intake	31.1-31.3 mm	1.225-1.233 in
Valves - Valve Disk Diameter - Exhaust	27.4-27.6 mm	1.079-1.087 in
Valves - Valve Seat Angle on Valve Disk	90°40' (+/-15')	
Valve Springs Longitude	42 mm	1.65 in
Valve Springs Longitude Under Load - Open	35.0 mm	1.38 in
Valve Springs Longitude Under Load - Close	25.0 mm	0.98 in
Engine Oil		
• Viscosity	SAE 0-W30, 0-W40, 5-W30 and 5-W40	
Quality	Dexos 1	
Quantity		
Oil Change Incl. Filter	4.5 1	4.76 quarts
 Oil Consumption Liter/1 000 km (1.057 quarts/621 miles) 	max. 0.6 1	max. 0.634 quarts
Cooling System		
Coolant Specification	Refer to Elec	tronic Parts Catalog
Water Pump Design	Rotary Pump	
Cooling System Capacity	5, 61	5.92 quarts
 Flow (Engine Outlet 6000 min ⁻¹, Thermostat Fully Open) 	160 l/min	42.27 US gal/min
• Flow (Radiator 6000 min ⁻¹ , Thermostat Fully Open)	165 l/min	174.4 quarts/min
Thermostat Opening - Electrical	90°C	194°F
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 3

Page 8

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

• Thermostat Opening - Thermic	105°C	221°F
--------------------------------	-------	-------

ADHESIVES, FLUIDS, LUBRICANTS, AND SEALERS

Adhesives, Fluids, Lubricants, and Sealers

. , , ,		GM Part Number		
Application	Type of Material	United States	Canada	
Bolt Connections	Screw Locking Compound	12345382	10953489	
Camshaft Bearings	Dexos1 Engine Oil	19293000	19286321	
Camshaft Front Oil Seal	Sealant	1052943	10953491	
Camshafts	Dexos1 Engine Oil	19293000	19286321	
Crankshaft Bearing Lubricant	Dexos1 Engine Oil	19293000	19286321	
Engine Block Oil Gallery Plugs	Sealant	1052943	10953491	
Engine Oil	Dexos1 Engine Oil	19293000	19286321	
Intake and Exhaust Valves	and Exhaust Valves Dexos1 Engine Oil		19286321	
Oil Pan	Sealant	12378521	88901148	
Oxygen Sensor	Assembly Paste - White	88862477	88862478	
Oxygen Sensor Threads	Anti-seize	12397953	NA	
Rear Crankshaft Main Bearing Cap	Sealant	12378521	88901148	
Rear Crankshaft Oil Seal	Dexos1 Engine Oil	19293000	19286321	
Rod Bearing - Rod Pins of Crankshaft	Dexos1 Engine Oil	19293000	19286321	
Seal Rings	Silicone Grease - White	12345579	10953481	
Turbo Heat Shield Fastener	Lubricant	12345996	10953501	
Water Pump Bearing	Sealant	1052943	10953491	

COMPONENT LOCATOR

ENGINE IDENTIFICATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:49 a. m.	Page 9	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 1: Engine Identification Code On Cylinder Block Courtesy of GENERAL MOTORS COMPANY

IMPORTANT: When a short block engine is installed, the engine number must be marked on the cylinder block before installing the engine.

The engine identification code is embossed on the flattened area of the cylinder block, arrow, at the transmission side.

DIAGNOSTIC INFORMATION AND PROCEDURES

SYMPTOMS - ENGINE MECHANICAL

Strategy Based Diagnostics

Perform the **Diagnostic System Check - Vehicle**.

All diagnosis on a vehicle should follow a logical process. Strategy based diagnostics is a uniform approach for repairing all systems. The diagnostic flow may always be used in order to resolve a system condition. The diagnostic flow is the place to start when repairs are necessary.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:49 a. m.	Page 10	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Visual/Physical Inspection

- Inspect for aftermarket devices which could affect the operation of the engine.
- Inspect the easily accessible or visible system components for obvious damage or conditions which could cause the symptom.
- Inspect for the correct oil level, proper oil viscosity, and correct filter application.
- Verify the exact operating conditions under which the concern exists. Note factors such as engine RPM, ambient temperature, engine temperature, amount of engine warm-up time, and other specifics.
- Compare the engine sounds, if applicable, to a known good engine and make sure you are not trying to correct a normal condition.

Intermittent

Test the vehicle under the same conditions that the customer reported in order to verify the system is operating properly.

Symptom List

Refer to a symptom diagnostic procedure from the following list in order to diagnose the symptom:

- Base Engine Misfire without Internal Engine Noises
- Base Engine Misfire with Abnormal Internal Lower Engine Noises
- Base Engine Misfire with Abnormal Valve Train Noise
- Base Engine Misfire with Coolant Consumption
- Base Engine Misfire with Excessive Oil Consumption
- Engine Noise on Start-Up, but Only Lasting a Few Seconds
- Upper Engine Noise, Regardless of Engine Speed
- Lower Engine Noise, Regardless of Engine Speed
- Engine Noise Under Load
- Engine Will Not Crank Crankshaft Will Not Rotate
- Coolant in Engine Oil
- Engine Compression Test
- Cylinder Leakage Test
- Oil Consumption Diagnosis
- Oil Pressure Diagnosis and Testing
- Oil Leak Diagnosis
- Crankcase Ventilation System Inspection/Diagnosis
- Drive Belt Chirping, Squeal, and Whine Diagnosis
- Drive Belt Rumbling and Vibration Diagnosis
- Drive Belt Falls Off and Excessive Wear Diagnosis
- Drive Belt Tensioner Diagnosis

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69	
viernes, 21 de abril de 2017 10:36:49 a. m.	Page 11	© 2011 Mitchell Repair Information Company, LLC.	

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

OIL PRESSURE DIAGNOSIS AND TESTING

Special Tools

- EN-498-B Oil Pressure Gauge
- EN-232 Adapter Oil Pressure Check

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

1. If necessary, remove the exhaust manifold heat shield. Refer to **Exhaust Manifold Heat Shield Replacement (LUJ)**, **Exhaust Manifold Heat Shield Replacement (LUW)**.




Fig. 2: Closure Bolt
Courtesy of GENERAL MOTORS COMPANY

- 2. Remove the closure bolt (1).
- 3. Clean the thread.

Measurement Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:49 a. m.	Page 12	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 3: Oil Pressure Test Gauge Courtesy of GENERAL MOTORS COMPANY

- 1. Install the **EN-498-B** gauge (2).
- 2. Install the EN-232 adapter (1).
- 3. Start the engine.
- 4. Check oil pressure.

At idling speed, the oil pressure must be at least 130 kPa (18.85 psi) and the oil temperature must be 80°C (170°F) or more.

Installation Procedure

- 1. Switch off the engine.
- 2. Remove the EN-232 adapter.
- 3. Remove the **EN-498-B** gauge.
- 4. Install new closure bolt in the cylinder head.

CAUTION: Refer to Fastener Caution.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:49 a. m.	Page 13	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 5. Tighten the closure bolt to 15 N.m (11 lb ft).
- 6. If necessary, install the exhaust manifold heat shield. Refer to **Exhaust Manifold Heat Shield Replacement (LUJ)**, **Exhaust Manifold Heat Shield Replacement (LUW)**.
- 7. Check the engine oil level.

viernes, 21 de abril de 2017 10:36:49 a.m.

OIL LEAK DIAGNOSIS

Oil Leak Diagnosis

Step	Action	Yes	No	
the compon	ON: You can repair most fluid leaks by first, visually locating the ent, or by resealing the gasket surface. Once the leak is identified the leak and the cause of the leak.			
1	 Operate the vehicle until it reaches normal operating temperature. Refer to Engine Mechanical Specifications. Park the vehicle on a level surface over a large sheet of paper or other clean surface. Wait 15 minutes. Inspect for drippings. Are drippings present?	Go to Step 2	System OK	
	Can you identify the type of fluid and the approximate	Go to Step 2	System OK	
2	location of the leak?	10	Go to Step 3	
3	 Visually inspect the suspected area. Use a small mirror to assist in looking at hard to see areas. Inspect for leaks at the following locations: Sealing surfaces Fittings Cracked or damaged components Can you identify the type of fluid and the approximate location of the leak? 	Go to Step	Go to Step 4	
4	 Completely clean the entire engine and surrounding components. Operate the vehicle for several miles at normal operating temperature and at varying speeds. Park the vehicle on a level surface over a large sheet of paper or other clean surface. Wait 15 minutes. Identify the type of fluid and the approximate location of the leak. 			
Afinacion de	e Motor y Diagnostico,OBDII,VW,Audi		044 664 252	34 69

Page 14

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

	Can you identify the type of fluid and the approximate location of the leak?	Go to Step 10	Go to Step 5
5	 Visually inspect the suspected area. Use a small mirror to assist in looking at hard to see areas. Inspect for leaks at the following locations: Sealing surfaces Fittings Cracked or damaged components 		
	Can you identify the type of fluid and the approximate location of the leak?	Go to Step 10	Go to Step 6
6	 Completely clean the entire engine and surrounding components. Apply an aerosol-type powder, for example, baby powder or foot powder, to the suspected area. Operate the vehicle for several miles at normal operating temperature and at varying speeds. Identify the type of fluid and the approximate location of the leak from the discolorations in the powder surface. 		
	Can you identify the type of fluid and the approximate location of the leak?	Go to Step 10	Go to Step 7
7	 Visually inspect the suspected area. Use a small mirror to assist in looking at hard to see areas. Inspect for leaks at the following locations: Sealing surfaces Fittings Cracked or damaged components Can you identify the type of fluid and the approximate location of the leak? 	Go to Step	Go to Step 8
8	Identify the type of fluid and the approximate location of the leak. Can you identify the type of fluid and the approximate location of the leak?	Go to Step	Go to Step 9
9	 Visually inspect the suspected area. Use a small mirror to assist in looking at hard to see areas. Inspect for leaks at the following locations: Sealing surfaces Fittings 		

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 15	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

	Cracked or damaged components		
	Can you identify the type of fluid and the approximate location of the leak?	Go to Step	System OK
	Inspect the engine for mechanical damage. Special interest should be shown to the following areas:		
	Higher than recommended fluid levels		
	Higher than recommended fluid pressures		
	 Plugged or malfunctioning fluid filters or pressure bypass valves 		
	 Plugged or malfunctioning engine ventilation system 		
10	Improperly tightened or damaged fasteners		
10	 Cracked or porous components 		
	 Improper sealants or gaskets, where required 		
	 Improper sealant or gasket installation 		
	 Damaged or worn gaskets or seals 		
	 Damaged or worn sealing surfaces 		
	2. Inspect the engine for customer modifications.		
	Is there mechanical damage or customer modifications to the engine?	Go to Step	System OK
11	Repair or replace all damaged or modified components. Did you complete the repair?	Go to Step 1	-

OIL CONSUMPTION DIAGNOSIS

Excessive oil consumption, not due to leaks, is the use of 0.6 L (0.14 gallon) engine oil within 1000 kilometers (622 miles). The causes of excessive oil consumption include the following conditions:

• External oil leaks

Tighten bolts and/or replace gaskets and oil seals as necessary.

• Incorrect oil level or improper reading of oil level indicator

With the vehicle on a level surface, allow adequate drain down time and inspect for the correct oil level.

• Improper oil viscosity

Use recommended SAE viscosity for the prevailing temperatures.

• Continuous high speed driving and/or severe usage

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- Crankcase ventilation system restrictions or malfunctioning components
- Valve guides and/or valve stem oil seals worn, or the seal omitted

Ream guides and install oversize service valves and/or new valve stem oil seals.

• Piston rings broken, improperly installed, worn, or not seated properly

Allow adequate time for rings to seat. Replace broken or worn rings, as necessary.

• Piston improperly installed or mis-fitted.

COOLANT IN COMBUSTION CHAMBER

Coolant in Combustion Chamber

Cause	Correction
DEFINITION: Excessive white smoke and/or coolan	t type odor coming from the exhaust pipe may
indicate coolant in the combustion chamber. Low co	olant levels, an inoperative cooling fan, or a faulty
thermostat may lead to an overtemperature condition	which may cause engine component damage.

- 1. A slower than normal cranking speed may indicate coolant entering the combustion chamber. Refer to **Engine Will Not Crank Crankshaft Will Not Rotate**.
- 2. Remove the spark plugs and inspect for spark plugs saturated by coolant or coolant in the cylinder bore.
- 3. Inspect by performing a cylinder leak-down test. During this test, excessive air bubbles within the coolant may indicate a faulty gasket or damaged component.
- 4. Inspect by performing a cylinder compression test. Two cylinders side-by-side on the engine block, with low compression, may indicate a failed cylinder head gasket. Refer to **Engine Compression Test**.

Faulty cylinder head gasket	Replace the head gasket and components as
	required. Refer to Cylinder Head Cleaning and
	Inspection, and Cylinder Head Replacement.
Warped cylinder head	Replace the cylinder head and gasket. Refer to
	Cylinder Head Replacement.
Cracked cylinder head	Replace the cylinder head and gasket. Cylinder
	Head Replacement
Cracked cylinder liner	Replace the components as required.
Cylinder head or block porosity	Replace the components as required.

COOLANT IN ENGINE OIL

Cause

Coolant in Engine Oil

Cause		Correction	
DEFINITION: Foamy or discolored oil or an engine the engine crankcase. Low coolant levels, an inoper		,	
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252	34 69
viernes, 21 de abril de 2017 10:36:50 a. m.	Page 17	© 2011 Mitchell Repair Information Company	, LLC.

Correction

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

an overtemperature condition which may cause engine component damage. Contaminated engine oil and oil filter should be changed.

- 1. Inspect the oil for excessive foaming or an overfill condition. Oil diluted by coolant may not properly lubricate the crankshaft bearings and may lead to component damage. Refer to <u>Lower Engine Noise</u>, <u>Regardless of Engine Speed</u>.
- 2. Inspect by performing a cylinder leak-down test. During this test, excessive air bubbles within the cooling system may indicate a faulty gasket or damaged component.
- 3. Inspect by performing a cylinder compression test. Two cylinders side-by-side on the engine block with low compression may indicate a failed cylinder head gasket. Refer to **Engine Compression**Test.

Faulty cylinder head gasket	Replace the head gasket and components as required. Refer to Cylinder Head Replacement .
Warped cylinder head	Replace the cylinder head and gasket. Refer to Cylinder Head Replacement.
Cracked cylinder head	Replace the cylinder head and gasket. Cylinder Head Replacement
Cracked cylinder liner	Replace the components as required.
Cylinder head or block porosity	Replace the components as required.

ENGINE NOISE UNDER LOAD

Engine Noise Under Load

Cause	Correction
Low oil pressure	 Perform an oil pressure test. Refer to <u>Oil</u> <u>Pressure Diagnosis and Testing</u>.
	2. Repair or replace as required.
Detonation or spark knock	Verify the correct operation of the ignition. Refer to Symptoms - Engine Controls .
Loose torque converter bolts	 Inspect the torque converter bolts and flywheel. Repair as required.
Cracked flywheel- automatic transmission	 Inspect the flywheel bolts and flywheel. Repair as required.
Excessive connecting rod bearing clearance	Inspect the following components and repair as required:
	The connecting rod bearings
	 The connecting rods
	The crankshaft
Excessive crankshaft bearing clearance	Inspect the following components and repair as required:

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 18	© 2011 Mitchell Repair Information Company, LLC.

2012 Chevrolet Cruze LS
2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

The crankshaft bearings
 The crankshaft journals
 The cylinder block crankshaft bearing bore

ENGINE NOISE ON START-UP, BUT ONLY LASTING A FEW SECONDS

Engine Noise on Start-Up, but Only Lasting a Few Seconds

Cause	Correction
Incorrect oil filter without anti-drainback feature	Install the correct oil filter.
Incorrect oil viscosity	1. Drain the oil.
	2. Install the correct viscosity oil.
High valve lash adjuster leak down rate	Replace the lash adjusters as required.
Worn crankshaft thrust bearing	Inspect the thrust bearing and crankshaft.
	2. Repair or replace as required.
Damaged or faulty oil filter by-pass valve	Inspect the oil filter by-pass valve for proper operation.
	2. Repair or replace as required.
Malfunctioning camshaft position actuators -	1. Verify correct engine oil viscosity by changing the engine oil and filter. Reevaluate the concern.
improper oil viscosity or contamination. The result is camshaft actuator locking pin does not lock	2. Isolate the noise to a specific camshaft position actuator.
	3. Replace the camshaft actuator, oil and filter.

BASE ENGINE MISFIRE WITHOUT INTERNAL ENGINE NOISES

Base Engine Misfire without Internal Engine Noises

Cause	Correction
Abnormalities, severe cracking, bumps, or missing areas in the accessory drive belt Abnormalities in the accessory drive system and/or components may cause engine revolutions per minute (RPM) variations and lead to a misfire diagnostic trouble code (DTC). A misfire code may be present without an actual misfire condition.	Replace the drive belt.
Worn, damaged, or mis-aligned accessory drive components or excessive pulley runout may lead to a misfire DTC. A misfire code may be present without an actual misfir condition.	Inspect the components, and repair or replace as required.
A loose or improperly installed engine flywheel or crankshaft balancer A misfire code may be present without an actual misfire	Repair or replace the flywheel and/or balancer as required.
Afinacion de Motor y Diagnostico,OBDII,VW,Audi	044 664 252 3
viernes 21 de abril de 2017 10:36:50 a m	oge 19 © 2011 Mitchell Repair Information Company

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

condition.	1
Restricted exhaust system A severe restriction in the exhaust flow can cause significant loss of engine performance and may set a DTC. Possible causes of restrictions include collapsed or dented pipes or plugged mufflers and/or catalytic converters.	Repair or replace as required.
Improperly installed or damaged vacuum hoses	Repair or replace as required.
Improper sealing between the intake manifold and cylinder heads or throttle body	Replace the intake manifold, gaskets, cylinder heads, and/or throttle body as required.
Improperly installed or damaged manifold absolute pressure (MAP) sensor The sealing grommet of the MAP sensor should not be torn or damaged.	Repair or replace the MAP sensor as required.
Damage to the MAP sensor housing	Replace the intake manifold.
Worn or loose rocker arms The rocker arm bearing end caps and/or needle bearings should be intact and in the proper position.	Replace the valve rocker arms as required.
Stuck valves Carbon buildup on the valve stem can cause the valve not to close properly.	Repair or replace as required.
Excessively worn or mis-aligned timing chain	Replace the timing chain and sprockets as required.
Worn camshaft lobes	Replace the camshaft and valve lifters.
Excessive oil pressure A lubrication system with excessive oil pressure may lead to excessive valve lifter pump up and loss of compression.	 Perform an oil pressure test. Refer to <u>Oil</u> <u>Pressure Diagnosis and Testing</u>. Repair or replace the oil pump as required.
Faulty cylinder head gaskets and/or cracking or other damage to the cylinder heads and engine block cooling system passages Coolant consumption may or may not cause the engine to overheat.	 Inspect for spark plugs saturated by coolant. Inspect the cylinder heads, engine block, and/or head gaskets. Repair or replace as required.
Worn piston rings Oil consumption may or may not cause the engine to misfire.	 Inspect the spark plugs for oil deposits. Inspect the cylinders for a loss of compression. Refer to Engine Compression Test. Perform cylinder leak down and compression testing to identify the cause. Repair or replace as required.
A damaged crankshaft reluctor wheel A damaged crankshaft reluctor wheel can result in different symptoms depending on the severity and	Replace the sensor and/or crankshaft as required.
Afinacion de Motor y Diagnostico,OBDII,VW,Audi	044 664 252 34
viernes, 21 de abril de 2017 10:36:50 a.m. Pag	e 20 © 2011 Mitchell Repair Information Company, Ll

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

location of the damage.

- Systems with electronic communications, DIS or coil per cylinder, and severe reluctor ring damage may exhibit periodic loss of crankshaft position, stop delivering a signal, and then re-sync the crankshaft position.
- Systems with electronic communication, DIS or coil per cylinder, and slight reluctor ring damage may exhibit no loss of crankshaft position and no misfire may occur. However, a DTC P0300 may be set.
- Systems with mechanical communications, high voltage switch, and severe reluctor ring damage may cause additional pulses and effect fuel and spark delivery to the point of generating a DTC P0300 or P0336.

BASE ENGINE MISFIRE WITH ABNORMAL INTERNAL LOWER ENGINE NOISES

Base Engine Misfire with Abnormal Internal Lower Engine Noises		
Cause	Correction	
Abnormalities, severe cracking, bumps or missing areas in the accessory drive belt Abnormalities in the accessory drive system and/or components may cause engine revolutions per minute (RPM) variations, noises similar to a faulty lower engine, and also lead to a misfire condition. A misfire code may be present without an actual misfire condition.	Replace the drive belt.	
Worn, damaged, or mis-aligned accessory drive components or excessive pulley runout A misfire code may be present without an actual misfire condition.	Inspect the components, repair or replace as required.	
Loose or improperly installed engine flywheel or crankshaft balancer A misfire code may be present without an actual misfire condition.	Repair or replace the flywheel and/or balancer as required.	
Worn piston rings Oil consumption may or may not cause the engine to misfire.	 Inspect the spark plugs for oil deposits. Inspect the cylinders for a loss of compression. Refer to Engine Compression Test. Perform cylinder leak down and compression testing to determine the cause. Repair or replace as required. 	
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 21 © 2011 Mitchell Repair Information Company, LLC	

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Worn crankshaft thrust bearings	Replace the crankshaft and bearings as required.	
Severely worn thrust surfaces on the		
crankshaft and/or thrust bearing may permit		
fore and aft movement of the crankshaft, and		
create a diagnostic trouble code (DTC)		
without an actual misfire condition.		

BASE ENGINE MISFIRE WITH ABNORMAL VALVE TRAIN NOISE

Base Engine Misfire with Abnormal Valve Train Noise

Cause	Correction
Worn or loose rocker arms The rocker arm bearing end caps and/or needle bearings should intact within the rocker arm assembly.	Replace the valve rocker arms as required.
Stuck valves Carbon buildup on the valve stem can cause the valve to not close properly.	Repair or replace as required.
Excessively worn or mis-aligned timing chain	Replace the timing chain and sprockets as required.
Worn camshaft lobes	Replace the camshaft and valve lash adjusters.
Sticking lifters	Replace as required.

BASE ENGINE MISFIRE WITH COOLANT CONSUMPTION

Base Engine Misfire with Coolant Consumption

Cause	Correction
Faulty cylinder head gasket and/or cracking, or other damage to the cylinder head and engine block cooling system passages. Coolant consumption may or may not cause the engine to overheat.	 Inspect for spark plugs saturated by coolant. Perform a cylinder leak down test. Inspect the cylinder head and engine block for damage to the coolant passages and/or a faulty head gasket. Repair or replace as required.

BASE ENGINE MISFIRE WITH EXCESSIVE OIL CONSUMPTION

Base Engine Misfire with Excessive Oil Consumption

Cause	Correction
Worn valves, valve guides, and/or valve stem oil seals	Inspect the spark plugs for oil deposits.Repair or replace as required.
Worn piston rings Oil consumption may or may not cause the engine to misfire.	 Inspect the spark plugs for oil deposits. Inspect the cylinders for a loss of compression. Refer to <u>Engine Compression Test</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a. m.	Page 22	© 2011 Mitchell Repair Information Company, LLC.

2012 Chevrolet Cruze LS	
2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze	

 Perform cylinder leak down and compression testing to determine the cause.
Repair or replace as required.

UPPER ENGINE NOISE, REGARDLESS OF ENGINE SPEED

Upper Engine Noise, Regardless of Engine Speed

Cause	Correction
Low oil pressure	Perform an oil pressure test. Refer to Oil Pressure Diagnosis and Testing.
	Repair or replace as required.
Loose and/or worn valve rocker arm attachments	• Inspect the valve rocker arm stud, nut, or bolt.
	Repair or replace as required.
Worn valve rocker arm	Replace the valve rocker arm.
Improper lubrication to the valve rocker arms	Inspect the following components and repair or replace as required:
	The valve rocker arm
	The valve lifter
	The oil filter bypass valve
	The oil pump and pump screen
	The engine block oil galleries
Broken valve spring	Replace the valve spring.
Worn or dirty valve lifters	Replace the valve lifters.
Stretched or broken timing belt and/or damaged sprocket teeth	Replace the timing belt and sprockets.
Worn, damaged, or faulty timing belt tensioners	Replace tensioners
Worn engine camshaft lobes	• Inspect the engine camshaft lobes.
	 Replace the camshaft and valve lifters as required.
Worn valve guides or valve stems	Inspect the following components, and repair as required:
	• The valves
	The valve guides
Stuck valves Carbon on the valve stem or valve seat may cause the valve to stay open.	Inspect the following components and repair as required:
	• The valves
	The valve guides

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 23	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

LOWER ENGINE NOISE, REGARDLESS OF ENGINE SPEED

Lower Engine Noise, Regardless of Engine Speed

viernes, 21 de abril de 2017 10:36:50 a.m.

Cause	Correction
Low oil pressure	Perform an oil pressure test. Refer to Oil Pressure Diagnosis and Testing.
	 Repair or replace damaged components as required.
Worn accessory drive components- abnormalities, such as severe cracking, bumps,	1. Inspect the accessory drive system.
or missing areas in the accessory drive belt and/or misalignment of system components	2. Repair or replace as required.
Loose or damaged crankshaft balancer	 Inspect the crankshaft balancer. Repair or replace as required.
Detonation or spark knock	Verify the correct operation of the ignition system. Refer to Symptoms - Engine Controls .
Loose torque converter bolts	 Inspect the torque converter bolts and flywheel. Repair or replace as required.
Loose or damaged flywheel	Repair or replace the flywheel.
Damaged oil pan, contacting the oil pump screen An oil pan that has been damaged, may improperly position the oil pump screen, preventing proper oil flow to the oil pump.	 Inspect the oil pan. Inspect the oil pump screen. Repair or replace as required.
Oil pump screen loose, damaged or restricted	 Inspect the oil pump screen. Repair or replace as required.
Excessive piston-to-cylinder bore clearance	 Inspect the piston and cylinder bore. Repair as required.
Excessive piston pin-to-bore clearance	 Inspect the piston, piston pin, and the connecting rod. Repair or replace as required.
Excessive connecting rod bearing clearance	Inspect the following components and repair as required:
	 The connecting rod bearings The connecting rods
	 The crankshaft The crankshaft journals
Excessive crankshaft bearing clearance	Inspect the following components and repair as required:

Page 24

© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

	 The crankshaft bearings The crankshaft journals
Incorrect piston, piston pin, and connecting rod installation Pistons must be installed with the mark, or dimple, on the top of the piston, facing the front of the engine. Piston pins must be centered in the connecting rod pin bore.	 Verify the pistons, piston pins and connecting rods are installed correctly. Repair as required.

ENGINE WILL NOT CRANK - CRANKSHAFT WILL NOT ROTATE

Engine Will Not Crank - Crankshaft Will Not Rotate

Cause	Correction
Seized accessory drive system component	1. Remove accessory drive belts.
	2. Rotate crankshaft by hand at the balancer or flywheel location.
 Hydraulically locked cylinder Coolant/antifreeze in cylinder Oil in cylinder Fuel in cylinder 	 Remove spark plugs and check for fluid. Inspect for broken head gasket. Inspect for cracked engine block or cylinder head. Inspect for a sticking fuel injector.
	5. Inspect for cracked cylinder wall.
Seized automatic transmission torque converter	 Remove the torque converter bolts. Rotate crankshaft by hand at the balancer or flywheel location.
Seized manual transmission	 Disengage the clutch. Rotate crankshaft by hand at the balancer or flywheel location.
Broken timing chain and/or gears	Inspect timing chain and gears.Repair as required.
Seized balance shaft	Inspect balance shaft.Repair as required.
 Material in cylinder Broken valve Piston material Foreign material Cracked cylinder wall 	 Inspect cylinder for damaged components and/or foreign materials. Inspect for fallen cylinder wall. Repair or replace as required.
Seized crankshaft or connecting rod bearings	
After a size of Materia Dispute a time CDDU VAV A sali	

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 25	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

	Inspect crankshaft and connecting rod bearings.
	Inspect for fallen cylinder wall.
	Repair as required.
Bent or broken connecting rod	Inspect connecting rods.
	Repair as required.
Broken crankshaft	Inspect crankshaft.
	Repair as required.

ENGINE COMPRESSION TEST

Removal Procedure

- 1. Remove the throttle body. Refer to **Throttle Body Assembly Replacement**.
- 2. Remove the spark plugs. Refer to **Spark Plug Replacement**.
- 3. Remove the relay holder cover.
- 4. Remove the fuel pump relay.

Measurement Procedure

Check Compression for all cylinders:

NOTE: Engine revs at least 300/min.

- 1. Start the engine (approx. 4 seconds).
- 2. Compare the compression values.

Maximum pressure differential 100 kPa (14.5 psi)

Installation Procedure

- 1. Install the fuel pump relay.
 - Place into the socket.
 - Ensure the plug contacts are sound.
- 2. Install the relay carrier cover.
- 3. Install the spark plugs. Refer to **Spark Plug Replacement**.
- 4. Install the throttle body. Refer to **Throttle Body Assembly Replacement**.

DRIVE BELT CHIRPING, SQUEAL, AND WHINE DIAGNOSIS

Diagnostic Aids

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a. m.	Page 26	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- A chirping or squeal noise may be intermittent due to moisture on the drive belts or the pulleys. It may be necessary to spray a small amount of water on the drive belts in order to duplicate the customers concern. If spraying water on the drive belt duplicates the symptom, cleaning the belt pulleys may be the probable solution.
- If the noise is intermittent, verify the accessory drive components by varying their loads making sure they are operated to their maximum capacity. An overcharged A/C system, power steering system with a pinched hose or wrong fluid, or a generator failing are suggested items to inspect.
- A chirping, squeal or whine noise may be caused by a loose or improper installation of a body or suspension component. Other items of the vehicle may also cause the noise.
- The drive belts will not cause a whine noise.

Test Description

The numbers below refer to the step numbers on the diagnostic table.

2

The noise may not be engine related. This step is to verify that the engine is making the noise. If the engine is not making the noise do not proceed further with this table.

3

The noise may be an internal engine noise. Removing the drive belts one at a time and operating the engine for a brief period will verify the noise is related to the drive belt. When removing the drive belt the water pump may not be operating and the engine may overheat. Also DTCs may set when the engine is operating with the drive belts removed.

4

Inspect all drive belt pulleys for pilling. Pilling is the small balls or pills or it can be strings in the drive belt grooves from the accumulation of rubber dust.

6

Misalignment of the pulleys may be caused from improper mounting of the accessory drive component, incorrect installation of the accessory drive component pulley, or the pulley bent inward or outward from a previous repair. Test for a misaligned pulley using a straight edge in the pulley grooves across two or three pulleys. If a misaligned pulley is found refer to that accessory drive component for the proper installation procedure for that pulley.

10

Inspecting of the fasteners can eliminate the possibility that a wrong bolt, nut, spacer, or washer was installed.

12

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 2	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Inspecting the pulleys for being bent should include inspecting for a dent or other damage to the pulleys that would prevent the drive belt from not seating properly in all of the pulley grooves or on the smooth surface of a pulley when the back side of the belt is used to drive the pulley.

14

This test is to verify that the drive belt tensioner operates properly. If the drive belt tensioner is not operating properly, proper belt tension may not be achieved to keep the drive belt from slipping which could cause a squeal noise.

15

This test is to verify that the drive belt is not too long, which would prevent the drive belt tensioner from working properly. Also if an incorrect length drive belt was installed, it may not be routed properly and may be turning an accessory drive component in the wrong direction.

16

Misalignment of the pulleys may be caused from improper mounting of the accessory drive component, incorrect installation of the accessory drive component pulley, or the pulley bent inward or outward from a previous repair. Test for a misaligned pulley using a straight edge in the pulley grooves across two or three pulleys. If a misaligned pulley is found refer to that accessory drive component for the proper installation procedure for that pulley.

17

This test is to verify that the pulleys are the correct diameter or width. Using a known good vehicle compare the pulley sizes.

19

Replacing the drive belt when it is not damaged or there is not excessive pilling will only be a temporary repair.

Drive Belt Chirping, Squeal, and Whine Diagnosis

Step	Action	Yes	No
CAUTION:			
Refer to E	Belt Dressing Caution .		

DEFINITION: The following items are indications of chirping:

- A high pitched noise that is heard once per revolution of the drive belt or a pulley.
- Chirping may occur on cold damp start-ups and will subside once the vehicle reaches normal operating temp.

DEFINITION: The following items are indications of drive belt squeal:

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 28	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- A loud screeching noise that is caused by a slipping drive belt. This is unusual for a drive belt with multiple ribs.
- The noise occurs when a heavy load is applied to the drive belt, such as an air conditioning compressor engagement snapping the throttle, or slipping on a seized pulley or a faulty accessory drive component.

DEFINITION: The following items are indications of drive belt whine:

- A high pitched continuous noise.
- The noise may be caused by an accessory drive component failed bearing.

1	Did you review the Drive Belt Symptom operation and perform the necessary		Go to Symptoms -
	inspections?	Go to Step 2	Engine Mechanical
2	Verify that there is a chirping, squeal or whine noise. Does the engine make the chirping squeal or whine noise?	Go to Step 3	Go to Diagnostic Aids above.
	1. Remove the drive belt.		
	If the engine has multiple drive belts, remove the belts one at a time and perform the test below each time a belt is removed.		
3	2. Operate the engine for no longer than 30-40 seconds.		
	3. Repeat this test if necessary by removing the remaining belt(s).		
	Does the chirping, squeal or whine noise still exist?	Go to Symptoms - Engine Mechanical	Go to Step 4
4	If diagnosing a chirping noise, inspect for severe pilling exceeding 1/3 of the belt groove depth. If diagnosing a squeal or whine noise, proceed to step 13.		
	Do the belt grooves have pilling?	Go to Step 5	Go to Step 6
5	Clean the drive belt pulleys with a suitable wire brush.	C . 4 . C . 20	C. A. St. C
	Did you complete the repair?	Go to Step 20	Go to Step 6
6	Inspect for misalignment of the pulleys. Are any of the pulleys misaligned?	Go to Step 7	Go to Step 8
7	Replace or repair any misaligned pulleys. Did you complete the repair?	Go to Step 20	Go to Step 8

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 29	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

8	Inspect for bent or cracked brackets.		
0	Did you find any bent or cracked brackets?	Go to Step 9	Go to Step 10
9	Replace any bent or cracked brackets.		
9	Did you complete the repair?	Go to Step 20	Go to Step 10
	Inspect for improper, loose or missing		
10	fasteners.		
	Did you find the condition?	Go to Step 11	Go to Step 12
	CAUTION:		
	Refer to Fastener Caution .		
	1. Tighten any loose fasteners. Refer to		
11	Fastener Tightening Specifications.		
	2. Replace any improper or missing		
	fasteners.		
	Did you complete the repair?	Go to Step 20	Go to Step 12
12	Inspect for a bent pulley.		
12	Did you find the condition?	Go to Step 18	Go to Step 19
	Inspect for an accessory drive component		
	seized bearing or a faulty accessory drive		
	component.		
13	If diagnosing a whine noise and the		
	condition still exist, proceed to Diagnostic Aids.		
	Did you find and correct the condition?	Go to Step 20	Go to Step 14
	Test the drive belt tensioner for proper	00 to 5tcp 20	Об 16 Биер 14
	operation. Refer to Drive Belt Tensioner		
14	Diagnosis.		
	Did you find and correct the condition?	Go to Step 20	Go to Step 15
4-	Inspect for the correct drive belt length.	1	1
15	Did you find and correct the condition?	Go to Step 20	Go to Step 16
17	Inspect for misalignment of a pulley.	*	•
16	Did you find and correct the condition?	Go to Step 20	Go to Step 17
17	Inspect for the correct pulley size.		
	Did you find and correct the condition?	Go to Step 20	Go to Diagnostic Aids
18	Replace the bent pulley.		
10	Did you complete the repair?	Go to Step 20	Go to Step 19
	Replace the drive belt. Refer to Drive Belt		
19	Replacement.	G . G: •	Go to Diagnostic Aids
	Did you complete the repair?	Go to Step 20	above.
2.0	Operate the system in order to verify the		
20	repair.	Courts OV	C + 5 C + 2
	Did you correct the condition?	System OK	Go to Step 3

DRIVE BELT RUMBLING AND VIBRATION DIAGNOSIS

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 30	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Diagnostic Aids

The accessory drive components can have an affect on engine vibration. Vibration from the engine operating may cause a body component or another part of the vehicle to make rumbling noise. Vibration can be caused by, but not limited to the A/C system over charged, the power steering system restricted or the incorrect fluid, or an extra load on the generator. To help identify an intermittent or an improper condition, vary the loads on the accessory drive components.

The drive belt may have a rumbling condition that can not be seen or felt. Sometimes replacing the drive belt may be the only repair for the symptom.

If replacing the drive belt, completing the diagnostic table, and the noise is only heard when the drive belts are installed, there might be an accessory drive component with a failure. Varying the load on the different accessory drive components may aid in identifying which component is causing the rumbling noise.

Test Description

The numbers below refer to the step numbers on the diagnostic table.

2

This test is to verify that the symptom is present during diagnosing. Other vehicle components may cause a similar symptom.

3

This test is to verify that one of the drive belts is causing the rumbling noise or vibration. Rumbling noise may be confused with an internal engine noise due to the similarity in the description. Remove only one drive belt at a time if the vehicle has multiple drive belts. When removing the drive belts the water pump may not be operating and the engine may overheat. Also DTCs may set when the engine is operating with the drive belts removed.

4

Inspecting the drive belts is to ensure that they are not causing the noise. Small cracks across the ribs of the drive belt will not cause the noise. Belt separation is identified by the plys of the belt separating and may be seen at the edge of the belt or felt as a lump in the belt.

5

Small amounts of pilling is normal condition and acceptable. When the pilling is severe the drive belt does not have a smooth surface for proper operation.

9

Inspecting of the fasteners can eliminate the possibility that the wrong bolt, nut, spacer, or washer was installed.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 31	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

11

This step should only be performed if the water pump is driven by the drive belt. Inspect the water pump shaft for being bent. Also inspect the water pump bearings for smooth operation and excessive play. Compare the water pump with a known good water pump.

12

Accessory drive component brackets that are bent, cracked, or loose may put extra strain on that accessory component causing it to vibrate.

Step	Action	Yes	No
CAUTIO	N:		
Refer to	Belt Dressing Caution .		
DEFINIT	ION: The following items are indications of c	drive belt rumbling:	
• A1	ow pitch tapping, knocking, or thumping nois	e heard at or just above	e idle.
• He	ard once per revolution of the drive belt or a p	oulley.	
• Ru	mbling may be caused from:	•	
	 Pilling, the accumulation of rubber dust the belt pulley groove 	at forms small balls (pi	ills) or strings in the drive
	o The separation of the drive belt		
	o A damaged drive belt		
	o A worn drive belt idler pulley		
DEFINIT	ION: The following items are indications of c	drive belt vibration:	
• The	e vibration is engine-speed related.		
• The	e vibration may be sensitive to accessory load		
	Did you review the Drive Belt Symptom		
1	operation and perform the necessary	Carta Star 2	Go to Symptoms -
	inspections?	Go to Step 2	Engine Mechanical
_	Verify that there is a rumbling noise or that the vibration is engine related.		
2	Does the engine make the rumbling noise		Go to Diagnostic Aids
	or vibration?	Go to Step 3	above.
	1. Remove the drive belt.		

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 32	© 2011 Mitchell Repair Information Company, LLC.

If the engine has multiple drive belts, remove the belts one at a time and perform the test below each time a

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

	belt is removed.		
,	2. Operate the engine for no longer than 30-40 seconds.		
3	3. Repeat this test if necessary by removing the remaining belt(s).		
	Does the rumbling or vibration still exist?	Go to <u>Symptoms -</u> Engine Mechanical	Go to Step 4
4	Inspect the drive belts for wear, damage, separation, sections of missing ribs, and debris build-up.		-
	Did you find any of these conditions? Inspect for severe pilling of more than 1/3	Go to Step 7	Go to Step 5
5	of the drive belt pulley grooves. Did you find severe pilling?	Go to Step 6	Go to Step 7
	1. Clean the drive belt pulleys using a suitable wire brush.		
6	 Reinstall the drive belts. Refer to <u>Drive Belt Replacement</u>. 		
	Did you correct the condition?	Go to Step 8	Go to Step 7
7	Install a new drive belt. Refer to Drive Belt	-	-
7	Replacement. Did you complete the replacement?	Go to Step 8	Go to Step 9
8	Operate the system in order to verify the repair.		
0	Did you correct the condition?	System OK	Go to Step 9
9	Inspect for improper, loose or missing fasteners.		
	Did you find any of these conditions?	Go to Step 10	Go to Step 11
	CAUTION: Refer to <u>Fastener Caution</u> .		
10	 Tighten any loose fasteners. Refer to <u>Fastener Tightening Specifications</u>. Replace improper or missing fasteners. 		
	Did you complete the repair?	Go to Step 13	Go to Step 11
11	Inspect for a bent water pump shaft. Refer to Water Pump Replacement (LUW), Water Pump Replacement (LUJ).	_	-
	Did you find and correct the condition?	Go to Step 13	Go to Step 12
12	Inspect for bent or cracked brackets.		

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 33	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

	Did you find and correct the condition?	Go to Step 13	Go to Diagnostic Aids
12	Operate the system in order to verify the		
13	repair. Did you correct the condition?	System OK	Go to Step 3

CYLINDER LEAKAGE TEST

Removal Procedure

- 1. Open the hood.
- 2. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.
- 3. Remove the right front wheelhouse liner. Refer to Front Wheelhouse Liner Replacement
- 4. Lower the vehicle.
- 5. Remove the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Removal**.
- 6. Remove the spark plugs. Refer to **Spark Plug Replacement**.
- 7. Detach the engine wiring harness from intake manifold, cylinder head cover and engine wiring harness bracket.
- 8. Remove the coolant expansion tank closure cap.
- 9. Remove the oil dipstick.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 34	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 4: Crankshaft TDC Position
Courtesy of GENERAL MOTORS COMPANY

- 10. Set up the crankshaft.
- 11. Move the crankshaft in the direction of the engine rotation to the first cylinder TDC position (mark 1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 35	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 5: Guidance Marks
Courtesy of GENERAL MOTORS COMPANY

- 12. Apply guidance marks.
- 13. Attach 3 markings (2) as an aid to one of the camshaft adjusters, each one offset by 90° to the marking applied (1).

Test Procedure

NOTE: Follow manufacturer instructions.

1. Calibrate the pressure loss tester and connect to the compressed air system.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 36	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 6: Pressure Loss Tester</u> Courtesy of GENERAL MOTORS COMPANY

2. Install the pressure loss tester.

NOTE: Wheels must be in contact with the ground.

- Engage first gear and apply the parking brake.
- Install the connecting piece into the spark plug thread of cylinder number 1.
- Apply compressed air to cylinder number 1.
- 3. Inspect for Pressure Loss
 - Take pressure loss reading.
 - The maximum permissible pressure differential between cylinders is approximately 10 percent.
 - o Maximum pressure loss of a cylinder is 25 percent.
 - Take note of any visible escape of compressed air.

Intake manifold, exhaust manifold, crankcase

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 37	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- Take note of any bubble formation in the coolant compensation tank.
- 4. Perform pressure loss test by analogy on cylinders 3, 4 and 2.

Installation Procedure

- 1. Remove the pressure loss tester.
- 2. Remove the connection piece from the spark plug thread.
- 3. Put the vehicle in neutral.
- 4. Insert the oil dipstick.
- 5. Install the coolant expansion tank closure cap.
- 6. Install the spark plugs. Refer to **Spark Plug Replacement**.
- 7. Install the engine wiring harness to the intake manifold.
- 8. Install the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Installation**.
- 9. Raise and support the vehicle.
- 10. Install the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**
- 11. Lower the vehicle.
- 12. Close the hood.

CRANKCASE VENTILATION SYSTEM INSPECTION/DIAGNOSIS

Results of Incorrect Operation

A plugged positive crankcase ventilation (PCV) orifice or hose may cause the following conditions:

- Rough idle
- Stalling or slow idle speed
- Oil leaks
- Oil in the throttle body
- Sludge in the engine

Functional Check

With these systems, any blow-by in excess of the system capacity, from a badly worn engine, sustained heavy load, etc., is exhausted into the throttle body and is drawn into the engine.

Proper operation of the crankcase ventilation system depends upon a sealed engine. If oil slugging or dilution is noted and the crankcase ventilation system is functioning properly, check the engine for a possible cause. Correct any problems.

If an engine is idling rough, inspect for a clogged PCV orifice, a dirty vent filter, air cleaner element, or plugged hose. Replace as required. Use the following procedure:

1. Remove the PCV hose from the cylinder head cover.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi			044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page	38	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 2. Operate the engine at idle.
- 3. Place your thumb over the end of the hose in order to check for a vacuum. If there is no vacuum at the hose, inspect for the following items:
 - Plugged hoses
 - The manifold port
- 4. Turn OFF the engine.
- 5. Inspect the PCV orifice in the cylinder head cover for debris or blockage.

DRIVE BELT FALLS OFF AND EXCESSIVE WEAR DIAGNOSIS

Diagnostic Aids

If the drive belt repeatedly falls off the drive belt pulleys, this is because of pulley misalignment.

An extra load that is quickly applied on released by an accessory drive component may cause the drive belt to fall off the pulleys. Verify the accessory drive components operate properly.

If the drive belt is the incorrect length, the drive belt tensioner may not keep the proper tension on the drive belt.

Excessive wear on a drive belt is usually caused by an incorrect installation or the wrong drive belt for the application.

Minor misalignment of the drive belt pulleys will not cause excessive wear, but will probably cause the drive belt to make a noise or to fall off.

Excessive misalignment of the drive belt pulleys will cause excessive wear but may also make the drive belt fall off.

Test Description

The numbers below refer to the step numbers on the diagnostic table.

2

This inspection is to verify the condition of the drive belt. Damage may of occurred to the drive belt when the drive belt fell off. The drive belt may of been damaged, which caused the drive belt to fall off. Inspect the belt for cuts, tears, sections of ribs missing, or damaged belt plys.

4

Misalignment of the pulleys may be caused from improper mounting of the accessory drive component, incorrect installation of the accessory drive component pulley, or the pulley bent inward or outward from a previous repair. Test for a misaligned pulley using a straight edge in the pulley grooves across two or three pulleys. If a misaligned pulley is found refer to that accessory drive component for the proper installation procedure of that pulley.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 39	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

5

Inspecting the pulleys for being bent should include inspecting for a dent or other damage to the pulleys that would prevent the drive belt from not seating properly in all of the pulley grooves or on the smooth surface of a pulley when the back side of the belt is used to drive the pulley.

6

Accessory drive component brackets that are bent or cracked will let the drive belt fall off.

7

Inspecting of the fasteners can eliminate the possibility that a wrong bolt, nut, spacer, or washer was installed. Missing. loose, or the wrong fasteners may cause pulley misalignment from the bracket moving under load. Over tightening of the fasteners may cause misalignment of the accessory component bracket.

13

The inspection is to verify the drive belt is correctly installed on all of the drive belt pulleys. Wear on the drive belt may be caused by mis-positioning the drive belt by one groove on a pulley.

14

The installation of a drive belt that is too wide or too narrow will cause wear on the drive belt. The drive belt ribs should match all of the grooves on all of the pulleys.

15

This inspection is to verify the drive belt is not contacting any parts of the engine or body while the engine is operating. There should be sufficient clearance when the drive belt accessory drive components load varies. The drive belt should not come in contact with an engine or a body component when snapping the throttle.

Drive Belt Falls Off and Excessive Wear Diagnosis

Step	Action	Yes	No
CAUTION	:		
Refer to B	elt Dressing Caution .		
	ON: The drive belt falls off the pulleys or may no e outside ribs of the drive belt due to an incorrectl		
1	Did you review the Drive Belt Symptom operation and perform the necessary inspections?	Go to Step 2	Go to Symptoms - Engine Mechanical
If diagnosing excessive wear, proceed to step 13. If diagnosing a drive belt that falls off, inspect			

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 40	© 2011 Mitchell Repair Information Company, LLC.

	for a damaged drive belt.		
	Did you find the condition?	Go to Step 3	Go to Step 4
3	Install a new drive belt. Refer to <u>Drive Belt</u> Replacement.		
	Does the drive belt continue to fall off?	Go to Step 4	System OK
4	Inspect for misalignment of the pulleys. Did you find and repair the condition?	Go to Step 12	Go to Step 5
5	Inspect for a bent or dented pulley. Did you find and repair the condition?	Go to Step 12	Go to Step 6
6	Inspect for a bent or a cracked bracket. Did you find and repair the condition?	Go to Step 12	Go to Step 7
7	Inspect for improper, loose or missing fasteners. Did you find loose or missing fasteners?	Go to Step 8	Go to Step 9
	CAUTION:		
	Refer to <u>Fastener Caution</u> .		
8	1. Tighten any loose fasteners. Refer to Fastener Tightening Specifications .		
	2. Replace improper or missing fasteners.		
	Does the drive belt continue to fall off?	Go to Step 9	System OK
9	Test the drive belt tensioner for operating correctly. Refer to Drive Belt Tensioner Diagnosis .		
	Does the drive belt tensioner operate correctly?	Go to Step 11	Go to Step 10
10	Replace the drive belt tensioner. Refer to Drive Belt Tensioner Replacement .		
10	Does the drive belt continue to fall off?	Go to Step 11	System OK
11	Inspect for failed drive belt idler and drive belt tensioner pulley bearings.		
11	Did you find and repair the condition?	Go to Step 12	Go to Diagnostic Aids
12	Operate the system in order to verify the repair. Did you correct the condition?	System OK	Go to Step 2
13	Inspect the drive belt for the proper installation. Refer to Drive Belt Replacement . Did you find this condition?		Go to Step 14
14	Inspect for the proper drive helt		Go to Step 15
15	Inspect for the drive belt rubbing against a bracket, hose, or wiring harness. Did you find and repair the condition?	Go to Step 16 Go to Step 17	Go to Diagnostic Aids above.
	Replace the drive belt. Refer to Drive Belt	Go to Step 17	auuve.
16	Replacement.		-
	Did you complete the replacement?	Go to Step 17	

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 41	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

17	Operate the system in order to verify the repair.			
1 /	Did you correct the condition?	System OK	_	l

DRIVE BELT TENSIONER DIAGNOSIS

Diagnosis consists of a function check on the automatic belt tensioner and a visual check on the belt and the components linked to the belt.




Fig. 7: Drive Belt Tensioner
Courtesy of GENERAL MOTORS COMPANY

- Apply tension to the belt tensioner via the cast projection (1) in the direction of the arrow, counterclockwise, and allow to slide back slowly.
- The tensioner must slide back to the initial position.

DUAL MASS FLYWHEEL DIAGNOSIS

Check for Thermal Overload

NOTE: These quick information shall help to carry out a correct diagnosis in case of a customer complaint.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 42	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Through friction of clutch plate on the friction surface of the dual mass flywheel temperatures up to 200 °C can arise during normal driving. At sliding clutch or through operating errors much higher temperatures can arise. These temperatures must not cause mandatory a reduced lifetime of the dual mass flywheel.

Possible indications for a high thermal load are:

- Tarnish (bluish) as well as local hotspots on friction surface
- Tarnish (bluish) near of mounting area and riveting area of clutch

If all other checkable features are well, the dual mass flywheel can stay in the vehicle.

Possible indications for a too high thermal load are:

- Cracks
- Fusion zones on friction surface (material smear)
- Scores in friction surface (for example through clutch lining riveting at destroyed or worn clutch plate)
- Tarnish (bluish) which reaches up to bearing area of dual mass flywheel
- Bluish discoloration of locating pins (3 locating pins in outer zone of dual mass flywheel)

In these cases the dual mass flywheel has to be replaced.

Overview Dual Mass Flywheel

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 8: Dual Mass Flywheel
Courtesy of GENERAL MOTORS COMPANY

Callout	Component Name
1	Bearing Area
2	Mounting Area Pressure Plate
3	Locating Pins
4	Friction Surface
5	Riveting Area

Exploded View Dual Mass Flywheel with Additional Mass

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 9: Dual Mass Flywheel With Additional Mass Courtesy of GENERAL MOTORS COMPANY

Callout	Component Name
1	Secondary Flywheel Mass
2	Additional Mass, Coupled with Cover and Pulse-Generator Ring
3	Flange
4	Primary Flywheel Mass with Bowed Springs and Plain Bearing/Bearing Bolt
5	Toothed Ring

Check for Damaged Components

All following checking procedures have to be carried out at installed dual mass flywheel. For visual check at vehicle very bright light and a additional bright and small pocket lamp is necessary. Damages like grease on primary flywheel and loose ore missing balance weights cannot be checked at installed condition. During visual check material alteration can be stated which eliminate a further operating suitability.

For comparison different damages at dual mass flywheel with the corresponding further procedure are presented here.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 45	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 10: Plain Bearing Courtesy of GENERAL MOTORS COMPANY

NOTE: In case of mechanical damages at plain bearing the dual mass flywheel has to be replaced.

1. Inspect plain bearing (1) for damages.

Dependent of the manufacturer damages can be detected through ventilation openings of secondary flywheel. Parts of the bearing (1) are detached or lie loose around the bearing bolt.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 11: Toothed Ring Courtesy of GENERAL MOTORS COMPANY

NOTE: Light abrasion on frontal areas of teeth is allowed. If problems occur during starting the engine the dual mass flywheel has to be replaced.

2. Inspect toothed ring (1) for damages.

The toothed ring is needed to start the engine. Through a lot of starting procedures and/or an incorrect engaging starter signs of abrasion can occur on teeth of the toothed ring. The profile of damages can reach from only low signs of abrasion up to heavy material removal. The installation of a pulse-generator ring depends on the manufacturer.

The image shows signs of abrasion and mechanical damages at toothed ring (1), they occur through abrasion due to a lot of starting procedures. In this case the dual mass flywheel has to be replaced.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a. m.	Page 47	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 12: Inspecting Tilt Clearance Courtesy of GENERAL MOTORS COMPANY

NOTE: The check must be carried out only by hand without any tools.

3. Inspect tilt clearance.

At dual mass flywheel the additional-mass ring looms over the gap between primary and secondary flywheel. It is not possible to carry out just a visual check.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 13: Tilt Clearance Height
Courtesy of GENERAL MOTORS COMPANY

NOTE: An absolute clear measurement is not possible with this check due to the different applied forces of the several workshop employees during the check.

- 4. Embrace dual mass flywheel and apply thumbs onto the outer radius of secondary flywheel.
- 5. Apply pressure onto the secondary flywheel alternating on upper, lower, left and right side

During the tilt clearance check a functional metal rattling noise may occur.

If tilt clearance is higher than 3 mm (MUST be measured, DO NOT make an estimation) (1) the dual mass flywheel has to be replaced.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a. m.	Page 49	© 2011 Mitchell Repair Information Company, LLC.




Fig. 14: Tilt Clearance Angle Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a. m.	Page 50	© 2011 Mitchell Repair Information Company, LLC.




Fig. 15: Rotating Secondary Flywheel Anticlockwise Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 51	© 2011 Mitchell Repair Information Company, LLC.




Fig. 16: Releasing Secondary Flywheel
Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 52	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 17: Mark On Flywheel And Toothed Ring For Starter Courtesy of GENERAL MOTORS COMPANY

6. Inspect clearance angle (1).

Before the inspection of the clearance angle the dual mass flywheel should be rotated several times clockwise and anticlockwise to receive a feeling for the resistance of the springs. In addition unusual loud clicking noise or possible rattle, crunch, grinding noise can be sounded out during rotating the dual mass flywheel.

If the rotation of the flywheel is impossible the flywheel is defective and has to be replaced.

The clearance angle is the angle (1) about the secondary and the primary flywheel can be turned light against each other. Thereby the flange wings are moved in the duct of the bowed springs without adjoining the bowed springs. Dictated by functional factors the clearance angle is up to 8 teeth.

Is the secondary flywheel rotated beyond this point the bowed springs in the duct are moved to spring arrestor in the primary flywheel/cover. Now the both spring are tensioned.

- Rotate secondary flywheel anticlockwise (arrow) until the elastic counterforce (spring force) is clear noticeable.
- Release secondary flywheel slowly until the bowed springs are relaxed, so no counterforce acts

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 53	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

onto the springs.

- Mark position with a vertical line by a white pencil on secondary flywheel (1) and on toothed ring for starter (2).
- Rotate secondary flywheel clockwise until the elastic counterforce is clear noticeable.
- Release secondary flywheel slowly until the bowed springs are relaxed.
- Apply new marking on secondary flywheel (1) on the height of the marking on the toothed ring for starter (3).
- Count amount of teeth on toothed ring for starter from marked tooth up to the height of the first marking on secondary flywheel (2). Dictated by functional factors up to 8 teeth are allowed.
- 7. ALWAYS replace the engine flywheel if following conditions are given:
 - The difference exceeds the amount of 8 teeth.
 - The dual mass flywheel cannot be rotated.
 - During rotating the dual mass flywheel a hard metallic arrestor is audible or noticeable.

REPAIR INSTRUCTIONS - ON VEHICLE

DRIVE BELT REPLACEMENT

Special Tools

EN 6349 Locking Pin

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

- 1. Open the hood.
- 2. Raise the vehicle. Refer to Lifting and Jacking the Vehicle.
- 3. Remove the right front wheelhouse liner. Refer to Front Wheelhouse Liner Replacement.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 54	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 18: Drive Belt Tensioner And Special Tool Courtesy of GENERAL MOTORS COMPANY

4. Release tension to the drive belt tensioner by rotating counterclockwise (1) and lock with **EN 6349** pin (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 5	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 19: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

5. Remove the drive belt (1).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 56	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 20: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

1. Install the drive belt (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:50 a.m.	Page 57	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 21: Checking Drive Belt Position
Courtesy of GENERAL MOTORS COMPANY

NOTE: Ensure that the drive belt is aligned on the generator pulley (4), crankshaft

balancer (5), drive belt tensioner (6) water pump pulley (7), and A/C compressor. The drive belt must lie on the water pump pulley between the

flange (1) and (2).

2. Check the position of the drive belt (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 58	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 22: Drive Belt Tensioner And Special Tool Courtesy of GENERAL MOTORS COMPANY

3. Release tension to the tensioner by rotating counterclockwise (1).

NOTE: Allow tensioner to slide back slowly.

- 4. Remove EN 6349 pin (2).
- 5. Apply tension to the tensioner clockwise (1).
- 6. Install the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 7. Lower the vehicle.
- 8. Close the hood.

DRIVE BELT TENSIONER REPLACEMENT

Removal Procedure

1. Remove the generator and air conditioning compressor belt. Refer to **Drive Belt Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 59	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 23: Drive Belt Tensioner Bolt
Courtesy of GENERAL MOTORS COMPANY

- 2. Remove the drive belt tensioner bolt (1).
- 3. Remove the drive belt tensioner (2).

Installation Procedure

1. Clean the drive belt tensioner thread.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 60	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 24: Drive Belt Tensioner Bolt Courtesy of GENERAL MOTORS COMPANY

2. Install drive belt tensioner (2).

CAUTION: Refer to Fastener Caution.

- 3. Install the drive belt tensioner bolt (1) and tighten to 55 N.m (41 lb ft).
- 4. Install the generator and air conditioning compressor belt. Refer to **Drive Belt Replacement**.

ENGINE MOUNT REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 61	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 25: Engine Mount And Bolts
Courtesy of GENERAL MOTORS COMPANY

viernes, 21 de abril de 2017 10:36:51 a.m.

Engine Mount Replacement

Callout	Component Name	
Preliminary Procedures		
1. Remove the air cleaner assem	ably. Refer to Air Cl	leaner Assembly Replacement .
2. Support the engine. Install a suitable engine lifting device. Install a suitable cable at the 3 engine lift brackets and at the engine lifting device.		
1	Engine Mount Bolt (Qty: 2) CAUTION: Refer to Fastener Caution. Tighten 62 N.m (46 lb ft)	
2	Engine Mount Bracket Bolt (Qty: 3) CAUTION: Refer to Torque-to-Yield Fastener Caution.	
Afinacion de Motor y Diagnostico,OBD	II,VW,Audi	044 664 252 34 (

Page 62

© 2011 Mitchell Repair Information Company, LLC.

2012 Chevrolet Cruze LS	
2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze	

	Procedure Install NEW bolts, do NOT reuse old bolts Tighten 50 N.m + 60°-75° (37 lb ft + 60°-75°)
3	Engine Mount Nut Tighten 62 N.m (46 lb ft)
4	Engine Mount

POWERTRAIN MOUNT BALANCING

NOTE: Follow the balance procedure steps listed below when no starting point has been established such as in a collision repair.

1. Raise and support the vehicle. Refer to <u>Lifting and Jacking the Vehicle</u>.





Fig. 26: Front Transaxle Mount Through Bolt Courtesy of GENERAL MOTORS COMPANY

2. Loosen the front transaxle mount through bolt (1) until it is finger tight.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 6	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 27: Rear Transaxle Mount And Through Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Loosen the rear transaxle mount (1) through bolt until it is finger tight.
- 4. Lower the vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 28: Supporting Engine/Transmission With Hydraulic Floor Jack Courtesy of GENERAL MOTORS COMPANY

5. Position two floor jacks with wood blocks under the engine and transaxle in order to support the powertrain assembly.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 65	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 29: Transaxle Bolts
Courtesy of GENERAL MOTORS COMPANY

6. Loosen the transaxle adapter to transaxle bolts (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 66	© 2011 Mitchell Repair Information Company, LLC.




Fig. 30: Engine Mount And Bracket Bolts
Courtesy of GENERAL MOTORS COMPANY

- 7. Loosen the engine mount (1) to bracket bolts (2).
- 8. Lower the floor jacks in order to allow a 1/4 inch (6 mm) gap between the upper engine mount and engine mount bracket, and also between the transmission and left transmission mount.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 67	© 2011 Mitchell Repair Information Company, LLC.




Fig. 31: Front And Rear Powertrain Mounts
Courtesy of GENERAL MOTORS COMPANY

- 9. Check that the front and rear mounts are centered (1) in the mount brackets, adjust if necessary.
- 10. Tighten the left hand (transaxle side) mount bolts, starting with the bolt nearest to the center of the mount. See the appropriate transmission mount replacement procedure for the fastener tightening specifications.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a. m.	Page 68	© 2011 Mitchell Repair Information Company, LLC.




Fig. 32: Transaxle Bolts
Courtesy of GENERAL MOTORS COMPANY

- 11. Tighten the right hand (engine side) mount bolts (1), starting with the bolt nearest to the center of the mount. See the appropriate engine mount replacement procedure for the fastener tightening specifications.
- 12. Remove the floor jacks from under the oil pan and transmission.
- 13. Raise the vehicle.
- 14. Shake the powertrain from front to rear and allow the powertrain to settle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 69	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 33: Rear Transaxle Mount And Through Bolt Courtesy of GENERAL MOTORS COMPANY

NOTE: It is essential that the lower mount through bolts should be as close to centered as possible in the oversized mount insert holes before tightening to specification.

15. Tighten the rear transaxle mount through bolt (1). See the appropriate transmission mount replacement procedure for the fastener tightening specifications.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 70	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 34: Front Transaxle Mount Through Bolt Courtesy of GENERAL MOTORS COMPANY

- 16. Tighten the front transaxle mount through bolt (1). See the appropriate transmission mount replacement procedure for the fastener tightening specifications.
- 17. Lower the vehicle.

POWERTRAIN MOUNT BALANCING - LOWER

NOTE: Follow the balance procedure steps listed below when front or rear mounts through bolts are loosened or removed during a repair procedure.

1. Raise and support the vehicle. Refer to <u>Lifting and Jacking the Vehicle</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 71	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 35: Front Transaxle Mount Through Bolt Courtesy of GENERAL MOTORS COMPANY

2. Loosen the front transaxle mount through bolt (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 36: Rear Transaxle Mount And Through Bolt Courtesy of GENERAL MOTORS COMPANY

- 3. Loosen the rear transaxle mount through bolt (1).
- 4. Shake the powertrain from front to rear and allow the powertrain to settle.

NOTE: It is essential that the through bolts are as close to centered as possible in the oversized mount insert holes before tightening to specification.

5. Tighten the rear transaxle mount through bolt (1). See the appropriate transmission mount replacement procedure for the fastener tightening specifications.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page	73 © 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 37: Front Transaxle Mount Through Bolt Courtesy of GENERAL MOTORS COMPANY

- 6. Tighten the front transaxle mount through bolt (1). See the appropriate transmission mount replacement procedure for the fastener tightening specifications.
- 7. Lower the vehicle.

ENGINE MOUNT REPLACEMENT - RIGHT SIDE

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a. m.	Page 74	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 38: Engine Mount And Bolts
Courtesy of GENERAL MOTORS COMPANY

Engine Mount Replacement - Right Side

viernes, 21 de abril de 2017 10:36:51 a.m.

Callout	Component Name	
Preliminary Procedures		
1. Remove the air cleaner assembly. Refer to Air Cleaner Assembly Replacement .		
2. Support the engine. Install a s lift brackets and at the engine	uitable engine lifting device. Install a suitable cable at the 3 engine lifting device.	
1	Engine Mount Bolt (Qty: 2) CAUTION: Refer to Fastener Caution. Tighten	
62 N.m (46 lb ft) Engine Mount Bracket Bolt (Qty: 3) CAUTION: Refer to Torque-to-Yield Fastener Caution.		
Afinacion de Motor y Diagnostico,OBD	II,VW,Audi 044 664 252	

Page 75

© 2011 Mitchell Repair Information Company, LLC.

2012 Chevrolet Cruze LS
2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

	Procedure	
	Use NEW bolts, do NOT reuse old bolts.	
	Tighten	
	$50 \text{ N.m} + 60^{\circ} - 75^{\circ} (37 \text{ lb ft} + 60^{\circ} - 75^{\circ})$	
	Engine Mount Nut	
3	Tighten	
	62 N.m (46 lb ft)	
4	Engine Mount	

ENGINE MOUNT INSPECTION

- 1. Install the engine support fixture. Refer to **Engine Support Fixture**.
- 2. Observe the engine mount while raising the engine. Raising the engine removes the weight from the engine mount and creates slight tension on the rubber.
- 3. Replace the engine mount if the engine mount exhibits any of the following conditions:
 - The hard rubber is covered with heat check cracks.
 - The rubber is separated from the metal plate of the engine mount.
 - The rubber is split through the center of the engine mount.
- 4. For engine mount replacement, refer to **Engine Mount Replacement Right Side**.
- 5. For rear transmission mount replacement, refer to the following:
 - Automatic transmission, refer to <u>Transmission Rear Mount Replacement (Electronic Power Steering)</u>.
 - Manual transmission, refer to **Transmission Rear Mount Replacement**.
- 6. For left transmission mount replacement, refer to the following:
 - Automatic transmission, refer to **Transmission Mount Replacement Left Side**.
 - Manual transmission, refer to <u>Transmission Mount Bracket Replacement Left Side</u>.

ENGINE MOUNT BRACKET REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a. m.	Page 7	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 39: Engine Mount Bracket Courtesy of GENERAL MOTORS COMPANY

Engine Mount Bracket Replacement

Engine Mount Bracket Replacement				
Callout	Component Name			
Preliminary Procedures				
Remove the engine mount. Refer to	Engine Mount Replacement.			
	Engine Mount Bracket Bolt (Qty: 3)			
	CAUTION			
	CAUTION:			
1	Refer to <u>Fastener Caution</u> .			
	Tighten			
	60 N.m (45 lb ft) + 45-60°			
2	Engine Mount Bracket			

INTAKE MANIFOLD REPLACEMENT

Removal Procedure

WARNING: Refer to Gasoline/Gasoline Vapors Warning.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page	77 © 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

WARNING: Refer to Safety Goggles and Fuel Warning.

WARNING: In order to reduce the risk of fire and personal injury observe the following items:

- Replace all nylon fuel pipes that are nicked, scratched or damaged during installation, do not attempt to repair the sections of the nylon fuel pipes
- Do not hammer directly on the fuel harness body clips when installing new fuel pipes. Damage to the nylon pipes may result in a fuel leak.
- Always cover nylon vapor pipes with a wet towel before using a torch near them. Also, never expose the vehicle to temperatures higher than 115°C (239°F) for more than one hour, or more than 90°C (194°F) for any extended period.
- Apply a few drops of clean engine oil to the male pipe ends before connecting fuel pipe fittings. This will ensure proper reconnection and prevent a possible fuel leak. (During normal operation, the Orings located in the female connector will swell and may prevent proper reconnection if not lubricated.)
- 1. Open the hood.
- 2. Remove the air cleaner outlet duct. Refer to Air Cleaner Outlet Duct Replacement.
- 3. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.
- 4. Place a drain pan underneath the vehicle.




Fig. 40: Intake Manifold Brace And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 5. Remove the 2 intake manifold brace bolts (2, 3).
- 6. Remove and disconnect the wiring harness plug from the heated oxygen sensor 1.
- 7. Remove the intake manifold brace (1).
- 8. Remove the evaporative emission canister purge solenoid valve. Refer to **Evaporative Emission** Canister Purge Solenoid Valve Replacement

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 79	© 2011 Mitchell Repair Information Company, LLC.





Fig. 41: Fuel Feed Pipe Courtesy of GENERAL MOTORS COMPANY

- 9. Unclip the fuel feed pipe (2) from the fuel feed pipe clip (3).
- 10. Release the fuel feed pipe (2) from the multiport fuel injection fuel rail (1) and remove the fuel feed pipe.
- 11. Close the fuel feed pipe with a suitable cap.


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page	80 © 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 42: Throttle Body And Positive Crankcase Ventilation Tube</u> Courtesy of GENERAL MOTORS COMPANY


- 12. Remove the positive crankcase ventilation tube (1) from throttle body (3) and the camshaft cover (2).
- 13. Remove the throttle body assembly. Refer to **Throttle Body Assembly Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 43: Throttle Body, Throttle Body Heater Inlet Hose And Throttle Body Heater Outlet Hose</u> Courtesy of GENERAL MOTORS COMPANY

- 14. Disconnect the manifold absolute pressure sensor wiring harness plug (5).
- 15. Remove the clamp (2) and remove the throttle body heater inlet hose (1) from throttle body (3).
- 16. Disconnect the throttle body heater outlet hose (4) from the throttle body (3).
- 17. Remove the engine management wiring harness and the fuel injectors wiring harness.



<u>Fig. 44: Intake Manifold, Multiport Fuel Injection Fuel Rail, Fuel Injectors, Seals And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 18. Remove the 2 multiport fuel injection fuel rail bolts (1).
- 19. Remove the multiport fuel injection fuel rail (2) and the fuel injectors (3) from the intake manifold (5).
- 20. Remove the 4 multiport fuel injector seals (4).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 83	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 45: Brake Servo Vacuum Line Courtesy of GENERAL MOTORS COMPANY

21. Disconnect the booster vacuum pipe (1) from the intake manifold.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 84	© 2011 Mitchell Repair Information Company, LLC.





Fig. 46: Intake Manifold And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 22. Remove the 7 intake manifold bolts (1).
- 23. Remove the intake manifold (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 85	© 2011 Mitchell Repair Information Company, LLC.


2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 47: Intake Manifold, Intake Manifold Seal And Throttle Body Seal</u> Courtesy of GENERAL MOTORS COMPANY

24. Remove the intake manifold gaskets (1, 3) from the intake manifold (2).


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 86	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 48: Intake Manifold, Manifold Absolute Pressure Sensor And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 25. Remove the manifold absolute pressure sensor bolt (1).
- 26. Remove the manifold absolute pressure sensor (2) from the intake manifold (3).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 49: Intake Manifold And Mount</u> Courtesy of GENERAL MOTORS COMPANY

27. Remove the rubber bracket (2) from intake manifold (1).

Cleaning and Inspection Procedure

Clean and inspect the intake manifold. Refer to **Intake Manifold Cleaning and Inspection**.

Installation Procedure

1. Clean the sealing surfaces.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a. m.	Page 88	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 50: Intake Manifold And Mount Courtesy of GENERAL MOTORS COMPANY

2. Install the rubber bracket (2) to intake manifold (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a. m.	Page 89	© 2011 Mitchell Repair Information Company, LLC.




<u>Fig. 51: Intake Manifold, Manifold Absolute Pressure Sensor And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Install the manifold absolute pressure sensor (2) to the intake manifold (3).
- 4. Install the manifold absolute pressure sensor bolt (1) and tighten to 6 N.m (53 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 90	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 52: Intake Manifold, Intake Manifold Seal And Throttle Body Seal</u> Courtesy of GENERAL MOTORS COMPANY

5. Install the NEW gaskets (1, 3) to the intake manifold (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 91	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 53: Intake Manifold And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

6. Install the intake manifold (2) and the 7 intake manifold bolts (1) and tighten to 20 N.m (15 lb ft).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 54: Brake Servo Vacuum Line Courtesy of GENERAL MOTORS COMPANY


7. Connect the booster vacuum pipe (1) to the intake manifold.



<u>Fig. 55: Intake Manifold, Multiport Fuel Injection Fuel Rail, Fuel Injectors, Seals And Bolts</u> Courtesy of GENERAL MOTORS COMPANY


- 8. Install the 4 multiport fuel injector seals (4).
- 9. Install the multiport fuel injection fuel rail (2) and the fuel injectors (3) to the intake manifold (5).
- 10. Install the 2 multiport fuel injection fuel rail bolts (1) and tighten to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 94	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 56: Throttle Body, Throttle Body Heater Inlet Hose And Throttle Body Heater Outlet Hose</u> Courtesy of GENERAL MOTORS COMPANY

- 11. Connect the throttle body heater outlet hose (4) to the throttle body (3).
- 12. Install the throttle body heater inlet hose (1) to the throttle body (3) and install the clamp (2).
- 13. Connect the manifold absolute pressure sensor wiring harness plug (5).
- 14. Install the engine management wiring harness and the fuel injectors wiring harness.



<u>Fig. 57: Throttle Body And Positive Crankcase Ventilation Tube</u> Courtesy of GENERAL MOTORS COMPANY

- 15. Install the positive crankcase ventilation tube (1) the to throttle body (3) and to the camshaft cover (2).
- 16. Install the throttle body assembly. Refer to **Throttle Body Assembly Replacement**.
- 17. Install the evaporative emission canister purge solenoid valve. Refer to **Evaporative Emission Canister Purge Solenoid Valve Replacement**

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 96	© 2011 Mitchell Repair Information Company, LLC.




Fig. 58: Fuel Feed Pipe Courtesy of GENERAL MOTORS COMPANY

- 18. Remove the cap from fuel feed pipe (2).
- 19. Install the fuel feed pipe (2) to the multiport fuel injection fuel rail (1).
- 20. Clip the fuel feed pipe (2) to the fuel feed pipe clip (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page	97 © 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 59: Intake Manifold Brace And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 21. Install the intake manifold brace (1).
- 22. Install and connect the wiring harness plug to the heated oxygen sensor 1.
- 23. Install the 2 intake manifold brace bolts (2, 3) and tighten to 8 N.m (71 lb in).
- 24. Lower the vehicle.
- 25. Install the air cleaner outlet duct. Refer to Air Cleaner Outlet Duct Replacement.
- 26. Close the hood.

TIMING BELT REPLACEMENT

Special Tools

- EN-6333 Timing Belt Tensioner Locking Pin
- EN-6340 Camshaft Locking Tool
- EN-6625 Crankshaft Locking Device
- EN-45059 Anglemeter

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 98	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Removal Procedure

- 1. Open the hood.
- 2. Remove the air cleaner assembly. Refer to Air Cleaner Assembly Replacement.
- 3. Remove the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Removal**.
- 4. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.
- 5. Remove the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 6. Remove the drive belt tensioner. Refer to **Drive Belt Tensioner Replacement**.
- 7. Remove the front compartment insulator. Refer to Front Compartment Insulator Replacement.
- 8. Set the engine to top dead center (TDC).
- 9. For vehicle with manual transmission: Remove the transmission front mount. Refer to <u>Transmission</u> <u>Front Mount Replacement</u>.





Fig. 60: Connection Bolt
Courtesy of GENERAL MOTORS COMPANY

10. For vehicle with manual transmission: Remove the bolted connection (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 99	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 61: Automatic Transmission Bracket Bolt</u> Courtesy of GENERAL MOTORS COMPANY

11. For vehicle with automatic transmission: Remove the bolt (1).




Fig. 62: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 12. Install EN-6625 locking device (2) to block the crankshaft.
- 13. Install the bolt or bolted connection (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:51 a.m.	Page 101	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 63: Crankshaft Balancer And Bolt Courtesy of GENERAL MOTORS COMPANY

14. Remove and DISCARD the crankshaft balancer bolt (1).




Fig. 64: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 15. Remove the 4 lower timing belt cover bolts (2).
- 16. Remove the lower timing belt cover (1).
- 17. Lower the vehicle.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 65: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE: The left half of the EN-6340 locking tool can be recognized by the lettering "left", arrow, on the tool.

- 18. Prepare the left half of the **EN-6340** locking tool.
 - 1. Remove the 2 bolts (2)
 - 2. Remove the front panel (1) from the EN-6340 locking tool left.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 104	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 66: Camshaft Adjuster Locking Tool
Courtesy of GENERAL MOTORS COMPANY

19. Install the EN-6340 locking tool into the camshaft adjusters.


NOTE: The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of EN-6340-left during this process but must be somewhat above as shown.

1. Install the EN-6340 locking tool - left (1) in the camshaft adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340-right.

- 2. Install EN-6340 locking tool right (2) in the camshaft adjusters as shown.
- 20. Remove EN-6340 locking tool.
- 21. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 105	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 67: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 22. Apply tension to the drive belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 23. Install the EN-6333 locking pin (3).
- 24. Remove the timing belt idler pulley. Refer to **Timing Belt Idler Pulley Replacement**.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 68: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

25. Remove the timing belt (1).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 107	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 69: Timing Belt And Assembly Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE:

Threading the timing belt through the engine mount bracket is only permissible in conjunction with the assembly tool supplied with NEW timing belts or otherwise it is possible to damage the toothed belt at this stage by kinking it.

NOTE: If the toothed belt has been used, observe the direction of rotation.

- 1. Install the timing belt (1) in the enclosed assembly tool (2).
- 2. Guide the timing belt through the engine mount bracket with the assembly tool.
- 3. Remove the assembly tool.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 108	© 2011 Mitchell Repair Information Company, LLC.





Fig. 70: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

- 4. Install the timing belt (1).
- 5. Guide the timing belt past the tensioner and place it on the crankshaft sprocket wheel.
- 6. Place the timing belt on the exhaust and intake camshaft position actuator adjusters.
- 7. Raise and support the vehicle.
- 8. Install the timing belt idler pulley. Refer to **Timing Belt Idler Pulley Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 10	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 71: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 9. Apply tension to the drive belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 10. Remove the **EN-6333** locking pin (3).

NOTE: The timing belt tensioner moves automatically to the correct position.

11. Release tension on timing belt tensioner.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 110	© 2011 Mitchell Repair Information Company, LLC.




Fig. 72: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 12. Remove bolt or bolted connection (1).
- 13. Remove EN-6625 locking device (2).
- 14. Lower the vehicle.
- 15. Remove the EN-6340 locking tool.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 11	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 73: Camshaft Adjuster Locking Tool **Courtesy of GENERAL MOTORS COMPANY**

16. Check the timing

NOTE: Note the marking at the camshaft sprockets.

1. Turn the crankshaft 720° in the direction of engine rotation by the crankshaft balancer bolt.

NOTE: The spot type marking (4) on the intake camshaft adjuster does not

correspond to the groove of EN-6340-left during this process but must be somewhat above as shown.

2. Install EN-6340-left locking tool (1) into the camshaft adjusters as shown.

The spot type marking (3) on the exhaust camshaft adjuster must NOTE:

correspond to the groove on EN-6340-right.

- 3. Install EN-6340-right locking tool (2) into the camshaft adjusters as shown.
- 17. Remove the **EN-6340** locking tool.
- 18. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 112	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 74: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

NOTE: The timing belt drive gear and oil pump housing must align.

19. Control the crankshaft balancer position.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 113	© 2011 Mitchell Repair Information Company, LLC.




Fig. 75: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 20. Install EN-6625 locking device (2) to block the crankshaft.
- 21. Install the bolt or bolted connection (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.




Fig. 76: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 22. Install the lower timing belt cover (1).
- 23. Install the 4 lower timing belt cover bolts (2) and tighten to 6 N.m (53 lb in).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 77: Crankshaft Balancer And Bolt Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Torque-to-Yield Fastener Caution.

- 24. Install the crankshaft balancer (2).
- 25. Install a NEW crankshaft balancer bolt (1) and tighten in 3 passes using the EN-45059 meter :
 - 1. First pass to 95 N.m (70 lb ft)
 - 2. Second pass to 45°
 - 3. Third pass to 15°

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 116	© 2011 Mitchell Repair Information Company, LLC.




Fig. 78: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 26. Remove bolt or bolted connection (1).
- 27. Remove EN-6625 locking device (2).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 79: Automatic Transmission Bracket Bolt Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

28. For vehicle with automatic transmission: Install the bolt (1) and tighten to 45 N.m (33 lb ft).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 80: Connection Bolt
Courtesy of GENERAL MOTORS COMPANY

- 29. For vehicle with manual transmission: Install the bolt (1) and tighten to 40 N.m (32 lb ft).
- 30. Install the drive belt tensioner. Refer to **Drive Belt Tensioner Replacement**.
- 31. Install the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 32. Lower the vehicle.
- 33. Remove the EN-6340 locking tool.
- 34. Install the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Installation**.
- 35. Install the air cleaner assembly. Refer to Air Cleaner Assembly Replacement.
- 36. Close the hood.

TIMING BELT IDLER PULLEY REPLACEMENT

Special Tools

EN-45059 Angle Meter

For equivalent tools, refer to **Special Tools**.

Removal Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 119	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

1. Remove the timing belt. Refer to **Timing Belt Replacement**.




Fig. 81: Timing Belt Idler Pulley Bolt Courtesy of GENERAL MOTORS COMPANY

- 2. Remove and DISCARD the timing belt idler pulley bolt (2).
- 3. Remove the timing belt idler pulley (1).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 120	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 82: Timing Belt Idler Pulley Bolt
Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

 $\textbf{CAUTION: Refer to } \underline{\textbf{Torque-to-Yield Fastener Caution}} \;.$

- 1. Install the timing belt idler pulley (1) and tighten the NEW bolt (2) in three passes use the **EN-45059** meter :
 - 1. First pass tighten to 20 N.m (15 lb ft).
 - 2. Second pass to 120 degrees.
 - 3. Final pass to 15 degrees.
- 2. Install the timing belt. Refer to **Timing Belt Replacement**.

TIMING BELT TENSIONER REPLACEMENT

Special Tools

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.


2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- EN-6333 Timing Belt Tensioner Locking Pin
- EN-6340 Camshaft Locking Tool
- EN-6625 Crankshaft Locking Device
- EN-45059 Torque Angle Sensor Kit

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

- 1. Open the hood.
- 2. Remove the air cleaner assembly. Refer to Air Cleaner Assembly Replacement.
- 3. Remove the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Removal**.
- 4. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.
- 5. Remove the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 6. Remove the drive belt tensioner. Refer to **Drive Belt Tensioner Replacement**.
- 7. Remove the front compartment insulator. Refer to Front Compartment Insulator Replacement.
- 8. Set the engine to top dead center (TDC).
- 9. For vehicle with manual transmission: Remove the transmission front mount. Refer to <u>Transmission</u> Front Mount Replacement.



Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 122	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Fig. 83: Connection Bolt Courtesy of GENERAL MOTORS COMPANY

10. For vehicle with manual transmission: Remove the bolted connection (1).




Fig. 84: Automatic Transmission Bracket Bolt Courtesy of GENERAL MOTORS COMPANY

11. For vehicle with automatic transmission: Remove the bolt (1).




Fig. 85: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 12. Install EN-6625 locking device (2) to block the crankshaft.
- 13. Install the bolt or bolted connection (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 86: Crankshaft Balancer And Bolt Courtesy of GENERAL MOTORS COMPANY

14. Remove and DISCARD the crankshaft balancer bolt (1).




Fig. 87: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 15. Remove the 4 lower timing belt cover bolts (2).
- 16. Remove the lower timing belt cover (1).
- 17. Lower the vehicle.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 88: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE: The left half of the EN-6340 locking tool can be recognized by the lettering "left", arrow, on the tool.

- 18. Prepare the left half of the **EN-6340** locking tool.
 - 1. Remove the 2 bolts (2)
 - 2. Remove the front panel (1) from the EN-6340 locking tool left.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 127	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 89: Camshaft Adjuster Locking Tool
Courtesy of GENERAL MOTORS COMPANY

19. Install the EN-6340 locking tool into the camshaft adjusters.


NOTE: The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of EN-6340-left during this process but must be somewhat above as shown.

1. Install the EN-6340 locking tool - left (1) in the camshaft adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340-right.

- 2. Install EN-6340 locking tool right (2) in the camshaft adjusters as shown.
- 20. Remove EN-6340 locking tool.
- 21. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 128	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 90: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 22. Apply tension to the drive belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 23. Install the EN-6333 locking pin (3).
- 24. Lower the vehicle.
- 25. Remove the engine mount bracket. Refer to **Engine Mount Bracket Replacement**.
- 26. Remove the timing belt center front cover. Refer to **Timing Belt Center Front Cover Removal**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 129	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 91: Timing Belt And Timing Belt Tensioner Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the direction of the belt, if the timing belt will be reused.

- 27. Remove the timing belt (1).
- 28. Remove and DISCARD the timing belt tensioner bolt (3).
- 29. Remove the timing belt tensioner (2).

Installation Procedure

1. Re-cut the timing belt tensioner thread.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 130	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 92: Timing Belt And Timing Belt Tensioner Courtesy of GENERAL MOTORS COMPANY

2. Install the timing belt tensioner (2).

NOTE: Service may offer bolts that are not microencapsulated. If this is the case apply thread lock agent to the bolt.


3. If fastener is microencapsulated, install a NEW timing belt tensioner bolt (3). DO NOT reuse the old bolt.

CAUTION: Refer to <u>Fastener Caution</u>.

- 4. Tighten the timing belt tensioner bolt to 20 N.m (15 lb ft).
- 5. Install the timing belt (1).
- 6. Guide the timing belt past the tensioner and place it on the crankshaft sprocket wheel.
- 7. Place the timing belt on the exhaust and intake camshaft position actuator adjusters.
- 8. Install the engine mount bracket. Refer to **Engine Mount Bracket Replacement**.
- 9. Install the timing belt center front cover. Refer to **Timing Belt Center Front Cover Installation**.
- 10. Raise the vehicle.

10: Italise the vehicle:		
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 131	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 93: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 11. Apply tension to the drive belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 12. Remove the **EN-6333** locking pin (3).

NOTE: The timing belt tensioner moves automatically to the correct position.

13. Release tension on timing belt tensioner.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 132	© 2011 Mitchell Repair Information Company, LLC.




Fig. 94: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 14. Remove bolt or bolted connection (1).
- 15. Remove EN-6625 locking device (2).
- 16. Lower the vehicle.
- 17. Remove the EN-6340 locking tool.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 95: Camshaft Adjuster Locking Tool
Courtesy of GENERAL MOTORS COMPANY

18. Check the timing

NOTE: Note the marking at the camshaft sprockets.

1. Turn the crankshaft 720° in the direction of engine rotation by the crankshaft balancer bolt.

NOTE: The spot type marking (4) on the intake camshaft adjuster does not

correspond to the groove of EN-6340-left during this process but

must be somewhat above as shown.

2. Install EN-6340-left locking tool (1) into the camshaft adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft adjuster must

correspond to the groove on EN-6340-right.

- 3. Install EN-6340-right locking tool (2) into the camshaft adjusters as shown.
- 19. Remove the **EN-6340** locking tool.
- 20. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 134	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 96: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

NOTE: The timing belt drive gear and oil pump housing must align.

21. Control the crankshaft balancer position.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 135	© 2011 Mitchell Repair Information Company, LLC.





Fig. 97: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 22. Install EN-6625 locking device (2) to block the crankshaft.
- 23. Install the bolt or bolted connection (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 136	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 98: Timing Belt Lower Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

- 24. Install the lower timing belt cover (1).
- 25. Install the 4 lower timing belt cover bolts (2) and tighten to 6 N.m (53 lb in).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 99: Crankshaft Balancer And Bolt Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u> in the Preface section.

- 26. Install the crankshaft balancer (2).
- 27. Install a NEW crankshaft balancer bolt (1) and tighten in 3 passes using the EN-45059 sensor kit:
 - 1. First pass to 95 N.m (70 lb ft).
 - 2. Second pass to 45° .
 - 3. Third pass to 15° .

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 138	© 2011 Mitchell Repair Information Company, LLC.




Fig. 100: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 28. Remove bolt or bolted connection (1).
- 29. Remove EN-6625 locking device (2).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 101: Automatic Transmission Bracket Bolt Courtesy of GENERAL MOTORS COMPANY

30. For vehicle with automatic transmission: Install the bolt (1) and tighten to 45 N.m (33 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a.m.	Page 140	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 102: Connection Bolt Courtesy of GENERAL MOTORS COMPANY

- 31. For vehicle with manual transmission: Install the bolted connection (1) and tighten to 40 N.m (32 lb ft).
- 32. Install the drive belt tensioner. Refer to **Drive Belt Tensioner Replacement**.
- 33. Install the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 34. Lower the vehicle.
- 35. Remove the EN-6340 locking tool.
- 36. Install the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Installation**.
- 37. Install the air cleaner assembly. Refer to Air Cleaner Assembly Replacement.
- 38. Close the hood.

TIMING BELT CENTER FRONT COVER REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 141	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 103: Timing Belt Center Front Cover Courtesy of GENERAL MOTORS COMPANY


Timing Belt Center Front Cover Replacement

Callout	Component Name				
Preliminary Procedure					
 Remove the timing belt upper front cover. Refer to <u>Timing Belt Upper Front Cover</u> <u>Replacement</u>. 					
2. Remove the engine mount bracket. Refer to Engine Mount Bracket Replacement.					
1	Timing Belt Center Front Cover				

TIMING BELT UPPER FRONT COVER REPLACEMENT

Removal Procedure


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:52 a. m.	Page 142	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 104: Air Cleaner</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Disconnect the wiring harness plug (2).
- 2. Unclip the wiring harness from the air cleaner (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 105: Timing Belt Upper Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Remove the 2 timing belt upper front cover bolts (2).
- 4. Remove the timing belt upper front cover (1).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 144	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 106: Timing Belt Upper Front Cover</u> Courtesy of GENERAL MOTORS COMPANY


1. Install the timing belt upper front cover (1).

CAUTION: Refer to Fastener Caution.

2. Install the 2 timing belt upper front cover bolts (2) and tighten to 6 N.m (53 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 145	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 107: Air Cleaner</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Connect the wiring harness plug (2).
- 4. Clip in the wiring harness to the air cleaner (1).

TIMING BELT LOWER FRONT COVER REPLACEMENT

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

- 1. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.
- 2. Remove the crankshaft balancer. Refer to <u>Crankshaft Balancer Replacement (Manual Transmission)</u>, <u>Crankshaft Balancer Replacement (Automatic Transmission)</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 146	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 108: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 3. Remove the 4 lower timing belt cover bolts (2).
- 4. Remove the lower timing belt cover (1).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi			044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 1	147	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 109: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

- 1. Install the lower timing belt cover (1).
- 2. Install the 4 lower timing belt cover bolts (2) and tighten to 6 N.m (53 lb in).
- 3. Install the crankshaft balancer. Refer to <u>Crankshaft Balancer Replacement (Manual Transmission)</u>, <u>Crankshaft Balancer Replacement (Automatic Transmission)</u>.
- 4. Lower the vehicle.

TIMING BELT REAR COVER REPLACEMENT

Removal Procedure

- 1. Remove the camshaft position actuator adjuster. Refer to <u>Camshaft Position Actuator Adjuster</u> Replacement.
- 2. Remove the timing belt tensioner. Refer to **Timing Belt Tensioner Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 148	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 110: Timing Belt Rear Cover And Bolts
Courtesy of GENERAL MOTORS COMPANY

3. Remove and DISCARD the 4 timing belt rear cover bolts (2).

NOTE: Oil can escape. Use a cloth, rag or paper to take the oil drain away from all timing components.


4. Remove the timing belt rear cover (1).

Installation Procedure

1. Re-cut the 4 timing belt rear cover threads.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 149	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 111: Timing Belt Rear Cover And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: If the cover is contaminated with oil. You have to clean it close.

2. Install the timing belt rear cover (1).

CAUTION: Refer to Fastener Caution.

NOTE: Service may offer bolts that are not microencapsulated. If this is the case apply thread lock agent to the bolt. If fastener is microencapsulated, install a NEW 4 timing belt rear cover bolts. DO NOT reuse the old bolt.

- 3. Install the 4 NEW timing belt rear cover bolts (2) and tighten to 6 N.m (53 lb in).
- 4. Install the timing belt tensioner. Refer to **Timing Belt Tensioner Replacement**.
- 5. Install the camshaft position actuator adjuster. Refer to <u>Camshaft Position Actuator Adjuster Replacement</u>.

VALVE LIFTER REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 150	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Special Tools

EN-845 Suction Device

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

1. Remove the camshafts. Refer to **Camshaft Replacement**.




Fig. 112: Valve Lifters
Courtesy of GENERAL MOTORS COMPANY

NOTE: Mark the assignments.

2. Remove the 16 valve lifters (1), using the EN-845 suction device.

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 151	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 113: Valve Lifters
Courtesy of GENERAL MOTORS COMPANY

NOTE: Observe the correct assignment.

NOTE: Coat the sliding surfaces with NEW engine oil.

- 1. Install the 16 valve lifters (1), using the EN-845 suction device.
- 2. Install the camshafts. Refer to **Camshaft Replacement**.

CYLINDER HEAD REPLACEMENT

Special Tools

- EN-6333 Timing Belt Tensioner Locking Pin
- EN-6340 Camshaft Adjuster Locking Tool
- EN-6625 Crankshaft Locking Device
- EN-6628-A Camshaft Locking Tool
- EN-45059 Angle Meter

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 152	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

- 1. Disconnect the battery negative cable. Refer to <u>Battery Negative Cable Disconnection and</u> Connection .
- 2. Remove the air cleaner assembly. Refer to Air Cleaner Assembly Replacement.
- 3. Raise and support the vehicle. Refer to <u>Lifting and Jacking the Vehicle</u>.
- 4. Drain the cooling system. Refer to <u>Cooling System Draining and Filling (GE-47716 Fill)</u>, <u>Cooling System Draining and Filling (Static Fill)</u>.
- 5. Drain the engine oil. Refer to **Engine Oil and Oil Filter Replacement**.
- 6. Remove the intake manifold. Refer to **Intake Manifold Replacement**.




Fig. 114: Radiator Inlet Hose And Clamp Courtesy of GENERAL MOTORS COMPANY

- 7. Loosen the radiator inlet hose clamp (2).
- 8. Remove the radiator inlet hose (3) from the engine coolant thermostat (1).
- 9. Remove the heater outlet hose from the engine coolant thermostat housing. Refer to <u>Heater Outlet Hose</u> <u>Replacement (LUJ)</u>, <u>Heater Outlet Hose Replacement (LUW)</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 15	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

10. Remove the heater inlet hose from the engine coolant thermostat housing. Refer to <u>Heater Inlet Hose</u> <u>Replacement (LUJ)</u>, <u>Heater Inlet Hose Replacement (LUW)</u>.




Fig. 115: Thermostat Housing Bracket, Bolts And Wiring Harness Courtesy of GENERAL MOTORS COMPANY

- 11. Disconnect the thermostat wiring harness plug (1).
- 12. Remove the thermostat housing bracket nut (3).
- 13. Hang the thermostat housing bracket (2) with attached wiring harness aside.
- 14. Remove the exhaust manifold. Refer to **Exhaust Manifold Replacement (LUW)**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 15	© 2011 Mitchell Repair Information Company, LLC.




Fig. 116: Timing Belt Upper Front Cover Courtesy of GENERAL MOTORS COMPANY

- 15. Remove the 2 timing belt upper front cover bolts (2).
- 16. Remove the timing belt upper front cover (1).
- 17. Remove the camshaft cover. Refer to **Camshaft Cover Replacement**.
- 18. Remove the 2 camshaft position sensor. Refer to **Camshaft Position Sensor Replacement**.
- 19. Remove the 2 camshaft position actuator solenoid valve. Refer to <u>Camshaft Position Actuator Solenoid</u> <u>Valve Replacement</u>.
- 20. Remove the drive belt tensioner. Refer to **Drive Belt Tensioner Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 155	© 2011 Mitchell Repair Information Company, LLC.




Fig. 117: Crankshaft TDC Position
Courtesy of GENERAL MOTORS COMPANY

- 21. Set the crankshaft balancer in direction of engine rotation until the markings (1) line up with the cylinder 1 at TDC.
- 22. Remove the crankshaft balancer. Refer to <u>Crankshaft Balancer Replacement (Manual Transmission)</u>, <u>Crankshaft Balancer Replacement (Automatic Transmission)</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 156	© 2011 Mitchell Repair Information Company, LLC.




Fig. 118: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 23. Remove the 4 lower timing belt cover bolts (2).
- 24. Remove the lower timing belt cover (1).
- 25. Lower the vehicle.
- 26. Support the engine under the oil pan.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 157	© 2011 Mitchell Repair Information Company, LLC.




Fig. 119: Engine Mount And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 27. Remove the engine mount nut (3).
- 28. Remove the 5 engine mount bolts (1, 2).
- 29. Remove the engine mount (4).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.




Fig. 120: Engine Mount Bracket And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 30. Remove the 3 engine mount bracket bolts (1).
- 31. Remove the engine mount bracket (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 15	© 2011 Mitchell Repair Information Company, LLC.




Fig. 121: Toothed Belt Cover Courtesy of GENERAL MOTORS COMPANY

- 32. Remove the center front timing belt cover from the rear timing belt cover at 2 locations.
- 33. Remove the center front timing belt cover (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 160	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 122: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

34. Install the EN-6340 locking tool into the camshaft adjusters.


NOTE: The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of EN-6340 locking tool - left during this process but must be somewhat above as shown.

• Install the EN-6340 locking tool - left (1) in the camshaft adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340 locking tool - right.

• Install EN-6340 locking tool - right (2) in the camshaft adjusters as shown.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 161	© 2011 Mitchell Repair Information Company, LLC.




<u>Fig. 123: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 35. Apply tension to the timing belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 36. Install the **EN-6333** pin (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 162	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 124: Timing Belt And Timing Belt Tensioner</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the direction of the belt, if the timing belt will be reused.

- 37. Remove the timing belt (1).
- 38. Remove and DISCARD the timing belt tensioner bolt (3).
- 39. Remove the timing belt tensioner (2).
- 40. Raise the vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 163	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 125: Timing Belt Idler Pulley Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 41. Remove the timing belt idler pulley bolt (1).
- 42. Remove the timing belt idler pulley (2).
- 43. Remove the **EN-6625** locking device.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 164	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 126: Turning Crankshaft Against Direction Of Engine Rotation Courtesy of GENERAL MOTORS COMPANY

44. Set the crankshaft in direction of engine rotation to 60 degrees (a) before TDC. Use the **EN-45059** meter and the crankshaft balancer bolt.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 127: Crankshaft Sprocket Courtesy of GENERAL MOTORS COMPANY

NOTE: Some engine oil will run out of the camshaft and the camshaft position actuator adjuster. That is the reason for the removal of the whole timing assembly.

- 45. Remove the crankshaft sprocket (1).
- 46. Lower the vehicle.
- 47. Remove the EN-6340 locking tool.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 166	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 128: Aligning Camshafts Horizontally
Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the arrows.

48. Turn the camshaft by the camshaft position actuator adjuster until the groove on the end of the camshafts is horizontal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 167	© 2011 Mitchell Repair Information Company, LLC.





Fig. 129: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

- 49. Install the EN-6628-A locking tool (1).
- 50. Place a collecting basin underneath the vehicle.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 130: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

51. Remove the camshaft position actuator adjuster closure bolt (1) of the intake camshaft position actuator adjuster and the exhaust camshaft position actuator adjuster (3).

NOTE: A second technician is required.

NOTE: Use an appropriate open-end wrench in order to counterhold the camshaft

hexagon. A thin cross-section wrench is required for a better fit. The usage of EN-6628-A locking tool is for the camshaft adjustment to prevent misalignment of the camshafts. The wrench is required to counterhold the

camshafts during bolt torque procedure.

- 52. Remove and DISCARD the intake camshaft position actuator adjuster bolt and/or the exhaust camshaft position actuator adjuster bolt (2).
- 53. Remove the intake camshaft position actuator adjuster and the exhaust camshaft position actuator adjuster (3).
- 54. Remove the timing belt rear cover. Refer to **Timing Belt Rear Cover Removal**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 169	© 2011 Mitchell Repair Information Company, LLC.




Fig. 131: Cylinder Head Bolts Tightening Sequence Courtesy of GENERAL MOTORS COMPANY

- 55. Loosen the 10 cylinder head bolts in sequence as shown.
 - 1. Loosen the 10 bolts 90 degrees.
 - 2. Loosen the 10 bolts 180 degrees.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 132: Cylinder Head And Bolts
Courtesy of GENERAL MOTORS COMPANY


- 56. Remove and DISCARD the 10 cylinder head bolts (1).
- 57. Remove the cylinder head (2).
- 58. Remove and DISCARD the cylinder head gasket (3).
- 59. In case of re-use, then clean and inspect the cylinder head. Refer to **Cylinder Head Cleaning and Inspection**.
- 60. Remove the thermostat housing. Refer to **Engine Coolant Thermostat Housing Removal**.
- 61. Remove the camshafts. Refer to **Camshaft Removal**.
- 62. Remove the valve lifter. Refer to **Valve Lifter Removal**.
- 63. Disassemble the cylinder head. Refer to **Cylinder Head Disassemble**.

Installation Procedure

- 1. Assemble the cylinder head. Refer to **Cylinder Head Assemble**.
- 2. Install the valve lifter. Refer to <u>Valve Lifter Installation</u>.
- 3. Install the camshafts. Refer to **Camshaft Installation**.
- 4. Install the thermostat housing. Refer to **Engine Coolant Thermostat Housing Installation**.
- 5. Clean the sealing surfaces.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a.m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

- 6. Inspect for plane surface.
 - Cylinder block, cylinder head
 - Straight-edge, feeler gauge



<u>Fig. 133: Cylinder Head And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 7. Install a NEW cylinder head gasket (3).
- 8. Install the cylinder head (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 134: Cylinder Head Bolts Tightening Sequence Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

 $\textbf{CAUTION: Refer to } \underline{\textbf{Torque-to-Yield Fastener Caution}} \;.$

- 9. Install 10 NEW cylinder head bolts (1).
- 10. Tighten the bolts as shown in sequence in 5 passes, using the EN-45059 meter :
 - 1. First pass to 25 (18 lb ft)
 - 2. Second pass to 90 degrees
 - 3. Third pass to 90 degrees
 - 4. Fourth pass to 90 degrees
 - 5. Final pass to 45 degrees
- 11. Install the timing belt rear cover. Refer to **Timing Belt Rear Cover Installation**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:53 a. m.	Page 173	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 135: Aligning Camshafts Horizontally
Courtesy of GENERAL MOTORS COMPANY

12. Align the camshafts horizontally by the hexagon arrows, until the **EN-6628-A** locking tool can be inserted in both camshafts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 174	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 136: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

13. Insert the EN-6628-A locking tool (1) into the camshafts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 175	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 137: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: If the cover is contaminated with oil, you have to clean it close.

NOTE: A second person is required. Counterhold against the hexagon of corresponding camshaft with an open-ended wrench.

- 14. Install intake camshaft position actuator adjuster and/or the exhaust camshaft position actuator adjuster (3).
- 15. Install a NEW intake camshaft position actuator adjuster bolt and/or a NEW exhaust camshaft position actuator adjuster bolt (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 138: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

16. Install the EN-6340 locking tool into the camshaft position actuator adjusters.

NOTE: The spot type marking (4) on the intake camshaft position actuator adjuster does not correspond to the groove of EN-6340 locking tool - left during this process but must be somewhat above as shown.

1. Install the EN-6340 locking tool - left (1) in the camshaft position actuator adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft position actuator adjuster must correspond to the groove on EN-6340 locking tool - right.

2. Install the EN-6340 locking tool - right (2) in the camshaft position actuator adjusters as shown.

CAUTION: Refer to Torque-to-Yield Fastener Caution.

NOTE: If the cover is contaminated with oil, you have to clean it close.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 177	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

NOTE: A second technician is required.

NOTE: Use an appropriate open-end wrench in order to counterhold the camshaft

hexagon. A thin cross-section wrench is required for a better fit. The Use of EN-6628-A locking tool is for the camshaft adjustment to prevent misalignment of the camshafts. The wrench is required to counterhold the

camshafts during bolt torque procedure.


17. Tighten the camshaft position actuator adjuster bolts (2) in three passes use the EN-45059 meter :

Hold at the appropriate camshaft hexagon.

- 1. First pass tighten to 50 (37 lb ft).
- 2. Second pass to 150 degrees.
- 3. Final pass to 15 degrees.

NOTE: Check the closure bolt seal ring.

- 18. Install the 2 camshaft position actuator adjuster closure plugs (1) and tighten to 30 (22 lb ft).
- 19. Remove the EN-6628-A locking tool.



Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 178	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Fig. 139: Crankshaft Sprocket Courtesy of GENERAL MOTORS COMPANY

NOTE: When installing the crankshaft sprocket, the cam and the groove must align (2).

20. Install the crankshaft sprocket (1).




Fig. 140: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

NOTE: The crankshaft sprocket and oil pump housing must align.

21. Set the crankshaft in the direction of engine rotation to TDC. Use the crankshaft balancer bolt.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 179	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 141: Timing Belt Tensioner
Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 22. Install the timing belt tensioner (2) and tighten the NEW timing belt tensioner bolt (1) in three passes use the **EN-45059** meter :
 - 1. First pass tighten to 20 (15 lb ft).
 - 2. Second pass to 120 degrees.
 - 3. Third pass to 15 degrees.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 180	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 142: Timing Belt Idler Pulley Bolt Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 23. Install the timing belt idler pulley (2) and tighten the NEW bolt (1) in three passes use the **EN-45059** meter :
 - 1. First pass tighten to 20 (15 lb ft).
 - 2. Second pass to 120 degrees.
 - 3. Third pass to 15 degrees.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 181	© 2011 Mitchell Repair Information Company, LLC.





Fig. 143: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

- 24. Install the timing belt (1).
- 25. Guide the timing belt past the tensioner and place it on the crankshaft sprocket wheel.
- 26. Place the timing belt on the exhaust and intake camshaft position actuator adjusters.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 182	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 144: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 27. Apply tension to the timing belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 28. Remove the **EN-6333** pin (3).

NOTE: The timing belt tensioner moves automatically to the correct position.

- 29. Release tension on timing belt tensioner.
- 30. Lower the vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 183	© 2011 Mitchell Repair Information Company, LLC.




Fig. 145: Engine Mount Bracket And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 31. Install the engine mount bracket (2).
- 32. Install the 3 engine mount bracket bolts (1) tighten to 62 (46 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 146: Engine Mount And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 33. Install the engine mount (4).
- 34. Install the 2 engine mount bolts (1) and tighten to 62 (46 lb ft).

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 35. Install the 3 engine mount bolts (2) and tighten in three passes use the EN-45059 meter.
 - 1. First pass tighten to 50 (37 lb ft).
 - 2. Second pass to 60 degrees.
 - 3. Third pass to 15 degrees.
- 36. Unsupport the engine.
- 37. Remove EN-6340 locking tool.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 185	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 147: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

38. Check the timing

NOTE: Note the marking at the camshaft sprockets.

• Turn the crankshaft 720 degrees in the direction of engine rotation by the bolt on the crankshaft balancer.

NOTE: The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of EN-6340 locking tool - left during this process but must be somewhat above as shown.

• Install EN-6340 locking tool - left (1) into the camshaft adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340 locking tool - right.

- Install EN-6340 locking tool right (2) into the camshaft adjusters as shown.
- Raise the vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 186	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 148: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

NOTE: The crankshaft sprocket and oil pump housing must align.

39. Check the crankshaft position.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 149: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

40. Install the lower timing belt cover (1).

CAUTION: Refer to Fastener Caution.

- 41. Install the 4 lower timing belt cover bolts (2) and tighten to 6 (53 lb in).
- 42. Install the crankshaft balancer. Refer to <u>Crankshaft Balancer Replacement (Manual Transmission)</u>, <u>Crankshaft Balancer Replacement (Automatic Transmission)</u>.
- 43. Lower the vehicle.
- 44. Remove the EN-6340 locking tool.
- 45. Install the camshaft position actuator solenoid valve. Refer to Camshaft Position Actuator Solenoid Valve Replacement.
- 46. Install the 2 camshaft position sensors. Refer to Camshaft Position Sensor Replacement.
- 47. Install the camshaft cover. Refer to **Camshaft Cover Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 188	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 150: Timing Belt Upper Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

- 48. Install the timing belt upper front cover (1).
- 49. Install the 2 timing belt upper front cover bolts (2) and tighten to 6 (53 lb in).
- 50. Install the exhaust manifold. Refer to **Exhaust Manifold Replacement (LUW)**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 189	© 2011 Mitchell Repair Information Company, LLC.





Fig. 151: Radiator Inlet Hose And Clamp Courtesy of GENERAL MOTORS COMPANY

- 51. Install the radiator inlet hose (3) with the radiator inlet hose clamp (2) to the engine coolant thermostat (1).
- 52. Install the heater inlet hose to the engine coolant thermostat housing. Refer to <u>Heater Inlet Hose</u> <u>Replacement (LUJ)</u>, <u>Heater Inlet Hose Replacement (LUW)</u>.
- 53. Install the heater outlet hose to the engine coolant thermostat housing. Refer to <u>Heater Outlet Hose</u> <u>Replacement (LUJ)</u>, <u>Heater Outlet Hose Replacement (LUW)</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 190	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 152: Thermostat Housing Bracket, Bolts And Wiring Harness</u> Courtesy of GENERAL MOTORS COMPANY

- 54. Install the engine coolant thermostat housing bracket (2).
- 55. Install the engine coolant thermostat housing bracket nut (3) and tighten to 6 (53 lb in).
- 56. Connect the thermostat wiring harness plug (1).
- 57. Install the intake manifold. Refer to **Intake Manifold Replacement**.
- 58. Install the air cleaner assembly. Refer to Air Cleaner Assembly Replacement.
- 59. Fill engine oil. Refer to **Engine Mechanical Specifications**.
- 60. Connect the battery negative cable. Refer to **Battery Negative Cable Disconnection and Connection**.
- 61. Fill the cooling system. Refer to <u>Cooling System Draining and Filling (GE-47716 Fill)</u>, <u>Cooling System Draining and Filling (Static Fill)</u>.

OIL PAN REPLACEMENT

Removal Procedure

- 1. Open the hood.
- 2. Raise and support the vehicle. Refer to <u>Lifting and Jacking the Vehicle</u>.
- 3. Place collecting basin underneath.


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 191	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 4. Remove the oil drain bolt.
- 5. Collect the engine oil.

CAUTION: Refer to Fastener Caution.

- 6. Install the NEW seal ring and the oil drain bolt, tighten to 14 N.m (124 lb in).
- 7. Lower the vehicle.
- 8. Remove the oil level indicator tube. Refer to Oil Level Indicator Tube Replacement.
- 9. Raise the vehicle.
- 10. Remove the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 11. Remove the engine oil heater. Refer to **Engine Oil Heater Replacement**.
- 12. Remove the exhaust front pipe. Refer to **Exhaust Front Pipe Replacement**.



<u>Fig. 153: Oil Pan Bolts</u> Courtesy of GENERAL MOTORS COMPANY

13. Remove the 3 oil pan bolts (1, 2) from the transmission.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 192	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 154: Oil Pan And Bolts
Courtesy of GENERAL MOTORS COMPANY

NOTE: Remove the oil pan evenly all the way around with a suitable tool.

14. Remove the 15 oil pan bolts (1) and remove the oil pan (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 193	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 155: Protecting Oil Screen From Damage Courtesy of GENERAL MOTORS COMPANY

NOTE: Use a screwdriver or another suitable tool.

- 15. To prevent damage to the oil screen, ensure that the oil screen (2) remains in the oil pan (3). If the oil screen gets caught on the cylinder block (1), push it into the oil pan.
- 16. Remove the oil pan.

Installation Procedure

1. Clean the sealing surfaces.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 194	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 156: Joints For Sealant Application
Courtesy of GENERAL MOTORS COMPANY

2. Apply an approximately 3.5 mm (0.14 in) thick bead of oil pan sealant to the joints (arrows).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 195	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 157: Sealant Application Area
Courtesy of GENERAL MOTORS COMPANY

NOTE: The assembly time including torque check must take no longer than 10 minutes.

3. Apply an approximately 3.5 mm (0.14 in) thick bead of oil pan sealant (1) as illustrated.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 196	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 158: Oil Pan And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

4. Install the 15 oil pan bolts (1) to the oil pan (2) and tighten to 10 N.m (89 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 197	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 159: Oil Pan Bolts
Courtesy of GENERAL MOTORS COMPANY

- 5. Install the 3 oil pan bolts (1, 2) to the transmission and tighten to 40 N.m (30 lb ft).
- 6. Install the exhaust front pipe. Refer to **Exhaust Front Pipe Replacement**.
- 7. Install the engine oil heater. Refer to **Engine Oil Heater Replacement**.
- 8. Install the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 9. Lower the vehicle.
- 10. Install the oil level indicator tube. Refer to Oil Level Indicator Tube Replacement.

NOTE: Inspect the engine oil level and correct if necessary.

- 11. Refill the collected engine oil.
- 12. Close the hood.

AUTOMATIC TRANSMISSION FLEX PLATE REPLACEMENT

Special Tools

EN-652 Automatic Transmission Flex Plate Holder


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 198	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

1. Remove the automatic transmission. Refer to **Transmission Replacement**.



<u>Fig. 160: Automatic Transmission Flex Plate And Holder</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Install the EN-652 holder (1) to hold the automatic transmission flex plate (2).
- 3. Loosen the 6 automatic transmission flex plate bolts.
- 4. Remove the **EN-652** holder (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 1	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 161: Automatic Transmission Flex Plate And Bolts Courtesy of GENERAL MOTORS COMPANY

- 5. Remove the 6 automatic transmission flex plate bolts (2).
- 6. Remove the automatic transmission flex plate (1).

Installation Procedure

1. Clean the automatic transmission flex plate bolt threads.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 200	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 162: Automatic Transmission Flex Plate And Holder Courtesy of GENERAL MOTORS COMPANY

2. Install the automatic transmission flex plate (2) and the **EN-652** holder to hold the automatic transmission flex plate (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 201	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 163: Automatic Transmission Flex Plate And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 3. Install the 6 NEW automatic transmission flex plate bolts (2) and tighten the bolts to 60 N.m (44 lb ft) \pm 5°.
- 4. Remove the EN-652 holder.
- 5. Install the automatic transmission. Refer to **Transmission Replacement**.

ENGINE FLYWHEEL REPLACEMENT (MANUAL TRANSMISSION)

Removal Procedure

- 1. Remove the manual transmission. Refer to **Transmission Replacement**.
- 2. Remove the clutch pressure and driven plate. Refer to <u>Clutch Pressure and Driven Plate Replacement</u>

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a. m.	Page 202	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

(1.4L LUJ), Clutch Pressure and Driven Plate Replacement (1.8L LUW).

3. Remove the engine flywheel. Refer to **Engine Flywheel Removal**.

Installation Procedure

- 1. Install the engine flywheel. Refer to **Engine Flywheel Installation**
- 2. Install the clutch pressure and driven plate. Refer to <u>Clutch Pressure and Driven Plate Replacement</u> (1.4L LUJ), <u>Clutch Pressure and Driven Plate Replacement (1.8L LUW)</u>.
- 3. Install the manual transmission. Refer to **Transmission Replacement**.

CRANKSHAFT BALANCER REPLACEMENT (AUTOMATIC TRANSMISSION)

Special Tools

- EN-6625 Crankshaft Locking Device
- EN-45059 Angle Meter

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

- 1. Open the hood.
- 2. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.
- 3. Remove the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 4. Remove the drive belt. Refer to **Drive Belt Replacement**.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 164: Automatic Transmission Bracket Bolt Courtesy of GENERAL MOTORS COMPANY

5. Remove the bolt (1).





Fig. 165: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 6. Install the EN-6625 locking device (2) to lock the crankshaft.
- 7. Install the bolt (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:55 a.m.	Page 205	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 166: Crankshaft Balancer And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 8. Remove and DISCARD the crankshaft balancer bolt (1).
- 9. Remove the crankshaft balancer (2).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 206	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 167: Crankshaft Balancer And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

1. Install the crankshaft balancer (2).

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to $\underline{\text{Torque-to-Yield Fastener Caution}}$.

- 2. Install a NEW crankshaft balancer bolt (1) and tighten in 3 passes using the EN-45059 meter:
 - 1. First pass to 95 N.m (70 lb ft).
 - 2. Second pass to 45°.
 - 3. Third pass to 15° .

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 207	© 2011 Mitchell Repair Information Company, LLC.




Fig. 168: Locking Device And Bolt Courtesy of GENERAL MOTORS COMPANY

- 3. Remove the bolt (1).
- 4. Remove EN-6625 locking device (2) to unlock the crankshaft.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 169: Automatic Transmission Bracket Bolt Courtesy of GENERAL MOTORS COMPANY

- 5. Install the bolt (1) and tighten to 45 N.m (33 lb ft).
- 6. Install the drive belt. Refer to **Drive Belt Replacement**.
- 7. Install the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 8. Lower the vehicle.
- 9. Close the hood.

CRANKSHAFT BALANCER REPLACEMENT (MANUAL TRANSMISSION)

Special Tools

- EN-6625 Crankshaft Locking Device
- EN-45059 Angle Meter

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

1. Open the hood.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 209	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 2. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle.
- 3. Remove the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 4. Remove the drive belt. Refer to **Drive Belt Replacement**.
- 5. Remove the transmission front mount. Refer to **Transmission Front Mount Replacement**.




Fig. 170: Connection Bolt Courtesy of GENERAL MOTORS COMPANY

6. Remove the bolted connection (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 2	© 2011 Mitchell Repair Information Company, LLC.





Fig. 171: Locking Device
Courtesy of GENERAL MOTORS COMPANY

- 7. Install the EN-6625 locking device (2) to lock the crankshaft.
- 8. Install the bolted connection (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 2	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 172: Crankshaft Balancer And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 9. Remove and DISCARD the crankshaft balancer bolt (1).
- 10. Remove the crankshaft balancer (2).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 212	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 173: Crankshaft Balancer And Bolt Courtesy of GENERAL MOTORS COMPANY

1. Install the crankshaft balancer (2).

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 2. Install a NEW crankshaft balancer bolt (1) and tighten in 3 passes using the EN-45059 meter :
 - 1. First pass to 95 N.m (70 lb ft).
 - 2. Second pass to 45°.
 - 3. Third pass to 15° .

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 213	© 2011 Mitchell Repair Information Company, LLC.




Fig. 174: Locking Device
Courtesy of GENERAL MOTORS COMPANY

- 3. Remove the bolted connection (1).
- 4. Remove EN-6625 locking device (2) to unlock the crankshaft.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 2	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 175: Connection Bolt
Courtesy of GENERAL MOTORS COMPANY

- 5. Install the bolted connection (1) and tighten to 40 N.m (30 lb ft).
- 6. Install the transmission front mount. Refer to **Transmission Front Mount Replacement**.
- 7. Install the drive belt. Refer to **Drive Belt Replacement**.
- 8. Install the right front wheelhouse liner. Refer to **Front Wheelhouse Liner Replacement**.
- 9. Lower the vehicle.
- 10. Close the hood.

CRANKSHAFT FRONT OIL SEAL REPLACEMENT

Special Tools

- EN-6351 Mounting Sleeves
- EN-45000 Remover


For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 215	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

1. Replace the timing belt. Refer to **Timing Belt Replacement**.



<u>Fig. 176: Crankshaft Sprocket</u> Courtesy of GENERAL MOTORS COMPANY

2. Remove the crankshaft sprocket (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 216	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 177: Crankshaft Front Oil Seal Removal Tool Courtesy of GENERAL MOTORS COMPANY


CAUTION: Clean the crankshaft sealing surface with a clean, lint-free towel. Inspect lead-in edge of crankshaft for burrs/sharp edges that could damage the rear main oil seal. Remove burrs/sharp edges with crocus cloth before proceeding.

3. Using the EN-45000 remover (3), remove the crankshaft front oil seal (1) from the crankshaft (2).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 217	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 178: Crankshaft And Crankshaft Front Oil Seal</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the sealing surfaces.
- 2. Slide the EN-6351 mounting sleeves (2) protective sleeve onto the crankshaft journal.
- 3. Slide the crankshaft front oil seal (1) over the protective sleeve on the crankshaft journal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 218	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 179: Crankshaft Drive Gear Bolt, Washer And Sleeves</u> Courtesy of GENERAL MOTORS COMPANY

- 4. Remove the protective sleeve, and using the **EN-6351** mounting sleeves (3), press the seal ring into the pump housing.
- 5. Use the crankshaft drive gear bolt (1) and washer (2) to press in the crankshaft front oil seal.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 180: Crankshaft Sprocket
Courtesy of GENERAL MOTORS COMPANY

NOTE: When installing the crankshaft sprocket, the cam and the groove must align (2).

- 6. Install the crankshaft sprocket (1).
- 7. Install the timing belt. Refer to **Timing Belt Replacement**.

CRANKSHAFT REAR OIL SEAL REPLACEMENT

Special Tools

- EN-235-D Installer Kit
- EN-328-B Pin Remover
- EN-658-1 Installer
- **EN-6624** Remover

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 220	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 1. For vehicle with automatic transmission: remove the automatic transmission flex plate. Refer to **Automatic Transmission Flex Plate Replacement**.
- 2. For vehicle with manual transmission: remove the engine flywheel. Refer to **Engine Flywheel Replacement (Manual Transmission)**.
- 3. Place the collecting basin underneath.





Fig. 181: Crankshaft Position Sensor And Bolt Courtesy of GENERAL MOTORS COMPANY

- 4. Remove the crankshaft position sensor bolt (2).
- 5. Remove the crankshaft position sensor (3) from the crankshaft rear oil seal housing (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 22	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 182: Crankshaft Position Sensor Reluctor Ring And Oil Seal Housing</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Do not allow the crankshaft encoder wheel to come into contact with external magnetic fields or sharp metal objects. Do not drop the crankshaft encoder wheel. Do not damage the rubberized encoder track. Failure to follow these precautions may cause damage to the component.

- 6. Remove the crankshaft rear oil seal housing (1).
- 7. Remove the crankshaft position sensor reluctor ring (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 222	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 183: Holes At 5 O'clock And 7 O'clock Positions Courtesy of GENERAL MOTORS COMPANY

NOTE: The diameter of the hole must not exceed 2 mm (0.0787 in). If the diameter of the hole exceeds 2 mm (0.0787 in), the bolt of EN-6624 remover will not be able to grip.

8. Only make a hole at the 5 o'clock and 7 o'clock positions (1), these are the only positions where is a cavity behind the seal ring.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 223	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 184: Scribe Tool
Courtesy of GENERAL MOTORS COMPANY

9. Using a suitable tool, such as a scribe (1), make a hole in the crankshaft rear oil seal.

Position the scribe (1) at the outer edge of the crankshaft rear oil seal.

10. Remove the seal ring.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 22	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 185: crankshaft Rear Oil Seal Removal Tool Courtesy of GENERAL MOTORS COMPANY

11. Install EN-6624 remover (1) to the crankshaft rear oil seal and tighten the bolt.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 225	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 186: Special Removal Tools</u> Courtesy of GENERAL MOTORS COMPANY

12. Install the EN-328-B remover (1) to EN-6624 remover (2) and remove the crankshaft rear oil seal.

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 226	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 187: Crankshaft Rear Oil Seal</u> Courtesy of GENERAL MOTORS COMPANY

1. Slide the crankshaft rear oil seal (2) across the EN-235-6 installer (1) contained in EN-235-D kit.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 188: Crankshaft Rear Oil Seal And Installer Courtesy of GENERAL MOTORS COMPANY

2. Install the crankshaft rear oil seal (1) with EN-235-6 installer (2) to the crankshaft.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 189: Oil Seal Installer Courtesy of GENERAL MOTORS COMPANY

3. Use EN-658-1 installer (2) to strike the crankshaft rear oil seal (1)

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 229	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 190: Check Crankshaft Rear Oil Seal For Proper Seat</u> Courtesy of GENERAL MOTORS COMPANY

4. Check the crankshaft rear oil seal for proper seat, the **EN-658-1** installer (1) must be flush with the cylinder block at the position (arrow).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 230	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 191: Crankshaft Position Sensor Reluctor Ring And Oil Seal Housing</u> Courtesy of GENERAL MOTORS COMPANY


5. Install the crankshaft position sensor reluctor ring (2).

CAUTION: Do not allow the crankshaft encoder wheel to come into contact with external magnetic fields or sharp metal objects. Do not drop the crankshaft encoder wheel. Do not damage the rubberized encoder track. Failure to follow these precautions may cause damage to the component.

6. Install the crankshaft rear oil seal housing (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 231	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 192: Crankshaft Position Sensor And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

7. Install the crankshaft position sensor (3) to the crankshaft rear oil seal housing (1).

CAUTION: Refer to Fastener Caution.

- 8. Install the crankshaft position sensor bolt (2) and tighten to 4.5 N.m (40 lb in).
- 9. Remove the collecting basin.
- 10. For vehicle with manual transmission: install the engine flywheel. Refer to **Engine Flywheel Replacement (Manual Transmission)**.
- 11. For vehicle with automatic transmission: install the automatic transmission flex plate. Refer to <u>Automatic Transmission Flex Plate Replacement</u>.


POSITIVE CRANKCASE VENTILATION HOSE/PIPE/TUBE REPLACEMENT

Removal Procedure

1. Open the hood.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 23	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 193: Positive Crankcase Ventilation Tube, Connectors And ECM Wiring Harness Guide</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Unclip the ECM wiring harness guide (3) from the cylinder head cover.
- 3. Disconnect the 2 positive crankcase ventilation tube connectors (1).
- 4. Remove the positive crankcase ventilation tube (2).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 233	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 194: Positive Crankcase Ventilation Tube, Connectors And ECM Wiring Harness Guide</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Install the positive crankcase ventilation tube (2).
- 2. Connect the 2 positive crankcase ventilation tube connectors (1).
- 3. Clip in the ECM wiring harness guide (3) to the cylinder head cover.
- 4. Close the hood.

ENGINE OIL HEATER REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 234	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 195: Engine Oil Heater And Bolt Courtesy of GENERAL MOTORS COMPANY

Engine Oil Heater Replacement

Callout	Component Name		
WARNING:			
While engine is operating, the exhaust system will become extremely hot. To prevent burns avoid contacting a hot exhaust system.			
Preliminary Procedures Disconne Disconnection and Connection.	ct the battery negative cable. Refer to <u>Battery Negative Cable</u>		
1	Engine Oil Heater Bolt CAUTION: Refer to Fastener Caution. Tighten		
2	40 N.m (30 lb ft) Engine Oil Heater Procedure Disconnect the wiring harness plug.		

ENGINE FRONT COVER WITH OIL PUMP REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 235	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Removal Procedure

- 1. Open the hood.
- 2. Disconnect the negative battery cable. Refer to <u>Battery Negative Cable Disconnection and</u> Connection .
- 3. Remove the exhaust manifold. Refer to **Exhaust Manifold Replacement (LUW)**.
- 4. Drain the cooling system. Refer to <u>Cooling System Draining and Filling (GE-47716 Fill)</u>, <u>Cooling System Draining and Filling (Static Fill)</u>.
- 5. Remove the air conditioning compressor. Refer to <u>Air Conditioning Compressor Replacement (LUJ)</u>, <u>Air Conditioning Compressor Replacement (LUW)</u>.
- 6. Remove the generator. Refer to Generator Replacement (LUJ), Generator Replacement (LUW).
- 7. Remove the timing belt rear cover. Refer to **Timing Belt Rear Cover Replacement**.
- 8. Remove the oil pan. Refer to **Oil Pan Replacement**.
- 9. Remove the radiator outlet hose from the water pump. Refer to <u>Radiator Outlet Hose Replacement</u> (<u>LUW</u>), <u>Radiator Outlet Hose Replacement</u> (<u>LUJ</u>).





Fig. 196: Engine Oil Cooler Outlet Pipe And Bolts Courtesy of GENERAL MOTORS COMPANY

10. Remove the engine oil cooler inlet pipe bolt (4).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 236	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 11. Push the engine oil cooler inlet pipe (1) into the engine oil cooler housing (2).
- 12. Remove the 2 engine oil cooler outlet pipe bolts (5) from the water pump.
- 13. Push the engine oil cooler outlet pipe (3) into the engine oil cooler housing (2).



<u>Fig. 197: Engine Front Cover, Seal And Bolts</u> Courtesy of GENERAL MOTORS COMPANY


- 14. Remove the 8 engine front cover bolts (2, 3).
- 15. Remove the engine front cover (4).
- 16. Remove the engine front cover seal (1).

Installation Procedure

1. Clean sealing surface.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 237	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 198: Engine Front Cover, Seal And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Install a NEW engine front cover seal (1).
- 3. Install the engine front cover (4).

CAUTION: Refer to Fastener Caution.

4. Install the 8 engine front cover bolts (2, 3) and tighten to 20 N.m (15 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 238	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 199: Engine Oil Cooler Outlet Pipe And Bolts Courtesy of GENERAL MOTORS COMPANY

- 5. Push the engine oil cooler outlet pipe (3) to the water pump (6).
- 6. Install the engine oil cooler outlet pipe bolts (5) and tighten to 8 N.m (71 lb in).
- 7. Push the engine oil cooler inlet pipe (1) into the water pump (6).
- 8. Install the engine oil cooler inlet pipe bolt (4) and tighten to 8 N.m (71 lb in).
- 9. Install the radiator outlet hose to the water pump. Refer to <u>Radiator Outlet Hose Replacement (LUW)</u>, <u>Radiator Outlet Hose Replacement (LUJ)</u>.
- 10. Install the oil pan. Refer to Oil Pan Replacement.
- 11. Install the timing belt rear cover. Refer to **Timing Belt Rear Cover Replacement**.
- 12. Install the generator. Refer to **Generator Replacement (LUJ)**, **Generator Replacement (LUW)**.
- 13. Install the air conditioning compressor. Refer to <u>Air Conditioning Compressor Replacement (LUJ)</u>, <u>Air Conditioning Compressor Replacement (LUW)</u>.
- 14. Install the exhaust manifold. Refer to **Exhaust Manifold Replacement (LUW)**.
- 15. Connect the negative battery cable. Refer to **Battery Negative Cable Disconnection and Connection** .
- 16. Fill the cooling system. Refer to <u>Cooling System Draining and Filling (GE-47716 Fill)</u>, <u>Cooling System Draining and Filling (Static Fill)</u>.
- 17. Close the hood.


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a.m.	Page 239	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

OIL PRESSURE RELIEF VALVE REPLACEMENT

Removal Procedure

1. Remove the oil pan. Refer to Oil Pan Replacement.



<u>Fig. 200: Oil Pressure Relief Valve Assembly</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Remove the oil pressure relief valve closure bolt (1).
- 3. Remove the oil pressure relief valve assembly (2).
- 4. Remove the piston (3) and the spring (4).

WARNING: Bodily injury may occur if the cleaning solvent is inhaled or exposed to the skin.

WARNING: To avoid eye injury, use approved safety lenses, goggles, or face shield when using buffing and cleaning equipment.

5. Clean the parts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 240	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 6. Inspect the parts.
- 7. Clean the thread.

Installation Procedure




Fig. 201: Oil Pressure Relief Valve Assembly Courtesy of GENERAL MOTORS COMPANY

- 1. Install the piston (3) and the spring (4).
- 2. Install the oil pressure relief valve assembly (2).

CAUTION: Refer to Fastener Caution.

- 3. Install the oil pressure relief valve closure bolt (1) and tighten to 21 N.m (16 lb ft).
- 4. Install the oil pan. Refer to Oil Pan Replacement.


ENGINE OIL COOLER HOUSING REPLACEMENT

Refer to <u>Engine Oil Cooler Replacement (LUW)</u>, <u>Engine Oil Cooler Replacement (LUJ)</u>, it is the same procedure.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 24	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

OIL FLOW CHECK VALVE REPLACEMENT



<u>Fig. 202: Oil Flow Check Valve</u> Courtesy of GENERAL MOTORS COMPANY

Oil Flow Check Valve Replacement

Callout	Component Name
Preliminary Procedure	
Remove the generator. Refer to Ger	nerator Replacement (LUJ), Generator Replacement (LUW).
	Oil Flow Check Valve Bore Plug
1	CAUTION: Refer to <u>Fastener Caution</u> .
	Tighten 21 N.m (16 lb ft)
2	Oil Flow Check Valve

OIL LEVEL INDICATOR TUBE REPLACEMENT

Removal Procedure

1. Open the hood.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 242	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

2. Remove the oil dipstick.

NOTE: If the engine oil level is at maximum, some oil may emerge when drawing out the oil dipstick guide tube.

3. Place collecting basin underneath.




Fig. 203: Oil Level Indicator Tube And Bolt Courtesy of GENERAL MOTORS COMPANY

- 4. Remove the oil level indicator tube bolt (1).
- 5. Remove the oil level indicator tube (2) and the oil level indicator seal.

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 243	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 204: Oil Level Indicator Tube And Bolt Courtesy of GENERAL MOTORS COMPANY

- 1. Install the oil level indicator tube (2).
- 2. Install a NEW oil level indicator tube gasket.

CAUTION: Refer to Fastener Caution.

- 3. Install the oil level indicator tube bolt (1) and tighten to 15 N.m (11 lb ft).
- 4. Install the oil dipstick.
- 5. Close the hood.

ENGINE REPLACEMENT


Removal Procedure

- 1. Disconnect the negative battery cable from the battery. Refer to <u>Battery Negative Cable Disconnection</u> and <u>Connection</u>.
- 2. Drain the engine cooling system. Refer to <u>Cooling System Draining and Filling (GE-47716 Fill)</u>, <u>Cooling System Draining and Filling (Static Fill)</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:56 a. m.	Page 244	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

3. Recover the air conditioning refrigerant. Refer to **Refrigerant Recovery and Recharging**.



<u>Fig. 205: Air Cleaner Assembly, Electrical Connector And Clamp</u> Courtesy of GENERAL MOTORS COMPANY

- 4. Disconnect the electrical connector (1).
- 5. Loosen the clamp (2) and remove air cleaner from air cleaner assembly (3).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 206: Air Cleaner Outlet Duct And Clamp Courtesy of GENERAL MOTORS COMPANY

- 6. Loosen the clamp (1) and remove the outlet duct (2).
- 7. Remove the charge air cooler inlet air hose. Refer to **Charge Air Cooler Inlet Air Hose Replacement**.
- 8. Remove the charge air cooler outlet air hose. Refer to <u>Charge Air Cooler Outlet Air Hose</u>

 <u>Replacement (Manual Transmission)</u>, <u>Charge Air Cooler Outlet Air Hose Replacement (Automatic Transmission)</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 2	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 207: Refrigerant Hose And Nut Courtesy of GENERAL MOTORS COMPANY

9. Remove refrigerant hose nut (1) from refrigerant hose (2).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 208: Fuel Feed Pipe Courtesy of GENERAL MOTORS COMPANY

10. Disconnect the fuel feed line (1) and reposition away from the engine. Refer to **Fuel Pressure Relief**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 2	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 209: Fuel Ventilation Pipe Courtesy of GENERAL MOTORS COMPANY

11. Disconnect the EVAP hose (1). Refer to <u>Plastic Collar Quick Connect Fitting Service</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 249	© 2011 Mitchell Repair Information Company, LLC.


2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 210: Brake Booster Vacuum Pipe</u> Courtesy of GENERAL MOTORS COMPANY

12. Disconnect the power brake booster vacuum pipe (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 211: Radiator Surge Tank Outlet Hose Clamp</u> Courtesy of GENERAL MOTORS COMPANY

13. Reposition the hose clamp (1) and remove the radiator surge tank outlet hose.


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 251	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 212: Heater Core Inlet And Outlet Hoses</u> Courtesy of GENERAL MOTORS COMPANY


14. Disconnect inlet (2) and outlet (1) heater core hoses.



<u>Fig. 213: Transmission Range Selector Lever And Cable Connection</u> Courtesy of GENERAL MOTORS COMPANY

- 15. On vehicles equipped with a automatic transmission, disconnect the transmission range selector lever cable terminal (1) from the transmission manual shift lever pin.
- 16. On vehicles equipped with a automatic transmission, press the locking tabs inward in order to release the transmission range selector lever cable (2) from the cable bracket.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 25	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 214: Selector Lever Cable, Bracket And Transmission Control Housing</u> Courtesy of GENERAL MOTORS COMPANY

- 17. On vehicles equipped with a manual transmission, using a suitable pry tool, disconnect the shift lever cables (2) from the shift levers (3)
- 18. On vehicles equipped with a manual transmission, remove the shift lever cables (2) from the cable bracket (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 254	© 2011 Mitchell Repair Information Company, LLC.





Fig. 215: Ground Strap And Bolt Courtesy of GENERAL MOTORS COMPANY

- 19. Remove the ground strap bolt (1) from the battery cable and reposition the strap (2) a side.
- 20. Remove the battery tray. Refer to **Battery Tray Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 255	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 216: Wiring Harnesses And Ground Nuts</u> Courtesy of GENERAL MOTORS COMPANY

- 21. Remove the ground nuts (1) and put the wiring harness (2) aside.
- 22. Disconnect the electrical connectors from the engine control module (ECM). Refer to **Engine Control Module Replacement**.
- 23. Disconnect the wiring harness from the accessory wiring junction block.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 256	© 2011 Mitchell Repair Information Company, LLC.





Fig. 217: Junction Connector Courtesy of GENERAL MOTORS COMPANY

- 24. Disconnect the wiring harness from the junction connector (1).
- 25. Place the ECM, transmission and the accessory wiring junction block wiring harnesses on the top of engine assembly.
- 26. Install the engine support fixture.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 25	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 218: Lower Steering Intermediate Shaft Bolt</u> Courtesy of GENERAL MOTORS COMPANY

27. Remove and DISCARD the lower steering intermediate shaft bolt (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 258	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 219: Brake Caliper And Brake Caliper Guide Pin Bolt</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Do Not disconnect the brake hoses from the calipers.

- 28. Remove the front brake calipers (1) and caliper bolts (2) from the caliper brackets, and then suspend the calipers with mechanics wire to the body.
- 29. Remove the exhaust system. Refer to Exhaust System Replacement.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 259	© 2011 Mitchell Repair Information Company, LLC.




Fig. 220: Stabilizer Link Nut
Courtesy of GENERAL MOTORS COMPANY

- 30. Remove and DISCARD the stabilizer link nut (1) from the strut assemblies. Refer to **Stabilizer Shaft Link Replacement**.
- 31. Disconnect the right wheel drive shaft from the intermediate shaft.
- 32. Disconnect the front steering knuckles from the strut assemblies. Refer to **Steering Knuckle Replacement**.
- 33. Disconnect the electronic power steering connectors from the electronic power steering assembly. Refer to **FEP Connectors (Steering Gear)**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 260	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 221: Transmission Bracket Mount To Mount Through Bolt Courtesy of GENERAL MOTORS COMPANY

34. Remove the rear transmission mount bracket to rear mount through bolt (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 261	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 222: Front Transmission Mount Through Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 35. Remove the transmission front mount through bolt (1).
- 36. Using suitable straps or chains, secure the front of vehicle to the hoist arms.

NOTE: Use the engine support fixture to slightly raise the powertrain assembly to aid in the removal of the engine and transmission mount bolts.

37. Use the engine support fixture to slightly raise the powertrain assembly to aid in the removal of the engine and transmission mount bolts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 26	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 223: Automatic Transmission Mount Bracket Bolts Courtesy of GENERAL MOTORS COMPANY

38. Remove and DISCARD the left transmission mount to bracket bolts (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 263	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 224: Engine Mount Bracket Bolts And Washers</u> Courtesy of GENERAL MOTORS COMPANY

- 39. Remove the engine mount to engine mount bracket bolts (1) and the washers (2).
- 40. Using a suitable engine support table, lower the vehicle until the drivetrain and front suspension frame contacts the engine support table.
- 41. Position blocks of wood below the oil pan and transmission to stabilize the powertrain on the support table.
- 42. Using the engine support fixture, lower the powertrain down until it is resting on the engine support table.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 264	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 225: Power Steering Gear, Inlet And Outlet Hose And Bolts Courtesy of GENERAL MOTORS COMPANY

- 43. Remove the power steering gear inlet and outlet hose bolts (1). Remove the inlet and outlet hose (2) from the steering gear (3).
- 44. Remove the engine support fixture.
- 45. Remove the drivetrain and front suspension frame reinforcements from the rear of the frame.
- 46. Remove the front drivetrain and front suspension frame retaining bolts.
- 47. Slowly and carefully raise the vehicle, ensure the engine, transmission, radiator assembly and drivetrain suspension frame are free from wiring, hoses and other engine compartment components.
- 48. Separate the transmission from the engine assembly.
- 49. Disconnect engine coolant hoses as necessary.
- 50. Disconnect electrical connectors as necessary.
- 51. Transfer components as necessary.

Installation Procedure

- 1. Position the engine to the transmission assembly.
- 2. Position the engine, transmission, radiator assembly and drivetrain suspension frame under the vehicle.
- 3. Slowly and carefully lower the vehicle, ensure the engine, transmission, radiator assembly and drivetrain

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 265	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

suspension frame are free from wiring, hoses and other engine compartment components.

CAUTION: Refer to Fastener Caution.

- 4. Install the four front drivetrain and front suspension frame retaining bolts, then tighten to the fasteners to 160 N.m (118 lb ft).
- 5. Install the drivetrain and front suspension frame reinforcements to the rear of the frame, then tighten the reinforcement fasteners to 22 N.m (16 lb ft).

NOTE: Use the engine support fixture to slightly raise the powertrain assembly to aid in the installation of the engine and transmission mount bolts.

6. Install the engine support fixture. Refer to **Engine Support Fixture**.





Fig. 226: Transmission Bracket Mount To Mount Through Bolt Courtesy of GENERAL MOTORS COMPANY

7. Install the transmission bracket mount to mount through bolt (1) and tighten to 100 N.m (74 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 266	© 2011 Mitchell Repair Information Company, LLC.




<u>Fig. 227: Front Transmission Mount Through Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 8. Install the transmission mount through bolt (1) and tighten to 58 N.m (43 lb ft).
- 9. Install the engine mount. Refer to **Engine Mount Replacement Right Side**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 26	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 228: Automatic Transmission Mount Bracket Bolts</u> Courtesy of GENERAL MOTORS COMPANY

WARNING: Refer to Torque-to-Yield Fastener Warning .

10. Install the NEW left transmission mount to transmission bolts (1) and tighten to 50 N.m (37 lb ft) plus 60-75 degrees.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 26	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 229: Power Steering Gear, Inlet And Outlet Hose And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 11. Install the inlet and outlet hose (2) to the steering gear (3).
- 12. Install power steering gear inlet and outlet hose bolts (1) and tighten to 11 N.m (97 lb in).




Fig. 230: Lower Steering Intermediate Shaft Bolt Courtesy of GENERAL MOTORS COMPANY

- 13. Instal NEW the lower steering intermediate shaft (1) bolt and tighten to 34 N.m (25 lb ft).
- 14. Connect the front steering knuckles to the strut assemblies. Refer to **Steering Knuckle Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 270	© 2011 Mitchell Repair Information Company, LLC.




Fig. 231: Stabilizer Link Nut
Courtesy of GENERAL MOTORS COMPANY

- 15. Install NEW the stabilizer link nut (1) to the strut assemblies. Refer to $\underline{\textbf{Stabilizer Shaft Link}}$ $\underline{\textbf{Replacement}}$.
- 16. Connect the right wheel drive shaft from the intermediate shaft.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 27	© 2011 Mitchell Repair Information Company, LLC.





Fig. 232: Brake Caliper And Brake Caliper Guide Pin Bolt Courtesy of GENERAL MOTORS COMPANY

- 17. Install the front brake caliper (1) and tighten the brake caliper guide pin bolt (2) to 28 N.m (21 lb ft).
- 18. Install the exhaust system. Refer to **Exhaust System Replacement**.
- 19. Connect the wheel speed connectors to the steering knuckles.
- 20. Remove the engine support fixture.
- 21. Connect the wiring connectors and ground strap to the transmission.
- 22. Connect the wiring harness to the accessory wiring junction block.
- 23. Connect the electrical connectors to the ECM. Refer to **Engine Control Module Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a. m.	Page 272	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 233: Wiring Harnesses And Ground Nuts</u> Courtesy of GENERAL MOTORS COMPANY

- 24. Install the wiring harnesses (2).
- 25. Install the ground nuts (1) and tighten to 9 N.m (80 lb in).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 234: Junction Connector Courtesy of GENERAL MOTORS COMPANY

26. Connect the wiring harness plugs (1).


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 274	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 235: Transmission Range Selector Lever And Cable Connection</u> Courtesy of GENERAL MOTORS COMPANY

- 27. On vehicles equipped with a automatic transmission, connect the transmission range selector lever cable terminal (1) to the transmission manual shift lever pin.
- 28. On vehicles equipped with a automatic transmission, press the locking tabs outward in order to lock the transmission range selector lever cable (2) to the cable bracket.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 27	© 2011 Mitchell Repair Information Company, LLC.




<u>Fig. 236: Selector Lever Cable, Bracket And Transmission Control Housing</u> Courtesy of GENERAL MOTORS COMPANY

- 29. On vehicles equipped with a manual transmission, connect the shift lever cables (2) to the shift levers (3)
- 30. On vehicles equipped with a manual transmission, install the shift lever cables (2) to the cable bracket (1).
- 31. Install the battery tray. Refer to $\underline{\textbf{Battery Tray Replacement}}$.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 276	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 237: Heater Core Inlet And Outlet Hoses</u> Courtesy of GENERAL MOTORS COMPANY

32. Connect inlet (2) and outlet (1) heater core hoses.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 277	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 238: Brake Booster Vacuum Pipe</u> Courtesy of GENERAL MOTORS COMPANY

33. Connect the power brake booster vacuum pipe (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 239: Radiator Surge Tank Outlet Hose Clamp Courtesy of GENERAL MOTORS COMPANY

34. Connect the coolant hose and reposition the clamp (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 240: Fuel Feed Pipe Courtesy of GENERAL MOTORS COMPANY

35. Connect the fuel feed line (1) and reposition away from the engine. Refer to <u>Fuel Pressure Relief</u>.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 280	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 241: Fuel Ventilation Pipe Courtesy of GENERAL MOTORS COMPANY

36. Connect the EVAP hose (1). Refer to Plastic Collar Quick Connect Fitting Service .

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:57 a.m.	Page 281	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 242: Refrigerant Hose And Nut Courtesy of GENERAL MOTORS COMPANY

NOTE: Use NEW O-ring seals. Refer to <u>Air Conditioning O-Ring Seal</u> <u>Replacement</u>.

- 37. Install refrigerant hose (2) and tighten the nut (1) to 19 N.m (14 lb ft).
- 38. Install the charge air cooler inlet air hose. Refer to **Charge Air Cooler Inlet Air Hose Replacement**.
- 39. Install the charge air cooler outlet air hose. Refer to Charge Air Cooler Outlet Air Hose Replacement (Manual Transmission), Charge Air Cooler Outlet Air Hose Replacement (Automatic Transmission).
- 40. Connect engine coolant hoses as necessary.
- 41. Connect electrical connectors as necessary.
- 42. Install the front fascia.
- 43. Install the front wheelhouse front liners.
- 44. Install the air cleaner assembly. Refer to Air Cleaner Assembly Replacement.
- 45. Fill the engine cooling system. Refer to <u>Cooling System Draining and Filling (GE-47716 Fill)</u>, Cooling System Draining and Filling (Static Fill).

46. Charge the air conditioning system. Refer to Refrigerant Recovery and Recharging

10. Charge the air conditioning system. Refer to refer the receivery and recentifing.		
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 282	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 47. Check engine oil level. Refer to Engine Oil and Oil Filter Replacement.
- 48. Connect the negative battery cable to the battery. Refer to <u>Battery Negative Cable Disconnection and Connection</u>.

ENGINE OIL AND OIL FILTER REPLACEMENT

Removal Procedure

- 1. Open hood.
- 2. Place a drain pan below the vehicle.

CAUTION: To prevent damage to oil filter cap ensure proper tool is used. Do not use an open end wrench which may cause damage to filter cap.

3. Using a 24mm socket or closed end wrench loosen oil filter cap. Unscrew filter cap 3 turns and let oil filter and cap assembly drain in housing for 30 seconds.




Fig. 243: Engine Oil Filter Cap, Cap Seal Ring And Oil Filter Element Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 283	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

NOTE: Use care when removing engine oil filter cap and filter to minimize fluid

spillage. If fluid spillage occurs it must be cleaned with appropriate

cleaner.

NOTE: Inspect oil filter cap for any cracks or damage. If oil filter cap is damaged it

must be replaced.

4. Remove the engine oil filter cap (2) with the engine oil filter cap seal ring (3) and the oil filter element (1).

- 5. Raise and support the vehicle. Refer to <u>Lifting and Jacking the Vehicle</u>.
- 6. Remove the oil pan drain plug and allow the oil to drain into the drain pan.

Installation Procedure

- 1. Clean the oil pan drain plug thread in the oil pan.
- 2. Install a NEW seal ring to the oil pan drain plug.

CAUTION: Refer to Component Fastener Tightening Caution.

- 3. Install the oil pan drain plug and tighten to 14 N.m (10 lb ft).
- 4. Lower the vehicle.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 244: Oil Filter Cap Seal Ring Courtesy of GENERAL MOTORS COMPANY

NOTE: Clean oil filter cap and lubricate the NEW oil filter cap seal ring with clean engine oil. Ensure oil filter cap seal ring is in proper position as shown.

5. Install a NEW oil filter cap seal ring (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 28	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 245: Engine Oil Filter Cap, Cap Seal Ring And Oil Filter Element</u> Courtesy of GENERAL MOTORS COMPANY

6. Install the engine oil filter cap (2) with NEW engine oil filter cap seal ring (3) and NEW oil filter element (1) hand tight.




Fig. 246: Oil Filter Cap Seal Ring

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 286	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Courtesy of GENERAL MOTORS COMPANY

CAUTION: Ensure oil filter cap is completely seated on oil filter housing. If not completely seated an oil leak may occur.

CAUTION: Over torquing the oil filter cap may cause damage to the oil filter cap resulting in an oil leak.

7. Using a 24mm socket or closed end wrench tighten the engine oil filter cap to 25 N.m (18 lb ft).

CAUTION: Using engine oils of any viscosity other than those viscosities recommended could result in engine damage.

NOTE: Do not overfill the engine with engine oil.

NOTE: Anytime engine oil is added (top off or oil changes) ensure all engine

surfaces are completely free of residual oil. If there is oil on any engine

surface clean as necessary.

8. Fill engine with NEW oil using DexosTM1 5W-30 specification.





Fig. 247: Proper Oil Filler Cap Seating
Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 287	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

NOTE: Oil fill cap must be properly seated and tightened during installation.

- 9. Install oil fill cap.
- 10. Start the engine and allow it to run until the oil pressure control indicator goes off. Inspect for any oil leaks around the drain plug, oil filter and oil fill cap.



<u>Fig. 248: Engine Oil Level Indicator</u> Courtesy of GENERAL MOTORS COMPANY

- 11. Inspect the engine oil level. The oil level should be in the cross-hatched section of the oil level indicator as shown.
- 12. Close hood.
- 13. Reset the engine oil life system monitor.

CAMSHAFT SEAL REPLACEMENT

Special Tools

- EN-422 Installer
- EN-45000 Remover

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 288	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

1. Remove the camshaft position actuator adjuster. Refer to <u>Camshaft Position Actuator Adjuster Replacement</u>.




Fig. 249: Camshaft Front Oil Seals And Tool Courtesy of GENERAL MOTORS COMPANY

NOTE: Do not damage the sealing surfaces.

2. Use the EN-45000 remover to loosen the camshaft front oil seals (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 289	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 250: Camshaft Front Oil Seals
Courtesy of GENERAL MOTORS COMPANY

3. Remove the camshaft front oil seals (1).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 290	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 251: Camshaft Front Oil Seals
Courtesy of GENERAL MOTORS COMPANY

1. Insert 2 NEW camshaft front oil seals (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 291	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 252: Camshaft Sprocket Bolt, Shims And Tool Courtesy of GENERAL MOTORS COMPANY

- 2. Tighten the seal ring with EN-422 installer (3) on the camshaft until this is in contact with the cylinder head.
- 3. To install, use camshaft sprocket bolt (1) in conjunction with shims (2) with a total thickness of approximately 10 mm (0.393 in).
- 4. Install the camshaft position actuator adjuster. Refer to <u>Camshaft Position Actuator Adjuster Replacement</u>.

CAMSHAFT COVER REPLACEMENT

Removal Procedure

- 1. Open the hood.
- 2. Remove the ignition coil. Refer to **Ignition Coil Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 292	© 2011 Mitchell Repair Information Company, LLC.





Fig. 253: Wiring Harness Guide And Cylinder Head Cover Courtesy of GENERAL MOTORS COMPANY

- 3. Unclip the ECM wiring harness guide (1) from the cylinder head cover.
- 4. Disconnect the wiring guide (2).
- 5. Remove the positive crankcase ventilation tube. Refer to **Positive Crankcase Ventilation Hose/Pipe/Tube Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 29	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 254: Camshaft Cover And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 6. Remove the 11 bolts (2, 3).
- 7. Remove the camshaft cover (1).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 294	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 255: Camshaft Cover And Bolts
Courtesy of GENERAL MOTORS COMPANY

1. Install the camshaft cover (1).

Insert a NEW gasket in the cylinder head cover.

CAUTION: Refer to Fastener Caution.

- 2. Install the 11 bolts (2, 3) and tighten to 8 N.m (71 lb in).
- 3. Install the positive crankcase ventilation tube. Refer to **Positive Crankcase Ventilation Hose/Pipe/Tube Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 29	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 256: Wiring Harness Guide And Cylinder Head Cover Courtesy of GENERAL MOTORS COMPANY

- 4. Clip in the ECM wiring harness guide (1) to the cylinder head cover.
- 5. Connect the wiring guide (2).
- 6. Install the ignition coil. Refer to **Ignition Coil Replacement**.
- 7. Close the hood.

CAMSHAFT POSITION ACTUATOR ADJUSTER REPLACEMENT

Special Tools

- EN-6340 Camshaft Adjuster Locking Tool
- EN-6333 Timing Belt Tensioner Locking Pin
- EN-6625 Crankshaft Locking Device
- EN-6628-A Camshaft Locking Tool
- EN-45059 Angle Meter


For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 296	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Removal Procedure

1. Remove the air cleaner housing. Refer to Air Cleaner Assembly Replacement.



<u>Fig. 257: Timing Belt Upper Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Remove the 2 timing belt upper front cover bolts (2).
- 3. Remove the timing belt upper front cover (1).
- 4. Remove the camshaft cover. Refer to **Camshaft Cover Replacement**.
- 5. Remove the 2 camshaft position actuator solenoid valve. Refer to <u>Camshaft Position Actuator Solenoid</u> <u>Valve Replacement</u>.
- 6. Remove the drive belt. Refer to **Drive Belt Replacement**.
- 7. Remove the drive belt tensioner. Refer to **Drive Belt Tensioner Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 297	© 2011 Mitchell Repair Information Company, LLC.




Fig. 258: Crankshaft TDC Position
Courtesy of GENERAL MOTORS COMPANY

- 8. Set the crankshaft balancer in direction of engine rotation until the markings (1) line up with the cylinder 1 at TDC.
- 9. Remove the crankshaft balancer. Refer to <u>Crankshaft Balancer Replacement (Manual Transmission)</u>, <u>Crankshaft Balancer Replacement (Automatic Transmission)</u>.
- 10. Remove the EN-6625 locking device.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 298	© 2011 Mitchell Repair Information Company, LLC.




Fig. 259: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 11. Remove the 4 lower timing belt cover bolts (2).
- 12. Remove the lower timing belt cover (1).
- 13. Lower the vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 299	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 260: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE: The right half of the EN-6340 locking tool can be recognized by the lettering "right", arrow, on the tool.

- 14. Prepare the right half of the EN-6340 locking tool.
 - 1. Remove the 2 bolts (2).
 - 2. Remove the front panel (1) from the EN-6340 locking tool right.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 300	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 261: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

15. Install the EN-6340 locking tool into the camshaft adjusters.

NOTE: The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of EN-6340 locking tool - left during this process but must be somewhat above as shown.

• Install the EN-6340 locking tool - left (1) into the camshaft adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340 locking tool - right.

• Install EN-6340 locking tool - right (2) into the camshaft adjusters as shown.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 301	© 2011 Mitchell Repair Information Company, LLC.





Fig. 262: Drive Belt Tensioner, Allen Key And Locking Pin Courtesy of GENERAL MOTORS COMPANY

- 16. Apply tension to the timing belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 17. Install the **EN-6333** pin (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.




<u>Fig. 263: Timing Belt Idler Pulley Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 18. Remove and DISCARD the timing belt idler pulley bolt (1).
- 19. Remove the timing belt idler pulley (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 264: Timing Belt And Timing Belt Tensioner</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the direction of the belt, if the timing belt will be reused.

- 20. Remove the timing belt (1).
- 21. Remove and DISCARD the timing belt tensioner bolt (3).
- 22. Remove the timing belt tensioner (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 304	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 265: Turning Crankshaft Against Direction Of Engine Rotation</u> Courtesy of GENERAL MOTORS COMPANY

23. Set the crankshaft in direction of engine rotation to 60 degrees (a) before TDC. Use the **EN-45059** meter and the crankshaft balancer bolt.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 266: Crankshaft Sprocket</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Some engine oil will run out of the camshaft and the camshaft position actuator adjuster. That is the reason for the removal of the whole timing assembly.

- 24. Remove the crankshaft sprocket (1).
- 25. Lower the vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 267: Aligning Camshafts Horizontally
Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the arrows.

26. Turn the camshaft by the hexagon until the groove on the end of the camshafts is horizontal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 307	© 2011 Mitchell Repair Information Company, LLC.





Fig. 268: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

- 27. Install the EN-6628-A locking tool (1).
- 28. Raise and support the vehicle. Refer to <u>Lifting and Jacking the Vehicle</u>.
- 29. Place a collecting basin underneath the vehicle.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 308	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 269: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

30. Remove the camshaft position actuator adjuster closure bolt (1) of the intake camshaft position actuator adjuster and/or the exhaust camshaft position actuator adjuster (3).

NOTE: A second technician is required.

NOTE: Use an appropriate open-end wrench in order to counterhold the camshaft

hexagon. A thin cross-section wrench is required for a better fit. The usage of EN-6628-A locking tool is for the camshaft adjustment to prevent misalignment of the camshafts. The wrench is required to counterhold the


camshafts during bolt torque procedure.

- 31. Remove and DISCARD the intake camshaft position actuator adjuster bolt and/or the exhaust camshaft position actuator adjuster bolt (2).
- 32. Remove the intake camshaft position actuator adjuster and/or the exhaust camshaft position actuator adjuster (3).

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 309	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 270: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: If the cover is contaminated with oil, you have to clean it close.

- 1. Install intake camshaft position actuator adjuster and/or the exhaust camshaft position actuator adjuster (3).
- 2. Install a NEW intake camshaft position actuator adjuster bolt and/or a NEW exhaust camshaft position actuator adjuster bolt (2). DO NOT tighten the bolts yet.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 271: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

3. Install the EN-6340 locking tool into the camshaft position actuator adjusters.

NOTE:

The spot type marking (4) on the intake camshaft position actuator adjuster does not correspond to the groove of EN-6340-left locking tool - left during this process but must be somewhat above as shown.

1. Install the EN-6340-left locking tool (1) in the camshaft position actuator adjusters as shown.


NOTE:

The spot type marking (3) on the exhaust camshaft position actuator adjuster must correspond to the groove on EN-6340-left locking tool - right.

2. Install the EN-6340-right locking tool (2) in the camshaft position actuator adjusters as shown.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 311	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 272: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

 $\textbf{CAUTION: Refer to } \underline{\textbf{Torque-to-Yield Fastener Caution}} \;.$

NOTE: A second technician is required.

NOTE: Use an appropriate open-end wrench in order to counterhold the camshaft

hexagon. A thin cross-section wrench is required for a better fit. The usage of EN-6628-A locking tool is for the camshaft adjustment to prevent misalignment of the camshafts. The wrench is required to counterhold the

camshafts during bolt torque procedure.

- 4. Tighten the camshaft position actuator adjuster bolts (2) in three passes use the EN-45059 meter :
 - 1. First pass tighten to 50 N.m (37 lb ft).
 - 2. Second pass to 150 degrees.


2. Second pass to 150 degrees.		
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 312	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

3. Final pass to 15 degrees.

NOTE: Check the closure bolt seal ring.

- 5. Install the 2 camshaft position actuator adjuster closure plugs (1) and tighten to 30 N.m (22 lb ft).
- 6. Remove the EN-6628-A locking tool.
- 7. Raise the vehicle.



<u>Fig. 273: Timing Belt Tensioner</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 8. Install the timing belt tensioner (2) and tighten the NEW timing belt tensioner bolt (1) in three passes use the **EN-45059** meter :
 - 1. First pass tighten to 20 N.m (15 lb ft).
 - 2. Second pass to 120 degrees.
 - 3. Final pass to 15 degrees.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 274: Timing Belt Idler Pulley Bolt Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 9. Install the timing belt idler pulley (2) and tighten the NEW bolt (1) in three passes use the **EN-45059** meter :
 - 1. First pass tighten to 20 N.m (15 lb ft).
 - 2. Second pass to 120 degrees.
 - 3. Final pass to 15 degrees.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a.m.	Page 314	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 275: Crankshaft Sprocket Courtesy of GENERAL MOTORS COMPANY

NOTE: When installing the crankshaft sprocket, the cam and the groove must align (2).

10. Install the crankshaft sprocket (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 276: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

11. Set the crankshaft in the direction of engine rotation to TDC. Use the crankshaft balancer bolt.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 316	© 2011 Mitchell Repair Information Company, LLC.





Fig. 277: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

- 12. Install the timing belt (1).
- 13. Guide the timing belt past the tensioner and place it on the crankshaft sprocket wheel.
- 14. Place the timing belt on the exhaust and intake camshaft position actuator adjusters.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:58 a. m.	Page 317	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 278: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 15. Apply tension to the timing belt tensioner (2) in the direction of the arrow, using an allen key (1).
- 16. Remove the **EN-6333** pin (3).

NOTE: The timing belt tensioner moves automatically to the correct position.

- 17. Release tension on timing belt tensioner.
- 18. Check position of the camshaft and camshaft position actuator adjuster.
 - 1. Turn crankshaft 720 degrees in the direction of engine rotation by the crankshaft balancer bolt.

NOTE: Note marking, camshaft position actuator adjuster.

2. Insert EN-6340 locking tool into camshaft position actuator adjuster.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 318	© 2011 Mitchell Repair Information Company, LLC.





Fig. 279: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

- 19. Insert the EN-6628-A locking tool (1) into the camshafts.
- 20. Align camshafts by hexagon until EN-6628-A locking tool can be inserted in both camshafts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 319	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 280: Aligning Timing Belt Drive Gear And Oil Pump Housing</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: The crankshaft sprocket and oil pump housing must align.

- 21. Check the crankshaft position.
- 22. Remove the **EN-6628-A** locking tool.





Fig. 281: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 23. Install the lower front timing belt cover (1) and tighten the 4 bolts (2) to 6 N.m (53 lb in).
- 24. Install the crankshaft balancer. Refer to <u>Crankshaft Balancer Replacement (Manual Transmission)</u>, <u>Crankshaft Balancer Replacement (Automatic Transmission)</u>.
- 25. Install the drive belt tensioner. Refer to **Drive Belt Tensioner Replacement**.
- 26. Install the drive belt. Refer to **Drive Belt Replacement**.
- 27. Lower the vehicle.
- 28. Install the camshaft position actuator solenoid valve. Refer to <u>Camshaft Position Actuator Solenoid</u> <u>Valve Replacement</u>.
- 29. Install the camshaft cover. Refer to **Camshaft Cover Replacement**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 321	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 282: Timing Belt Upper Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

- 30. Install the timing belt upper front cover (1).
- 31. Install the 2 timing belt upper front cover bolts (2) and tighten to 6 N.m (53 lb in).
- 32. Install the air cleaner housing. Refer to Air Cleaner Assembly Replacement.

CAMSHAFT POSITION ACTUATOR SOLENOID VALVE REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 322	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 283: Camshaft Position Actuator Solenoid Valve Courtesy of GENERAL MOTORS COMPANY

Camshaft Position Actuator Solenoid Valve Replacement

Callout	Component Name
	Camshaft Position Actuator Solenoid Valve Bolt (Qty: 2)
	CAUTION:
1	Refer to <u>Fastener Caution</u> .
	Tighten
	6 N.m (53 lb in)
2	Camshaft Position Actuator Solenoid Valve (Qty: 2)
3	Camshaft Position Actuator Solenoid Valve Seal (Qty: 2) TIP: Coat the camshaft position actuator solenoid valve seals with
3	NEW engine oil.

CAMSHAFT REPLACEMENT

Special Tools

- EN-422 Installer
- EN-6628-A Locking Tool

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 323	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

- 1. Remove the camshaft adjuster. Refer to **Camshaft Position Actuator Adjuster Replacement**.
- 2. Remove the rear timing belt cover. Refer to **Timing Belt Rear Cover Replacement**.
- 3. Remove intake camshaft position sensor. Refer to **Camshaft Position Sensor Replacement**.
- 4. Remove exhaust camshaft position sensor. Refer to Camshaft Position Sensor Replacement.
- 5. Remove EN-6628-A locking tool.

Counterhold at hexagon of camshaft.




Fig. 284: Camshaft Bearing Cap And Camshaft Bearing Cap Bolts Removal Sequence Courtesy of GENERAL MOTORS COMPANY

NOTE: Note removal sequence 1-4.


6. Remove the 4 camshaft bearing cap bolts.

NOTE: Release the bearing support by striking it gently with a plastic hammer.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 32	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

7. Remove the first camshaft bearing cap (1).



<u>Fig. 285: Exhaust Camshaft Bearing Cap Bolts Loosening Sequence</u> Courtesy of GENERAL MOTORS COMPANY


- 8. Loosen the 8 exhaust camshaft bearing cap bolts working from outside to inside in a spiral in steps of 1/2 up to 1 turn.
- 9. Remove the 8 exhaust camshaft bearing cap bolts.

NOTE: Mark camshaft bearing caps before removal.

- 10. Remove the 4 exhaust camshaft bearing caps Numbers 6-9 from the cylinder head.
- 11. Remove the exhaust camshaft (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 286: Intake Camshaft Bearing Cap Bolts Loosening Sequence</u> Courtesy of GENERAL MOTORS COMPANY

- 12. Loosen the 8 intake camshaft bearing cap bolts working from outside to inside in a spiral in steps of 1/2 up to 1 turn.
- 13. Remove the 8 intake camshaft bearing cap bolts.

NOTE: Mark camshaft bearing caps before removal.

- 14. Remove the 4 intake camshaft bearing caps Numbers 2-5 from the cylinder head.
- 15. Remove the intake camshaft (1).
- 16. Detach the seal rings from the camshafts.

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 326	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 287: Intake Camshaft Bearing Cover Bolts Tightening Sequence Courtesy of GENERAL MOTORS COMPANY

NOTE: Lubricate with clean engine oil.

1. Install the intake camshaft (1).

NOTE: Note the identification marking on the camshaft bearing cover.


2. Install the 4 intake camshaft bearing cover Numbers 2-5.

CAUTION: Refer to Fastener Caution.

3. Install the 8 intake camshaft bearing cover bolts and tighten in a spiral from the inside to the outside to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 327	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 288: Exhaust Camshaft Bearing Cover Bolts Tightening Sequence</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Lubricate with clean engine oil.

4. Install the exhaust camshaft (1).

NOTE: Note the identification marking on the camshaft bearing cover.

- 5. Install the 4 exhaust camshaft bearing cover Numbers 6-9.
- 6. Install the 8 exhaust camshaft bearing cover bolts and tighten in a spiral from the inside to the outside to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 328	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 289: Oil Duct Courtesy of GENERAL MOTORS COMPANY


NOTE: Sealing surfaces must be free from oil and grease.

7. Clean sealing surfaces of the first camshaft bearing support and the cylinder head with a suitable tool.

Clean oil duct from any sealant residue.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 290: Sealing Surfaces And Grooves</u> Courtesy of GENERAL MOTORS COMPANY

NOTE:

- Sealing surfaces must be free from oil and grease.
- It is essential to ensure that no sealant is applied outside the marked sealing areas.
- The grooves adjacent to the sealing surfaces must remain free from sealant.
- 8. Apply surface sealant to sealing surfaces (1) of the first camshaft bearing cap thinly and evenly.
- 9. Position the first camshaft bearing cap on the cylinder block and tighten the bolts approximately to 2 N.m (18 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 291: Camshaft Bearing Cap Courtesy of GENERAL MOTORS COMPANY

NOTE: No sealant may reach the camshafts.


10. Install the first camshaft bearing cap (1).

NOTE: Note installation sequence 1-4.

11. Install the first camshaft bearing cap bolts and tighten to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 331	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 292: Camshaft Sprocket Bolt, Shims And Tool</u> Courtesy of GENERAL MOTORS COMPANY

- 12. Install 2 NEW sealing rings to the camshafts.
- 13. Tighten the seal ring with **EN-422** installer (3) on the camshaft until this is in contact with the cylinder head.
- 14. To install, use camshaft sprocket bolt (1) in conjunction with shims (2) with a total thickness of approximately 10 mm (0.394 in).
- 15. Remove the EN-422 installer (3).
- 16. Turn the intake camshaft against the direction of engine rotation.
- 17. Install EN-6628-A locking tool.
- 18. Turn the exhaust camshaft in the direction of rotation of the engine.
- 19. Install EN-6628-A locking tool.
- 20. Install exhaust camshaft position sensor. Refer to Camshaft Position Sensor Replacement.
- 21. Install intake camshaft position sensor. Refer to **Camshaft Position Sensor Replacement**.
- 22. Install the rear timing belt cover. Refer to **Timing Belt Rear Cover Replacement**.
- 23. Install the camshaft adjuster. Refer to **Camshaft Position Actuator Adjuster Replacement**.

VALVE STEM OIL SEAL AND VALVE SPRING REPLACEMENT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 332	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze


Special Tools

- 207649 Rod Hairpin Clips
- **547324** Flange Screws
- EN-840 Pliers / Remover
- EN-958 Installer
- EN-45059 Angle Meter
- EN-50717 Kit
- J-43649-2 Rods

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

- 1. Remove the spark plugs. Refer to **Spark Plug Replacement**.
- 2. Remove the camshaft position actuator adjuster. Refer to <u>Camshaft Position Actuator Adjuster</u> <u>Replacement</u>.
- 3. Remove both camshafts. Refer to **Camshaft Replacement**.
- 4. Remove the valve lifter. Refer to **Valve Lifter Replacement**.



Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 333	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Fig. 293: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

- 5. For cylinder 1 and 4 set the crankshaft to TDC marking, cylinder number 1. Use the crankshaft balancer bolt.
- 6. For cylinder 2 and 3, set the crankshaft BDC (180 degrees from TDC marking). Use the crankshaft balancer bolt.

NOTE: Wheels must contact the ground.

7. Shift to 1. gear (MT) or park position (AT) and apply the park brake.

Valve Stem Oil Seal Removal





Fig. 294: Special Tools
Courtesy of GENERAL MOTORS COMPANY

- 1. Install the 2 EN-50717-1 stands (1) to the cylinder head and fix them with the 547324 screws.
- 2. Install the 2 J-43649-2 rods (2) and the EN-51717-2 compressor (3) to the B-side of the EN-50717-1 stands. Secure the rods with the 207649 clips then.
- 3. Install an suitable air pressure adapter (4) to the spark plug hole.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 334	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 4. Apply air pressure to the corresponding cylinder.
- 5. Position the **EN-51717-2** compressor (3) so that its adapter proper contacts the valve spring retainer and pretension the compressor.




<u>Fig. 295: Valve Spring Retainer And Valve Spring</u> Courtesy of GENERAL MOTORS COMPANY

WARNING: Valve springs can be tightly compressed. Use care when removing the retainers and plugs. Personal injury could result.

- 6. Apply pressure to the **EN-50717-2** compressor to push down the vale spring retainer (1) and compress the valve spring (3) until the valve keys (2) are free from tension. Carefully remove the valve keys then.
- 7. Release the tension from the EN-50717-2 compressor.
- 8. Remove the valve spring retainer (1) and the valve spring (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 335	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 296: Valve Stem Seal Removal Tool</u> Courtesy of GENERAL MOTORS COMPANY

9. Remove and DISCARD the valve stem oil seal, using the EN-840 pliers (1).

Valve Stem Oil Seal Installation

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 336	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 297: Intake Valve Stem Oil Seal Installation Tool</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Lubricate the NEW valve stem oil seal with clean engine oil.

- 1. Install the NEW valve stem oil seal, using the EN-958 installer (1).
- 2. Loosely install the valve spring and the valve spring retainer.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 33	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 298: Valve Spring Compressor</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: The valve stem keys must correctly seat in the valve spring cap. Engine damage may occur by not installing properly.

- 3. Using the **EN-51717-2** compressor (4), push down the valve spring retainer (1) and compress the valve spring (3) until the valve keys (2) can be inserted. Carefully insert the valve keys then, so that they are proper installed to the valve stem grooves.
- 4. Carefully release the tension from the EN-50717-2 compressor.
- 5. Inspect the valve keys and valve spring retainer for proper seat.
- 6. Repeat the procedure with the remaining valves and cylinders. Transfer the **EN-50717-1** stands and the **EN-51717-2** compressor as needed.
- 7. Take care that air pressure is always applied to the combustion chamber of the treated cylinder.

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 338	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 299: Turning Crankshaft Against Direction Of Engine Rotation Courtesy of GENERAL MOTORS COMPANY

- 1. Set the crankshaft in direction of engine rotation to 60 degrees (a) before TDC. Use the **EN-45059** meter and the crankshaft balancer bolt.
- 2. Install the valve lifter. Refer to **Valve Lifter Replacement**.
- 3. Install both camshafts. Refer to Camshaft Replacement.
- 4. Install the camshaft position actuator adjuster. Refer to <u>Camshaft Position Actuator Adjuster Replacement</u>.
- 5. Install the spark plugs. Refer to **Spark Plug Replacement**.

VALVE GUIDE REAMING, AND VALVE AND SEAT GRINDING

Valve Cleaning Procedure

- 1. Use soft bristle wire brush to clean any carbon build-up from the valve head. DO NOT use a wire brush on any part of the valve stem. The valve stem is chrome plated to provide enhanced wear characteristics. Wire brushing the stem could remove the chrome plating.
- 2. Thoroughly clean the valve with solvent and wipe dry.

Valve Visual Inspection Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 339	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 300: Inspection Points For Valve Damage Courtesy of GENERAL MOTORS COMPANY

- 1. Inspect the valve for damage from the head to tip for the following conditions:
 - Pitting in the valve seat area (1)
 - Lack of valve margin (2)
 - Bending in the valve stem (3)
 - Pitting or excessive wear in the stem (4)
 - Worn valve key grooves (5)
 - Worn valve tip (6)
- 2. Replace the valve if any of these conditions exist.

Valve Measurement and Reconditioning Overview

NOTE: Proper v

• Proper valve service is critical to engine performance. Therefore, all

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 340	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- detailed measurement procedures must be followed to identify components that are out of specification.
- If the measurement procedures reveal that the valve or valve seat must be reconditioned, it is critical to perform the measurement procedures after reconditioning.

Valve Seat Width Measurement Procedure




Fig. 301: Checking Valve Seat Width
Courtesy of GENERAL MOTORS COMPANY

1. Measure the valve seat width in the cylinder head using a proper scale.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 341	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 302: Measuring Seat Width On Valve Face Courtesy of GENERAL MOTORS COMPANY

2. Measure the seat width on the valve face (1) using a proper scale.

NOTE:

The seat contact area must be at least 0.5 mm (0.020 in) from the outer diameter (margin) of the valve. If the contact area is too close to the margins, the seat must be reconditioned to move the contact area away from the margin.

- 3. Compare your measurements with the specifications, refer to **Engine Mechanical Specifications**.
- 4. If the seat widths are acceptable, check the valve seat roundness using the Valve Seat Roundness Measurement Procedure.
- 5. If the seat width is not acceptable, you must grind the valve seat using the Valve and Seat Reconditioning Procedure to bring the width back into specification. Proper valve seat width is critical to providing the correct amount of valve heat dissipation.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 342	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze


Valve Seat Roundness Measurement Procedure

1. Measure the valve seat roundness using a dial indicator attached to a tapered pilot installed in the guide. The pilot should have a slight bind when installed in the guide.

CAUTION: The correct size pilot must be used. Do not use adjustable diameter pilots. Adjustable pilots may damage the valve guides.

- 2. Compare your measurements with the specifications, refer to **Engine Mechanical Specifications**.
- 3. If the valve seat exceeds the roundness specification, you must grind the valve and valve seat using the Valve and Seat Reconditioning Procedure.
- 4. If new valves are being used, the valve seat roundness must be within 0.05 mm (0.002 in).

Valve Margin Measurement Procedure



Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 343	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Fig. 303: Valve Margin Measurement Courtesy of GENERAL MOTORS COMPANY

- 1. Measure the valve margin using an appropriate scale.
- 2. Reference the specifications in this section for minimum valve margin and compare them to your measurements.
- 3. If the valve margins are beyond specification, replace the valves.
- 4. If the valve margins are within specification and do not require refacing, test the valve for seat concentricity using the Valve-to-Seat Concentricity Measurement Procedure.

Valve-to-Seat Concentricity Measurement Procedure




Fig. 304: Valve Contact Face Measurements
Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 344	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

NOTE:

- Checking the valve-to-seat concentricity determines whether the valve and seat are sealing properly.
- You must measure the valve face and the valve seat to ensure proper valve sealing.
- 1. Coat the valve face lightly with blue dye (3).
- 2. Install the valve in the cylinder head.
- 3. Turn the valve against the seat with enough pressure to wear off the dye.
- 4. Remove the valve from the cylinder head.
- 5. Inspect the valve face.
 - If the valve face is concentric, providing a proper seal, with the valve stem, a continuous mark will be made around the entire face (1).

NOTE:

The wear mark MUST be at least 0.5 mm (0.020 in) from the outer diameter, the margin, of the valve. If the wear mark is too close to the margin, the seat must be reconditioned to move the contact area away from the margin.

• If the face is not concentric with the stem, the mark will NOT be continuous around the valve face. The valve should be refaced or replaced and the seat must be reconditioned using the Valve and Seat Reconditioning Procedure.

Valve and Seat Reconditioning Procedure

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 305: Valve Seat Proper Angles
Courtesy of GENERAL MOTORS COMPANY

NOTE:

- If the valve seat width, roundness or concentricity is beyond specifications, you must grind the seats in order to ensure proper heat dissipation and prevent the build up of carbon on the seats.
- It is necessary to reface the valve if seat reconditioning is required unless a new valve is used.
- 1. Grind the valve seats (2) to the proper angle specification, refer to **Engine Mechanical Specifications**.
- 2. Using the proper angle specification, refer to **Engine Mechanical Specifications**, grind, relieve, the valve seats (1) to correctly position the valve seating surface (2) to the valve.
- 3. Using the proper angle specification listed in engine mechanical specifications, refer to **Engine**Mechanical Specifications, grind, undercut, the valve seats (3) to narrow the valve seat widths to the specifications, refer to **Engine Mechanical Specifications**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 346	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze


- 4. If the original valve is being used, grind the valve to the specifications, refer to **Engine Mechanical Specifications**. Measure the valve margin again after grinding using the Valve Margin Measurement Procedure. Replace the valve if the margin is out of specification. New valves do not require grinding.
- 5. When grinding the valves and seats, grind off as little material as possible. Cutting valve seat results in lowering the valve spring pressure.
- 6. Install the valve in the cylinder head.
 - If you are using refaced valves, lap the valves into the seats with a fine grinding compound. The refacing and reseating operations should leave the refinished surfaces smooth and true so that minimal lapping is required. Excessive lapping will groove the valve face and prevent a good seat when hot.

NOTE: Be sure to clean any remaining lapping compound from the valve and seat with solvent and compressed air prior to final assembly.

- If you are using new valves, do not lap the valves under any condition.
- 7. After obtaining the proper valve seat width in the cylinder head, you must re-measure the valve stem height using the Valve Stem Height Measurement Procedure.
- 8. If the valve stem height is acceptable, test the seats for concentricity using the Valve-to-Seat Concentricity Measurement Procedure.

Valve Stem Height Measurement Procedure

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 306: Measuring Valve Stem Height</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: To determine the valve stem height measurement, measure from the valve spring seat to the valve spring retainer.

- 1. Install the valve into the valve guide.
- 2. Ensure the valve is seated to the cylinder head valve seat.
- 3. Install the valve stem oil seal.
- 4. Install the valve spring retainer and valve stem locks.
- 5. Measure the distance (1) between the cylinder head to the bottom of the valve spring retainer. Refer to **Engine Mechanical Specifications**.
- 6. If the maximum height specification is exceeded, a new valve should be installed and the valve stem height re-measured.

CAUTION: DO NOT grind the valve stem tip. The tip of the valve is hardened and grinding the tip will eliminate the hardened surface causing

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 348	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

premature wear and possible engine damage.

CAUTION: DO NOT use shims in order to adjust valve stem height. The use of shims will cause the valve spring to bottom out before the camshaft lobe is at peak lift and engine damage could result.

7. If the valve stem height still exceeds the maximum height specification, the cylinder head must be replaced.

VALVE SPRING INSPECTION AND MEASUREMENT

Special Tool

GE-22738-B Valve Spring Tester

For equivalent regional tools, refer to **Special Tools**.

Inspection Procedure

1. Clean the valve springs in solvent.

WARNING: Wear safety glasses in order to avoid eye damage.

- 2. Dry the valve springs with compressed air.
- 3. Inspect the valve springs for broken coils or coil ends.

Measurement Procedure


- 1. Measure the tension of the valve spring using the **GE-22738-B** tester. Refer to **Engine Mechanical Specifications**.
- 2. If low valve spring load is found, replace the valve springs. DO NOT use shims to increase spring load. The use of shims can cause the valve spring to bottom out before the camshaft lobe is at peak lift.


REPAIR INSTRUCTIONS - OFF VEHICLE

ENGINE SUPPORT FIXTURE

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 349	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze








Fig. 307: Engine Support Fixture
Courtesy of GENERAL MOTORS COMPANY

Engine Support Fixture

Callout	Component Name	
Preliminary Procedure		
Remove the Front Fender Shipping Cover. Refer to Front Fender Shipping Cover Replacement.		

Special Tools

- J-43405 Engine Support Fixture Adapter
- J-28467-518 Main Support Beam
- J-28467-1A Cross Bracket
- J-28467-5A Strut Tower Support Assembly
- J-28467-2A Radiator Tube Shelf Assembly
- J-36857 Engine Lift Bracket
- J-28467-8A Hook Assembly

HO	r 00111170	lent regional	Ltaalc	ratar to	NACIOL	
1.()	i tanniya	ichi icytona	1 100015		THELIAL	

1		
		Engine Support Fixture Adapter Leg (Qty: 2)
	1	Procedure
		Install the bracket to fender frame. Do not install on top of fender lip.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69	
viernes, 21 de abril de 2017 10:36:59 a.m.	Page 350	© 2011 Mitchell Repair Information Company, LLC.	

2012 Chevrolet Cruze LS 2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

2	Main Support Beam
3	Cross Bracket
4	Strut Tower Support Assembly Procedure
4	Adjust the length of the strut tower support assembly.
5	Radiator Tube Shelf Assembly
6	Hook Assembly Procedure Use a grade 10.9 bolt to install the engine lift bracket. TIP: If the engine is not equipped with engine lift bracket, install J-
	36857 in place.

TIMING BELT INSPECTION

Special Tools

- EN-6340 Locking Tool
- EN-6628-A Locking Tool

For equivalent regional tools, refer to **Special Tools**.

Removal Procedure

1. Remove the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Removal**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69	
viernes, 21 de abril de 2017 10:36:59 a. m.	Page 351	© 2011 Mitchell Repair Information Company, LLC.	

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 308: Crankshaft TDC Position
Courtesy of GENERAL MOTORS COMPANY

- 2. Set the crankshaft balancer in the direction of the engine rotation to "1st cylinder TDC" (mark 1).
- 3. Remove the camshaft cover. Refer to **Camshaft Cover Removal**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69	
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 352	© 2011 Mitchell Repair Information Company, LLC.	

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 309: Front Panel And Bolts
Courtesy of GENERAL MOTORS COMPANY

NOTE: The right half of the EN-6340 locking tool can be recognized by the lettering "right", arrow, on the tool.

- 4. Prepare the right half of the EN-6340 locking tool.
 - 1. Remove the 2 bolts (2).
 - 2. Remove the front panel (1) from the EN-6340 locking tool -right.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 353	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 310: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

NOTE:

- The spot type marking (4) on the intake camshaft position actuator adjuster does not correspond to the groove of the EN-6340 locking tool - left (1) during this process, but must be somewhat above.
- The spot type marking (3) on the exhaust camshaft position actuator adjuster must correspond to the groove on EN-6340 locking tool right (2).
- 5. Insert the **EN-6340** locking tool left (1) and the **EN-6340** locking tool right (2) in the camshaft position actuator adjuster.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 354	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 311: Aligning Camshafts Horizontally
Courtesy of GENERAL MOTORS COMPANY

NOTE: If the EN-6628-A locking tool cannot be inserted, the timing must be set.

6. Align the camshafts horizontally by the hexagon (arrows) until the **EN-6628-A** locking tool can be inserted in both camshafts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 355	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 312: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

7. Insert the EN-6628-A locking tool (1) into the camshafts.

Installation Procedure

- 1. Remove the EN-6628-A locking tool.
- 2. Remove the EN-6340 locking tool.
- 3. Install the camshaft cover. Refer to **Camshaft Cover Installation**.
- 4. Install the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Installation**.

TIMING BELT ADJUSTMENT

Special Tools

- EN-652 Flywheel Holder
- EN-6333 Locking Pin
- EN-6340 Locking Tool
- EN-6628-A Locking Tool
- EN-45059 Torque Angle Sensor Kit

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69	
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 356	© 2011 Mitchell Repair Information Company, LLC.	

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tool, refer to **Special Tools**.

Removal Procedure

1. Remove the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Removal**.




Fig. 313: Crankshaft TDC Position
Courtesy of GENERAL MOTORS COMPANY

- 2. Set the crankshaft balancer in the direction of the engine rotation to "1st cylinder TDC" (mark 1).
- 3. Remove the camshaft cover. Refer to **Camshaft Cover Removal**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 35	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 314: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE: The right half of the EN-6340 locking tool can be recognized by the lettering "right", arrow, on the tool.

- 4. Prepare the right half of the EN-6340 locking tool.
 - 1. Remove the 2 bolts (2).
 - 2. Remove the front panel (1) from the EN-6340 locking tool right.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 358	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 315: Camshaft Holder And Markings Courtesy of GENERAL MOTORS COMPANY

NOTE:

- The spot type marking (4) on the intake camshaft position actuator adjuster does not correspond to the groove of the EN-6340 locking tool - left (1) during this process, but must be somewhat above.
- The spot type marking (3) on the exhaust camshaft position actuator adjuster must correspond to the groove on EN-6340 locking tool right (2).
- 5. Insert the **EN-6340** locking tool left (1) and the **EN-6340** locking tool right (2) in the camshaft position actuator adjuster.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 359	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 316: Tooth Belt Tensioner
Courtesy of GENERAL MOTORS COMPANY

- 6. Install the EN-6333 locking pin (1), apply tension to the timing belt tension roller (2) in the direction of the arrow. Install the EN-6333 locking pin (3).
- 7. Mark timing belt in direction of rotation.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 317: Flywheel And Flywheel Holder Courtesy of GENERAL MOTORS COMPANY

8. Install the **EN-652** flywheel holder (1), lock the flywheel (2) (or automatic transmission flex respectively) via the starter ring gear.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 36	© 2011 Mitchell Repair Information Company, LLC.




Fig. 318: Crankshaft Balancer And Bolt Courtesy of GENERAL MOTORS COMPANY

- 9. Remove and DISCARD the crankshaft balancer bolt (1).
- 10. Remove the crankshaft balancer (2).




Fig. 319: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

- 11. Remove the 4 timing belt lower front cover bolts (2).
- 12. Remove the timing belt lower front cover (1).




Fig. 320: Timing Belt Idler Pulley Bolt Courtesy of GENERAL MOTORS COMPANY

- 13. Remove the timing belt idler pulley bolt (1).
- 14. Remove the timing belt idler pulley (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 364	© 2011 Mitchell Repair Information Company, LLC.




Fig. 321: Timing Belt Tensioner
Courtesy of GENERAL MOTORS COMPANY

- 15. Remove the tensioner bolt (1).
- 16. Remove the timing belt tensioner (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a. m.	Page 36	© 2011 Mitchell Repair Information Company, LLC.




Fig. 322: Timing Belt And Timing Belt Tensioner Courtesy of GENERAL MOTORS COMPANY

- 17. Remove the timing belt (1).
- 18. Stop the timing belt tensioner (2).
- 19. Remove the **EN-652** flywheel holder to unlock the crankshaft.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 366	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 323: Turning Crankshaft Against Direction Of Engine Rotation Courtesy of GENERAL MOTORS COMPANY

20. Turn the crankshaft 60° (A) against the direction of engine rotation.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 367	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 324: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

21. Remove the 2 camshaft position actuator adjuster closure bolts (1).

NOTE: A second technician is required.

22. Loosen the camshaft position actuator adjuster bolts (2).

Hold at the appropriate camshaft hexagon.

23. Remove and DISCARD the camshaft position actuator adjuster bolts (2) and the camshaft position actuator adjuster (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 368	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 325: Aligning Camshafts Horizontally
Courtesy of GENERAL MOTORS COMPANY

24. Align the camshafts horizontally by the hexagon arrows, until the **EN-6628-A** locking tool can be inserted in both camshafts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 369	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 326: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

25. Insert the EN-6628-A locking tool (1) into the camshafts.

Installation Procedure

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 370	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 327: Camshaft Position Actuator Adjuster Closure Bolt Courtesy of GENERAL MOTORS COMPANY

NOTE: Do not tighten the camshaft adjuster bolts.

- 1. Install the camshaft position actuator adjuster (3).
- 2. Install NEW camshaft position actuator adjuster bolts (2).

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

NOTE: A second technician is required.

3. Tighten the camshaft position actuator adjuster bolts (2) in three passes:

Hold at the appropriate camshaft hexagon.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 371	© 2011 Mitchell Repair Information Company, LLC.

- 1. First pass tighten to 65 N.m (48 lb ft).
- 2. Second pass to 120°.
- 3. Third pass to 15°.
- 4. Replace the camshaft position actuator adjuster seal rings.
- 5. Install the 2 camshaft position actuator adjuster closure plugs (1) and tighten to 30 N.m (22 lb ft).
- 6. Remove the EN-6628-A locking tool.




Fig. 328: Timing Belt Tensioner
Courtesy of GENERAL MOTORS COMPANY

- 7. Clean the timing belt tensioner thread.
- 8. Install the timing belt tensioner (2) and tighten the NEW timing belt tensioner bolt (1) to 20 N.m (15 lb ft).
- 9. Clean the timing belt idler pulley thread.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 329: Timing Belt Idler Pulley Bolt Courtesy of GENERAL MOTORS COMPANY

10. Install the timing belt idler pulley (2) and tighten the NEW bolt (1) to 25 N.m (18 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 373	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 330: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

NOTE: The timing belt drive gear and oil pump housing must align.

11. Turn the crankshaft in the direction of engine rotation, by the crankshaft balancer bolt, to cylinder 1 TDC of combustion stroke.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 37	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 331: Flywheel And Flywheel Holder Courtesy of GENERAL MOTORS COMPANY

12. Install the **EN-652** flywheel holder (1), lock the flywheel (2) (or automatic transmission flex respectively) via the starter ring gear.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 375	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 332: Timing Belt And Timing Belt Tensioner Courtesy of GENERAL MOTORS COMPANY

NOTE: Observe direction of rotation.

- 13. Insert the timing belt (1).
- 14. Apply preliminary tension clockwise to the timing belt tension roller.
- 15. Remove the EN-6333 locking pin.
- 16. Release the tension on the timing belt tensioner.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 333: Timing Belt Lower Front Cover Courtesy of GENERAL MOTORS COMPANY

17. Install the lower front timing belt cover (1) and tighten the 4 bolts (2) to 6 N.m (53 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 377	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 334: Crankshaft Balancer And Bolt Courtesy of GENERAL MOTORS COMPANY

- 18. Install the crankshaft balancer (2) and NEW bolt (1) and tighten in 3 passes using the **EN-45059** sensor kit:
 - 1. First pass to 95 N.m (70 lb ft).
 - 2. Second pass to 45°.
 - 3. Third pass to 15° .
- 19. Remove the EN-652 flywheel holder to unlock the crankshaft.
- 20. Remove the **EN-6340** locking tool.
- 21. Check position of the camshaft position actuator adjuster.
 - 1. Turn crankshaft 720° in the direction of engine rotation by the crankshaft balancer bolt.

NOTE: Note marking, camshaft position actuator adjuster.

2. Insert EN-6340 locking tool into camshaft timing gears.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 378	© 2011 Mitchell Repair Information Company, LLC.




Fig. 335: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

- 22. Insert the EN-6628-A locking tool (1) into the camshafts.
- 23. Align camshafts by hexagon until EN-6628-A locking tool can be inserted in both camshafts.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 379	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 336: Crankshaft TDC Position
Courtesy of GENERAL MOTORS COMPANY

- 24. Check the crankshaft position.
- 25. Marking on crankshaft balancer must align with marking on timing belt lower cover, see mark (1).
- 26. Remove the EN-6628-A locking tool.
- 27. Install the camshaft cover. Refer to **Camshaft Cover Installation**.
- 28. Install the timing belt upper front cover. Refer to **Timing Belt Upper Front Cover Installation**.

DRAINING FLUIDS AND OIL FILTER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 380	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 337: Oil Filter Cap, Oil Filter Seal And Oil Filter Insert</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Place a drip pan underneath.
- 2. Remove the oil filter cap (1).
- 3. Remove the oil filter cap seal (2).
- 4. Remove and properly dispose of the oil filter insert (3).
- 5. Re-install the oil filter cap.
- 6. Remove the oil drain bolt.
- 7. Drain the engine oil into the drip pan.

AUTOMATIC TRANSMISSION FLEX PLATE REMOVAL

Special Tools

EN-652 Automatic Transmission Flex Plate Holder

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 381	© 2011 Mitchell Repair Information Company, LLC.




Fig. 338: Automatic Transmission Flex Plate And Holder Courtesy of GENERAL MOTORS COMPANY

- 1. Install the EN-652 holder (1) to hold the automatic transmission flex plate (2).
- 2. Loosen the 6 automatic transmission flex plate bolts.
- 3. Remove the EN-652 holder (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 339: Automatic Transmission Flex Plate And Bolts Courtesy of GENERAL MOTORS COMPANY

- 4. Remove the 6 automatic transmission flex plate bolts (2).
- 5. Remove the automatic transmission flex plate (1).

ENGINE FLYWHEEL REMOVAL

Special Tools

EN-652 Flywheel Holder

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 383	© 2011 Mitchell Repair Information Company, LLC.




Fig. 340: Flywheel And Flywheel Holder Courtesy of GENERAL MOTORS COMPANY

- 1. Install the EN-652 holder (1), lock the flywheel via the starter ring gear.
- 2. Loosen the 6 flywheel bolts.
- 3. Remove the **EN-652** holder (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 384	© 2011 Mitchell Repair Information Company, LLC.




Fig. 341: Flywheel And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 4. Remove and DISCARD the 6 flywheel bolts (1, 2).
- 5. Remove the flywheel (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 385	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 342: Crankshaft Position Reluctor Ring Courtesy of GENERAL MOTORS COMPANY

6. Remove the crankshaft position reluctor ring (1).

CRANKSHAFT REAR OIL SEAL REMOVAL

Special Tools

- EN-328-B Pin Remover
- EN-6624 Remover

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:00 a.m.	Page 386	© 2011 Mitchell Repair Information Company, LLC.





Fig. 343: Crankshaft Position Sensor And Bolt Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the crankshaft position sensor bolt (2).
- 2. Remove the crankshaft position sensor (3) from the crankshaft rear oil seal housing (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 344: Crankshaft Position Sensor Reluctor Ring And Oil Seal Housing</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Do not allow the crankshaft encoder wheel to come into contact with external magnetic fields or sharp metal objects. Do not drop the crankshaft encoder wheel. Do not damage the rubberized encoder track. Failure to follow these precautions may cause damage to the component.

- 3. Remove the crankshaft rear oil seal housing (1).
- 4. Remove the crankshaft position sensor reluctor ring (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a. m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 345: Holes At 5 O'clock And 7 O'clock Positions Courtesy of GENERAL MOTORS COMPANY

NOTE: The diameter of the hole must not exceed 2 mm (0.0787 in). If the diameter of the hole exceeds 2 mm (0.0787 in), the bolt of EN-6624 remover will not be able to grip.

5. Only make a hole at the 5 o'clock and 7 o'clock positions (1), these are the only positions where is a cavity behind the seal ring.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 389	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 346: Scribe Tool
Courtesy of GENERAL MOTORS COMPANY

6. Using a suitable tool, such as a scribe (1), make a hole in the crankshaft rear oil seal.

Position the scribe (1) at the outer edge of the crankshaft rear oil seal.

7. Remove the seal ring.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 347: crankshaft Rear Oil Seal Removal Tool Courtesy of GENERAL MOTORS COMPANY

8. Install EN-6624 remover (1) to the crankshaft rear oil seal and tighten the bolt.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 391	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 348: Special Removal Tools</u> Courtesy of GENERAL MOTORS COMPANY

9. Install the EN-328-B remover (1) to EN-6624 remover (2) and remove the crankshaft rear oil seal.

POSITIVE CRANKCASE VENTILATION PIPE REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 392	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 349: Positive Crankcase Ventilation Tube, Connectors And ECM Wiring Harness Guide</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Unclip the ECM wiring harness guide (3) from the cylinder head cover.
- 2. Disconnect the 2 positive crankcase ventilation tube connectors (1).
- 3. Remove the positive crankcase ventilation tube (2).

DRIVE BELT REMOVAL

Special Tools

EN-6349 Locking Pin

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a. m.	Page 393	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 350: Drive Belt Tensioner And Special Tool Courtesy of GENERAL MOTORS COMPANY

1. Release tension to the drive belt tensioner counterclockwise (1) and lock with EN-6349 pin (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 394	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 351: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

2. Remove the drive belt (1).

DRIVE BELT TENSIONER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 395	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 352: Drive Belt Tensioner Bolt Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the drive belt tensioner bolt (1).
- 2. Remove the drive belt tensioner (2).

TIMING BELT UPPER FRONT COVER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 396	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 353: Timing Belt Upper Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 2 timing belt upper front cover bolts (2).
- 2. Remove the timing belt upper front cover (1).

TIMING BELT CENTER FRONT COVER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 397	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 354: Toothed Belt Cover Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the center front timing belt cover from the rear timing belt cover at 2 locations.
- 2. Remove the center front timing belt cover (1).

CRANKSHAFT BALANCER REMOVAL

Special Tools

EN-652 Flywheel Holder

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 398	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 355: Flywheel And Flywheel Holder Courtesy of GENERAL MOTORS COMPANY

1. Install the **EN-652** holder (1). Lock the flywheel (2) or the automatic transmission flex plate via the starter ring gear.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 3	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 356: Crankshaft Balancer, Washer And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Remove and DISCARD the crankshaft balancer bolt (4).
- 3. Remove the crankshaft balancer washer (3).
- 4. Remove the crankshaft balancer (2).

TIMING BELT LOWER FRONT COVER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a. m.	Page 400	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 357: Timing Belt Lower Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 4 timing belt lower front cover bolts (2).
- 2. Remove the timing belt lower front cover (1).

TIMING BELT REMOVAL

Special Tools

- EN-6333 Locking Pin
- EN-6340 Locking Tool

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 401	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 358: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY

NOTE: The timing belt drive gear and oil pump housing must align.

1. Turn the crankshaft in the direction of engine rotation, by the crankshaft balancer bolt, to cylinder 1 TDC of combustion stroke.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 40	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 359: Front Panel And Bolts
Courtesy of GENERAL MOTORS COMPANY

NOTE: The right half of the EN-6340 locking tool can be recognized by the lettering right, arrow, on the tool.

- 2. Prepare the right half of the EN-6340 locking tool.
 - 1. Remove the 2 bolts (2).
 - 2. Detach the front panel (1) from the EN-6340 locking tool right.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 403	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 360: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

NOTE:

- The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of the EN-6340 locking tool - left (1) during this process, but must be somewhat above.
- The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340 locking tool right (2).
- 3. Insert the EN-6340 locking tool left (1) and the EN-6340 locking tool right (2) in the camshaft adjuster.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 404	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 361: Drive Belt Tensioner, Allen Key And Locking Pin Courtesy of GENERAL MOTORS COMPANY

- 4. Install the **EN-6333** locking pin (3), apply tension to the timing belt tension roller (2) in the direction of the arrow, using an Allen key (1).
- 5. Stop the timing belt tensioner.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 362: Timing Belt And Timing Belt Tensioner Courtesy of GENERAL MOTORS COMPANY


NOTE: Observe direction of rotation.

6. Remove the timing belt (1).

TIMING BELT TENSIONER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 406	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 363: Timing Belt Tensioner</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the tensioner bolt (1).
- 2. Remove the timing belt tensioner (2).

TIMING BELT IDLER PULLEY REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 407	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 364: Timing Belt Idler Pulley Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the timing belt idler pulley bolt (1).
- 2. Remove the timing belt idler pulley (2).

CRANKSHAFT SPROCKET REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 408	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 365: Crankshaft Sprocket Courtesy of GENERAL MOTORS COMPANY

Remove the crankshaft sprocket (1).

CAMSHAFT POSITION ACTUATOR SOLENOID VALVE REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 409	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 366: Camshaft Position Actuator Solenoid Valves, Bolts And Seals Courtesy of GENERAL MOTORS COMPANY</u>

- 1. Remove the camshaft position actuator solenoid valve bolts (1).
- 2. Remove the camshaft position actuator solenoid valves (2).
- 3. Remove the camshaft position actuator solenoid valve seals (3).

CAMSHAFT POSITION ACTUATOR ADJUSTER REMOVAL

Special Tools

- EN-6340 Camshaft Adjuster Locking Tool
- EN-6628-A Camshaft Locking Tool

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 410	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 367: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE: The right half of the EN-6340 locking tool can be recognized by the lettering "right", arrow, on the tool.

- 1. Prepare the right half of the EN-6340 locking tool.
 - 1. Remove the 2 bolts (2).
 - 2. Remove the front panel (1) from the EN-6340 locking tool right.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 411	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 368: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

2. Install the EN-6340 locking tool into the camshaft adjusters.

NOTE: The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of EN-6340 locking tool - left during this process but must be somewhat above as shown.

• Install the EN-6340 locking tool - left (1) into the camshaft adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340 locking tool - right.

• Install EN-6340 locking tool - right (2) into the camshaft adjusters as shown.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 412	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 369: Aligning Camshafts Horizontally
Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the arrows.

3. Turn the camshaft by the hexagon until the groove on the end of the camshafts is horizontal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 413	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 370: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

4. Install the EN-6628-A locking tool (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 414	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 371: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

5. Remove the camshaft position actuator adjuster closure bolt (1) of the intake camshaft position actuator adjuster and/or the exhaust camshaft position actuator adjuster (3).

NOTE: A second technician is required.

NOTE: Use an appropriate open-end wrench in order to counterhold the camshaft

hexagon. A thin cross-section wrench is required for a better fit. The usage of EN-6628-A locking tool is for the camshaft adjustment to prevent misalignment of the camshafts. The wrench is required to counterhold the

camshafts during bolt torque procedure.

- 6. Remove and DISCARD the intake camshaft position actuator adjuster bolt and/or the exhaust camshaft position actuator adjuster bolt (2).
- 7. Remove the intake camshaft position actuator adjuster and/or the exhaust camshaft position actuator adjuster (3).

CRANKSHAFT FRONT OIL SEAL REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 41	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Special Tools

EN-45000 Remover

For equivalent regional tools, refer to **Special Tools**.




Fig. 372: Crankshaft Front Oil Seal Removal Tool Courtesy of GENERAL MOTORS COMPANY


CAUTION: Clean the crankshaft sealing surface with a clean, lint-free towel. Inspect lead-in edge of crankshaft for burrs/sharp edges that could damage the rear main oil seal. Remove burrs/sharp edges with crocus cloth before proceeding.

Using the EN-45000 remover (3), remove the crankshaft front oil seal (1) from the crankshaft (2).

TIMING BELT REAR COVER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a. m.	Page 416	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 373: Timing Belt Rear Cover And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove and DISCARD the 4 timing belt rear cover bolts (2).
- 2. Remove the timing belt rear cover (1).

THROTTLE BODY ASSEMBLY REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 417	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 374: Throttle Body And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 4 throttle body bolts (2).
- 2. Remove the throttle body (1).
- 3. Remove the throttle body seal.

INTAKE MANIFOLD REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a. m.	Page 418	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 375: Intake Manifold Brace And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 2 intake manifold brace bolts (2, 3).
- 2. Remove the intake manifold brace (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:01 a.m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 376: Intake Manifold And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Remove the 7 intake manifold bolts (1).
- 4. Remove the intake manifold (2) and the 4 intake manifold gaskets.

OIL LEVEL INDICATOR AND TUBE REMOVAL

1. Remove the oil dipstick.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 420	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 377: Oil Level Indicator Tube And Bolt Courtesy of GENERAL MOTORS COMPANY

2. Remove the oil level indicator tube bolt (1).

NOTE: If the engine oil level is at the maximum level, oil may emerge while removing the oil dipstick guide tube.

3. Remove the oil level indicator tube (2) and oil level indicator seal.

EXHAUST MANIFOLD REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 421	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 378: Exhaust Manifold And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 9 exhaust manifold nuts (4).
- 2. Remove the 2 exhaust manifold bolts (2)
- 3. Remove the exhaust manifold (3) and gasket (1).
- 4. Clean all of the gasket surfaces.

ENGINE COOLANT THERMOSTAT REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 422	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 379: Engine Coolant Thermostat Assembly Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Engine Coolant Thermostat Housing Caution.

- 1. Remove the 4 engine coolant thermostat bolts (3).
- 2. Remove the engine coolant thermostat assembly (2).
- 3. Remove the engine coolant seal (1).

ENGINE COOLANT THERMOSTAT HOUSING REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 423	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 380: Engine Coolant Thermostat Housing Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Engine Coolant Thermostat Housing Caution.

- 1. Remove the engine coolant thermostat housing retainer nut (4).
- 2. Remove the engine coolant thermostat housing retainer (1).
- 3. Remove the 4 engine coolant thermostat housing bolts (3).
- 4. Remove the engine coolant thermostat housing (2).

ENGINE OIL COOLER HOUSING REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 424	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 381: Engine Oil Cooler Outlet Pipe And Bolts Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 2 engine oil cooler pipe bolts (1).
- 2. Remove the oil cooler pipe (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 425	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 382: Engine Oil Cooler Housing, Bolts And Engine Oil Cooler Inlet Pipe</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Remove the 5 engine oil cooler housing bolts (2).
- 4. Remove the engine oil cooler housing (1).
- 5. Remove the engine oil cooler inlet pipe (3).

ENGINE OIL COOLER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 426	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 383: Engine Oil Cooler Courtesy of GENERAL MOTORS COMPANY

Remove the 6 engine oil cooler bolts (3), the engine oil cooler (1) and the engine oil cooler gasket (2) from the engine oil cooler housing.

WATER PUMP PULLEY REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 427	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 384: Water Pump And Water Pump Pulley Courtesy of GENERAL MOTORS COMPANY

NOTE: Counterhold the crankshaft balancer. For this procedure the drive belt has to be installed.

- 1. Loosen the 3 water pump pulley bolts (1).
- 2. Remove the 3 water pump pulley bolts (1).
- 3. Remove the water pump pulley (2) from the water pump (3).

WATER PUMP REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 428	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 385: Water Pump And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 5 water pump bolts (2).
- 2. Remove the water pump (1).
- 3. Remove the water pump seal.

ENGINE OIL HEATER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 429	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 386: Engine Oil Heater</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the engine oil heater bolt (1).
- 2. Remove the engine oil heater (2).

OIL PAN REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 430	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 387: Oil Pan And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 15 oil pan bolts (1) from the engine block.
- 2. Use a suitable tool to remove the oil pan (2) evenly all the way around.

ENGINE FRONT COVER AND OIL PUMP REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 431	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 388: Engine Oil Pump Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the different screw lengths.

- 1. Remove the 8 bolts (2, 3).
- 2. Remove the engine front cover with the included oil pump (4).
- 3. Remove the gasket (1).

NOTE: Do not damage the sealing surfaces.

4. Clean the sealing surface.

IGNITION COIL REMOVAL

Special Tools

EN-6009 Remover/Installer Ignition Module

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 43	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

NOTE: Note the arrow on the cover.

- 1. Remove the cover of the DIS ignition coil in the direction of the arrow.
- 2. Remove the 2 ignition coil bolts.




Fig. 389: Special Remover/Installer Tool
Courtesy of GENERAL MOTORS COMPANY

3. Install the EN-6009 remover/installer (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 43	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 390: Ignition Coil Module And Special Tool Courtesy of GENERAL MOTORS COMPANY

4. Remove the ignition coil module (2) with the EN-6009 remover/installer (1).

CAMSHAFT COVER REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 434	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 391: Camshaft Cover And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 11 bolts (2, 3).
- 2. Remove the camshaft cover (1).

CAMSHAFT REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 435	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 392: Camshaft Bearing Cap And Camshaft Bearing Cap Bolts Removal Sequence</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Note removal sequence 1-4.

1. Remove the 4 camshaft bearing cap bolts.

NOTE: Release the bearing support by striking it gently with a plastic hammer.

2. Remove the first camshaft bearing cap (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 436	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 393: Exhaust Camshaft Bearing Cap Bolts Loosening Sequence Courtesy of GENERAL MOTORS COMPANY

- 3. Loosen the 8 exhaust camshaft bearing cap bolts working from outside to inside in a spiral in steps of 1/2 up to 1 turn.
- 4. Remove the 8 exhaust camshaft bearing cap bolts.

NOTE: Mark camshaft bearing caps before removal.

- 5. Remove the 4 exhaust camshaft bearing caps numbers 6-9 from the cylinder head.
- 6. Remove the exhaust camshaft (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 394: Intake Camshaft Bearing Cap Bolts Loosening Sequence Courtesy of GENERAL MOTORS COMPANY

- 7. Loosen the 8 intake camshaft bearing cap bolts working from outside to inside in a spiral in steps of 1/2 up to 1 turn.
- 8. Remove the 8 intake camshaft bearing cap bolts.

NOTE: Mark camshaft bearing caps before removal.

- 9. Remove the 4 intake camshaft bearing caps numbers 2-5 from the cylinder head.
- 10. Remove the intake camshaft (1).
- 11. Remove the camshaft seal rings.

VALVE LIFTER REMOVAL


Special Tools

EN-845 Suction Device

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 438	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 395: Valve Lifters</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Mark the locations.

Remove the 16 valve lifter (1) use the EN-845 suction device.

CYLINDER HEAD REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 439	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 396: Cylinder Head Bolts Tightening Sequence Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 10 cylinder head bolts in sequence as shown.
 - 1. Loosen the 10 bolts 90°.
 - 2. Loosen the 10 bolts 180°.
- 2. Remove the cylinder head and place on a suitable base.
- 3. Remove the cylinder head gasket.

PISTON, CONNECTING ROD, AND BEARING REMOVAL

- 1. Install the crankshaft balancer bolt.
- 2. Set the pistons 1 and 4 to TDC in direction of engine rotation.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 397: Connecting Rod And Bearing Cap Courtesy of GENERAL MOTORS COMPANY

NOTE: Note cylinder sequence.

3. Mark the connecting rod with the connecting rod bearing cover (1).



<u>Fig. 398: Connecting Rod Bearing, Connecting Rod Bearing Caps And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 4. Remove the 4 connecting rod bearing caps bolts (2) of cylinder 1 and 4.
- 5. Remove the connecting rod bearing caps (1) and the connecting rod bearing (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 399: Pistons 1, 4 And Cylinder Bore Courtesy of GENERAL MOTORS COMPANY

6. Push the pistons 1 and 4 (1) out of the cylinder bore (2).

NOTE: The shear surfaces of the con-rod and the con-rod bearing cover form a unique fit and must not be swapped or damaged. Do not lay down on the shear surfaces.

- 7. Remove the pistons 1 and 4 (1).
- 8. Turn crankshaft on crankshaft balancer through 180° in direction of rotation of engine.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 443	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 400: Connecting Rod And Bearing Cap Courtesy of GENERAL MOTORS COMPANY

NOTE: Note cylinder sequence.


9. Mark the connecting rod with the connecting rod bearing cover (1).



<u>Fig. 401: Connecting Rod Bearing, Connecting Rod Bearing Caps And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 10. Remove the 4 connecting rod bearing caps bolts (2) of cylinder 2 and 3.
- 11. Remove the connecting rod bearing caps (1) and the connecting rod bearing (3).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 402: Pistons 2, 3 And Cylinder Bore</u> Courtesy of GENERAL MOTORS COMPANY


12. Push the pistons 2 and 3 (1) out of the cylinder bore (2).

NOTE: The shear surfaces of the con-rod and the con-rod bearing cover form a unique fit and must not be swapped or damaged. Do not lay down on the shear surfaces.

13. Remove the pistons 2 and 3 (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 446	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 403: Connecting Rod And Bearings</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Observe correct fitting position, observe alignment.

- 14. Remove the connecting rod bearing (1, 2).
- 15. Check the components. Refer to **Piston**, **Connecting Rod**, and **Bearing Cleaning and Inspection**.

CRANKSHAFT AND BEARING REMOVAL

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 447	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 404: Connecting Rod And Bearing Cap Courtesy of GENERAL MOTORS COMPANY

1. Identify all the connecting rod bearing caps (1).




Fig. 405: Connecting Rod Bearing Caps
Courtesy of GENERAL MOTORS COMPANY

- 2. Remove the 4 bolts.
- 3. Remove the connecting rod bearing caps 1 and 4 (1).
- 4. Turn the crankshaft through 180°.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.





Fig. 406: Connecting Rod Bearing Caps
Courtesy of GENERAL MOTORS COMPANY

- 5. Remove the 4 bolts.
- 6. Remove the connecting rod bearing caps 2 and 3 (1).
- 7. Identify the crankshaft bearing caps.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a. m.	Page 45	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 407: Crankshaft Bearing Cap Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 8. Remove the crankshaft bearing caps (1).
- 9. Remove the 10 bolts.
- 10. Remove the crankshaft (2).
- 11. Remove the crankshaft bearing clips.

INTAKE MANIFOLD DISASSEMBLE

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:02 a.m.	Page 451	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 408: Intake Manifold, Manifold Absolute Pressure Sensor And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the intake manifold absolute pressure sensor bolt (1).
- 2. Remove the manifold absolute pressure sensor (2) from the intake manifold (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 409: Intake Manifold And Mount Courtesy of GENERAL MOTORS COMPANY

3. Remove the intake manifold mount (2) from the intake manifold (1).


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 453	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 410: Intake Manifold, Intake Manifold Seal And Throttle Body Seal</u> Courtesy of GENERAL MOTORS COMPANY

- 4. Remove the throttle body seal (1).
- 5. Remove the intake manifold seal (3) from the intake manifold (2).


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 454	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 411: Intake Manifold, Evaporative Emission Canister Purge Solenoid Valve Bracket And Bolts Courtesy of GENERAL MOTORS COMPANY</u>

- 6. Remove the 2 evaporative emission canister purge solenoid valve bracket bolts (2).
- 7. Remove the evaporative emission canister purge solenoid valve bracket (1) from the intake manifold (3).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 412: Intake Manifold, Multiport Fuel Injection Fuel Rail, Fuel Injectors, Seals And Bolts Courtesy of GENERAL MOTORS COMPANY</u>

- 8. Remove the 2 multiport fuel injection fuel rail bolts (1).
- 9. Remove the multiport fuel injection fuel rail (2) and the fuel injectors (3) from the intake manifold (5).
- 10. Remove the 4 multiport fuel injector seals (4).

CYLINDER HEAD DISASSEMBLE

Special Tools

- EN-840 Pliers/Remover
- EN-8062 Valve Spring Compressor
- EN-8062-5 Adapter
- EN-50717-2 Compressor Assembly of EN-50717 Kit

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 456	© 2011 Mitchell Repair Information Company, LLC.




Fig. 413: Valve Spring Compressor And Adapter Assembly Courtesy of GENERAL MOTORS COMPANY

- 1. Install the EN-50717-2 assembly (1) to the EN-8062 compressor (4).
- 2. Install the EN-8062-5 adapter (3) to the EN-8062 compressor.
- 3. Install the compressor assembly to the cylinder head, so that the adapter (5) of the EN-50717-2 assembly (1) contacts the valve spring retainer properly and the EN-8062-5 adapter (3) contacts the valve disc (2). Prefix the EN-8062 compressor (4).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 414: Valve Spring Retainer And Valve Spring Courtesy of GENERAL MOTORS COMPANY

WARNING: Valve springs can be tightly compressed. Use care when removing the retainers and plugs. Personal injury could result.

4. Apply pressure to the **EN-50717-2** assembly to push down the vale spring retainer (1) and compress the valve spring (3) until the valve keys (2) are free from tension. Carefully remove the valve keys.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 458	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 415: Spring Compressor
Courtesy of GENERAL MOTORS COMPANY

- 5. Slowly and carefully loosen the EN-50717-2 assembly until the valve spring is entirely expanded.
- 6. Remove the compressor assembly from the cylinder head.
- 7. Remove the valve spring retainer (1) and the valve spring (3).
- 8. Remove and DISCARD the valve stem oil seal (4), using the EN-840 pliers (2).
- 9. Remove the valve (5).

NOTE: Ensure that the valve train components are kept together and identified in order for proper installation in their original position.

- 10. Repeat the procedure with the remaining valves.
- 11. In case of re-using the cylinder head, refer to **Cylinder Head Cleaning and Inspection**.

PISTON AND CONNECTING ROD DISASSEMBLE

1. Remove the piston with connection rod. Refer to **Piston, Connecting Rod, and Bearing Removal**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 459	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 416: Detaching Piston From Connecting Rod Courtesy of GENERAL MOTORS COMPANY

NOTE: Note installation position of the piston in respect of the connection rod.


2. Detach the piston from the connection rod.

NOTE: Do not damage the bore.

- 3. Remove the retainer (1) from the piston eye.
- 4. Press the piston pin out of the piston.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 417: Piston Rings And Piston Ring Pliers</u> Courtesy of GENERAL MOTORS COMPANY

5. Remove the piston rings, using piston ring pliers (1).

Remove oil carbon from the groove with a split piston ring, filed to a wedge-shape.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 461	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 418: Rectangular Compression Ring, Tapered Compression Ring And Oil Scraper Ring</u> Courtesy of GENERAL MOTORS COMPANY

- 6. Measure the piston ring gap.
 - Tension the piston ring in the cylinder and measure the gap with a feeler gauge.
 - Permissible ring gap:
 - o Rectangular compression ring (1): 0.20-0.40 mm (0.007-0.015 in)
 - o Tapered compression ring (2): 0.40-0.60 mm (0.015-0.023 in)
 - o Oil scraper ring (3): 0.25-0.75 mm (0.009-0.029 in)





Fig. 419: Checking Piston Ring Vertical Play With Feeler Gauge Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 463	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 420: Rectangular Compression Ring, Tapered Compression Ring And Oil Scraper Ring</u> Courtesy of GENERAL MOTORS COMPANY

7. Check piston ring vertical play with a feeler gauge (1) in the piston ring groove.

Permissible vertical play:

- Rectangular compression ring (1): 0.04-0.08 mm (0.001-0.003 in)
- Tapered compression ring (2): 0.03-0.07 mm (0.001-0.002 in)
- Oil scraper ring (3): 0.03-0.13 mm (0.001-0.005 in)

ENGINE BLOCK DISASSEMBLE

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 464	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 421: Cylinder Head Locating Pins Courtesy of GENERAL MOTORS COMPANY

1. Remove the cylinder head locating (1, 2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 465	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 422: Oil Pressure Switch
Courtesy of GENERAL MOTORS COMPANY

2. Remove the oil pressure switch (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 466	© 2011 Mitchell Repair Information Company, LLC.




Fig. 423: Knock Sensor And Bolt Courtesy of GENERAL MOTORS COMPANY

- 3. Remove the knock sensor bolt (2) and the knock sensor (1).
- 4. Clean the thread.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 424: Oil Flow Check Valve Courtesy of GENERAL MOTORS COMPANY

5. Remove the oil flow check valve (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 468	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 425: Oil Pressure Relief Valve Closure Bolt Courtesy of GENERAL MOTORS COMPANY

6. Remove the oil pressure relief valve closure bolt (1) and the oil pressure relief valve.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 469	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 426: Piston, Spring And Oil Pressure Relief Valve Closure Bolt Courtesy of GENERAL MOTORS COMPANY

- 7. Remove the piston (1) and spring (2) from the oil pressure relief valve closure bolt (3).
- 8. Clean and inspect the components. Refer to **Engine Block Cleaning and Inspection**.
- 9. Clean the thread.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 427: Piston Oil Nozzles
Courtesy of GENERAL MOTORS COMPANY

10. Remove the 4 piston oil nozzles (1).

INTAKE MANIFOLD CLEANING AND INSPECTION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 471	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 428: Intake Manifold And Sealing Surfaces Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the intake manifold mating surfaces.
- 2. Inspect the intake manifold (2) for damage.
- 3. Inspect the intake manifold for cracks near metallic inserts.
- 4. Inspect the crankcase ventilation passages in the intake manifold face for blockage.

WARNING: Wear safety glasses in order to avoid eye damage.

- 5. Clean the crankcase ventilation passages with compressed air if necessary. Use a maximum of 172 kPa (25 psi) of air pressure.
- 6. Clean the throttle body sealing surface (1).
- 7. Clean the intake manifold to cylinder head sealing surface (3).
- 8. Replace the intake manifold as necessary.

EXHAUST MANIFOLD CLEANING AND INSPECTION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 429: Exhaust Manifold Courtesy of GENERAL MOTORS COMPANY

1. Clean the exhaust manifold (1) in solvent.

WARNING: Wear safety glasses in order to avoid eye damage.

- 2. Dry the exhaust manifold (1) with compressed air.
- 3. An exhaust manifold leak or damage may cause an exhaust leak and may effect OBD II system performance. A damaged exhaust must be replaced.

OIL PAN CLEANING AND INSPECTION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 473	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 430: Oil Pan Components
Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the 2 oil pan baffle bolts (1) and the oil pan baffle (2).
- 2. Remove the oil pump screen (3).
- 3. Clean the oil pan (4). Remove all the sludge and the oil deposits.
- 4. Remove the oil pan drain plug (5) and the oil pan drain plug seal (6).
- 5. Inspect the thread of the oil pan drain plug.
- 6. Inspect the oil pan for cracking near the pan rail and the transmission mounting points.
- 7. Inspect the oil pan for cracking resulting from impact or flying road debris.
- 8. Inspect the oil pan baffle and oil pump screen.
- 9. Repair or replace the oil pan as necessary.

OIL PUMP CLEANING AND INSPECTION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 474	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 431: Inspecting Axial Clearance Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the external rotor with the internal rotor.
- 2. Visually inspect the components.
- 3. Install the external and the internal rotors.
- 4. Inspect the axial clearance of the rotors in respect to the control unit housing upper edge.

Specifications

Permissible measurement is 0.02-0.058 mm (0.00079-0.00228 in).

CYLINDER HEAD CLEANING AND INSPECTION

Valve Cleaning and Inspection

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 475	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 432: Inspection Points For Valve Damage Courtesy of GENERAL MOTORS COMPANY

WARNING: Bodily injury may occur if the cleaning solvent is inhaled or exposed to the skin.

NOTE: Do not scratch the valve stem with the wire brush.

- 1. Clean the valves of carbon, oil and varnish. Carbon can be removed with a wire brush. Varnish can be removed by soaking in Parts Immersion Solvent.
- 2. Clean the valve guides.
- 3. Inspect the valve stem for wear (4).
- 4. Inspect the valve key groove for chipping or wear (5). Replace the valve if chipped or worn.
- 5. Inspect the valve face for burning or cracking (1). If pieces are broken off, inspect the corresponding piston and cylinder head area for damage.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 476	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 6. Inspect the valve stem for burrs and scratches. Burrs and minor scratches may be removed with an oil stone.
- 7. Inspect the valve stem for straightness and the valve head for bending or distortion (3) using V blocks. Bent or distorted valves must be replaced.
- 8. Clean the deposits from the valve face. Inspect the valve face for grooving.
- 9. Replace the valve if the face is grooved. Valve faces cannot be machined. If worn, or damaged, the valves must be replaced.
- 10. The valves may be lightly lapped to the valve seats.

Cylinder Head and Gasket Surface Cleaning and Inspection

- 1. Remove the spark plugs. Refer to **Spark Plug Replacement**.
- 2. Inspect the cylinder head gasket and mating surfaces for leaks, corrosion and blow-by. If the gasket has failed, use the following faults to determine the cause:
 - 1. Improper installation.
 - 2. Loose or warped cylinder head.
 - 3. Missing, off location or not fully seated dowel pins.
 - 4. Corrosion in the seal area around the coolant passages.
 - 5. Chips or debris in the cylinder head bolt holes.
 - 6. Bolt holes in the cylinder block not drilled or tapped deep enough.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 433: Inspecting Cylinder Head Gasket Surface Courtesy of GENERAL MOTORS COMPANY

- 3. Inspect the cylinder head gasket surface.
 - Cylinder head may be reused if corrosion is found only outside a 4 mm (0.375 in) band around each combustion chamber (1).
 - Replace the cylinder head if the area between the valve seats is cracked (2).
 - Replace the cylinder head if corrosion has been found inside a 4 mm (0.375 in) band around each combustion chamber (3).
- 4. Clean the cylinder head bolts.

NOTE: Do not use a wire brush on any gasket sealing surface.

5. Clean the cylinder head. Remove all varnish, soot and carbon to the bare metal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 6. Clean the valve guides.
- 7. Clean the threaded holes. Use a nylon bristle brush.
- 8. Clean the remains of the sealer from the plug holes.
- 9. Inspect the cylinder head bolts for damaged threads or stretching and damaged heads caused by improper use of tools.
- 10. Replace all suspect bolts.
- 11. Inspect the cylinder head for cracks. Check between the valve seats and in the exhaust ports.

NOTE: Do not attempt to weld the cylinder head, replace it.

12. Inspect the cylinder head deck for corrosion, sand inclusions and blow holes.




Fig. 434: Inspecting Cylinder Head Surfaces For Flatness Courtesy of GENERAL MOTORS COMPANY

- 13. Inspect the cylinder head deck surface for flatness. Refer to **Engine Mechanical Specifications**. If the cylinder head is out of specification, replace the cylinder head. Do not machine the cylinder head.
- 14. Inspect all the threaded holes for damage. Threads may be reconditioned with thread inserts.
- 15. Inspect the sealing surfaces.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 479	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

16. Inspect the cylinder head plugs.

PISTON, CONNECTING ROD, AND BEARING CLEANING AND INSPECTION

Special Tools

EN-45059 Torque Angle Sensor Kit

For equivalent regional tools, refer to **Special Tools**.

1. Remove the oil pan. Refer to Oil Pan Removal.





Fig. 435: Connecting Rod Bearing Cap Courtesy of GENERAL MOTORS COMPANY

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 436: Marking Position On Connecting Rod Bearing Cap</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Remove the connecting rod bearing cap (1).
 - 1. Mark the installation position (1) of the connecting rod bearing cap.
 - 2. Remove the 2 bolts.
 - 3. Degrease the connecting rod bearing cap and wet the connecting rod bearing clip with engine oil.

NOTE: Do not rotate the crankshaft.

3. Lay on plastigage. Refer to Adhesives, Fluids, Lubricants, and Sealers.

Lay plastigage (flexible plastic thread) over the entire width of the connecting rod bearing journal.

4. Install the connecting rod bearing cap.

CAUTION: Refer to Fastener Caution

5. Tighten the 2 bolts in three passes using the EN-45059 sensor kit:

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 4	81 © 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 1. First pass tighten to 35 N.m (26 lb ft).
- 2. Second pass tighten to an additional 45°
- 3. Third pass tighten to an additional 15°




Fig. 437: Connecting Rod Bearing Cap Courtesy of GENERAL MOTORS COMPANY

- 6. Remove the 2 bolts.
- 7. Remove the connecting rod bearing cap (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 48	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 438: Measuring Connecting Rod Bearing Play Using Measuring Scale Courtesy of GENERAL MOTORS COMPANY

NOTE: When reading the value, do not confuse millimeters and inches on the measuring scale (1).

- 8. Measure the connecting rod bearing play.
 - Compare the width of the flattened plastic thread with the measuring scale.
 - Permissible connecting rod bearing play: 0.019-0.071 mm (0.0007-0.0028 in).

NOTE: Check markings on parts.

- 9. Install the connecting rod bearing cap.
 - Wet the connecting rod bearing journal and con-rod bearing clips with engine oil.
 - Renew the bolts.
- 10. Tighten the 2 bolts in three passes using the EN-45059 sensor kit:
 - 1. First pass tighten to 35 N.m (26 lb ft)
 - 2. Second pass tighten to an additional 45°
 - 3. Third pass tighten to an additional 15°

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:03 a.m.	Page 483	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

11. Install the oil pan. Refer to Oil Pan Installation.

CRANKSHAFT AND BEARING CLEANING AND INSPECTION

Special Tools

- EN-45059 Torque Angle Sensor Kit
- **GE-571-B** Dial Gauge

For equivalent regional tools, refer to **Special Tools**.

Crankshaft End Play, Check




Fig. 439: Gauge Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE: Crankshaft attached with crankshaft bearing caps.

- 1. Install the **GE-571-B** gauge (1).
 - 1. Install in the holder on the front of the engine block.
 - 2. Place the dial gauge plunger against the crankshaft and adjust.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 484	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 2. Measure the longitudinal play of the crankshaft.
 - 1. Move the crankshaft in the longitudinal direction.
 - 2. Permissible crankshaft end play: 0.100-0.202 mm (0.0039-0.0080 in)
- 3. Remove the **GE-571-B** gauge.

Crankshaft Out-of-Round, Check




Fig. 440: Gauge Tool
Courtesy of GENERAL MOTORS COMPANY

NOTE: Crankshaft removed.

- 1. Insert the crankshaft in the engine block.
- 2. Install the **GE-571-B** gauge.
 - 1. Attach to the bracket on the engine block.
 - 2. Place the dial gauge plunger against the crankshaft bearing journal and adjust.
- 3. Check the rotational play of the crankshaft.
 - 1. Turn the crankshaft evenly.
 - 2. Maximum permissible rotational play: 0.03 mm (0.001 in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 485	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

4. Remove the **GE-571-B** gauge (1).

Check Crankshaft Bearing Clearance (With Plastigage)




Fig. 441: Plastigage On Bearing Journal Courtesy of GENERAL MOTORS COMPANY

NOTE:

- Crankshaft removed.
- Do not rotate the crankshaft.
- 1. Lay on plastigage.

Lay out plastigage (flexible plastic thread) around the entire width of the con-rod bearing journal (1).

CAUTION: Refer to Fastener Caution.

NOTE:

- Note the correct tightening sequence.
- The bolts can be reused for checking the crankshaft bearing play.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 486	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 2. Install the crankshaft bearing cap. Tighten the 2 crankshaft bearing cap bolts in 3 passes. Use the **EN-45059** sensor kit:
 - 1. First pass to 50 N.m (37 lb ft)
 - 2. Second pass to 45°
 - 3. Third pass to 15°
- 3. Remove the 2 crankshaft bearing cap bolts.




Fig. 442: Measuring Crankshaft Bearing Play Using Measuring Scale Courtesy of GENERAL MOTORS COMPANY

NOTE: When reading the value, do not confuse millimeters and inches on the measuring scale (1).

- 4. Measure the crankshaft bearing play.
 - 1. Compare the width of the flattened plastic thread (arrow) to the measuring scale.
 - 2. Permissible crankshaft bearing play: 0.005-0.059 mm (0.0002-0.0023 in).

Check Crankshaft Bearing Clearance (With Micrometer Gauge Internal Measuring Device)

NOTE: • Note the correct tightening sequence.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 48	87 © 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- The bolts can be reused for checking the crankshaft bearing play.
- 1. Install the crankshaft bearing cap with the crankshaft bearing clips to the cylinder block.

Tighten the 2 crankshaft bearing cap bolts in 3 passes. Use the EN-45059 sensor kit:

- 1. First pass to 50 N.m (37 lb ft)
- 2. Second pass to 45°
- 3. Third pass to 15°





Fig. 443: Micrometer Gauge Courtesy of GENERAL MOTORS COMPANY

2. Install the inner plunger and calibrate with the micrometer gauge (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 488	© 2011 Mitchell Repair Information Company, LLC.


2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 444: Measuring Crankshaft Bearing Diameter At Points</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Measure the crankshaft bearing diameter at 3 points.
 - Measure at points A, B and C with the internal measuring device.
 - Calculate the average crankshaft bearing diameter.
 - Formula: A + B + C/3.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 445: Measuring Crankshaft Bearing Journal Diameter At 2 Points</u> Courtesy of GENERAL MOTORS COMPANY

4. Measure the crankshaft bearing journal diameter at 2 points.

Measure at points I and II with the micrometer gauge.

5. Calculate the average crankshaft bearing journal diameter.

Formula: I + II/2.

6. Determine the crankshaft bearing play.

Calculation formula: average crankshaft bearing diameter minus average crankshaft bearing journal diameter.

7. Nominal-Actual comparison.

Permissible crankshaft bearing play: 0.005-0.059 mm (0.0002-0.0023 in).

ENGINE BLOCK CLEANING AND INSPECTION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 490	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Special Tools

EN-8087 Cylinder Gauge

For equivalent regional tools, refer to **Special Tools**.





Fig. 446: Engine Block Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the sealing material from the gasket mating surfaces (2).
- 2. Clean the engine block (1) and lower crankcase in a cleaning tank with solvent appropriate for aluminum. Refer to **Adhesives, Fluids, Lubricants, and Sealers** for the recommended solvent.
- 3. Flush the engine block with clean water or steam.
- 4. Clean the oil passages.
- 5. Clean the blind holes.
- 6. Spray the cylinder bores and the machined surfaces with engine oil.
- 7. Inspect the threaded holes. Clean the threaded holes with a rifle brush. If necessary, drill out the holes and install thread inserts. Refer to **Thread Inserts**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 491	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 447: Inspecting Engine Block For Sag In Length And Width On Sealing Surfaces</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Do not attempt to machine the lower crankcase to engine block surfaces.

8. Inspect the engine block for sag in length and width on the sealing surfaces.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 492	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 448: Inspecting Engine Block For Distortion Along Diagonals</u> Courtesy of GENERAL MOTORS COMPANY

9. Inspect the engine block for distortion along the diagonals.

If the deck surface is out of specification, replace the block. Do not machine the block.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 449: Cleaning Gasket Mating Surfaces</u> Courtesy of GENERAL MOTORS COMPANY

10. Clean the sealing material from the gasket mating surfaces (1) on the lower crankcase oil pan side.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 494	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 450: Measuring Bearing Bore Concentricity And Alignment Using Gauge Tool Courtesy of GENERAL MOTORS COMPANY

- 11. Inspect the crankshaft main bearing bores. Use the **EN-8087** gauge (1) to measure the bearing bore concentricity and alignment.
- 12. Replace the engine block and bed plate if the crankshaft bearing bores are out of specification.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 451: Inspecting Cylinder Bore Courtesy of GENERAL MOTORS COMPANY

- 13. Inspect the cylinder bores using the EN-8087 gauge (1). Inspect for the following items:
 - Wear
 - Taper
 - Runout
 - Ridging
- 14. Check the cylinder bores specifications. Refer to **Engine Mechanical Specifications**.
- 15. If the cylinder bores are out of specification, replace the engine block.

SERVICE PRIOR TO ASSEMBLY

The importance of cleanliness during assembly cannot be overstated. Dirt or debris will cause engine damage. An automobile engine is a combination of many machined, honed, polished and lapped surfaces with minor tolerances. When any internal engine parts are serviced, care and cleanliness are important. A liberal coating of engine oil should be applied to friction areas during assembly in order to protect and lubricate the surfaces on initial operation. Throughout this section, it should be understood that proper cleaning and protection of machined surfaces and friction areas are part of the repair procedure. This is considered standard shop practice even if not specifically stated.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 49	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Use the proper tools to measure the components when checking for excessive wear. Components not within the manufacturer's specification must be repaired or replaced.

Lubricate all moving parts with engine oil or a specified assembly lubricant. This will provide lubrication for initial start up.

When the components are reinstalled into an engine, return the components to their original location, position, and direction.

ENGINE BLOCK ASSEMBLE





Fig. 452: Piston Oil Nozzles
Courtesy of GENERAL MOTORS COMPANY

1. Install the 4 piston oil nozzles (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 497	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 453: Piston, Spring And Oil Pressure Relief Valve Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

2. Install the piston (1) and spring (2) to the oil pressure relief valve closure bolt (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 454: Oil Pressure Relief Valve Closure Bolt Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

3. Install the oil pressure relief valve and the oil pressure relief valve closure bolt (1) and tighten to 21 N.m (16 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 4	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 455: Knock Sensor And Bolt Courtesy of GENERAL MOTORS COMPANY

4. Install the knock sensor (1) and the knock sensor bolt (2) and tighten to 20 N.m (15 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 500	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 456: Oil Flow Check Valve Courtesy of GENERAL MOTORS COMPANY

5. Install the oil flow check valve (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 501	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 457: Oil Pressure Switch
Courtesy of GENERAL MOTORS COMPANY

6. Install the oil pressure switch (1) and tighten to 20 N.m (15 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 502	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 458: Cylinder Head Locating Pins
Courtesy of GENERAL MOTORS COMPANY

7. Install the cylinder head locating (1, 2).

PISTON AND CONNECTING ROD ASSEMBLE

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 503	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 459: Piston Ring Joint Positions
Courtesy of GENERAL MOTORS COMPANY

- 1. Install the piston rings.
 - Insert into the pistons with piston ring wrench and "TOP" pointing upwards.
 - Set the piston ring gap.
 - o First piston ring (right-hand ring) in position (1)
 - o Second piston ring (minute ring) in position (2)
 - o Interim ring of oil scraper ring in position (3), steel band rings of oil scraper ring in position (4 and/or 5)

NOTE: Note installation position of the piston in respect of the connection rod.

- 2. Attach the piston to the connection rod.
 - 1. Press the piston pin into the piston and the connection rod by hand.
 - 2. Insert the retainer in the annular groove on the piston.
 - 3. Ensure the retainer is firmly seated in the groove.
- 3. Install the piston with connection rod. Refer to **Piston, Connecting Rod, and Bearing Installation**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 504	© 2011 Mitchell Repair Information Company, LLC.


2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

CYLINDER HEAD ASSEMBLE

Special Tools

- EN-958 Valve Stem Seal Installer
- EN-8062 Valve Spring Compressor
- EN-8062-5 Adapter
- EN-50717-2 Compressor Assembly of EN-50717 Kit

For equivalent regional tools, refer to **Special Tools**.



<u>Fig. 460: Valve Stem Oil Seal And Installer</u> Courtesy of GENERAL MOTORS COMPANY

1. Lubricate the valve stem and the valve guide with clean engine oil.

NOTE: Ensure all valve train components will be installed in their original position.

- 2. Install the valve (5).
- 3. Install the NEW valve stem oil seal (4), using the EN-958 installer (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 505	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

4. Loosely install the valve spring (3) and the valve spring retainer (1).




Fig. 461: Valve Spring Compressor And Adapter Assembly Courtesy of GENERAL MOTORS COMPANY

- 5. Install the EN-50717-2 assembly (1) to the EN-8062 compressor (4).
- 6. Install the EN-8062-5 adapter (3) to the EN-8062 compressor.
- 7. Install the compressor assembly to the cylinder head, so that the adapter (5) of the **EN-50717-2** assembly (1) contacts the valve spring retainer properly and the **EN-8062-5** adapter (3) contacts the valve disc (2). Prefix the **EN-8062** compressor (4).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 506	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 462: Valve Spring Retainer And Valve Spring Courtesy of GENERAL MOTORS COMPANY


CAUTION: The valve stem keys must correctly seat in the valve spring cap. Engine damage may occur by not installing properly.

- 8. Apply pressure to the **EN-50717-2** assembly to push down the vale spring retainer (1) and compress the valve spring (3) until the valve keys (2) can be inserted. Carefully insert the valve keys then, so that they are proper installed to the valve stem grooves.
- 9. Carefully release the tension from the **EN-50717-2** assembly.
- 10. Inspect the valve keys and valve spring retainers for proper seat.
- 11. Remove the compressor assembly from the cylinder head.
- 12. Repeat the procedure with the remaining valves.

INTAKE MANIFOLD ASSEMBLE

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 507	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 463: Intake Manifold, Multiport Fuel Injection Fuel Rail, Fuel Injectors, Seals And Bolts</u> Courtesy of GENERAL MOTORS COMPANY


- 1. Install the 4 NEW multiport fuel injector seals (4).
- 2. Install the multiport fuel injection fuel rail (2) and the fuel injectors (3) to the intake manifold (5).

CAUTION: Refer to Fastener Caution.

3. Install the 2 multiport fuel injection fuel rail bolts (1) and tighten to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 5	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 464: Intake Manifold, Evaporative Emission Canister Purge Solenoid Valve Bracket And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 4. Install the evaporative emission canister purge solenoid valve bracket (1) to the intake manifold (3).
- 5. Install the 2 evaporative emission canister purge solenoid valve bracket bolts (2) and tighten to 7 N.m (62 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 5	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 465: Intake Manifold, Intake Manifold Seal And Throttle Body Seal</u> Courtesy of GENERAL MOTORS COMPANY

- 6. Install the NEW intake manifold seal (3) to the intake manifold (2).
- 7. Install the NEW throttle body seal (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 466: Intake Manifold And Mount Courtesy of GENERAL MOTORS COMPANY

8. Install the intake manifold mount (2) to the intake manifold (1) and tighten to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 5	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 467: Intake Manifold, Manifold Absolute Pressure Sensor And Bolt</u> Courtesy of GENERAL MOTORS COMPANY

- 9. Install the manifold absolute pressure sensor (2) to the intake manifold (3).
- 10. Install the intake manifold absolute pressure sensor bolt (1) and tighten to 6 N.m (53 lb in).

CRANKSHAFT AND BEARING INSTALLATION

Special Tools

EN-45059 Torque Angle Sensor Kit

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 512	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 468: Crankshaft Bearing Clip Courtesy of GENERAL MOTORS COMPANY

NOTE: Inspect the installation position.

- 1. Install the crankshaft bearing clips, oil bearing clips.
- 2. Install the crankshaft.

NOTE: Inspect the installation position.


- 3. Install the crankshaft bearing caps 1-4.
 - Oil bearing clips.
 - Install the 8 NEW crankshaft bearing cap bolts.

NOTE: Inspect the installation position.

- 4. Install the crankshaft bearing cap.
 - 1. Apply black adhesive sealing compound to the grooves of the rear crankshaft bearing cap.
 - 2. Install the 2 NEW crankshaft bearing cap bolts.

	•	
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a.m.	Page 513	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 469: Crankshaft Bearing Cap Bolts</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 5. Tighten the bolts for the crankshaft bearing caps (1) in 3 passes using the EN-45059 sensor kit:
 - First pass to 50 N.m (37 lb ft)
 - Second pass to 45°
 - Third pass to 15°

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 514	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 470: Connecting Rod Bearing Caps
Courtesy of GENERAL MOTORS COMPANY

NOTE: Inspect the installation position.

- 6. Install the connecting rod bearing caps 2 and 3 (1) and oil the bearing clips.
- 7. Install 4 NEW connecting rod bearing cap bolts and tighten in 3 passes use the EN-45059 sensor kit:
 - First pass to 35 N.m (26 lb ft)
 - Second pass to 45°
 - Third pass to 15°

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:04 a. m.	Page 515	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 471: Connecting Rod Bearing Caps</u> Courtesy of GENERAL MOTORS COMPANY

8. Turn the crankshaft through 180°.

NOTE: Inspect the installation position.

- 9. Install the connecting rod bearing caps 1 and 4 (1) and oil the bearing clips.
- 10. Install 4 NEW connecting rod bearing cap bolts and tighten in 3 passes use the EN-45059 sensor kit:
 - First pass to 35 N.m (26 lb ft)
 - $\bullet~$ Second pass to 45°
 - Third pass to 15°

PISTON, CONNECTING ROD, AND BEARING INSTALLATION


Special Tools

EN-45059 Angle Meter

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a. m.	Page 51	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 1. Lubricate the piston rings, piston, inner cylinder bore surface and a piston ring compressor with clean engine oil.
- 2. Install the piston ring compressor in order to compress the piston rings.



<u>Fig. 472: Connecting Rod Assembly, Connecting Rod Bearing And Connecting Rod Cap</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Install the piston and connecting rod assembly (4).
- 4. Install the connecting rod bearing (3).
- 5. Install the connecting rod cap (1).

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to Torque-to-Yield Fastener Caution.

- 6. Install NEW connecting rod bolts (2) and tighten a first pass to 35 N.m (26 lb ft).
- 7. Tighten the NEW connecting rod bolts a second pass to an additional 45 degrees, using the **EN-45059** meter.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a. m.	Page 51	7 © 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze


- 8. Tighten the NEW connecting rod bolts a final pass to an additional 15 degrees, using the **EN-45059** meter.
- 9. Assemble the caps and connecting rods in the marked position.
- 10. Rotate the crankshaft to a position where the connecting rod bolts are easy accessible.

CYLINDER HEAD INSTALLATION

Special Tools

EN-45059 Torque Angle Sensor Kit

- 1. Clean the sealing surfaces.
- 2. Inspect for plane surface.
 - Cylinder block, cylinder head
 - Straight-edge, feeler gauge
- 3. Install the cylinder head gasket.
- 4. Install the cylinder head.



Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 518	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Fig. 473: Cylinder Head Bolts Tightening Sequence Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

NOTE: Note the correct tightening sequence.

- 5. Install NEW cylinder head bolts.
- 6. Tighten the bolts (1) in 5 passes. Use the EN-45059 sensor kit:
 - First pass to 25 N.m (18 lb ft)
 - Second pass to 90°
 - Third pass to 90°
 - Fourth pass to 90°
 - Fifth pass to 45°

VALVE LIFTER INSTALLATION

Special Tool

EN-845 Suction Device

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 474: Valve Lifters
Courtesy of GENERAL MOTORS COMPANY

NOTE: Observe the correct locations.

NOTE: Coat the sliding surfaces with NEW engine oil.

Install the 16 valve lifter (1), using the EN-845 suction device.


CAMSHAFT INSTALLATION

Special Tools

EN-422 Installer

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 520	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 475: Intake Camshaft Bearing Cover Bolts Tightening Sequence</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Coat with MoS 2 lubricating paste. Refer to <u>Adhesives, Fluids, Lubricants, and Sealers</u>.

1. Install the intake camshaft (1).

NOTE: Note the identification marking on the camshaft bearing cover.


2. Install the 4 intake camshaft bearing cover number 2-5.

CAUTION: Refer to Fastener Caution.

3. Install the 8 intake camshaft bearing cover bolts and tighten in a spiral from the inside to the outside to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 521	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 476: Exhaust Camshaft Bearing Cover Bolts Tightening Sequence</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: Coat with MoS 2 lubricating paste. Refer to <u>Adhesives, Fluids, Lubricants, and Sealers</u>.

4. Install the exhaust camshaft (1).

NOTE: Note the identification marking on the camshaft bearing cover.

- 5. Install the 4 exhaust camshaft bearing cover number 6-9.
- 6. Install the 8 exhaust camshaft bearing cover bolts and tighten in a spiral from the inside to the outside to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 522	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 477: Oil Duct Courtesy of GENERAL MOTORS COMPANY

NOTE: Sealing surfaces must be free from oil and grease.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 478: Sealing Surfaces And Grooves
Courtesy of GENERAL MOTORS COMPANY

NOTE:

- Sealing surfaces (arrows) must be free from oil and grease.
- It is essential to ensure that no sealant is applied outside the marked sealing areas (1).
- The grooves adjacent to the sealing surfaces must remain free from sealant.
- 7. Clean sealing surfaces of the first camshaft bearing support and the cylinder head with a suitable tool.

Clean oil duct from any sealant residue.

- 8. Apply surface sealant to sealing surfaces of the first camshaft bearing cap thinly and evenly.
- 9. Position the first camshaft bearing cap on the cylinder block and tighten the bolts approximately to 2 N.m (18 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 524	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 479: Camshaft Bearing Cap Courtesy of GENERAL MOTORS COMPANY

NOTE: No sealant may reach the camshafts.

10. Install the first camshaft bearing cap.

NOTE: Note installation sequence 1-4.

11. Install the first camshaft bearing cap (1) bolts and tighten to 8 N.m (71 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 525	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 480: Camshaft Sprocket Bolt, Shims And Tool Courtesy of GENERAL MOTORS COMPANY

- 12. Install 2 NEW sealing rings to the camshafts.
- 13. Tighten the seal ring with **EN-422** installer (3) on the camshaft until this is in contact with the cylinder head.
- 14. To install, use camshaft sprocket bolt (1) in conjunction with shims (2) with a total thickness of approximately 10 mm.
- 15. Remove the EN-422 installer (3).

CAMSHAFT COVER INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 526	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 481: Camshaft Cover And Bolts
Courtesy of GENERAL MOTORS COMPANY

1. Install the camshaft cover (1).

Insert a NEW gasket in the camshaft cover.

CAUTION: Refer to Fastener Caution.

2. Install the 11 bolts (2, 3) and tighten to 8 N.m (71 lb in).

IGNITION COIL INSTALLATION

Special Tools

EN-6009 Remover/Installer Ignition Module

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 527	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 482: Ignition Coil Module And Special Tool Courtesy of GENERAL MOTORS COMPANY

- 1. Install the ignition coil module (2) with the EN-6009 remover/installer (1).
- 2. Remove the **EN-6009** remover/installer (1).

CAUTION: Refer to Fastener Caution

NOTE: Note the arrow on the cover.

3. Install the 2 ignition coil bolts and tighten to 8 N.m (71 lb in).

NOTE: Note the arrow on the cover.

4. Install the cover of the DIS ignition coil against the direction of the arrow.

ENGINE FRONT COVER AND OIL PUMP INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 528	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 483: Engine Oil Pump Courtesy of GENERAL MOTORS COMPANY

- 1. Install the NEW engine cover gasket (1).
- 2. Install the engine cover with the included oil pump (4).

CAUTION: Refer to Fastener Caution.

3. Install the 8 engine cover bolts (2, 3) and tighten to 20 N.m (15 lb ft).

OIL PAN INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 529	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 484: Joints For Sealant Application
Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the sealing surfaces.
- 2. Apply approximately a 3.5 mm (0.138 in) thick bead of oil pan sealant to the joints (arrows). Refer to **Adhesives, Fluids, Lubricants, and Sealers** for the recommended sealant.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 53	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 485: Sealant Application Area
Courtesy of GENERAL MOTORS COMPANY

NOTE: The assembly time, including torque check, must take no longer than 10 minutes.

3. Apply approximately a 3.5 mm (0.138 in) thick bead of oil pan sealant (1) to the oil pan. Refer to **Adhesives, Fluids, Lubricants, and Sealers** for the recommended sealant.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 53	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 486: Oil Pan And Bolts
Courtesy of GENERAL MOTORS COMPANY

4. Install the oil pan (2).


CAUTION: Refer to Fastener Caution

5. Install the 15 oil pan bolts (1) on the cylinder block and tighten to 10 N.m (89 lb in).

ENGINE OIL HEATER INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a. m.	Page 532	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 487: Engine Oil Heater</u> Courtesy of GENERAL MOTORS COMPANY

1. Install the engine oil heater (2).


CAUTION: Refer to Fastener Caution.

2. Install the engine oil heater bolt (1) and tighten to 40 N.m (30 lb ft).

WATER PUMP INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 533	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 488: Water Pump And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the sealing surfaces and the 3 coolant pump threads.
- 2. Install NEW gasket.

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to Torque-to-Yield Fastener Caution.

- 3. Install the coolant pump (1).
- 4. Install 5 NEW bolts (2) and tighten to 8 N.m (71 lb in).

WATER PUMP PULLEY INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 534	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 489: Water Pump And Water Pump Pulley Courtesy of GENERAL MOTORS COMPANY

NOTE: Counterhold the crankshaft balancer. The belt has to be installed for this procedure.

1. Install the water pump pulley (2) to the water pump (3).

CAUTION: Refer to Fastener Caution.

2. Install the 3 water pump pulley bolts (1) with locking compound and tighten to 20 N.m (15 lb ft).

Refer to Adhesives, Fluids, Lubricants, and Sealers.

ENGINE OIL COOLER INSTALLATION

1. Clean the engine oil cooler to the oil filter housing sealing surfaces.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 535	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 490: Engine Oil Cooler Courtesy of GENERAL MOTORS COMPANY

2. Install the NEW engine oil cooler gasket (2) and the engine oil cooler (1) to the engine oil cooler housing.

CAUTION: Refer to Fastener Caution.


3. Install the 6 engine oil cooler bolts (3) and tighten to 8 N.m (71 lb in).

ENGINE OIL COOLER HOUSING INSTALLATION

- 1. Clean the engine oil cooler housing to thermostat housing sealing surfaces.
- 2. Install 2 NEW gaskets.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 536	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 491: Engine Oil Cooler Housing, Bolts And Engine Oil Cooler Inlet Pipe</u> Courtesy of GENERAL MOTORS COMPANY

- 3. Install the engine oil cooler inlet pipe (3).
- 4. Install the engine oil cooler housing (1) and the 5 engine oil cooler bolts (2) and tighten to 25 N.m (18 lb ft).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 5	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 492: Engine Oil Cooler Outlet Pipe And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 5. Install the thermostat housing coolant pipe (2) to the engine oil cooler housing.
- 6. Install the 2 thermostat housing coolant pipe bolts (1) and tighten to 8 N.m (71 lb in).

ENGINE COOLANT THERMOSTAT HOUSING INSTALLATION

CAUTION: Refer to Engine Coolant Thermostat Housing Caution.

- 1. Clean sealing surface.
- 2. Install a NEW engine coolant thermostat housing seal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 538	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 493: Engine Coolant Thermostat Housing Courtesy of GENERAL MOTORS COMPANY

3. Install the engine coolant thermostat housing (2).


CAUTION: Refer to Fastener Caution.

NOTE: Screw in the 4 bolts until the engine coolant thermostat housing is in contact with the cylinder head.

4. Install the 4 engine coolant thermostat housing bolts (3) and tighten to 2 N.m (18 lb in).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 539	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 494: Engine Coolant Thermostat Housing Bolts Tightening Sequence</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Following the proper fastener tightening sequence and torque is essential. Failure to do so may fracture the thermostat housing.

5. Tighten the 4 engine coolant thermostat housing bolts to 8 N.m (71 lb in) in sequence (1-2-3-4).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 540	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 495: Engine Coolant Thermostat Housing Courtesy of GENERAL MOTORS COMPANY

- 6. Install the engine coolant thermostat housing retainer (1).
- 7. Install the engine coolant thermostat housing retainer nut (4) and tighten to 6 N.m (53 lb in).

ENGINE COOLANT THERMOSTAT INSTALLATION

CAUTION: Refer to Engine Coolant Thermostat Housing Caution.

1. Clean the engine coolant sealing surfaces.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 541	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 496: Engine Coolant Thermostat Assembly Courtesy of GENERAL MOTORS COMPANY

- 2. Install the engine coolant seal (1).
- 3. Install the engine coolant thermostat assembly (2).

CAUTION: Refer to Fastener Caution.

4. Install the 4 engine coolant thermostat bolts (3) and tighten to 8 N.m (71 lb in).

EXHAUST MANIFOLD INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 542	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 497: Exhaust Manifold And Bolts
Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the exhaust manifold sealing surface.
- 2. Install a NEW exhaust manifold gasket (1) to the cylinder head.

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to $\underline{\text{Torque-to-Yield Fastener Caution}}$.

- 3. Install the exhaust manifold (3) and tighten the NEW nuts (4) to 20 N.m (15 lb ft).
- 4. Install the 2 exhaust manifold bracket bolts (2) to 20 N.m (15 lb ft).

OIL LEVEL INDICATOR AND TUBE INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 543	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 498: Oil Level Indicator Tube And Bolt Courtesy of GENERAL MOTORS COMPANY

- 1. Install a NEW oil level indicator tube gasket.
- 2. Install the oil level indicator tube (2).

CAUTION: Refer to Fastener Caution.

- 3. Install the oil level indicator tube bolt (1) and tighten to 15 N.m (11 lb ft).
- 4. Install the oil dipstick.

INTAKE MANIFOLD INSTALLATION

- 1. Clean the sealing surfaces.
- 2. Install 4 NEW gaskets.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:05 a.m.	Page 544	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 499: Intake Manifold And Bolts
Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

3. Install the intake manifold (2) and the 7 intake manifold bolts (1) and tighten to 20 N.m (15 lb ft).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 500: Intake Manifold Brace And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 4. Install the intake manifold brace (1).
- 5. Install the 2 intake manifold brace bolts (2, 3) and tighten to 8 N.m (71 lb in).

THROTTLE BODY ASSEMBLY INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 546	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 501: Throttle Body And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Install a NEW throttle body seal.
- 2. Install the throttle body (1).

CAUTION: Refer to Fastener Caution.

3. Install the 4 throttle body bolts (2) and tighten to 8 N.m (71 lb in).

CRANKSHAFT FRONT OIL SEAL INSTALLATION


Special Tools

EN-6351 Mounting Sleeves

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 547	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




<u>Fig. 502: Crankshaft And Crankshaft Front Oil Seal</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the sealing surfaces.
- 2. Slide the EN-6351 sleeves (2) protective sleeve onto the crankshaft journal.
- 3. Slide the crankshaft front oil seal (1) over the protective sleeve on the crankshaft journal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 548	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 503: Crankshaft Drive Gear Bolt, Washer And Sleeves</u> Courtesy of GENERAL MOTORS COMPANY


- 4. Remove the protective sleeve, and using the **EN-6351** sleeves (3), press the seal ring into the pump housing.
- 5. Use the crankshaft drive gear bolt (1) and washer (2) to press in the crankshaft front oil seal.

TIMING BELT REAR COVER INSTALLATION

1. Re-cut the 4 rear timing belt cover threads.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 549	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 504: Timing Belt Rear Cover And Bolts</u> Courtesy of GENERAL MOTORS COMPANY

2. Install the timing belt rear cover (1).

CAUTION: Refer to Fastener Caution.

Service may offer bolts that are not microencapsulated. If this is the case apply thread lock agent to the bolt. If fastener is microencapsulated, install a NEW 4 timing belt rear cover bolts. DO NOT reuse the old bolt.

3. Install the 4 NEW timing belt rear cover bolts (2) and tighten to 6 N.m (53 lb in).

CAMSHAFT POSITION ACTUATOR ADJUSTER INSTALLATION

Special Tools

NOTE:

- EN-6340 Camshaft Adjuster Locking Tool
- EN-6628-A Camshaft Locking Tool
- EN-45059 Angle Meter

- Zi (1000) Tingio Iviotoi		
Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 550	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tools, refer to **Special Tools**.




Fig. 505: Aligning Camshafts Horizontally
Courtesy of GENERAL MOTORS COMPANY

NOTE: Note the arrows.

1. Turn the camshaft by the hexagon until the groove on the end of the camshafts is horizontal.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 551	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 506: Locking Tool
Courtesy of GENERAL MOTORS COMPANY

2. Install the EN-6628-A locking tool (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 552	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 507: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: If the cover is contaminated with oil, you have to clean it close.

- 3. Install intake camshaft position actuator adjuster and/or the exhaust camshaft position actuator adjuster (3).
- 4. Install a NEW intake camshaft position actuator adjuster bolt and/or a NEW exhaust camshaft position actuator adjuster bolt (2). DO NOT tighten the bolts yet.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 5	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 508: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

NOTE:

5. Install the EN-6340 locking tool into the camshaft position actuator adjusters.

The spot type marking (4) on the intake camshaft position actuator adjuster does not correspond to the groove of EN-6340-left locking tool - left during this process but must be somewhat above as

shown.

1. Install the EN-6340-left locking tool (1) in the camshaft position actuator adjusters as shown.

NOTE: The spot type marking (3) on the exhaust camshaft position actuator


adjuster must correspond to the groove on EN-6340-left locking tool -

right.

2. Install the EN-6340-right locking tool (2) in the camshaft position actuator adjusters as shown.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 554	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 509: Camshaft Position Actuator Adjuster Closure Bolt</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

NOTE: A second technician is required.

NOTE: Use an appropriate open-end wrench in order to counterhold the camshaft

hexagon. A thin cross-section wrench is required for a better fit. The usage of EN-6628-A locking tool is for the camshaft adjustment to prevent misalignment of the camshafts. The wrench is required to counterhold the

camshafts during bolt torque procedure.

- 6. Install the camshaft position actuator adjuster bolts (2) and tighten the bolts in 3 passes using the **EN-45059** meter.
 - 1. First pass to 50 N.m (37 lb ft)

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 555	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- 2. Second pass to an additional 150 degrees
- 3. Final pass to an additional 15 degrees

NOTE: Check the closure bolt seal ring.

- 7. Install the 2 camshaft position actuator adjuster closure plugs (1) and tighten to 30 N.m (22 lb ft).
- 8. Remove the EN-6628-A locking tool.
- 9. After the installation of the timing belt, rotate the engine 720 degrees and check the position of the crankshaft and camshafts, again. Refer to **Timing Belt Adjustment**.

CAMSHAFT POSITION ACTUATOR SOLENOID VALVE INSTALLATION




Fig. 510: Camshaft Position Actuator Solenoid Valves, Bolts And Seals Courtesy of GENERAL MOTORS COMPANY

NOTE: Lubricate the NEW camshaft position actuator solenoid valve seals with NEW engine oil. Refer to <u>Adhesives</u>, <u>Fluids</u>, <u>Lubricants</u>, <u>and Sealers</u>.

- 1. Install NEW camshaft position actuator solenoid valve seals (3).
- 2. Install the camshaft position actuator solenoid valves (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 55	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

CAUTION: Refer to Fastener Caution.

3. Install the camshaft position actuator solenoid valve bolts (1) and tighten to 6 N.m (53 lb in).

CRANKSHAFT SPROCKET INSTALLATION




Fig. 511: Crankshaft Sprocket Courtesy of GENERAL MOTORS COMPANY

NOTE: When installing the crankshaft sprocket, the cam and the groove must align (2).

Install the crankshaft sprocket (1).

TIMING BELT IDLER PULLEY INSTALLATION

Special Tools

EN-45059 Angle Meter

For equivalent tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 557	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 512: Timing Belt Idler Pulley Bolt Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

 $\textbf{CAUTION: Refer to } \underline{\textbf{Torque-to-Yield Fastener Caution}} \;.$

- 1. Install the timing belt idler pulley (1) and tighten the NEW bolt (2) in three passes use the **EN-45059** meter :
 - 1. First pass tighten to 20 N.m (15 lb ft).
 - 2. Second pass to 120 degrees.
 - 3. Final pass to 15 degrees.
- 2. Install the timing belt. Refer to **Timing Belt Replacement**.


TIMING BELT TENSIONER INSTALLATION

Special Tools

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 55	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

EN-45059 Angle Meter



<u>Fig. 513: Timing Belt Tensioner</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Clean the timing belt tensioner thread.
- 2. Install the timing belt tensioner (2).

CAUTION: Refer to Fastener Caution.

CAUTION: Refer to Torque-to-Yield Fastener Caution.

- 3. Install a NEW timing belt tensioner bolt (1) and tighten the bolt in 3 passes using the EN-45059 meter.
 - 1. First pass to 20 N.m (15 lb ft).
 - 2. Second pass to an additional 120 degrees.
 - 3. Final pass to an additional 15 degrees.

TIMING BELT INSTALLATION


Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a. m.	Page 559	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Special Tools

- EN-6333 Locking Pin
- EN-6340 Locking Tool

For equivalent regional tools, refer to **Special Tools**.



<u>Fig. 514: Aligning Timing Belt Drive Gear And Oil Pump Housing</u> Courtesy of GENERAL MOTORS COMPANY

NOTE: The timing belt drive gear and oil pump housing must align.

1. Turn the crankshaft in the direction of engine rotation, by the crankshaft balancer bolt, to cylinder 1 TDC of combustion stroke.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 560	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 515: Front Panel And Bolts
Courtesy of GENERAL MOTORS COMPANY

NOTE: The right half of the EN-6340 locking tool can be recognized by the lettering right, arrow, on the tool.

- 2. Prepare the right half of the EN-6340 locking tool.
 - 1. Remove the 2 bolts (2).
 - 2. Detach the front panel (1) from the EN-6340 locking tool right.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 561	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 516: Spot Type Markings And Special Tool Courtesy of GENERAL MOTORS COMPANY

NOTE:

- The spot type marking (4) on the intake camshaft adjuster does not correspond to the groove of the EN-6340 locking tool - left (1) during this process, but must be somewhat above.
- The spot type marking (3) on the exhaust camshaft adjuster must correspond to the groove on EN-6340 locking tool right (2).
- 3. Insert the EN-6340 locking tool left (1) and the EN-6340 locking tool right (2) in the camshaft adjuster.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 50	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 517: Timing Belt And Timing Belt Tensioner Courtesy of GENERAL MOTORS COMPANY

NOTE: Observe direction of rotation.

4. Insert the timing belt (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 563	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 518: Drive Belt Tensioner, Allen Key And Locking Pin</u> Courtesy of GENERAL MOTORS COMPANY

- 5. Apply tension to the timing belt tensioner (2) in the direction of the arrow, using an Allen key (1).
- 6. Remove the EN-6333 locking pin (3).

NOTE: The timing belt tensioner moves automatically to the correct position.

- 7. Release tension on timing belt tensioner.
- 8. Remove the EN-6340 locking tool.
- 9. Check position of the camshaft sprocket.
 - 1. Turn crankshaft 720° in the direction of engine rotation by the crankshaft balancer bolt.

NOTE: Note the marking on the camshaft sprocket.

2. Insert EN-6340 locking tool into camshaft sprockets.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 564	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 519: Aligning Timing Belt Drive Gear And Oil Pump Housing Courtesy of GENERAL MOTORS COMPANY


NOTE: The timing belt drive gear and oil pump housing must align.

10. Check the crankshaft position.

TIMING BELT LOWER FRONT COVER INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a. m.	Page 565	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 520: Timing Belt Lower Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

Install the timing belt cover (1) and tighten the 4 timing belt lower front cover bolts (2) to 6 N.m (53 lb in).

CRANKSHAFT BALANCER INSTALLATION

Special Tools

- EN-652 Flywheel Holder
- EN-45059 Angle Meter

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 566	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 521: Flywheel And Flywheel Holder Courtesy of GENERAL MOTORS COMPANY

1. Install the EN-652 holder (1), lock the flywheel (2) or the automatic transmission flex plate via the starter ring gear.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 56	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 522: Crankshaft Balancer, Washer And Bolt Courtesy of GENERAL MOTORS COMPANY

NOTE: Use care that the height (1) of the washer is facing towards the bolt.

2. Install the crankshaft balancer (2) and the washer (3).

CAUTION: Refer to Fastener Caution.


CAUTION: Refer to <u>Torque-to-Yield Fastener Caution</u>.

- 3. Install a NEW crankshaft balancer bolt (4) and tighten the bolt in 3 passes using the EN-45059 meter
 - 1. First pass to 95 N.m (70 lb ft).
 - 2. Second pass to an additional 45°,
 - 3. Final pass to an additional 15°.

TIMING BELT CENTER FRONT COVER INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a. m.	Page 568	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 523: Timing Belt Center Front Cover</u> Courtesy of GENERAL MOTORS COMPANY

Install the timing belt center front cover (1) to the timing belt rear cover at 2 locations.

TIMING BELT UPPER FRONT COVER INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 569	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 524: Timing Belt Upper Front Cover Courtesy of GENERAL MOTORS COMPANY

1. Install the timing belt upper front cover (1).

CAUTION: Refer to Fastener Caution.

2. Install the 2 timing belt upper front cover bolts (2) and tighten to 6 N.m (53 lb in).

DRIVE BELT INSTALLATION

Special Tools

EN-6349 Locking Pin

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 570	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 525: Drive Belt Routing Courtesy of GENERAL MOTORS COMPANY

1. Install the drive belt (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 571	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 526: Checking Drive Belt Position
Courtesy of GENERAL MOTORS COMPANY

NOTE: Make sure that the drive belt is aligned on the generator pulley (4), crankshaft balancer (5), drive belt tensioner (6) and water pump pulley (7). The drive belt must lie on the water pump pulley between the flange (1)

and (2).

2. Check the position of the drive belt (3).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 572	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 527: Drive Belt Tensioner And Special Tool Courtesy of GENERAL MOTORS COMPANY

3. Release tension to the tensioner counterclockwise (1).

NOTE: Allow tensioner to slide back slowly.

- 4. Remove EN-6349 pin (2).
- 5. Apply tension to the tensioner at projection (1) clockwise.

DRIVE BELT TENSIONER INSTALLATION

1. Clean the drive belt tensioner thread.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 573	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 528: Drive Belt Tensioner Bolt Courtesy of GENERAL MOTORS COMPANY

2. Install drive belt tensioner (2).


CAUTION: Refer to Fastener Caution.

3. Install drive belt tensioner bolt (1) and tighten to 55 N.m (41 lb ft).

POSITIVE CRANKCASE VENTILATION PIPE INSTALLATION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 574	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 529: Positive Crankcase Ventilation Tube, Connectors And ECM Wiring Harness Guide</u> Courtesy of GENERAL MOTORS COMPANY

- 1. Install the positive crankcase ventilation tube (2).
- 2. Connect the 2 positive crankcase ventilation tube connectors (1).
- 3. Clip in the ECM wiring harness guide (3) to the cylinder head cover.

ENGINE FLYWHEEL INSTALLATION

Special Tools

- EN-652 Flywheel Holder
- EN-45059 Torque Angle Sensor Kit

For equivalent regional tools, refer to **Special Tools**.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:06 a.m.	Page 575	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 530: Crankshaft Position Reluctor Ring Courtesy of GENERAL MOTORS COMPANY

1. Install the crankshaft position reluctor ring (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 576	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 531: Flywheel And Flywheel Holder</u> Courtesy of GENERAL MOTORS COMPANY

- 2. Install the flywheel (2).
- 3. Install the EN-652 holder (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a. m.	Page 577	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 532: Flywheel And Bolts
Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

 $\textbf{CAUTION: Refer to } \underline{\textbf{Torque-to-Yield Fastener Caution}} \; .$

- 4. Install the 6 NEW flywheel bolts (1, 2) and tighten the bolts in 3 passes using the EN-45059 sensor kit:
 - 1. First pass to 60 N.m (44 lb ft).
 - 2. Second pass to additional 45°.
 - 3. Third pass to an additional 15° .
- 5. Remove the EN-652 holder.

AUTOMATIC TRANSMISSION FLEX PLATE INSTALLATION

Special Tools

EN-652 Automatic Transmission Flex Plate Holder

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 578	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tools, refer to **Special Tools**.

1. Clean the automatic transmission flex plate bolt threads.




Fig. 533: Automatic Transmission Flex Plate And Holder Courtesy of GENERAL MOTORS COMPANY

2. Install the automatic transmission flex plate (2) and the **EN-652** holder to hold the automatic transmission flex plate (2).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 57	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 534: Automatic Transmission Flex Plate And Bolts Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

 $\textbf{CAUTION: Refer to } \underline{\textbf{Torque-to-Yield Fastener Caution}} \; .$

- 3. Install the 6 NEW automatic transmission flex plate bolts (2) and tighten the bolts to 60 N.m (44 lb ft) \pm 5°.
- 4. Remove the EN-652 holder.

CRANKSHAFT REAR OIL SEAL INSTALLATION

Special Tools

- EN-658-1 Installer
- EN-235-6 Installer

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a. m.	Page 580	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

For equivalent regional tools, refer to **Special Tools**.





Fig. 535: Crankshaft Rear Oil Seal Courtesy of GENERAL MOTORS COMPANY

1. Slide the crankshaft rear oil seal (2) across the EN-235-6 installer (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 536: Crankshaft Rear Oil Seal And Installer</u> Courtesy of GENERAL MOTORS COMPANY

2. Install the crankshaft rear oil seal (1) with EN-235-6 installer (2) to the crankshaft.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 582	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze





Fig. 537: Oil Seal Installer Courtesy of GENERAL MOTORS COMPANY

3. Use EN-658-1 installer (2) to strike the crankshaft rear oil seal (1)

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 5	© 2011 Mitchell Repair Information Company, LLC.


2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze



<u>Fig. 538: Check Crankshaft Rear Oil Seal For Proper Seat</u> Courtesy of GENERAL MOTORS COMPANY

4. Check the crankshaft rear oil seal for proper seat, the **EN-658-1** installer must be flush with the cylinder block at the position (1).

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a. m.	Page 584	© 2011 Mitchell Repair Information Company, LLC.



<u>Fig. 539: Crankshaft Position Sensor Reluctor Ring And Oil Seal Housing</u> Courtesy of GENERAL MOTORS COMPANY

- 5. Install the reluctor ring (2).
- 6. Install the crankshaft rear oil seal housing (1).

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 540: Crankshaft Position Sensor And Bolt Courtesy of GENERAL MOTORS COMPANY

7. Install the crankshaft position sensor (3) to the crankshaft rear oil seal housing (1).

CAUTION: Refer to Fastener Caution.

8. Install the crankshaft position sensor bolt (2) and tighten to 4.5 N.m (40 lb in).

DESCRIPTION AND OPERATION

CLEANLINESS AND CARE

An automobile engine is a combination of many machined, honed, polished, and lapped surfaces with tolerances that are measured in ten thousandths of an inch. When any internal engine parts are serviced, care and cleanliness are important. A liberal coating of engine oil should be applied to friction areas during assembly to protect and lubricate the surfaces during initial operation. Throughout this section, it should be understood that proper cleaning and protection of machined surfaces and friction areas are part of the repair procedure. This is considered standard shop practice even if not specifically stated.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a. m.	Page 58	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

When valve train components are removed for service, they should be retained in order. At the time of installation, they should be installed in the same locations and with the same mating surfaces as when removed.

ENGINE COMPONENT DESCRIPTION

Cylinder Block

The cylinder hollow frame structured 4 cylinder in-line. The block has 5 crankshaft bearings with the thrust bearing located on the third bearing from the front of the engine.

Crankshaft

The crankshaft is a steel crankshaft. It is supported in 5 main journals with main bearings which have oil clearance for lubricating. The 3rd bearing of the 5 main bearing is the thrust bearing whose the crankshaft has properly axial end play. A harmonic damper is used to control torsional vibration.

Oil Pump

The oil pump is a crankshaft driven oil pump integrated in pump module. The oil pump draws engine oil from the oil pan and feeds it under pressure to the various parts of the engine. An oil strainer is mounted before the inlet of the oil pump to remove impurities which could clog or damage the oil pump or other engine components. When the crankshaft rotates, the oil pump driven gear rotates. This causes the space between the gears to constantly open and narrow, pulling oil in from the oil pan when the space opens and pumping the oil out to the engine as it narrows. At high engine speeds, the oil pump supplies a much higher amount of oil than required for lubrication of the engine. The oil pressure regulator prevents too much oil from entering the engine lubrication passages.

Oil Pan

The oil pan is a structural aluminum oil pan with transmission attachment. It includes the oil suction pipe, this pipe is connected with the oil pump. The oil pan is attached at the engine block.

Piston and Connecting Rod

The Pistons are aluminum pistons with top land and floating pin. The connecting rods are fractured steel connecting rods with bushing.

Cylinder Head

This cylinder head is double over head camshaft (DOHC) type and has 2 camshafts that open 4 valves per cylinder with tappets. The camshaft sprocket wheels are installed in front of the camshafts. The cylinder head is made of cast aluminum alloy for better strength in hardness with light weight. The combustion chamber of the cylinder head is designed for increasing of squish and swirl efficiency and then this is maximized to gasoline combustion efficiency.

Valves

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 587	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

There are 2 intake and 2 exhaust valves with tappets per cylinder.

Camshaft

Two camshafts are used, one for all intake valves, the other for all exhaust valves. The camshafts are cast iron. The camshafts are driven by the crankshaft over the timing belt.

Camshaft Drive

A timing belt is used for camshaft drive. There is a tensioner to control the tension of the belt. Instead of camshaft gears or camshaft sprockets the engine is equipped with camshaft adjuster. The camshaft adjuster readjust itself at the engine speed. So the valve timing is adjusted for a low consumption, optimal power and torque.

Intake Manifold

The intake manifold is the air flow passage to the cylinder combustion chamber through the throttle body and has an effect on engine torque, power, noise, drivability, emission, fuel economy and performance. It is made of plastic for better strength in hardness with little weight.

Exhaust Manifold

The exhaust manifold is located to the cylinder head and channels the exhaust gas out of the combustion chamber. It is designed to endure on high pressure and high temperature. The exhaust manifold includes the catalytic converter.

Positive Crankcase Ventilation System

The crankcase ventilation system is used to consume crankcase vapors in the combustion process instead of venting vapors to the atmosphere. Fresh air from the intake system is supplied to the crankcase, mixed with blow-by gases and then passed through a calibrated orifice into the throttle body. The primary control is through the positive crankcase ventilation (PCV) orifice which meters the flow at a rate depending on inlet vacuum. The PCV orifice is an integral part of the camshaft cover. If abnormal operating conditions occur, the system is designed to allow excessive amounts of blow-by gases to back flow through the crankcase vent into the intake system to be consumed by normal combustion.

LUBRICATION DESCRIPTION

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 588	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze




Fig. 541: Engine Lubrication System
Courtesy of GENERAL MOTORS COMPANY

Oil is applied under pressure to the crankshaft (8), connecting rods (5), camshaft adjuster (1), camshaft bearing surfaces (3) and valve tappets (4). All other moving parts are lubricated by gravity flow or splash. Oil enters the rotor type oil pump (10) through a fixed inlet screen (9). The oil pump is driven by the crankshaft. The oil pump body is within the engine front cover (11). The pressurized oil from the pump passes through the oil cooling system and the oil filter (6). The oil filter is integrated with the oil cooling system housing (7) that is connected to the front of the engine block. The oil filter is a disposable cartridge type. A by-pass valve in the filter cap allows continuous oil flow in case the oil filter should become restricted. The connecting rod bearings are oiled by constant oil flow passages through the crankshaft connecting the main journals to the rod journals. A groove around each upper main bearing furnishes oil to the drilled crankshaft passages. The pressurized oil passes through the cylinder head restrictor orifice into the cylinder head and then into each camshaft feed gallery. An engine oil pressure switch or sensor is installed at the end. Oil returns to the oil pan through passages cast into the cylinder head. The crankcase ventilation system does not contain to the lubrication system, but to the oil circuit. It is used to consume crankcase vapors in the combustion process instead of venting them to atmosphere. Fresh air from the intake system is supplied to the crankcase, mixed with blow by gases and then passed through a calibrated orifice of the crankcase ventilation tube (2) into the intake manifold.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 589	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

REPLACING ENGINE GASKETS

Gasket Reuse and Applying Sealants

- Do not reuse any gasket unless specified.
- Gaskets that can be reused will be identified in the service procedure.
- Do not apply sealant to any gasket or sealing surface unless called out in the service information.

Separating Components

- Use a rubber mallet to separate components.
- Bump the part sideways to loosen the components.
- Bumping should be done at bends or reinforced areas to prevent distortion of parts.

Cleaning Gasket Surfaces

- Remove all gasket and sealing material from the part using a scraping tool.
- Care must be used to avoid gouging or scraping the sealing surfaces.
- Do not use any other method or technique to remove sealant or gasket material from a part.
- Do not use abrasive pads, sand paper, or power tools to clean the gasket surfaces.
 - o These methods of cleaning can cause damage to the component sealing surfaces.
 - o Abrasive pads also produce a fine grit that the oil filter cannot remove from the oil.
 - o This grit is abrasive and has been known to cause internal engine damage.

Assembling Components

- When assembling components, use only the sealant specified or equivalent in the service procedure.
- Sealing surfaces should be clean and free of debris or oil.
- Specific components such as crankshaft oil seals or valve stem oil seals may require lubrication during assembly.
- Components requiring lubrication will be identified in the service procedure.
- When applying sealant to a component, apply the amount specified in the service procedure.
- Do not allow the sealant to enter into any blind threaded holes, as it may prevent the bolt from clamping properly or cause component damage when tightened.
- Tighten bolts to specifications. Do not overtighten.

SEPARATING PARTS

NOTE:

 Disassembly of the piston, press fit design piston pin, and connecting rod may create scoring or damage to the piston pin and piston pin bore. If the piston, pin, and connecting rod have been disassembled, replace the components as an assembly.

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 590	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

- Many internal engine components will develop specific wear patterns on their friction surfaces.
- When disassembling the engine, internal components MUST be separated, marked, or organized in a way to ensure installation to their original location and position.

Separate, mark, or organize the following components:

- Piston and the piston pin
- Piston to the specific cylinder bore
- Piston rings to the piston
- Connecting rod to the crankshaft journal
- Connecting rod to the bearing cap-A paint stick or etching/engraving type tool are recommended. Stamping the connecting rod or cap near the bearing bore may affect component geometry.
- Crankshaft main and connecting rod bearings
- Camshaft and valve tappets
- Valve to the valve guide
- Valve spring and shim to the cylinder head location
- Engine block main bearing cap location and direction
- Oil pump drive and driven gears

TOOLS AND EQUIPMENT

Special tools are listed and illustrated throughout this section with a complete listing at the end of the section. These tools, or their equivalents, are specially designed to quickly and safely accomplish the operations for which they are intended. The use of these special tools will also minimize possible damage to engine components. Some precision measuring tools are required for inspection of certain critical components. Torque wrenches and a torque angle meter are necessary for the proper tightening of various fasteners.

To properly service the engine assembly, the following items should be readily available:

- Approved eye protection and safety gloves
- A clean, well lit, work area
- A suitable parts cleaning tank
- A compressed air supply
- Trays or storage containers to keep parts and fasteners organized
- An adequate set of hand tools
- Approved engine repair stand
- An approved engine lifting device that will adequately support the weight of the components

USE OF ROOM TEMPERATURE VULCANIZING (RTV) AND ANAEROBIC SEALANT

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a. m.	Page 591	© 2011 Mitchell Repair Information Company, LLC.

2012 ENGINE Engine Mechanical - 1.8L (LUW) - Cruze

Pipe Joint Compound

NOTE:

Three types of sealer are commonly used in engines. These are RTV sealer, anaerobic gasket eliminator sealer, and pipe joint compound. The correct sealer and amount must be used in the proper location to prevent oil leaks. DO NOT interchange the 3 types of sealers. Use only the specific sealer or the equivalent as recommended in the service procedure.

- Pipe joint compound is a pliable sealer that does not completely harden. This type sealer is used where 2 non-rigid parts, such as the oil pan and the engine block, are assembled together.
- Do not use pipe joint compound in areas where extreme temperatures are expected. These areas include: exhaust manifold, head gasket, or other surfaces where gasket eliminator is specified.
- Follow all safety recommendations and directions that are on the container.

To remove the sealant or the gasket material.

- Apply the pipe joint compound to a clean surface. Use a bead size or quantity as specified in the procedure. Run the bead to the inside of any bolt holes. Do not allow the sealer to enter any blind threaded holes, as it may prevent the bolt from clamping properly or cause component damage when the bolt is tightened.
- Apply a continuous bead of pipe joint compound to one sealing surface. Sealing surfaces to be resealed must be clean and dry.
- Tighten the bolts to specifications. Do not overtighten.

SPECIAL TOOLS AND EQUIPMENT

Afinacion de Motor y Diagnostico, OBDII, VW, Audi

viernes, 21 de abril de 2017 10:37:07 a.m.

SPECIAL TOOLS

Illustration	Tool Number/Description
	207649 Rod Hairpins
Quinton Quinton	547324 Flange Screws
	EN-232 KM-232 J-21867-L40 Oil Pressure Check Adapter

Page 592

044 664 252 34 69

© 2011 Mitchell Repair Information Company, LLC.

EN-235-6 KM-235-6 Installer
EN-328-B GE-328-B KM-328-B GE-6125-1B Remover
EN-422 KM-422 83 94 959 Installer
EN-498-B GE-21867-A J-21867-A KM-498-B CH-48027 Pressure Gauge and Adapter Set
EN-652 KM-652 Flywheel Holder
EN-658-1 KM-658-1 J-35264 Installer
EN-796 KM-796-A Dismantler

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 593	© 2011 Mitchell Repair Information Company, LLC.

	CH-807 KM-807 Closure Plugs
	EN-840 KM-840 J-36017 83 94 157 Remover
\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	EN-845 KM-845 Suction Device
	EN-849 KM-849 Assembly Tray
	EN-958 KM-958 Valve Stem Seal Installer
	EN-6009 KM-6009 83 96 335 J-43301 Remover/Installer
	EN-6333 KM-6333 Locking Pin
	EN-6340 KM-6340 Locking Tool

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a. m.	Page 594	© 2011 Mitchell Repair Information Company, LLC.

EN-6349 KM-6349 Locking Pin
EN-6351 KM-6351 Assembly Sleeves
EN-6361 KM-6361 Feeler Gauge Set
EN-6624 KM-6624 Remover
EN-6625 KM-6625 Flywheel Locking Device
EN-6628-A KM-6628-A Locking Tool
EN-8087 J-8087 Cylinder Bore Gauge
EN-28467-B J-28467-B Universal Engine Support Fixture

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a.m.	Page 59	© 2011 Mitchell Repair Information Company, LLC.

	EN-34730-91 KM-34730-91 Pressure Tester
	EN-36857 J-36857 Engine Lift Bracket
	EN-43405 J-43405 Support Foot Set
	EN-45000 KM-45000 J-45000 Seal Remover
G. 195 © MIGGE METERS ON TREASON O	EN-45059 J-45059 Angle Meter
	GE-571-B MKM-571-B GE-8001 J-8001 Dial Gauge
	GE-22738-B J-22738-B Valve Spring Tester
	J-37088-A KM-37088A Fuel Line Disconnect Tool Set

Afinacion de Motor y Diagnostico,OBDII,VW,Audi		044 664 252 34 69
viernes, 21 de abril de 2017 10:37:07 a. m.	Page 596	© 2011 Mitchell Repair Information Company, LLC.

EN-50717-1 Stands
EN-50717-2 Compressor
EN-8062 J-8062 Valve Spring Compressor